

LKK Auto Conjultants Attn: Vic

SMRT AUTOMOTIVE SERVICES PTE LTD

60 Woodlands Industrial Park E4 Singapore 757705 Tel: 65 6866 2652 Fax: 65 6368 7421 www.smrt.com.sq

Date: 9. 1. 2020.

Our Ref .: Tax 11119 2141 /37

Dear Sirs.

ACCIE	DENT INVOLV	VING SHD	648	1P & S	KK 65.	DOM	
						(Thomson	Flyored

LETTER OF CLAIM

We claim on behalf of <u>SMRT TAXIS PTE LTD</u>, owner of motor taxi no.: <u>SHD 64 &1 P</u>.

Your insured's negligent driving has caused the above accident. As a result, my client has suffered the following losses:-

1.	Cost of Repair	:	\$	5,073.96
2.	Loss of Rental for 13 days @ S\$_108.07/day	;	\$	1,404.9)
3.	Loss of Income for 13 days @ S\$60.00 /day	:	\$	780.00
4.	Police Report/ SAS Report/ LTA Search Fee	:	\$	7,00.
5.	Survey Fee	;	\$	- 7.00.
6.	Others	:	-	
	Total Claims		\$ -	1, 2 65.87

We enclose the following documents:-

X	Repair Invoice	X	Vehicle laid-up report	
X	Police Report / SAS Report	X	LTA Search result	
X	Letter of Authorisation		Others:	
	Investigation results	1.		
X	Proof of Loss of Use/Rental/Income	2.		

We look forward to your confirmation to settle our claims within 15 days from the date of this letter. Payment by cheque shall be crossed and made payable to **SMRT TAXIS PTE LTD**.

Yours sincerely,

SMRT AUTOMOTIVE SERVICES PTE LTD

Selena Tan For Manager, Claims Claims Department

Direct line: 6866 2653
Email address: tanselena@smrt.com.sg



Date: AIAIS

Our Ref. No.:

Letter	of	Autl	noris	sation
Contract of the last of the la	-			

registered	hirer relief driver / taxi share driver of SMRT taxi registration number
	hereby authorise SMRT Automotive Services Pte Ltd
and <u>SKK</u>	s") to deal with all matters arising out of the accident between my taxi (6520 M / SMM 35360 happened on 30/10/2019me 12.58 pm PLF TINARDS CHANGE (THINGEN PLYOVER)
	dent") on my behalf, including but not limited to instituting and any claims or
7	gs against such party or parties (as AutoSvs deems fit in its absolute
272	in respect of any claim, demand, loss, cost, expense, liability, damages or
6	de against us or incurred or suffered by us.
actionmad	le against us of incurred of suffered by us.
and settle	rejudice to the foregoing, I further authorise AutoSvs to negotiate, resolve any proceeding or claim arising out of the accidents, including but not limited my act or executing any document or signing the Discharge Voucher on my may be required.
Name	SI628350/I. Signature:
NRIC No.	
Tel No.	88167475
Address	B)K 142 PETIR ROAD #06-300
	Singafore. 670/42



Customer Code: 3000063

SMRT TAXIS PTE LTD

Block Unit

60 WOODLANDS INDUSTRIAL PARK E4

SINGAPORE 757705



SMRT Automotive Services Pte Ltd 251 North Bridge Road Singapore 179102 Tel: 65 63311000 Fax: 65 63340247

Tax Invoice

GST Reg No. : MR-8500001-7
CRN : 199004280Z
Invoice No. : IV191200508
Date : 26.12.2019
Vehicle No. : SHD6481P

Your Ref No. : TAX/11/19/2141

Our Ref No. : 24104651 Terms : 30 Days

Description	Qty		Unit	Add	1	(Di	scount)	Amount
			Cost	용		A	mount	20010
Parts								
BUMPER REAR	1.00	\$	458.60	(25.00)	\$	114.65	\$ 343.95
BUMPER CLIPS	10.00	\$	2.10	(25.00)	\$	5.25	\$ 15.75
PIXEL STICKER	2.00	\$	60.00	0.00		\$	0.00	\$ 120.00
BUMPER REINFORCEMENT REAR	1.00	\$	205.70	(25.00)	\$	51.42	\$ 154.28
ARM SUB-ASSY. RR BUMPER RH	1.00	\$	139.60	(25.00)	\$	34.90	\$ 104.70
ARM SUB-ASSY. RR BUMPER LH	1.00	\$	139.60	(25.00)	\$	34.90	\$ 104.70
ANTENNA, ELECTRICAL LOWER REAR	0.00	\$	157.40	0.00		\$	0.00	\$ 0.00
SENSOR REVERSE	1.00	\$	180.00	0.00		\$	0.00	\$ 180.00
BUMPER SIDE RETAINER RR/LH	1.00	\$	94.80	(25.00)	\$	23.70	\$ 71.10
BUMPER SIDE RETAINER RR/RH .	1.00	\$	94.80	(25.00)	\$	23.70	\$ 71.10
BUMPER SEAL, RR LH	0.00	\$	88.90	0.00		\$	0.00	\$ 0.00
BUMPER SEAL, RR RH	0.00	\$	65.70	0.00		\$	0.00	\$ 0.00
BUMPER LIP COVER RR/LH	0.00	\$	72.20	0.00		\$	0.00	\$ 0.00
BUMPER LIP COVER RR/RH	0.00	\$	118.10	0.00		\$	0.00	\$ 0.00
BUMPER LIP REAR	1.00	\$	228.90	(25.00)	\$	57.22	\$ 171.68
UNDER COVER SUB-ASSY, RR FLOOR	0.00	\$	514.50	0.00		\$	0.00	\$ 0.00
UNDER COVER RR SHIELD	0.00	\$	63.90	0.00		\$	0.00	\$ 0.00
END PANEL	1.00	\$	602.10	(25.00)	\$	150.52	\$ 451.58
SEALANT SIKAFLEX	1.00	\$	37.00	0.00		\$	0.00	\$ 37.00
TAILGATE ASY	1.00	\$ 3	1007.90	(25.00)	\$	251.97	\$ 755.93
TAILGATE DOOR GLASS MOULDING, RH	1.00	\$	29.40	(25.00)	\$	7.35	\$ 22.05
TAILGATE DOOR GLASS MOULDING, LH	1.00	\$	29.40	(25.00)	\$	7.35	\$ 22.05
SEALANT W/SCREEN	3.00	\$	37.00	0.00		\$	0.00	\$ 111.00
FAILGATE DOOR LOCK	1.00	\$	444.10	(25.00)	\$	111.02	\$ 333.08
NAME PLATE (HYBRID)	1.00	\$	51.90	(25.00)	\$	12.97	\$ 38.93
TAIL LAMP RH	0.00	S	557.80	0.00		\$	0.00	\$ 0.00

Authorised Signature

for SMRT Automotive Services Pte Ltd



Customer Code: 3000063

SMRT TAXIS PTE LTD

Block Unit

60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705

SMRT Automotive Services Pte Ltd

251 North Bridge Road Singapore 179102

Tel: 65 63311000 Fax: 65 63340247

Tax Invoice

GST Reg No. : MR-8500001-7 CRN : 199004280Z Invoice No. : IV191200508 Date : 26.12.2019

Vehicle No. : SHD6481P
Your Ref No. : TAX/11/19/2141

Our Ref No. : 24104651 Terms : 30 Days

Description	Qty	Unit	Add	/	(Dis	count)		Amount
		Cost	용		An	nount	•	
BUMPER LIP COVER RR/LH	1.00	\$ 72.20	(25.00)	\$	18.05	\$	54.15
UNDER COVER SUB-ASSY, RR FLOOR	1.00	\$ 514.50	(25.00)	\$	128.62	\$	385.88
TAILGATE DOOR WEATHER STRIP	1.00.	\$ 353.40	(25.00)	\$	88.35	\$	265.05
				Su	b-Tot	tal	\$	3813.96
Labour					*			2
TO REPAIR REAR PORTION	1.00	\$ 400.00	0.00		\$	0.00	\$	400.00
Others								
TO REMOVE AND REFIX REAR WINDSCREEN	1.00	\$ 120.00	0.00		\$	0.00	\$	120.00
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	1.00	\$ 60.00	0.00		\$	0.00	\$	60.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	1.00	\$ 20.00	0.00		\$	0.00	\$	20.00
TO TRANSFER REAR TAILGATE MECHANISM	1.00	\$ 60.00	0.00		\$	0.00	\$	60.00
TO REPLACE SUNDRY PARTS	1.00	\$ 20.00	0.00		\$	0.00	\$	20.00
TO CHECK WIRING AND SYSTEM FUNCTION	1.00	\$ 20.00	0.00		\$	0.00	\$	20.00
TO WASH AND VACUUM	0.00	\$ 60.00	0.00		\$	0.00	\$	0.00
TO RESPRAY REAR BUMPER	1.00	\$ 200.00	0.00		\$	0.00	\$	200.00
TO RESPRAY BUMPER BEAM	1.00	\$ 80.00	0.00		\$	0.00	\$	80.00
TO RESPRAY REAR PANEL	1.00	\$ 80.00	0.00		\$	0.00	\$	80.00
TO RESPRAY TAIL GATE	1.00	\$ 200.00	0.00		\$	0.00	\$	200.00
			GR	AND	TOTA	.L	\$	5,073.96

Remark:

Make/Model : TOYOTA PRIUS Accident Date : 30.11.2019

N.B. Payment by cheque should be crossed and made payable to 'SMRT Automotive Services Pte Ltd'. No receipt will be issued unless requested.

Authorised Signature for SMRT Automotive Services Pte Ltd

Page 2/2



SMRT Taxis Pte Ltd

MEMORANDUM

To:

Claims Dept

Our Ref: TAX/11/19/2141

From: SMRT Taxis Pte Ltd

Date:

10/12/2019

ACCIDENT INVOLVING SHD6481P AND SKK6520M ON 30/11/2019 12:58 PM ALONG PIE TOWARDS CHANGI (THOMSON FLYOVER).

This is to confirm that the daily rental rate for SHD6481P is \$108.07 per day.

Please proceed to recover any rental loss from the third party as a result of the above accident.

Thank you.

Yours sincerely SMRT TAXIS PTE LTD

for Manager



Laid Up Report

Accident Start Date: 30/11/2019

Accident End Date : 30/12/2019

Case Reference Number | Vehicle Registration | Number |

TAX/11/19/2141

SHD6481P

Date Generated: 10/01/2020

User Name : TanSelena

14/12/2019 8:44 AM	30/11/2019 5:00 PM	24104651	PRIUS	TOYOTA	SMRT Taxis Pte Ltd.	-
Date and Time (Repair Completed)	Date and Time (Accident Repair)	Job Card Number	Vehicle Model	Vehicle Make	Company Type	

13.12°

13 days

Page 1 of 1

Enquire Transaction History

Log Date/Time:

03 Dec 2019 / 08:44:59

Asset Type: Asset ID:

User ID:

Vehicle

SKK6520M

18.32 Insurance Enquiry (GIRO Payment)

ESASBAHO - BALQISH BINTE ABDUL HALIL

\$7.49

Channel:

Transaction Amount:

External Agency

Business Transaction Reference No.: 20191203084459114598

Search Date / Time:

Transaction Type:

30 Nov 2019 12:58:00

insurance Company:

LONPAC INSURANCE BHD

Information displayed is correct as at the \log date and time.

Enquire Related Logs

Back to List