

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5533K**AAD1912-001***Not Notarized**11 Sep 8 0501*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

03 DEC 2019

SHC 5533K

VF1ABL15AUC278875

RENAULT

LATITUDE

29.11.19

CHINA TAIPING

15/8/2014

PART		LIST	
1	BUMPER COVER FRT	\$	747.20
1	BUMPER SPOILER FRT	\$	344.70
1	BUMPER ABSORBER FRT	\$	394.68
1	BUMPER RETAINER FRT LH	\$	101.40
1	BUMPER SUPPORT FRT	\$	10.70
1	BUMPER UNDERTRAY FRT	\$	292.50
1	BUMPER GRILLE LOWER FRT	\$	147.00
1	BUMPER FOG LAMP GRILLE LH	\$	207.21
1	BUMPER BEAM FRT	\$	663.70
1	HEADLAMP LH	\$	743.60
1	HEADLAMP PANEL FRT LH	\$	127.70
1	FENDER PANEL FRT LH	\$	414.40
1	WHEELARCH FRT LH	\$	112.30
1	FENDER BRACKET FRT LH	\$	38.90
1	FENDER BRACKET LOWER LH	\$	11.80
1	FENDER INSULATOR LH	\$	65.50
1	FENDER BRACKET FRT LH	\$	38.90
1	FRONT BRACE PANEL	\$	177.22
1	BONNET	\$	1,312.70
1	BONNET INSULATOR	\$	294.30
1	BONNET STRUT LH	\$	53.30
1	BONNET STRUT RH	\$	53.30
1	BONNET HINGE LH	\$	236.50
1	BONNET HINGE RH	\$	237.40
1	BONNET LOCK	\$	152.80
1	BONNET CABLE	\$	55.20
1	BONNET CABLE COVER	\$	80.60

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5533K**AAD1912-001**

1	BONNET SEAL OUTER	\$	83.20	} <i>SHC X</i>
1	BONNET SEAL INNER	\$	70.10	
1	RADIATOR GRILLE	\$	969.90	
1	RADIATOR GRILLE BADGE 'RENAULT'	\$	225.36	
1	RADIATOR GRILLE FRAME	\$	686.00	
1	FRAME FULL SUPPORT PANEL	\$	592.70	
1	FRAME FULL SUPPORT BRACKET	\$	41.60	
1	AIR CLEANER BOX	\$	464.20	
1	AIR CLEANER HOSE	\$	175.85	
1	AIR CLEANER LOWER	\$	271.26	
1	DOOR PANEL FRT LH	\$	2,844.66	} <i>SHC</i>
1	DOOR MIRROR ASSY LH	\$	727.90	
1	DOOR MIRROR GLASS LH L70Y	\$	151.70	
1	DOOR MIRROR BACK COVER LH L70Y	\$	128.70	
1	DOOR MIRROR LAMP LH	\$	134.10	} <i>SHC X</i>
1	DOOR HARNESS WIRE LH	\$	<i>SHC</i> 2,670.00	
1	ROCKER PANEL INNER GARNISH LH	\$	<i>SHC</i> 466.51	
1	ROCKER PANEL INNER LH	\$	<i>SHC</i> 1,024.79	
1	ROCKER PANEL OUTER LH	\$	<i>SHC</i> 1,184.99	} <i>X</i>
1	ROCKER PANEL CENTER LH	\$	<i>SHC</i> 990.25	
1	LOWER ARM LH L70Y	\$	<i>SHC</i> 192.70	
1	KNUCKLE ARM LH L70Y	\$	<i>SHC</i> 481.50	
1	ABSORBER FRT LH L70Y	\$	<i>SHC</i> 274.10	
1	DRIVESHAFT LH	\$	<i>SHC</i> 1,355.70	
1	STABILIZER BAR FRT	\$	<i>SHC</i> 427.90	
TOTAL		\$	23,751.18	
10%		\$	2,375.12	
		\$	21,376.06	

Special Nett

1	BUMPER CLIP FRT	\$	<i>SHC</i> 66.00	} <i>X</i>
1	BUMPER BRACKET CLIP FRT LH	\$	<i>SHC</i> 12.00	
1	BUMPER SUPPORT CLIP FRT LH	\$	<i>SHC</i> 10.50	
1	BUMPER GRILLE LOWER CLIP	\$	<i>SHC</i> 69.00	
1	WHEELARCH CLIP FRT LH	\$	<i>SHC</i> 30.50	
1	FRAME FULL SUPPORT PANEL CLIP	\$	<i>SHC</i> 70.00	

Trans-cab Auto Services Pte Ltd**AAD1912-001**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5533K

1SET	FRAME FULL SUPPORT PANEL NUT	\$	20.00	} <i>nn</i> <i>X</i>
2	FRAME FULL SUPPORT PANEL STUD	\$	30.00	
1SET	RADIATOR GRILLE SCREW	\$	16.00	
1SET	RADIATOR GRILLE FRAME CLIP	\$	52.00	
1	FRONT LEFT TYRE	\$	300.00	
1	FRONT LEFT TYRE RIM	\$	380.00	
1SET	Front licence plate with holder	\$	80.00	
1	WINDSCREEN SEALANT	\$	253.80	
1	FRONT WINDSCREEN MOULDING	\$	120.00	
1	FRONT WINDSCREEN INNER SPONGE SEAL	\$	100.00	
6	BONNET INSULATOR CLIP L70Y	\$	7.30	
2	BONNET CABLE CLIP L70Y	\$	6.31	
2	BONNET CABLE COVER SCREW L70Y	\$	10.85	
1	FRONT DOOR STICKER 'Trans-Cab'	\$	80.00	
1	FRONT DOOR STICKER 'Classic'	\$	80.00	
TOTAL		\$	1,794.27	
TOTAL PARTS		\$	23,170.33	

LABOUR

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	6,000.00	<i>60k</i>
To transfer of front bumper fittings, attachment and perform water seepage test.	\$	<i>nn</i> 170.00	<i>X</i>
To transfer of front fender fittings, attachment and perform water seepage test.	\$	<i>nn</i> 170.00	<i>X</i>
To transfer of front windscreen glass to facilitate bodywork repair.	\$	<i>nn</i> 170.00	<i>X</i>
To check steering geometry and computer wheel alignment	\$	<i>nn</i> 220.00	<i>X</i>

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5533K**AAD1912-001**

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	nn 380.00	X
To transfer of tire, rim and on wheel balancing.	\$	nn 170.00	X
Putty and spray painting of the affected portion.	\$	6,000.00	601
To transfer of bonnet fittings, attachment and perform water seepage test.	\$	nn 170.00	X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	↪ 380.00	X
To transfer of front door fittings, attachment and perform water seepage test.	\$	↪ 170.00	X
To dismantle and refit front end suspension, undercarriage parts, final checking and testing.	\$	↪ 380.00	X
To Check Electrical Lighting Concerned.	\$	170.00	201
To rust-proofing of the affected areas.	\$	↪ 170.00	X
To check ABS and brake efficiency, final checking and testing.	\$	↪ 380.00	X
TOTAL	\$	15,100.00	
Over All Total	\$	38,270.33	

LUMP SUM (REPAIR DAY)**20 days****1 day**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: