

ASS. REC. BY:

REF: CS/CTI/9621437/Avf312

Special Instruction:

Surveyor: Adrian

ASSIGNMENT (Office)

From (Person): Irene Tay Hui Ping

of CTI

Date/Time: 4.12.19 14.40p.m

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To inspect Vehicle No: SF4 1269H

Insured: SJ C 5950R

at Workshop m/s Alpha Car

Tel: 65 09 8258

of BIK C Kaki Bukit Ave (A01-59)

Policy No:

Claim No: SVM190205722102

Sum Insured:

Excess:

Make of Veh:

D.O.A. 29.11.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

rep

Date/Time: 4.12.19 2.53p.m

Person Contacted:

Cai Ling

H.O.D. Endorsement:

Vehicle IN/OUT

Date/Time	Action/Instruction ( ✓ ) Estimate
	SF4 1269H - X
	SJC 5950R - X
13/2/20	Adrian confirmed LS \$1800 (Recd 13,217.45, 88%)

# ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To inspect Vehicle No: \_\_\_\_\_  
 at Workshop no: \_\_\_\_\_  
 of: \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No: \_\_\_\_\_  
 Claims No: \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Express: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

N/S	O/S

(Policy Condition)  
 Remark: The veh had commenced its  
 repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: \_\_\_\_\_ days Res: Yes or No  
 Lum Sum: \_\_\_\_\_ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Vehicle No: **SFY1269H.** Reg: **2005 Sept.**  
 Type: ☒ Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or

Make: **Toyota Camry** Yr: **1998**  
 Colour: **Black** A/C: Insured / Std / NI / NA  
 Sp. Reading: **371741** T/Ratio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_  
 C/No: **MR0S3BK3106012458**

Gen. Cond: ☒ Good / Fair / Poor / Burnt  
 Steering: ☒ In order / Jammed / Leaked / Burnt or  
 Brake: ☒ In order / Jammed / Leaked / Burnt or  
 Modi: Nil ☒ S/Rim / STD A/Rim or

Tyre Size: F: **205/65R15**  
 R: **205/65R15.**

BS / DUN / EXNOVA / GY / FS / LIZA / ☒ M/C / OHTSU / PIR / SUMI /  
 TOYO / YOKO or

Front		Rear	
R/Bal. <b>06</b>	mm	R/Bal. <b>06</b>	mm
L/Bal. <b>06</b>	mm	L/Bal. <b>06</b>	mm
D.O.A. _____		D.O.I. <b>04/12/19.</b>	

Survey held at **Alpha.**

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

**Front O/S.**

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction  
**TP Ching.**

COE Expiry: **31/08/2020.**

MV: **7K**  
 PV: **5.2K**  
 Nett: **1.8K**

RECEIVED 13 FEB 2020

Date/Time, File Path in? ☐ : Preli. Report

1) ☐ : Final Report

Date/Time, File Path in?

2) **3/2 - typst**

Report Format:

Long Form / Short Form

**Merimen**

**4/5 \$1800**

Days Of Repair: **5**

Resurvey No. of Trip: **1**

Grid Fee: ☐ Site Insp. \$

☐ Interview \$

☐ Tech. Sp. \$

☐ Road work \$

Survey Fee:

Transportation:

1) - P1

2) - P2

3) - P3

4) - P4

## ...CLAIM SUBFOLDER...(New Assignment)

## CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	04 Dec 2019		04 Dec 2019 14:40 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

<a href="#">Main</a>	<a href="#">Reference</a>	<a href="#">Claim Details</a>	<a href="#">Documents</a>	<a href="#">Show All</a>
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

## CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:			
Main Claimant:	LIM KENG BOON		
Vehicle Reg. No.:	SFY1269H	Date of Loss:	29/11/2019 23:00 - :59
Claim Type:	TP / SNM19D205722C02	Policy/Cover Note No.:	DMPCSN30127719000
Vehicle Reg. No. (Insured):	SJC5950R	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	Alpha Car Services Pte Ltd (HQ) Blk C, Kaki Bukit Ave 6 #01-59, Kaki Bukit Autobay, 417883 Kaki Bukit - Tel: 65098258		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 13/12/2019]		
Adj Asg. Remarks:	PLEASE SURVEY AND REVERT		

## ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.



## ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Nivitha (LKK Auto)

---

**From:** Irene Tay <irene.tay@sg.cntaiping.com>  
**Sent:** Wednesday, 4 December 2019 2:32 PM  
**To:** jiamin.mak@alt.sg; assignments; Admin A  
**Cc:** 'Jerdine'; vincent@alt.sg; allister@alt.sg; 'Alpha Car Services'  
**Subject:** RE: OUR REF: SNM19D205722/SJC5950R/IRENE- RE: PRI - SFY 1269 H

Dear Sir (LKK),

We refer to the above matter.

Please get your surveyor to liaise with ALPHA CAR to conduct survey.

Regards,

**Irene Tay**

Executive  
Claims Department (Motor Division)

**China Taiping Insurance (Singapore) Pte. Ltd.**

3 Anson Road #15-00 Springleaf Tower Singapore 079909

DID: (65) 63896192 | F: (65) 62247478/62247175

**W:** [www.sg.cntaiping.com](http://www.sg.cntaiping.com) | **FB:** [www.facebook.com/chinataipingsg/](https://www.facebook.com/chinataipingsg/) | **WeChat:** 太平獅城 Taiping SG

*Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.*

**From:** jiamin.mak@alt.sg [mailto:jiamin.mak@alt.sg]  
**Sent:** Wednesday, December 4, 2019 12:30 PM  
**To:** Irene Tay <irene.tay@sg.cntaiping.com>  
**Cc:** 'Jerdine' <jerdine.wang@alt.sg>; vincent@alt.sg; allister@alt.sg; 'Alpha Car Services' <alphacarservices@hotmail.com>  
**Subject:** RE: OUR REF: SNM19D205722/SJC5950R/IRENE- RE: PRI - SFY 1269 H

Dear Sir,

We refer to your email dated 4 December 2019.

Our client agreed to appoint **Mr Simon Ho** to be the Single Joint Expert.

Thank you.

*\* Kindly be reminded of the change of our address as stated below.*

Best Regards,

Jiamin

For and on behalf of  
Allister Lim

**ALLISTER LIM & THRUMURGAN  
ADVOCATES & SOLICITORS**

1 Coleman Street  
#05-01, The Adelphi  
Singapore 179803  
Telephone : 6422 2187  
Facsimile : 6438 1211

*Email Confidentiality Warning:*

*This message contains information which is subject to legal professional privilege and/or is confidential. If you are not the intended recipient, you are notified that any unauthorised disclosure, copying, distribution or use of this information is strictly prohibited. If you have received this message in error, please notify us by e-mailing us at [mail@alt.sg](mailto:mail@alt.sg) and delete it from your system. Unless the contents of this email relate to matters within the scope of the firm's engagement, any opinions, views and other information are expressed in the sender's personal capacity. You should scan this email and any file attached for viruses.*

---

**From:** Irene Tay <[irene.tay@sg.cntaiping.com](mailto:irene.tay@sg.cntaiping.com)>  
**Sent:** Wednesday, December 4, 2019 10:27 AM  
**To:** [jiamin.mak@alt.sg](mailto:jiamin.mak@alt.sg); [jerdine.wang@alt.sg](mailto:jerdine.wang@alt.sg)  
**Subject:** RE: OUR REF: SNM19D205722/SJC5950R/IRENE- RE: PRI - SFY 1269 H

**WITHOUT PREJUDICE**

Dear Sir,

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

LKK / LBS / STA

ADRIAN LING
Kelvin Ang
SEE CHEW SENG
MOHD FADHILAH BIN OSMAN
XING QUO QIANG
KENNETH KONG
SIMON HO
CHUA WEIJIE
MARCUS CHUA
HENRY NG

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.  
You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Thank you,

Regards,

**Irene Tay**

Executive  
Claims Department (Motor Division)

**China Taiping Insurance (Singapore) Pte. Ltd.**

3 Anson Road #15-00 Springleaf Tower Singapore 079909  
DID: (65) 63896192 | F: (65) 62247478/62247175

**W:** [www.sg.cntaiping.com](http://www.sg.cntaiping.com) | **FB:** [www.facebook.com/chinataipingsg/](https://www.facebook.com/chinataipingsg/) | **WeChat:** 太平獅城 Taiping SG

*Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.*

---

**From:** Lim Shu Min

**Sent:** Wednesday, December 4, 2019 10:26 AM

**To:** Irene Tay <[irene.tay@sg.cntaiping.com](mailto:irene.tay@sg.cntaiping.com)>

**Subject:** FW: OUR REF: SNM19D205722/SJC5950R/IRENE- RE: PRI - SFY 1269 H

Thank you

**Lim Shu Min**

Executive  
Claims Department

**China Taiping Insurance (Singapore) Pte. Ltd.**

3 Anson Road #15-00 Springleaf Tower Singapore 079909  
DID: (65) 63896156 | F: (65) 62247175

**W:** [www.sg.cntaiping.com](http://www.sg.cntaiping.com) | **FB:** [www.facebook.com/chinataipingsg/](https://www.facebook.com/chinataipingsg/) | **WeChat:** 太平獅城 Taiping SG

*Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.*

---

**From:** Lim Shu Min

**Sent:** Tuesday, 3 December, 2019 5:55 PM

**To:** Lim Shu Min <[shumin.lim@sg.cntaiping.com](mailto:shumin.lim@sg.cntaiping.com)>

**Subject:** FW: OUR REF: SNM19D205722/SJC5950R/IRENE- RE: PRI - SFY 1269 H

---

**From:** Claims Dept of CTI

**Sent:** Tuesday, December 03, 2019 5:22 PM

**To:** 'jiamin.mak@alt.sg'

**Cc:** [jerdine.wang@alt.sg](mailto:jerdine.wang@alt.sg); [vincent@alt.sg](mailto:vincent@alt.sg); [allister@alt.sg](mailto:allister@alt.sg); 'ALPHA CAR SERVICES'

**Subject:** OUR REF: SNM19D205722/SJC5950R/IRENE- RE: PRI - SFY 1269 H

Dear Irene,

Please conduct PRS for SFY1269H.

Note : officer in charge – Irene Tay 63896192.

\*\*\* Kindly quote our reference number when replying.

Thank you

Claims Department

**China Taiping Insurance (Singapore) Pte. Ltd.**

3 Anson Road #15-00 Springleaf Tower Singapore 079909

DID: (65) 63896116 | F: (65) 62247175

**W:** [www.sg.cntaiping.com](http://www.sg.cntaiping.com) | **FB:** [www.facebook.com/chinataipingsg/](https://www.facebook.com/chinataipingsg/) | **WeChat:** 太平獅城 Taiping SG

*Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.*

**From:** [jiamin.mak@alt.sg](mailto:jiamin.mak@alt.sg) [mailto:[jiamin.mak@alt.sg](mailto:jiamin.mak@alt.sg)]

**Sent:** Monday, December 02, 2019 3:57 PM

**To:** Claims Dept of CTI

**Cc:** [jerdine.wang@alt.sg](mailto:jerdine.wang@alt.sg); [vincent@alt.sg](mailto:vincent@alt.sg); [allister@alt.sg](mailto:allister@alt.sg); 'ALPHA CAR SERVICES'

**Subject:** PRI - SFY 1269 H

Your Ref: SJC 5950 R

Our Ref: AL.INS.2019.SFY1269H

2 December 2019

**CHINA TAIPING INSURANCE (SINGAPORE)**

**COMPANY LTD**

3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909

**BY EMAIL ONLY**

Dear Sirs,

**ACCIDENT INVOLVING SFY 1269 H & SJC 5950 R AT HOUGANG STREET 51 CARPARK ON 29 NOVEMBER 2019 AT ABOUT 2305 HOURS**

We act for the owner of vehicle no. SFY 1269 H.

We are instructed to claim damages against you in connection with the above accident.

Pursuant to NIMA protocol, we hereby give you notice to conduct a pre-repair inspection of our client's motor vehicle at the under-stated workshop:-

**ALPHA CAR SERVICES PTE LTD**

Blk C Kaki Bukit Ave 4

#01-59 Kaki Bukit Autobay

Singapore 417883

Person In-Charge: Cailing

Mobile Number: 6509 8258

TAKE NOTICE that you are required to respond to us within 2 working days (excluding Saturday, Sunday and Public Holiday) of receipt of this notice as to whether you wish to carry out or waive a pre-repair inspection. If we do not

hear from you in this regard by the stipulated time, we shall construe your silence as waiver of the requirement for a pre-repair inspection and our client's repairers shall proceed to repair our client's vehicle.

Please contact our staff, Jerdine / Jiamin at 6422 2187 or email us at [jerdine.wang@alt.sg](mailto:jerdine.wang@alt.sg) / [jiamin.mak@alt.sg](mailto:jiamin.mak@alt.sg) for future correspondences.

*\* Kindly be reminded of the change of our address as stated below.*

Best Regards,

Jiamin

For and on behalf of  
Allister Lim

**ALLISTER LIM & THRUMURGAN  
ADVOCATES & SOLICITORS**

1 Coleman Street  
#05-01, The Adelphi  
Singapore 179803  
Telephone : 6422 2187  
Facsimile : 6438 1211

*Email Confidentiality Warning:*

*This message contains information which is subject to legal professional privilege and/or is confidential. If you are not the intended recipient, you are notified that any unauthorised disclosure, copying, distribution or use of this information is strictly prohibited. If you have received this message in error, please notify us by e-mailing us at [mail@alt.sg](mailto:mail@alt.sg) and delete it from your system. Unless the contents of this email relate to matters within the scope of the firm's engagement, any opinions, views and other information are expressed in the sender's personal capacity. You should scan this email and any file attached for viruses.*

---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---

---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---



> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	533B
Vehicle Details	
Vehicle No.:	SFY1269H
Vehicle to be Exported:	Yes
Intended Deregistration Date:	04 Dec 2019
Vehicle Make:	TOYOTA
Vehicle Model:	CAMRY 2.0
Primary Colour:	Black
Manufacturing Year:	2005
Engine No.:	1AZ3207079
Chassis No.:	MR053BK3106012458
Maximum Power Output:	106.0 kW (142 bhp)
Open Market Value:	\$27,777.00
Original Registration Date:	01 Sep 2005
First Registration Date:	01 Sep 2005
Transfer Count:	1
Actual ARF Paid:	\$30,555.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	31 Aug 2020
COE Category:	E - Open Category
COE Period(Years):	5
PQP Paid:	\$35,227.00
COE Rebate Amount:	\$5,208.00
Total Rebate Amount:	\$5,208.00
Remarks	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 04 Dec 2019

OK

# Alpha Car Services Pte Ltd

Blk C, #01-59 Kaki Bukit Ave 6, Kaki Bukit Autobay Singapore 417883  
ROC No. 201717633Z

Vehicle Number : SFY1269H

Model : Toyota Camry

MR053BK3106012458

3/12/2019

TP China Veron.

Damaged Area: (Front Right Portion)

Supplementary may be included during the cost of repair :

## Parts / Material :

- 1 Front Bumper *Distorted*
- 2 Front Bumper Side Bracket RH *New*
- 3 Front Bumper Retainer RH *New*
- 4 Front bumper Reinforcement *New*
- 5 Front Bumper Fog Lamp Garnish RH *New*
- 6 Front Bumper Fog Lamp RH *Can't*
- 7 Front Bumper Protector with Moulding RH *Distorted*
- 8 Front Bumper Lower Lip *New*
- 9 Front Bumper Clips *New*
- 10 Front Headlamp Assy RH *Can't*
- 11 Front Headlamp Bracket RH *Best*
- 12 Front Radiator Grille *New*
- 13 Front Radiator Grille Clips *New*
- 14 Front Support Panel *New*
- 15 Centre Brace Panel *New*
- 16 Front Bonnet *New*
- 17 Front Bonnet Insulator Clips *New*
- 18 Wiper Washer Tank *Deformed*
- 19 Front Fender RH *Distorted*
- 20 Front Fender Emblem VVTI *New*
- 21 Front Fender Inner Shield RH *Tom*
- 22 Front Fender Inner Shield Clips *New*
- 23 Front Right Suspension *New*
- 24 Front Right Lower Arm *New*
- 25 Front Right Knuckle Arm *New*
- 26 Front Right Hub Bearing *New*
- 27 Front Right Steering Rack and Pinion *New*
- 28 Front Right ABS Sensor

## Quantity

	\$	1,108.20 <i>523</i>
	\$	98.00 <i>+</i>
	\$	68.00 <i>+</i>
	\$	486.50 <i>+</i>
	\$	195.40 <i>+</i>
	\$	435.70 <i>289</i>
	\$	175.40 <i>+</i>
	\$	358.60 <i>k.</i>
	\$	60.00 <i>30</i>
\$6.00 X 10pcs	\$	1,120.00 <i>945</i>
	\$	98.40 <i>+</i>
	\$	762.30 <i>+</i>
	\$	60.00 <i>+</i>
\$6.00 X 10pcs	\$	738.50 <i>+</i>
	\$	165.20 <i>+</i>
	\$	964.20 <i>+</i>
	\$	60.00 <i>+</i>
\$6.00 X 10pcs	\$	365.40 <i>165</i>
	\$	853.40 <i>708</i>
	\$	68.00 <i>+</i>
	\$	286.70 <i>+</i>
	\$	60.00 <i>30</i>
\$6.00 X 10pcs	\$	428.20 <i>+</i>
	\$	386.50 <i>+</i>
	\$	467.80 <i>+</i>
	\$	385.70 <i>+</i>
	\$	1,635.80 <i>+</i>
	\$	365.20 <i>+</i>
Parts :	\$	12,256.60
Less Parts 25% :	\$	3,064.15
Total Parts :	\$	9,192.45

## Special Net Items :

- Front Right Rim *lit*
- Front Right Tire *new*
- Radiator Coolant *new*
- Front Number Plate with Garnish *new*

\$	400	850.00 <i>400</i>
\$		450.00 <i>+</i>
\$		95.00 <i>+</i>
\$		80.00 <i>+</i>
Total S/N Parts :	\$	1,475.00

## Labour :

- To Remove & Renew Affected Accident Areas
- To Putty, Spray Paint on Front Affected Accident Areas
- To Check & Re-Connect all electrical wiring
- To Conduct AC Leakage Test & Top Up Gas

\$	1,500.00 <i>600</i>
\$	1,400.00 <i>500</i>
\$	50.00 <i>30</i>
\$	200.00 <i>+</i>

To Conduct Radiator Pressure Test & Check for Leakage  
 To Renew & Install Front Right Undercarriage to facilitate Repairs  
 To Re-Programme & Reset Diagnostic  
 To Replace, Balance Tyre into RIM  
 To Conduct All Wheel Alignment  
 To Rust Proof Affected Areas

\$	200.00	X
\$	250.00	X
\$	250.00	X
\$	150.00	X
\$	250.00	80
\$	100.00	50
<b>Total Labour : \$</b>		<b>4,350.00</b>

<b>TOTAL PARTS :</b>	\$	9,192.45
<b>TOTAL SPECIAL NET ITEM :</b>	\$	1,475.00
<b>TOTAL LABOUR :</b>	\$	4,350.00
<b>TOTAL REPAIR COST :</b>	<u>\$</u>	<u>15,017.45</u>

Adrian G  
 L/S 04/12/19.

05 Days.

total 4199.87

L/S 1.81k

(Nett Value)

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI19021437/AVF3N2

Date: 13/02/2020

## REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSN30127719000

Claimant Vehicle No: SFY1269H Insured Vehicle No: SJC5950R

Date of Loss: 29/11/2019 Nature of Claim: TP Claim No: SNM19D205722C02

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SFY1269H Engine No: 1AZ3207079

Make & Model: TOYOTA CAMRY, 2.0 (A) Chassis No: MR053BK3106012458

Reg. Date: 01/09/2005 (Man. Year: 2005) Odometer: 371741 km

Colour: Black

Engine Capacity: 1998 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 205/65R15 Rear Tyre Size: 205/65R15

Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,667.45	2,939.87	7,727.58	72.44
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,350.00	1,260.00	3,090.00	71.03
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>15,017.45</b>	<b>4,199.87</b>	<b>10,817.58</b>	<b>72.03</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>1,800.00</b>		
<b>Nett Amount (S\$)</b>	<b>15,017.45</b>	<b>1,800.00</b>	<b>13,217.45</b>	<b>88.01</b>

## INSPECTION

Date of Assignment: 04/12/2019

Date Inspected: 04/12/2019 Inspected At: Alpha Car Services Pte Ltd (HQ)  
Blk C, Kaki Bukit Ave 6 #01-59, Kaki Bukit Autobay  
Singapore 4178831\*963

Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

## Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 13 Feb 2020)
<b>Parts:</b> 143	TOYOTA CAMRY 2.0 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for SFY1269H)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	1,108.20 FL	*523.00 FL
2	1		*FRONT BUMPER SIDE BRACKET RH	Not Necessary	98.00 FL	*- FL
3	1		*FRONT BUMPER RETAINER RH	Damaged	68.00 FL	*68.00 FL
4	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	486.50 FL	*- FL
5	1		*FRONT BUMPER FOG LAMP GARNISH RH	Not Necessary	195.40 FL	*- FL
6	1		*FRONT BUMPER FOG LAMP RH	Cracked	435.20 FL	*289.00 FL
7	1		*FRONT BUMPER PROTECTOR WITH MOULDING RH	Distorted	175.40 FL	*175.40 FL
8	1		*FRONT BUMPER LOWER LIP	Not Necessary	358.60 FL	*- FL
9	10		*FRONT BUMPER CLIPS	Necessary	60.00 FL	*30.00 FL
10	1		*FRONT HEADLAMP ASSY RH	Cracked	1,120.00 FL	*945.00 FL
11	1		*FRONT HEADLAMP BRACKET RH	Bent	98.40 FL	*98.40 FL
12	1		*FRONT RADIATOR GRILLE	Not Necessary	762.30 FL	*- FL
13	10		*FRONT RADIATOR GRILLE CLIPS	Not Necessary	60.00 FL	*- FL
14	1		*FRONT SUPPORT PANEL	Repair	738.50 FL	*- FL
15	1		*CENTRE BRACE PANEL	Not Necessary	165.20 FL	*- FL
16	1		*FRONT BONNET	Not Necessary	964.20 FL	*- FL
17	10		*FRONT BONNET INSULATOR CLIPS	Not Necessary	60.00 FL	*- FL
18	1		*WIPER WASHER TANK	Deformed	365.40 FL	*165.00 FL
19	1		*FRONT FENDER RH	Distorted	853.40 FL	*708.00 FL
20	1		*FRONT FENDER EMBLEM VVTI	Necessary	68.00 FL	*68.00 FL
21	1		*FRONT FENDER INNER SHIELD RH	Torn	286.70 FL	*286.70 FL
22	10		*FRONT FENDER INNER SHIELD CLIPS	Necessary	60.00 FL	*30.00 FL
23	1		*FRONT RIGHT SUSPENSION	Not Necessary	428.20 FL	*- FL
24	1		*FRONT RIGHT LOWER ARM	Not Necessary	386.50 FL	*- FL
25	1		*FRONT RIGHT KNUCKLE ARM	Not Necessary	467.80 FL	*- FL
26	1		*FRONT RIGHT HUB BEARING	Not Necessary	385.70 FL	*- FL
27	1		*FRONT RIGHT STEERING RACK AND PINION	Not Necessary	1,635.80 FL	*- FL
28	1		*FRONT RIGHT ABS SENSOR	Not Necessary	365.20 FL	*- FL
29	1		*FRONT RIGHT RIM	Cut	850.00 FS	*400.00 FS
30	1		*FRONT RIGHT TIRE	Not Necessary	450.00 FS	*- FS
31	1		*RADIATOR COOLANT	Not Necessary	95.00 FS	*- FS
32	1		*FRONT NUMBER PLATE WITH GARNISH	Not Necessary	80.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>13,731.60</b>	<b>3,786.50</b>
<b>- List Item Discount on L Items 25.00/25.00% (\$\$)</b>	<b>3,064.15</b>	<b>846.63</b>
<b>Total Parts (\$\$)</b>	<b>10,667.45</b>	<b>2,939.87</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE & RENEW AFFECTED ACCIDENT AREAS.	New	1,500.00	600.00
2	TO PUTTY,SPRAY PAINT ON FRONT AFFECTED ACCIDENT AREAS	New	1,400.00	500.00
3	TO CHECK & RE-CONNECT ALL ELECTRICAL WIRING	New	50.00	30.00
4	TO CONDUCT AC LEAKAGE TEST & TOP UP GAS	New	200.00	0.00
5	TO CONDUCT RADIATOR PRESSURE TEST & CHECK FOR LEAKAGE	New	200.00	0.00
6	TO RENEW & INSTALL FRONT RIGHT UNDERCARRIAGE TO FACILITATE REPAIRS	New	250.00	0.00
7	TO RE-PROGRAMME & RESET DIAGNOSTIC	New	250.00	0.00
8	TO REPLACE,BALANCE TYRE INTO RIM	New	150.00	0.00
9	TO CONDUCT ALL WHEEL ALIGNMENT	New	250.00	80.00
10	TO RUST PROOF AFFECTED AREAS	New	100.00	50.00
<b>Gross Labour Cost (\$\$)</b>			<b>4,350.00</b>	<b>1,260.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >