

Alpha Car Services Pte Ltd

Blk C , #01-59 Kaki Bukit Ave 6 , Kaki Bukit Autobay Singapore 417883

ROC No. 201717633Z

Vehicle Number : SFY1269H

3/12/2019

Model : Toyota Camry

Damaged Area: (Front Right Portion)

Supplementary may be included during the cost of repair :

Parts / Material :

	Quantity		
1 Front Bumper <i>Distorted</i>		\$	1,108.20
2 Front Bumper Side Bracket RH <i>Recess</i>		\$	98.00 +
3 Front Bumper Retainer RH <i>Dark</i>		\$	68.00
4 Front bumper Reinforcement		\$	486.50
5 Front Bumper Fog Lamp Garnish RH <i>Recess</i>		\$	195.40 +
6 Front Bumper Fog Lamp RH <i>Cracked</i>		\$	435.20
7 Front Bumper Protector with Moulding RH <i>Distorted</i>		\$	175.40
8 Front Bumper Lower Lip <i>Recess</i>		\$	358.60
9 Front Bumper Clips <i>Recess</i>	\$6.00 X 10pcs	\$	60.00 - 30
10 Front Headlamp Assy RH <i>Cracked</i>		\$	1,120.00
11 Front Headlamp Bracket RH <i>Best</i>		\$	98.40
12 Front Radiator Grille <i>Recess</i>		\$	762.30 +
13 Front Radiator Grille Clips <i>Recess</i>	\$6.00 X 10pcs	\$	60.00 +
14 Front Support Panel <i>Recess</i>		\$	738.50 +
15 Centre Brace Panel <i>Recess</i>		\$	165.20 +
16 Front Bonnet <i>Recess</i>		\$	964.20 +
17 Front Bonnet Insulator Clips <i>Recess</i>	\$6.00 X 10pcs	\$	60.00 +
18 Wiper Washer Tank <i>Deformed</i>		\$	365.40
19 Front Fender RH <i>Distorted</i>		\$	853.40
20 Front Fender Emblem VVTI <i>Recess</i>		\$	68.00
21 Front Fender Inner Shield RH <i>Recess</i>		\$	286.70
22 Front Fender Inner Shield Clips <i>Recess</i>	\$6.00 X 10pcs	\$	60.00 - 30
23 Front Right Suspension <i>Recess</i>		\$	428.20 +
24 Front Right Lower Arm <i>Recess</i>		\$	386.50 +
25 Front Right Knuckle Arm <i>Recess</i>		\$	467.80 +
26 Front Right Hub Bearing <i>Recess</i>		\$	385.70 +
27 Front Right Steering Rack and Pinion <i>Recess</i>		\$	1,635.80 +
28 Front Right ABS Sensor <i>Recess</i>		\$	365.20
Parts :		\$	12,256.60
Less Parts 25% :		\$	3,064.15
Total Parts :		\$	9,192.45

Special Net Items :

Front Right Rim <i>lit</i>	\$	850.00 400
Front Right Tire <i>metal Recess</i>	\$	450.00 300 +
Radiator Coolant <i>Recess</i>	\$	95.00 x
Front Number Plate with Garnish <i>Recess</i>	\$	80.00 x
Total S/N Parts :		\$ 1,475.00

Labour :

To Remove & Renew Affected Accident Areas	\$	1,500.00 600
To Putty, Spray Paint on Front Affected Accident Areas	\$	1,400.00 500
To Check & Re-Connect all electrical wiring	\$	50.00 30
To Conduct AC Leakage Test & Top Up Gas	\$	200.00 x

To Conduct Radiator Pressure Test & Check for Leakage
 To Renew & Install Front Right Undercarriage to facilitate Repairs
 To Re-Programme & Reset Diagnostic
 To Replace, Balance Tyre into RIM
 To Conduct All Wheel Alignment
 To Rust Proof Affected Areas

\$	200.00	X
\$	250.00	?
\$	250.00	+
\$	150.00	+
\$	250.00	-80
\$	100.00	-50
Total Labour : \$	4,350.00	

TOTAL PARTS :	\$	9,192.45
TOTAL SPECIAL NET ITEM :	\$	1,475.00
TOTAL LABOUR :	\$	4,350.00
TOTAL REPAIR COST :	<u>\$</u>	<u>15,017.45</u>

Adrian G
 L/S 04/12/19.
 OSDu/s.