

ASS. REC. BY:

REF:

293/CT11902148/EP302

Special Instruction:

Assignor: Steve

ASSIGNMENT (Office)

From (Person): Cheng Bora Jen

of

CTI

Date/Time:

04/12/19

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLN 1030R

Insured:

GBJ 7357Z

at Workshop m/s

Gold Autoworks

Tel:

8199 9149 Simon

of 48 Toh Guan Rd East, Enterprise Hub #01-119

Policy No:

Claim No:

SNM19D205754 Cor

Sum Insured:

Excess:

Make of Veh:
(Client's Record)

D.O.A.

24/11/19

CA / REV / REP. / REV 24 HRS

YRS

H.O.D. Endorsement:

Date/Time:

04/12/19 @ 4.35pm

Person Contacted:

Simon

Vehicle: IN/OUT

Date/Time	Action/Instruction
	Estimate ()
	SLN 1030R-X
	GBJ 7357Z-X

ASS. REC. BY: Steve

REF: CT1

ASSIGNMENT

PRS

From: _____ Date: 05/12/19

Veh No: SLN 1030R Yr Regn: 21/4/17

Estimated Cost: _____

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OD: (TP) WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

To Inspect Vehicle No: SLN 1030R

Make: Honda Shuttle C.C. 1496

at Workshop m/s GOLD Auto works

Colour: Silver A/C: Insured / Std / NI / NA

of 48 Toh Guan Rd East, Enterprise Hub

Sp. Reading: 207376 T/Radio: Insured / Std / NI / NA

Insured: #01-49 8(608586)

Eng/No: _____

Policy No. _____

C/No: GK 81191006

Claims No. _____

Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured: _____ Excess: _____

Steering: In order / Jammed / Leaked / Burnt or

(Client's Record)

Brake: In order / Jammed / Leaked / Burnt or

Make of Veh: _____

Modi: Nil / SRM / STD A/Rim or

(Policy Condition) PRS

N/S	O/S

Remark: The veh had commenced its repair at the time of inspection.

Tyre Size: F: 185/60R15
R: 1

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or Fire 29

Bal. or Market Value: _____

Front 5 mm Rear 5 mm

IDAC Accident Rpt: _____ Consistent?: Yes or No

R/Bal. 5 mm L/Bal. 5 mm

GIA / PR Seen: _____ Consistent?: Yes or No

D.O.A. 24/11/19 D.O.I. 5/12/19

Est. Repairs: _____ days Res.: Yes or No

*Survey held at GOLD Auto works

Lum Sum: _____ % 3 Val.: Yes or No

Des. of Damages Fr / v O/S / N/S / U/C / Rooftop or

CA / REV / REP. / 24 HRS

The U/C / Chassis frame / Body Structure affected due to collision.

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Date / Time	Action / Instruction
	<u>MV-66K 2k-3k repair range</u>
	<u>3 repair days</u>
	<u>Repair Range \$2k-3k. 3 days</u>
	<u>Submit PRS Report.</u>
	<u>11/12/2019</u>

RECEIVED 16 DEC 2019

Date/Time, File Pass to? : Preli. Report

Days Of Repair: 3

10/12 Typist

: Final Report

Resurvey No. of Trip: 1

Date/Time, File Return to? 2)

Add Fee: : Site Insp (\$)

Survey Fee:	<u>190</u>
Transportation:	
S + RS, SI	
Photos	
Others	
TOTAL	<u>190</u>

Report Format: TP-PRS

: Interview (\$)

: Tech. Invs (\$)

: Week end (\$)

Lump Sum / B.B.F: (\$)

Summer Lee (LKK Auto)

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Sent: Wednesday, 4 December, 2019 4:33 PM
To: claims@goldautoworks.com.sg
Cc: 'assignments'; 'assignments'
Subject: RE: OUR REF: SNM19D205754/GBJ7357Z/CBS - Requesting for PRE-Repair survey for our vehicle number SLN1030R

WITHOUT PREJUDICE
SAVE AS TO COSTS

Dear Hui Ting,

We regret to inform that we are not agreeable to your list of proposed surveyors and will be assigning our panel surveyor, M/s LKK Auto Consultants to conduct the Pre-repair survey.

Please contact our surveyor to conduct the post repair inspection before returning the repaired vehicle to the claimant.

Aside to LKK,

Please refer to the email below and liaise with third party workshop accordingly.

Thank you.

Chong Boon Sen
Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/ | WeChat: 太平狮城 Taiping SG 3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

-----Original Message-----

From: claims@goldautoworks.com.sg [mailto:claims@goldautoworks.com.sg]
Sent: Wednesday, December 4, 2019 1:29 PM
To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Subject: Re: OUR REF: SNM19D205754/GBJ7357Z/CBS - Requesting for PRE-Repair survey for our vehicle number SLN1030R

Without Prejudice
Dear Sir/Madam,

We have instructions to reject your surveyors and propose to engage a surveyor from the list below:-

- 1) Appraisal VP Pte Ltd - Victor Png

- 2) Appraisal VP Pte Ltd - Jaclyn Loh
- 3) Prominent Appraisal - Hon Andrew
- 4) Absolute Appraisal Services Pte Ltd - Nicky Seah

Kindly see our attached letter and the workshop details as below:-

Workshop Name: Gold Autoworks Pte Ltd

Address: 48 Toh Guan Rd East, Enterprise Hub #01-119 Singapore 608586 Contact Person: Simon Contact Number: 8199-9149

THANKS & REGARDS,
SIMON TAN
GOLD AUTOWORKS PTE LTD
8199-9149

On 2019-12-04 11:33, Chong Boon Sen wrote:

- > Without prejudice
- > Dear Sir,
- > LKK
- >
- > STA
- > LBS
- >
- >
- > Chong Boon Sen
- > Claims Executive
- > Department
- >
- > China Taiping Insurance (Singapore) Pte. Ltd.
- > 3 Anson Road #16-00 Springleaf Tower Singapore 079909
- > DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033
- >
- > W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/
- > | WeChat: 太平狮城 Taiping SG 3 Anson Road #16-00 Springleaf Tower
- > Singapore 079909
- > DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033
- >
- >
- > -----Original Message-----
- > From: Claims Dept of CTI
- > Sent: Wednesday, December 4, 2019 11:30 AM
- > To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>; Chee So Chow
- > <sochow.chee@sg.cntaiping.com>; claims@goldautoworks.com.sg
- > Subject: OUR REF: SNM19D205754/GBJ7357Z/CBS - Requesting for
- > PRE-Repair survey for our vehicle number SLN1030R
- >
- > Dear Boon Sen,
- >
- > Please conduct PRS for SLN1030R.
- >
- > Note: officer in charge – Boon Sen 63896171.
- >
- >

> *** Kindly quote our reference number when replying.
>
>
> Regards,
>
> Claims Department
>
> China Taiping Insurance (Singapore) Pte. Ltd.
> 3 Anson Road #15-00 Springleaf Tower Singapore 079909
> T: (65) 63896116 | F: (65) 62247175
>
> W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/
> | WeChat: 太平獅城 Taiping SG
>
>
> Disclaimer: This e-mail and any files transmitted with it is intended
> only for the named recipients and may contain confidential
> information. Any unauthorized disclosure, use or dissemination of this
> message, either in whole or partial, is prohibited. If you are not the
> intended recipient, please notify the sender immediately. Please
> delete the e-mail and any copies of it thereafter.
>
>
> -----Original Message-----
> From: claims@goldautoworks.com.sg [<mailto:claims@goldautoworks.com.sg>]
> Sent: Tuesday, 3 December, 2019 4:41 PM
> To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>
> Subject: Requesting for PRE-Repair survey for our vehicle number
> SLN1030R
>
> ATTENTION MOTOR CLAIM DEPARTMENT
>
> Dear Sir/Mdm,
>
> Accident involving SLN1030R & GBJ7357Z AT WOODLANDS NORTH PLAZA
>
> 1. We are here to notify you of a road traffic accident on 24/11/19 ;
> 13:30HRS at WOODLANDS NORTH PLAZA involving our client vehicle
> registration number SLN1030R
>
> and vehicle registration number GBJ7357Z driven by your insured at
> the material time.
>
> 2. As a result of the accident, our client vehicle SLN1030R has been
> damaged.
>
> Please arrange and conduct a PRE- REPAIR SURVEY for the vehicle
> SLN1030R. If we do not receive any reply from you within the
> stipulated timeline, our client shall
>
> proceed to repair the vehicle without further reference to you.
>
> 3. Please kindly arrange a PRE-REPAIR SURVEY on 4/12/2019 wednesday at
> 48,TOH GUAN RD EAST, ENTERPRISE HUB #01-119 S(608586)
>

>
>
>
> THANKS & REGARDS,
> SIMON TAN
> GOLD AUTOWORKS PTE LTD
> 8199-9149
>

> This email has been scanned by the Symantec Email Security.cloud
> service.
> For more information please visit <http://www.symanteccloud.com>
>

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	26/11/2019 10:55
Date Of Accident	24/11/2019 13:30
Exact Location Of Accident	WOODLANDS NORTH PLAZA
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLN1030R
Insured/Policyholder	
Name Of Registered Owner	DRIVE U SERVICES
Co Reg No	53329617W
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97479664
Alternative Phone No	OFFICE-97479664
Vehicle Particulars	
Manufacturer	HONDA
Model	SHUTTLE
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5089849806-02(CLASSIC)
Cover Note Number	
Driver	
Name of Driver	HUANG RUISENG, RICKSON
NRIC No	S9043639B
Date Of Birth	18/11/1990
Occupation	OUTDOOR
Date Of Driving Pass	02/09/2010
Driving Experience	9 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97479664
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address BLK 638 WOODLANDS RING RD #09-53
 Postcode
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OTHER - RENTAL
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles (including own vehicle) involved in the accident 2
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance?
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

PLS REFER ATTACHED ACCIDENT REPORT FROM THE DRIVER.


Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? YES
 Remarks/ Reasons: WILL EMAIL IF REQUIRED
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GBJ7357Z
 Vehicle Make/Model/Colour
 Details Of Properties
 Vehicle Category COMMERCIAL VEHICLE
 Name of Driver
 NRIC/Passport Number
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver)

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was going to pick up rider at pick up point at Woodlands North Plaza and as i stopped the van in front suddenly reversed and hit my car

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:

HDAC BUKIT BATOK (VAC)

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



**SINGAPORE
POLICE FORCE**



T/20191130/2053

Police Station Of Origin:
Woodlands East N.P.C.
3 Woodlands Drive 63 SINGAPORE 737890
Tel No: 1800-7679999

3 of 3

Report No. T/20191130/2053

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: L / ON ZHI WEI, ROGER	
Signature Of Interpreter: Not applicable	
Officer In Charge Of Case: TP / HRT / SI KALESWARI PALANI Contact No: 65476902	SN-130
Authentication Stamp: NP168	Signature:
Singapore Police Force	

Signature Of Informant:	
Date/Time:	30/11/2019 12:28
Classification Of Case:	

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	617W
Vehicle Details	
Vehicle No.:	SLN1030R
Vehicle to be Exported:	No
Intended Deregistration Date:	05 Dec 2019
Vehicle Make:	HONDA
Vehicle Model:	SHUTTLE 1.5G CVT
Primary Colour:	Silver
Manufacturing Year:	2016
Engine No.:	L15B5001201
Chassis No.:	GK81101006
Maximum Power Output:	97.0 kW (130 bhp)
Open Market Value:	\$17,432.00
Original Registration Date:	21 Apr 2017
First Registration Date:	21 Apr 2017
Transfer Count:	0
Actual ARF Paid:	\$7,432.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	20 Apr 2027
PARF Rebate Amount:	\$5,574.00
Intended COE Rebate Details	
COE Expiry Date:	20 Apr 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$52,000.00
COE Rebate Amount:	\$38,350.00
Total Rebate Amount:	\$43,924.00

The information contained herein is correct as at 05 Dec 2019

OK

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	04 Dec 2019		04 Dec 2019 18:30 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	-, Co. Reg. No.: -								
Main Claimant:	drive u services								
Vehicle Reg. No.:	SLN1030R	Date of Loss:	24/11/2019 00:00 - :59 [31 Months and 3 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM19D205754C02	Policy/Cover Note No.:	DMCVSN19299919000						
Vehicle Reg. No. (Insured):	GBJ7357Z	Policy No. (Claimant):							
		Excess:	S\$0.00						
Repairer:	Gold Autoworks Pte Ltd (HQ) 48 TOH GUAN ROAD EAST, #01-119 ENTERPRISE HUB, 608586 Jurong East - Tel:								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by CHEN TSUE YEE] ... [Final Rpt due 13/12/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SLN1030R (SNM19D205754C02)**
[GBJ7357Z]
TP
drive u services
Nov 24 2019 12:00AM
[-]
Gold Autoworks Pte Ltd

Upload Documents | Upload Photos | Compose New Letter

View

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	05/12/19 18:48	General View		<input checked="" type="checkbox"/>
2	05/12/19 18:48	General View		<input checked="" type="checkbox"/>
3	05/12/19 18:48	General View		<input checked="" type="checkbox"/>
4	05/12/19 18:48	General View		<input checked="" type="checkbox"/>
5	05/12/19 18:48	General View		<input checked="" type="checkbox"/>
6	05/12/19 18:48	Odometer Reading		<input checked="" type="checkbox"/>
7	05/12/19 18:48	Chassis Number		<input checked="" type="checkbox"/>
8	05/12/19 18:48	General View		<input checked="" type="checkbox"/>
9	05/12/19 18:48	General View		<input checked="" type="checkbox"/>
10	05/12/19 18:48	General View		<input checked="" type="checkbox"/>
11	05/12/19 18:48	General View		<input checked="" type="checkbox"/>
12	05/12/19 18:48	General View		<input checked="" type="checkbox"/>
13	05/12/19 18:48	General View		<input checked="" type="checkbox"/>
14	05/12/19 18:48	General View		<input checked="" type="checkbox"/>
15	05/12/19 18:48	General View		<input checked="" type="checkbox"/>
16	05/12/19 18:48	General View		<input checked="" type="checkbox"/>
17	05/12/19 18:48	General View		<input checked="" type="checkbox"/>
18	05/12/19 18:48	General View		<input checked="" type="checkbox"/>
19	05/12/19 18:48	General View		<input checked="" type="checkbox"/>
20	05/12/19 18:48	General View		<input checked="" type="checkbox"/>
21	05/12/19 18:48	General View		<input checked="" type="checkbox"/>
22	05/12/19 18:48	General View		<input checked="" type="checkbox"/>
23	05/12/19 18:48	General View		<input checked="" type="checkbox"/>
24	05/12/19 18:48	General View		<input checked="" type="checkbox"/>
25	05/12/19 18:48	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
26	05/12/19 18:48	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
27	05/12/19 18:48	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
28	05/12/19 18:48	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
29	05/12/19 18:48	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
30	05/12/19 18:48	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
31	05/12/19 18:48	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
32	05/12/19 18:48	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
33	05/12/19 18:48	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
34	05/12/19 18:48	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
35	05/12/19 18:48	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
36	05/12/19 18:48	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
37	05/12/19 18:48	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
38	05/12/19 18:48	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
39	05/12/19 18:48	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
40	05/12/19 18:48	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
41	05/12/19 18:48	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
42	05/12/19 18:48	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
43	05/12/19 18:48	Photographs of Damaged Parts		<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
44	05/12/19 18:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	05/12/19 18:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	11/12/19 09:48	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
47	11/12/19 09:48	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
48	11/12/19 09:48	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
49	11/12/19 09:48	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
50	11/12/19 09:48	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
51	11/12/19 09:49	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
52	11/12/19 09:49	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
53	11/12/19 09:49	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
54	11/12/19 09:49	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	04/12/19 18:31	PRI CONTACT	 Load PDF	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)				
<div style="border: 1px solid black; width: 100%; height: 100%;"></div>				
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>				

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CT119021448/ETF3E2

Date: 16/12/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN19299919000
Claimant Vehicle No :	SLN1030R	Insured Vehicle No :	GBJ7357Z
Date of Loss:	24/11/2019	Nature of Claim: TP	Claim No: SNM19D205754C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLN1030R	Engine No:	L15B5001201
Make & Model:	HONDA SHUTTLE, 1.5 (A)	Chassis No:	GK81101006
Reg. Date:	21/04/2017 (Man. Year: 2016)	Odometer:	207376 km
Colour:	Silver		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Firenza 5 mm	Rear Left Side:	Firenza 5 mm
Front Right Side:	Firenza 5 mm	Rear Right Side:	Firenza 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	04/12/2019		
Date Inspected:	05/12/2019	Inspected At:	Gold Autoworks Pte Ltd (HQ) 48 TOH GUAN ROAD EAST, #01-119 ENTERPRISE HUB Singapore 608586
Estimated Period of Repair:	3.0 days		

Adjuster: CHEN TSUE YEE

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000.00 - \$3,000.00

REPAIR DETAILS

Reference		
Part Source:		(Last Synchronised: 16 Dec 2019)
Parts:	N/A	HONDA SHUTTLE 1.5 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLN1030R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >