

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Pauline Tham

Date: 23 Dec 2019

## **Preliminary Advice**

|                    |                                                                                               |                         |              |
|--------------------|-----------------------------------------------------------------------------------------------|-------------------------|--------------|
| Insured Vehicle No | : GBE856Y                                                                                     | Accident Date           | : 02/12/2019 |
| TP Vehicle No      | : SHC8933U                                                                                    | Assignment Date         | : 04/12/2019 |
| Make               | : HYUNDAI I40                                                                                 | Est. Duration of Repair | : 7 days     |
| Date of Inspection | : 05/12/2019                                                                                  |                         |              |
| Inspection At      | : Chunni Motor Work Pte Ltd - Amk (HQ)<br>Blk 10 #01-05/06, AMK Autopoint<br>Singapore 568047 |                         |              |

### **Point of Impact / General Description of Damages**

The vehicle sustained impact / damages front & rear portion and parts claimed are consistent to the accident.

|                             |      |           |
|-----------------------------|------|-----------|
| Repairer's Estimate (Gross) | :S\$ | 23,842.78 |
| Revised Amount              | :S\$ | 14,633.18 |
| Check Items (Estimated)     | :S\$ | 0.00      |
| Total                       | :S\$ | 14,633.18 |

|                 |      |
|-----------------|------|
| Lump Sum Repair | :S\$ |
|-----------------|------|

### **Total Loss Consideration**

|                    |      |
|--------------------|------|
| New for Old Value  | :S\$ |
| Pre-Accident Value | :S\$ |
| COE / PARF Rebate  | :S\$ |
| Salvage Value      | :S\$ |
| Margin for Repair  | :S\$ |

### **Remarks**

( ) The vehicle is economical/not economical for repair.

( X ) The above survey was conducted on a 'without prejudice' basis.