

**COMFORTDELGRO
ENGINEERING**

Kk anchors

Our Job Ref No : 305358709

Date : 26. Nov. 2019

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508989
Fax: 6546 8156

FINALIZATION FORM

To : LKK

Fax :

Attn : GUO QIANG

Vehicle Reg No. : SHA2306E

Date of Accident: 2. Dec. 2019

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: AIG SJG1505Z
2. The finalized amount shall be:

(a) Spare Parts after List discount	\$521.70
(b) Labour Charges	\$560.00
Total for Part-By-Part Repair Cost	\$1,081.70
(c) Lumpsum Repair (if applicable)	
Total for Lumpsum repair cost after Less:	
Final Lumpsum Repair cost	



3. Estimated normal period for repairs: 2 working days.
4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**
5. Thank you for your assistance. We confirm the estimates and finalized amount

Signature : *[Signature]*
 Name : Larry Ng
 Tel : 6214 8316
 Fax : 6546 8156

Signature : *[Signature]*
 Name : _____
 Date : 03/11/2020

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid				
3. Survey Fees				
4. LTA Search Fee	\$2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHA 2306E

DATE : 3.12.2019

MAKE :

MODEL : HYUNDAI IONIQ

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Labour Charge			
	Spray Painting Charge- Frt Bumper X NN			\$ 250.00
	TOTAL LABOUR			\$ 250.00
	Rear Bumper X Repair NN			\$ 459.40
	Rear Bumper Reinforcement X NN			\$ 294.80
	Rear Bumper Reinforcement Bracket (LH/RH) X NN	\$	138.10	\$ 276.20
	Rear Bumper Centre Moulding Assy / SCR			\$ 451.25
	Rear Bumper Lower Centre Moulding Assy X			\$ 155.00
	Rear Bumper Stay X			\$ 138.10
	Rear Bumper Side Bracket (LH/RH) X NN	\$	33.10	\$ 66.20
	Rear Bumper Cover Clips X			\$ 22.00
	SUB TOTAL			\$ 1,862.95
	LESS 20%			\$ 372.59
	DISCOUNTED TOTAL			\$ 1,490.36
	Rear No.Plates / CA			\$ 25.00
	Rear No.Plates Trim Cover X NN			\$ 30.00
	Rear Bumper Reverse Sensor / DMS			\$ 135.70
	Rear Bumper Rubber Mat X NN			\$ 50.00
	2 Days P/P before part photos. Give Qimp 04/12/19 12pm			\$ 240.70
	Labour Charge			\$ 350.00
	Panel Beating			\$ 250.00
	Spray Painting Charge			\$ 50.00
	Wiring Charge			\$ 120.00
	Remove/Refix Reverse Sensor			
	TOTAL LABOUR			\$ 770.00
	ESTIMATE TOTAL			\$ 2,751.06

Larry Ng

LIK Auto Consultants hence notify the Repairer of the following:

- To survey before/after spray painting
- To display the estimate (s) during resurvey
- Parts price subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplementary items must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

361

Nett ✓
Nett ✓
Nett ✓
Nett ✓

320
200
X NN
40
560

1081.7

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.