

ACCIDENT REPAIR ESTIMATES

Our Ref:

Type of Claim : TPVehicle No. : SMN2065YMake & Model : BLUE CARYear of Manufacture : 2018Chassis No. : VL4BCEB4RJT003533Ins Company : AIG ASIA PACIFIC
INSURANCE PTE LTDEngine No. : 922403C18W473311893

Excess : _____

Policy No. : _____

Date of Accident : 02/11/2019Time of Accident : 13:30

Suggested Days of Repair : _____

Case Owner : BLUECAR EAST ASIA PTE LTD**Repair Estimates**TP Vehicle No. : SKM7003YParts (a) Cost / List-Price Items \$ 4,383.00Plus/Less 15% \$ 657.45Total of Cost / List \$ 5,040.45(b) Nett Price Items \$ -

Less _____

Total of Nett Item _____

(c) Special Nett Items \$ 110.00Total Parts Cost (Appendix A) \$ 5,150.45Labour (Appendix B) \$ 1,400.00Total Repair Cost \$ 6,550.45LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____

The above total will be subjected to 7% G. S. T.

Name of Surveyor : Eno Q'ap - 8288 0282Company : LKKSurvey conducted on : 05/12/19 at _____Remarks By Surveyor

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : 5 day(s)(c) Resurvey : Required / Not Required Q'S

(d) Excess : \$ _____

(e) Signature of surveyor : _____ Date: _____

part by part.
before paint photos.

ESTIMATED REPAIR COST DETAILS

Vehicle No : SMN2065Y Case Owner : 0

Make & Model : BLUE CAR Year Manufacture : 2018

Chassis No : VL4BCEB4RJ003533 Engine No : 922403C18W47331189

Date & Time : _____ Supplier : _____

Order By : _____ Type of Claim : TP

S/No	Part Description	QTY	Cost Price		List Price	Nett Price	S/N
			Unit	Sub-Total			
1	Front right fender <i>X Repair</i>	1	\$ 1,040.00	\$ 1,040.00			
2	Right door <i>/ Bnc</i>	1	\$ 2,705.00	\$ 2,705.00			
3	Right door clip & rivet <i>/ ncc</i>	10	\$ 2.00	\$ 20.00			
4	Right door outer lock with key <i>/ Cut</i>	1	\$ 165.00	\$ 165.00			
5	Right door sticker <i>/ ncc</i>	1	\$ -	\$ -			\$ 70.00
6	Rear right fender cover <i>/ Scr</i>	1	\$ 195.00	\$ 195.00			
7	Rear right fender cover screw <i>/ ncc</i>	5	\$ 2.00	\$ 10.00			
8	Rear right fender sticker <i>/ ncc</i>	1	\$ -				\$ 40.00
9	Right side skirt <i>/ Cut</i>	1	\$ 195.00	\$ 195.00			
10	Rear right rim cover <i>X Scr NN</i>	1	\$ 53.00	\$ 53.00			
11	0						
12	0						
13	0						
14	0						
15	0						
16	0						
17	0						
18	0						
19	0						
20	0						
21	0						
22	0						
23	0						
24	0						
25	0						
26	0						
27	0						
28	0						
29	0						
30	0						

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

T \$ 4,357.00 \$ 4,383.00 \$ - \$ - \$ 110.00

Indeco

VEHICLES & EQUIPMENT DIVISION

No . 39 DEFU LANE 12, SINGAPORE 539139

Tel: (65) 382 2736 FAX: (65) 6382 2817

Labour

Vehicle No.	:	<u>SMN2065Y</u>
Make & Model	:	BLUE CAR

Case Owner
Year of Manufacture

BLUECAR
EAST ASIA
: PTE LTD
: 2018

[illegible]

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any