

ACCIDENT REPAIR ESTIMATES

Our Ref:

Type of Claim : TPVehicle No. : SMN2065YMake & Model : BLUE CARYear of Manufacture : 2018Chassis No. : VL4BCEB4RJT003533Ins Company : AIG ASIA PACIFIC
INSURANCE PTE LTDEngine No. : 922403C18W473311893Excess : Policy No. : Date of Accident : 02/11/2019Time of Accident : 13:30Suggested Days of Repair : Case Owner : BLUECAR EAST ASIA PTE LTDTP Vehicle No. : SKM7003Y**Repair Estimates****Parts** (a) Cost / ~~List~~ Price Items \$ 4,383.00Plus/Less— 15% \$ 657.45Total of Cost / List \$ 5,040.45(b) Nett Price Items \$ -Less Total of Nett Item (c) Special Nett Items \$ 110.00**Total Parts Cost (Appendix A)** \$ 5,150.45**Labour (Appendix B)** \$ 1,400.00**Total Repair Cost** \$ 6,550.45*The above total will be subjected to 7% G.S.T.*Name of Surveyor : Company : Survey conducted on : at **Remarks By Surveyor**

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$ (e) Signature of surveyor : Date:



VEHICLES & EQUIPMENT DIVISION

No . 39 DEFU LANE 12, SINGAPORE 539139

Tel: (65) 382 2736 FAX: (65) 6382 2817

ESTIMATED REPAIR COST DETAILS

Vehicle No : SMN2065Y Case Owner : 0

Make & Model : BLUE CAR Year Manufacture : 2018

Chassis No : VL4BCEB4RJT003533 Engine No : 922403C18W47331189

Date & Time : _____ Supplier : _____

Order By : _____ Type of Claim : TP

S/No	Part Description	QTY	Cost Price		List Price	Nett Price	S/N
			Unit	Sub-Total			
1	Front right fender	1	\$ 1,040.00	\$ 1,040.00			
2	Right door	1	\$ 2,705.00	\$ 2,705.00			
3	Right door clip & rivet	10	\$ 2.00	\$ 20.00			
4	Right door outer lock with key	1	\$ 165.00	\$ 165.00			
5	Right door sticker	1	\$ -	\$ -			\$ 70.00
6	Rear right fender cover	1	\$ 195.00	\$ 195.00			
7	Rear right fender cover screw	5	\$ 2.00	\$ 10.00			
8	Rear right fender sticker	1	\$ -				\$ 40.00
9	Right side skirt	1	\$ 195.00	\$ 195.00			
10	Rear right rim cover	1	\$ 53.00	\$ 53.00			
11	0						
12	0						
13	0						
14	0						
15	0						
16	0						
17	0						
18	0						
19	0						
20	0						
21	0						
22	0						
23	0						
24	0						
25	0						
26	0						
27	0						
28	0						
29	0						
30	0						

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

T \$ 4,357.00 \$ 4,383.00 \$ - \$ - \$ 110.00



Tel: (65) 382 2736 FAX: (65) 6382 2817

: 2018

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any