

Estimate

Date 11 / 06 / 2019

001 / 001

Name	QUOTATION FOR SLN709Z	Tel (Home)	
Address		Tel (Office)	
E-Mail		Tel (Portable)	
		Fax	
		Model Name	S13
		Body Model	SJGDKK8
		Vin-Code	JF1SJGK85GG078249

Part Number	Part Code Name	Part Code	Q'ty	Price
60409SG0119P	PANEL ASSEMBLY-REAR DOOR, LEFT <i>X Regard</i>	FIG-605 60410A	1	684.00
62280SG030	WEATHER STRIP-DOOR, REAR OUTER LEFT <i>X</i>	FIG-605 62280B	1	100.80
61160FJ000EN	HANDLE-DOOR, OUTER <i>X</i>	FIG-607 61160E	1	46.80
61035SG010	LATCH & ACTUATOR ASSEMBLY-REAR, LEFT <i>X</i>	FIG-607 62176E	1	234.00
90422SG070	TAPE-REAR DOOR SASH LEFT <i>X</i>	FIG-905 90422D	1	18.00
90422SG090	TAPE-REAR DOOR SASH, CENTER LEFT <i>X</i>	FIG-905 90422H	1	10.80
90422SG110	TAPE-REAR DOOR SASH, REAR LEFT <i>X</i>	FIG-905 90422J	1	14.40
63512SG011	WEATHER STRIP-REAR DOOR, LEFT <i>X</i>	FIG-901 63512A	1	144.00
63527SG030	RUN CHANNEL-REAR DOOR, LEFT <i>X</i>	FIG-901 62234B	1	72.00
63572SG001	WEATHER STRIP-BODY SIDE, FLANGE REAR <i>ser.</i>	FIG-901 63572	1	72.00
91112SG252	GARNISH-REAR DOOR, LEFT <i>CA</i>	FIG-914 91111V	1	194.10
28111SG140	DISK WHEEL-ALUMINIUM <i>Ant</i>	FIG-290 28111	1	1,400.00
		Page-Total		2,990.90
		Sub-Total		2,990.90
		Total		2,990.90
		Tax		0.00
		Grand Total		2,990.90

Memo

Grand Total
2,990.90

--

Tel



19 Lorong 8 Toa Payoh
Singapore 319255



ESTIMATE / QUOTATION COST OF ACCIDENT REPAIR

REG NO: SLN709Z	MODEL : FORESTER 2.0XT AWD CVT
REF NO:INS/IC/CHI/0409/2019	YEAR: 21-APR-2017
ENGINE NO: FA20B829205	CHASSIS NO: JF1SJGK85GG078249
DOA: 04/11/2019	TOA: 1000HRS
TYPE OF CLAIM: OD	INS COMPANY: AIG

S/N	NATURE OF JOB	AMOUNT
1.	REPAIR/REPLACE LH REAR DOOR & LH REAR ROCKER PANEL	\$1000.00
2.	RESpray LH REAR DOOR & LH REAR ROCKER PANEL	\$800.00
3.	TRANSFER / BALANCE TYRE / RIM LH REAR	\$28.00
4.	TO CONDUCT WATER SEEPAGE TEST	\$85.00
5.	TRANSFER DOOR LH REAR MECHANISM	\$142.00
6.	REMOVE & REFIX CARPET, SEATS TO FACILITATE REPAIRS	\$342.00
7.	FAULT DIAGNOSTIC	\$235.00
8.	SUNDRIES	\$100.00
9.		
10.		
Total Labour		\$2712.00

2732

DATE APPROVAL:	05/12/19.
TIME APPROVAL:	
SURVEY BY:	Guo Qianp
HP / EMAIL:	828802812
BEFORE PAINT:	After repair photos.
DAYS GIVEN:	

Not Authorised.
2 Park.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: