

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III19021484/GGA3Q2

Date: 27/07/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No: D19MCV0001025
Claimant Vehicle No : SMA4649T	Insured Vehicle No : PC5925T
Date of Loss: 28/11/2019	Nature of Claim: TP
	Claim No: MCV2019D0001593

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMA4649T	
Make & Model:	TOYOTA PRIUS, 1.5 (A)	Engine No: 1NZ6400589
Reg. Date:	25/09/2012 (Man. Year: 2012)	Chassis No: JTDKD3B3901020523
Colour:	White	Odometer: 104601 km
Engine Capacity:	1497 cc	
Market Value/New Car Price:	N/A	
Sum Insured (S\$):	Market Value/New Car Price	

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Giti 5 mm	Rear Left Side:	Giti 5 mm
Front Right Side:	Giti 5 mm	Rear Right Side:	Giti 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,062.50	434.43	2,628.07	85.81
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,680.00	600.00	1,080.00	64.29
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,742.50	1,034.43	3,708.07	78.19
Approved Total (Overridden) (S\$)		800.00		
	(S\$)	4,742.50	800.00	3,942.50
	+ GST 7.00/7.00% (S\$)	331.98	56.00	275.98
	Nett Amount (S\$)	5,074.48	856.00	4,218.48
	+ Loss of Use (4.0 x S\$60.00/day) (S\$)		240.00	
	+ Doc/Search Fee (S\$)		29.00	
	Nett Liability (S\$)		1,125.00	
	Global Sum Settlement (S\$)		1,100.00	

INSPECTION

Date of Assignment: 05/12/2019

Date Inspected: 05/12/2019 Inspected At:

Yee Auto Pte Ltd (HQ)
160 SIN MING DRIVE, #02-17 SIN

MING AUTOCITY
Singapore 575722

Estimated Period of Repair: 3.0 days

Adjuster: XING GUO QIANG

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 22 May 2020)
Parts: 144	TOYOTA PRIUS 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMA4649T)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	850.90 F	*539.24 FL
2	1		*SET REAR BUMPER CLIPS	Necessary	60.00 FS	*30.00 FS
3	1		*REAR BUMPER REINFORCEMENT	Not Necessary	425.10 F	*- FL
4	1		*REAR BUMPER SIDE BRACKET (TOP)-LH	Not Necessary	85.00 F	*- FL
5	1		*REAR BUMPER SIDE BRACKET (TOP)-RH	Not Necessary	85.00 F	*- FL
6	1		*REAR BUMPER SIDE RETAINER -LH	Not Necessary	75.50 F	*- FL
7	1		*REAR BUMPER SIDE RETAINER -RH	Not Necessary	75.50 F	*- FL
8	1		*REAR END PANEL	Repair	560.00 F	*- FL
9	1		*REAR TAILLAMP -RH	Not Necessary	485.50 F	*- FL
10	1		*SET REVERSE SENSORS	Not Necessary	300.00 F	*- FL
11	1		*REAR NUMBER PLATE	Not Necessary	60.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	3,062.50	569.24
- List Item Discount on L Items 0.00/25.00% (\$)	0.00	134.81
Total Parts (\$)	3,062.50	434.43

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE & REPLACE DAMAGED PARTS ,PANEL BEAT WHERE NECESSARY	New	800.00	300.00
2	TO PUTTY ,APPLY PRIMER & SPRAY -PAINT ON THE AFFECTED PORTION	New	800.00	300.00
3	TO CHECK WIRING FUNCTIONS	New	80.00	0.00
			Gross Labour Cost (\$\$)	600.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >