



YEE AUTO PTE LTD

160 Sin Ming Drive #02-17/#07-12 Sin Ming AutoCity Singapore 575722
Tel: 6457 5768 Fax: 6252 8459 Mobile: 9687 4031
Email: yeeautopteLtd@gmail.com

Registration No: 20171925T Vehicle No: 201719251W

M/S : India International Insurance Pte Ltd
64 Cecil Street
#05-01 IOB Building
Singapore 049711

ATTN: Motor Claim Department
Your Ref No: -
Claim Type: Third Party
Accident Date: 28/11/2019
TP Veh Reg No: PC5925T

the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices to be subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Estimate No: ES1900140

Date: 05 Dec 2019

Veh Reg No: SMA4649T

Make/Model: TOYOTA PRIUS C CVT

Chassis No: JTDKD3B3901020523

Engine No: 1NZ6400589

Reg. Date: 25/09/2012

Acknowledged by Repairer
Signature:
Date:

Estimate Repair Cost to Vehicle No :SMA4649T

Description	U/Price	Quantity	List Price	Amount
			<u>SS</u>	<u>SS</u>
Net Price				
1 REAR NUMBER PLATE	60.00	1 PC	60.00	60.00
Spare Parts				
2 REAR BUMPER X repair ?	850.90	1 PC	850.90	
3 REAR BUMPER CLIPS X - MEC	60.00	1 SET	60.00	
4 REAR BUMPER REINFORCEMENT	425.10	1 PC	425.10	
5 REAR BUMPER SIDE BRACKET (TOP) - LH X	85.00	1 PC	85.00	
6 REAR BUMPER SIDE BRACKET (TOP) - RH X	85.00	1 PC	85.00	
7 REAR BUMPER SIDE RETAINER - LH X	75.50	1 PC	75.50	
8 REAR BUMPER SIDE RETAINER - RH X	75.50	1 PC	75.50	
9 REAR END PANEL X	560.00	1 PC	560.00	
10 REAR TAILLAMP - RH X	485.50	1 PC	485.50	
11 REVERSE SENSORS X	300.00	1 SET	300.00	
			3,002.50	3,002.50
Labour				
12 TO DISMANTLE & REPLACE DAMAGED PARTS, PANEL BEAT WHERE NECESSARY.	800.00	1 JOB	800.00	200
13 TO PUTTY, APPLY PRIMER & SPRAY-PAINT ON THE AFFECTED PORTION.	800.00	1 JOB	800.00	200
14 TO CHECK WIRING FUNCTIONS.	80.00	1 JOB	80.00	X NN
			1,680.00	1,680.00
			Total	SS 4,742.50
			Add GST @ 7%	331.98
			Total Amount Payable	SS 5,074.48

TOTAL: SINGAPORE DOLLAR FIVE THOUSAND SEVENTY FOUR AND CENTS FORTY EIGHT ONLY

2 Dms.
part by part.
After repair photos.
Gino Liang - 82880282
05/12/19.

For Yee Auto Pte Ltd

AUTHORISED SIGNATURE