

ASS. FILE NO.

Store

REF:

MG CC3/AIG1904495/Fqf3²⁴

ASSIGNMENT

From

Date:

05/12/19

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SGU 5056M

at Workshop m/s

Premium

of

24 Bona Sector

Insured:

Policy No.

1800003116

Claims No.

391101641756

Sum Insured:

Excess:

TBA 800

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

102k

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SGU 5056M

Yr Regn:

16/1/18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Audi Q2

C.C.

999

Colour

Grey

A/C:

Insured / Std / NI / NA

Sp. Reading

10507

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

WAUZZZGA2JA 041528

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

215/60R16

R:

1

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

4/12/19

D.O.I.

5/12/19

Survey held at

Premium

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

MV - 102,000

PV - 55,419

NV - 46,581

RECEIVED 11 MAR 2020

05/12/19 @ 5.44pm revert to Victor via Messenger.

06/12/19 @ 2.51pm Andy Fong informed C/A via Messenger.

06/12/19 @ 3.40pm informed Tony C/A by email: 8800 by email.

27/12/20 @ 3.12pm confirmed with Jia Yee final fig @ 29920.16, 14 days by email.
Cred @ 32295.84, 52%.

Date/Time, File Pass to?

☐

: Preli. Report

1) 01/3 typhax

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

14

Resurvey No. of Trip:

1

Add Fee:

☐

: Site Insp (\$)

☐

: Interview (\$)

☐

: Tech. Insp (\$)

☐

: Wheel stud (\$)

Survey Fee:

Transportation:

S + PS. SI

Fines:

OSER:

TOTAL

Report Format:

MER200

Lump Sum / L.P.F. (\$)

29920.16

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Thursday, 27 February 2020 3:12 PM
To: jiajee.yap@premiumauto.com.sg; Steve Chen (LKK Auto); SUR
Cc: 'Boo seng yak'; 'Carrine Leong'; 'Chang Chee Sing'
Subject: RE: FINAL REVISION - SGU5056M - OD AIG - SURVEYED 05 DEC 19

Dear Jia Yee,

WITHOUT PREJUDICE

Confirm final fig \$29,920.16 before excess \$800.00 & GST and 14 repair days.

Kindly expedite the discharge voucher and tax invoice to us for close case.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: jiajee.yap@premiumauto.com.sg <jiajee.yap@premiumauto.com.sg>
Sent: Wednesday, 26 February 2020 5:17 PM
To: Steve Chen (LKK Auto) <SteveChen@lkkauto.com>; SUR <sur@lkkauto.com>; Admin A <admin-a@lkkauto.com>; CS A Team <cs-a@lkkauto.com>; Adrian Ling (LKKAUTO) <adrianling@lkkauto.com>; Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>
Cc: 'Boo seng yak' <boojohnny@gmail.com>; 'Carrine Leong' <carrine.leong@premiumauto.com.sg>; 'Chang Chee Sing' <claims@premiumauto.com.sg>
Subject: FINAL REVISION - SGU5056M - OD AIG - SURVEYED 05 DEC 19

Hi Steve and all,

Revised estimate and photographs is attached.

Please confirm repair cost of \$29,920.16 @ 14 days exclude 1 PH and 2 Sunday.

Your early closure is well appreciated.

Thanks & Best Regard

JiaYee Yap

Claims Administrator

Premium Automobiles Pte Ltd (Reg No 199902271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9925 f. +65 6841 1183

e. jiajee.yap@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Friday, 6 December 2019 3:40 PM
To: Claims Dept; Admin-D (LKKAUTO); SUR
Subject: RE: OD CLAIM FOR SGU 5056 M ON 4/12/2019

Dear Tony,

Instructed by our client, please proceed to repair the insured vehicle **SGU 5056M (Excess \$800/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

Any check item or supplementary are subjected to further approval from our client.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claims Dept <claims@premiumauto.com.sg>
Sent: Thursday, 5 December 2019 4:12 PM
To: Admin-D (LKKAUTO) <admin-d@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: 'Claims Dept' <claims@premiumauto.com.sg>
Subject: RE: OD CLAIM FOR SGU 5056 M ON 4/12/2019

Dear SUR,

Attached revise estimate for your kind reference.

Kindly assist follow up on repair approval.

Thank you.

Best Regards,
Tony Foong
Claims Advisor

Premium Automobiles Pte Ltd (Reg No 199902271W)

55 Ubi Road 1 Singapore 408699

p. +65 6366 2323, d. +65 67689911

e.<mailto:claims@premiumauto.com.sg> w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223

Claim Audit

AUDIT TRAIL

No.	On	Audit	Remarks	By
1	04 Dec 2019 14:11	Clim Veh Model Changed		[] Merimen Administrator
2	04 Dec 2019 14:11	Clim Created	Reg No: SGU5056M, Policy No: 1800003116-01, Acct Date: 2019/12/04, Claim Type: SC, Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG), Ins.Status => Notification, Created from SAS:MPA119160010	[I] Merimen Administrator
3	05 Dec 2019 14:15	Clim Registration Modified	Setl.Type:3->0, Claim Type:SC->OD.	[] SHIAU CHAN
4	05 Dec 2019 14:15	Adj Clim Retrieved	Adj: LKK Auto Consultants Pte Ltd (HQ)	[] SHIAU CHAN
5	05 Dec 2019 14:15	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] SHIAU CHAN
6	05 Dec 2019 14:15	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/12/16	[A] SHIAU CHAN
7	05 Dec 2019 14:15	Adj Mandate Set	Approved:8000.00.Reinsp:Adj decides.	[A] SHIAU CHAN
8	05 Dec 2019 14:15	Clim Registration Modified	Rep:1137->200611.	[A] SHIAU CHAN
9	05 Dec 2019 14:15	Clim Veh Model Changed	(205236) AUDI Q2 999cc 1.0 TFSI S TRONIC (A).	[A] SHIAU CHAN
10	05 Dec 2019 14:15	Assignment 1st Accessed		[A] SHIAU CHAN
11	05 Dec 2019 14:15	Adj Adjuster Assigned	[None] -> CHEN TSUE YEE	[A] SHIAU CHAN
12	05 Dec 2019 14:19	Adj Rpt Initiated		[A] SHIAU CHAN
13	05 Dec 2019 14:19	Insured Phone No Updated	[None] -> [+6582332814]	[A] SHIAU CHAN
14	05 Dec 2019 14:19	Clim Dtl Modified	JPJ Reg. Date: -> 2018/01/16.	[A] SHIAU CHAN
15	05 Dec 2019 14:19	Clim Details Notified		[A] SHIAU CHAN
16	05 Dec 2019 17:42	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2019/12/16	[A] SHIAU CHAN
17	05 Dec 2019 17:44	Adj Mandate Request	Cur.Req:40052.00:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. WE HAVE NOT AUTHORISE REPAIR.	[A] SHIAU CHAN
18	06 Dec 2019 09:07	Clim Registration Modified	Init.Est.->5,000 - 6,000. 2F Remarks: -> Not Applicable. GST: -> 7.00.	[I] Chan, Yoke Shi
19	06 Dec 2019 09:07	Clim Registration Modified	Acct Time:07:40:00->07:00:00. Pol No:1800003116-01->1800003116.	[I] Chan, Yoke Shi
20	06 Dec 2019 14:37	Clim Registration Modified	Excess: -> 800.00.	[I] Chan, Yoke Shi
21	06 Dec 2019 14:37	Label Added	(20226):Coverage Confirmed.	[A] Merimen Administrator
22	06 Dec 2019 14:51	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/12/16	[I] Fong, Andy-SY
23	06 Dec 2019 14:51	Adj Mandate Set	Approved:40052.00.	[I] Fong, Andy-SY

Date From



Date To



Audit Type None

Go

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Bill Type	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
2368436	05 Dec 2019 14:19:34	OD/TP Case (Adjuster)	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SGU5056M		11.77

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #08-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Mohd Rizal, Nur Mariah Huibrechts

Date: 05 Dec 2019

Preliminary Advice

Vehicle No	: SGU5056M	Accident Date	: 04/12/2019
Make	: AUDI Q2	Policy No.	: 1800003116-01
Assignment Date	: 05/12/2019	Excess	: S\$0.00
Date of Inspection	: 05/12/2019	Est. Duration of Repair	: 14.00
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (UBI) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	62,216.00
Revised Amount	:S\$	28,211.00
Check Items (Estimated)	:S\$	11,841.00
Total	:S\$	40,052.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	102,000.00
COE / PARF Rebate	:S\$	55,419.00
Salvage Value	:S\$	
Margin for Repair	:S\$	46,581.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	04/12/2019 13:54
Date Of Accident	04/12/2019 07:40
Exact Location Of Accident	OUTSIDE BUKIT TIMAH POLICE STATION
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGU5056M
Insured/Policyholder	
Name Of Registered Owner	TREVOR VAIL
NRIC No	S2745996Z
Email Address	TREVORVAIL@MAC.COM
Mobile Phone No	(LOCAL) +65-82332814
Alternative Phone No	OFFICE-82332814

Vehicle Particulars

Manufacturer	AUDI
Model	Q2 1.0 TFSI S TRONIC
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	1800003116-01
Cover Note Number	

Driver

Name of Driver	TARNYA LISA VAIL
NRIC No	S2754544J
Date Of Birth	04/11/1967
Occupation	INDOOR
Date Of Driving Pass	20/07/2007
Driving Experience	12 YEARS AND 4 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-82332785
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	23 CLAYMORE ROAD #22-03
Postcode	229546
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

COMING FROM SLIP ROAD ON TO BUKIT TIMAH, OUTSIDE BUKIT TIMAH POLICE STATION. TRUCK IN FRONT WAS STATIONERY ALTHOUGH ROAD IN FRONT WAS CLEAR. I MOVED FORWARD AND HIT THE BACK OF THE TRUCK

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	YP8132U
Vehicle Make/Model/Colour	SILVER POWERLIFT TRUCK (ELEFANTCAR)
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	MURUGAIYAN BALASUBRAMANIAN
NRIC/Passport Number	034884560
Contact Number	90862467
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Singapore NRIC
Owner ID:	9962

Vehicle Details

Vehicle No.:	SCU5056M
Vehicle to be Exported:	No
Intended Deregistration Date:	05 Dec 2019
Vehicle Make:	AUDI
Vehicle Model:	Q2 1.0 TFSI S TRONIC
Primary Colour:	Grey
Manufacturing Year:	2017
Engine No.:	CHZ598948
Chassis No.:	WAUZZZGA2JA041526
Maximum Power Output:	85.0 kW (113 bhp)
Open Market Value:	\$26,517.00
Original Registration Date:	16 Jan 2018
First Registration Date:	16 Jan 2018
Transfer Count:	0
Actual ARF Paid:	\$29,124.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	15 Jan 2028
PARF Rebate Amount:	\$21,843.00

Intended COE Rebate Details

COE Expiry Date:	15 Jan 2028
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period (Years):	10
QP Paid:	\$41,400.00
COE Rebate Amount:	\$33,576.00
Total Rebate Amount:	\$55,419.00

The information contained herein is correct as at 05 Dec 2019

OK

Please do not use your browser's Back or Forward buttons as this may result in information loss

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	996Z
Vehicle Details	
Vehicle No.:	SGU5056M
Vehicle to be Exported:	No
Intended Deregistration Date:	05 Dec 2019
Vehicle Make:	AUDI
Vehicle Model:	Q2 1.0 TFSI S TRONIC
Primary Colour:	Grey
Manufacturing Year:	2017
Engine No.:	CHZ598948
Chassis No.:	WAUZZZGA2JA041528
Maximum Power Output:	85.0 kW (113 bhp)
Open Market Value:	\$26,517.00
Original Registration Date:	16 Jan 2018
First Registration Date:	16 Jan 2018
Transfer Count:	0
Actual ARF Paid:	\$29,124.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	15 Jan 2028
PARF Rebate Amount:	\$21,843.00
Intended COE Rebate Details	
COE Expiry Date:	15 Jan 2028
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$41,400.00
COE Rebate Amount:	\$33,576.00
Total Rebate Amount:	\$55,419.00

The information contained herein is correct as at 05 Dec 2019

OK

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 21720

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/1431/2019/NS
Date : 4-Dec-19

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Trevor Vail
Address : 23 Claymore Road
#22-03
Singapore 229546
Telephone : (HP) +65 82332814
Type of Claim : Own Damage Claims
Policy No. : 1800003116-01
Vehicle No : **SGU 5056 M**
Model Code : Audi Q2 1.0 TFSI S Tronic
Model / Year : 16/1/2018
Engine No : CHZ 598948
Chassis No : WAUZZZGA2JA041528
Mileage : 10507
Date In : 4-Dec-19
Estimated By : Johnny Boo / Allan Wu
Accident Date : 4-Dec-19
Place of Accident : Outside Bukit Timah Police Station

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SGU 5056 M

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
1	To tow and recover vehicle from scene of accident.	S/N \$ 280.00	X
2	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N \$ 360.00	//
3	To remove and renew aircond condenser, radiator and additional radiatore. Check electrical fans and control unit. Pressurise cooling sytem. To carry out vacuum and regas.	S/N \$ 1,400.00	//
4	To renew front windscreen.	S/N \$ 480.00	//
5	To install front windscreen solar film.	S/N \$ 400.00	//
SUB TOTAL LABOUR CHARGES		: \$ 2,920.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SGU 5056 M

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
6	To dislodge and reinstall lhs A-pillar and rhs front door harness.	S/N \$ 1,200.00	X
7	To remove and reinstall lhs front assy, ABCD pillar trims, carpets, electronic components and fuse trays.	S/N \$ 1,800.00	X
8	To dismantle and renew front bumper, bonnet, both front fenders, and both headlights. To cut out and reweld lhs upper A-pillar. To renew front lock carrier and align to position. Re-organise crash management components. Reinstall all parts removed.	\$ 9,600.00	4750 4000
9	To respray front bumper, bonnet, hinges, both front fenders and both front upper A-pillars.	\$ 6,300.00	2750
10	To carry out diagnostic check.	S/N \$ 192.00	//
TOTAL LABOUR CHARGES		: \$ 22,012.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SGU 5056 M

S/N	Parts Description	Damaged Parts & Prices		Remarks
		S/Nett		
1	FRONT BUMPER / DP	\$	1,706.00	1324 ✓
2	FRONT BUMPER FIXING PARTS X H NAI	\$	314.00	
3	HEADLIGHT WASHER COVER CAP X NAI	\$	104.00	
4	FRON BUMPER TOWING EYE COVER X NAI	\$	36.00	
5	FRONT BUMPER GRILLE - CENTRE X NAI	\$	179.00	
6	FRONT BUMPER AIR GUIDE GRILLE - LH / RH X NAI	2 \$	308.00	
7	FRONT BUMPER END CAP - LH / RH X NAI	2 \$	62.00	
8	FRONT BUMPER SPOILER X NAI	\$	273.00	
9	FRONT BUMPER CLOSING ELEMENT X NAI	\$	142.00	
10	FRONT WHEEL SPOILER - LH / RH X NN	2 \$	62.00	
11	FRONT BUMPER ADAPTER - LH X NAI	\$	32.00	
12	FRONT BUMPER ADAPTER - RH X NAI	\$	38.00	
13	RADIATOR GRILLE / BR	\$	1,301.00	1040.80 ✓
14	RADIATOR GRILLE STRIKER PLATE / BR	\$	114.00	91.70 ✓
15	FRONT BUMPER CARRIER / BT	\$	625.00	499.60 ✓
16	FRONT BUMPER GUIDE SECTION - LH / RH ? X NAI	2 \$	64.00	X
17	FRONT BUMPER COVER / CUT	\$	91.00	72.50 ✓
18	FRONT BUMPER FOAM FILLER PIECE ? / CRA	\$	71.00	56.09 ✓
19	FRONT BUMPER DISTANCE PIECE ? X NAI	\$	12.00	X
20	CAUTION SIGN STICKER / AK	NEC \$	13.00	9.76
SUB TOTAL SPARE PARTS		:	\$	<u>5,547.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SGU 5056 M

S/N	Parts Description			Damaged Parts & Prices	
				S/Nett	Remarks
21	AIRCON STICKER / MC	NEC	\$	7.00	5.12 /
22	HORN - LH LOW TONE X NM		\$	262.00	
23	SIGNAL HORN - RH HIGH TONE X NM		\$	180.00	
24	SPRING SHACKLE - LH / RH X NM	2	\$	58.00	
25	FRONT FENDER - LH / RH / DD	2	\$	2,094.00	1675.70 /
26	FRONT FENDER ATTACHMENT PARTS MC X NM		\$	36.00	
27	FRONT FENDER BRACKET - LH / RH / MC	2	\$	28.00	22.08 /
28	FRONT FENDER BRACKET - LH / RH / MC	2	\$	86.00	68.16 /
29	FRONT FENDER BRACKET - LH / RH / MC	2	\$	28.00	22.08 /
30	FRONT FENDER BRACE - LH / RH ? X NM	2	\$	58.00	X
31	FRONT FENDER CLOSING ELEMENT - LH / RH ? X NM		\$	60.00	X
32	FRONT FENDER INSULATION - LH / RH ? X NM	2	\$	138.00	X
33	FRONT FENDER INSULATION BRACKET - LH / RH ? X NM		\$	42.00	X
34	FRONT WHEEL HOUSING LINER - LH / RH X NM	2	\$	366.00	
35	WHEEL HOUSING LINER ATTACHMENT PARTS X NM		\$	52.00	
36	BONNET / DD		\$	2,549.00	2039.70 /
37	BONNET ATTACHMENT PARTS / MC		\$	149.00	119.70 /
38	BONNET LID HINGE - LH / RH / DT	2	\$	112.00	89.48 /
39	BONNET GAS FILLED STRUT X NM		\$	93.00	
40	GAS FILLED STRUT BRACKET - RH X NM		\$	31.00	
SUB TOTAL SPARE PARTS			:	\$ 6,429.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SGU 5056 M

S/N	Parts Description	Damaged Parts & Prices		Remarks
		S/Nett		
41	BONNET STRIKER - LH / RH / <i>BT</i>	2	\$ 200.00	159.04 /
42	BONNET SOUND ABSORBER / <i>MC</i>		\$ 201.00	160.80 /
43	BONNET IMPACT PROTECTION - CENTRE / <i>MC</i>		\$ 27.00	21.20 /
44	BONNET IMPACT PROTECTION - LH / <i>MC</i>		\$ 28.00	22 /
45	BONNET IMPACT PROTECTION - RH / <i>MC</i>		\$ 27.00	21.20 /
46	BONNET COVER - LH / RH X <i>NM</i>	2	\$ 74.00	
47	BONNET COVER - LH / RH X <i>NM</i>	2	\$ 28.00	
48	PLENUM CHAMBER COVER - FRONT / <i>CUT</i>		\$ 144.00	114.80 /
49	WATER BOX X <i>NM</i>		\$ 124.00	
50	BONNET LID LOCK ? / <i>BT</i>	2	\$ 367.00	293.60 ✓
51	BONNET BOWDEN CABLE - CENTRE / <i>TN</i>		\$ 53.00	41.68 /
52	BONNET LID LOCK CABLE / <i>TN</i>		\$ 67.00	53.36 /
53	BONNET RELEASE ELEMENT ? / <i>CRA</i>		\$ 53.00	41.68 ✓
54	BONNET RELEASE LEVER ? / <i>Joined</i>		\$ 12.00	9.60 ✓
55	BONNET BOWDEN CABLE - LH / RH X <i>TN</i>	2	\$ 106.00	83.36 /
56	HEADLIGHT MOUNTING - LH / RH / <i>DR</i>	2	\$ 214.00	171.20 /
57	LED HEADLIGHT - LH / RH / <i>DR / CUT</i>	2	\$ 8,982.00	7185.60 ✓
58	MAIN LIGHT ELECTRONICS POWER MODULE ? / <i>SM</i>	2	\$ 1,385.00	554 ✓
59	LIGHT CONTROL UNIT ? / <i>SM</i>	2	\$ 1,015.00	406 ✓
60	LED WITH HEAT SINK - LH / RH ? / <i>SM</i>	2	\$ 1,332.00	532.40 ✓
SUB TOTAL SPARE PARTS			\$ 14,439.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SGU 5056 M

S/N	Parts Description			Damaged Parts & Prices		Remarks
				S/Nett		
61	HEADLIGHT HOSE - LH / RH ? X NM	2	\$	52.00	X	
62	LIFT CYLINDER - LH / RH ? X NM	2	\$	256.00	X	
63	HEADLIGHT HOSE - LH / RH ? X NM	2	\$	170.00	X	
64	HEADLIGHT DISTRIBUTOR ? X NM		\$	27.00	X	
65	HEADLIGHT PUMP ? X NM		\$	147.00	X	
66	HEADLIGHT WASH WATER RESERVOIR / CRH		\$	156.00		124.50 /
67	FRONT WHEEL COVER - LH / RH / RC	2	\$	588.00		469.60 /
68	LOCK CARRIER / BR		\$	907.00		725.60 /
69	AIRCON CONDENSER ? X NM		\$	503.00	X	
70	REFRIGERANT LINE ? X NM		\$	461.00	X	
71	REFRIGERANT LINE ? X NM		\$	601.00	X	
72	REFRIGERANT LINE ? X NM		\$	461.00	X	
73	REFRIGERANT LINE BRACKET ? X NM		\$	25.00	X	
74	DUAL CLIP ? X NM		\$	28.00	X	
75	RADIATOR ? X NM		\$	878.00	X	
76	ADDITIONAL RADIATOR ? X NM		\$	837.00	X	
77	READY MIX COOLANT ? X NM	4	\$	84.00	X	
78	RADIATOR BRACKET - UPPER / BR	2	\$	77.00		61.78 /
79	RADIATOR BUSH - LOWER / RC	2	\$	18.00		14.74 /
80	RADIATOR SEALING STRIP - RH / (H) ? / CRA	1	\$	32.00		12.08 /
SUB TOTAL SPARE PARTS			:	\$	6,308.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SGU 5056 M

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
81	RADIATOR FAN ? X NM	\$ 1,483.00	X
82	RADIATOR AIR GUIDE - LH/ RH / CRV 21	\$ 54.00	42.72 /
83	RADIATOR AIR GUIDE - UPPER CENTRE ? / CRA	\$ 19.00	15.20 /
84	RADIATOR AIR INLET ? / CRA	\$ 53.00	41.84 /
85	RADIATOR AIR INLET COVER ? X NM	\$ 27.00	X
86	RADIATOR AIR FILTER ? X NM	\$ 62.00	X
87	RADIATOR AIR DUCT ? X NM	\$ 19.00	X
88	RADIATOR WATER DRAINAGE HOSE ? X NM	\$ 31.00	X
89	RADIATOR INTAKE MANIFOLD ? X NM	\$ 129.00	X
90	RADIATOR AIR FILTER HOUSING ? X NM	\$ 259.00	X
91	RADIATOR INTAKE MANIFOLD ? X NM	\$ 588.00	X
92	FRONT WINDSCREEN / DR	\$ 913.00	730.40 /
93	RAIN SENSOR X NM	\$ 728.00	
94	PRIMER ~ ~ X NM	\$ 19.00	X
95	SECTIONAL PART A/B PILLAR - LH X R	\$ 1,703.00	
96	EXTERNAL TEMPERATURE SENSOR X NM	\$ 54.00	
97	FRONT NO PLATE / BT	S/N \$ 40.00	/
98	ACRYLIC SEALANT / MC	S/N \$ 180.00	/
99	CAVITY WAX / MC	S/N \$ 140.00	/
100	STONE CHIP / MC	S/N \$ 180.00	/
101	FRONT WINDSCREEN SEALANT / MC	S/N \$ 200.00	/
102	SUNDRIES / MC	\$ 600.00	64.96 /

TOTAL SPARE PARTS : \$ 40,204.00
TOTAL LABOUR CHARGES : \$ 22,012.00
GRAND TOTAL : \$ 62,216.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
 Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

9
9/12/19

Telefax

Name

:

Steve (LKK)

Surveyed Date

:

Authorised Date

:

Excess Cost

:

Liability

:

Remarks

:

5/12/19, 2.00 pm

OD - Not Authorise (Repair)

Excess - ?

14 days

P/P

Ry Bel SM

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

X
for record purpose.

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 - Fax: 6256 4315

Estimate No. PA/OD/1431/2019/NS
Date 13-Dec-19
Service Advisor Glory Tan
Pages 1 of 1
Regn No SGU 5056 M
Model No Audi Q2 1.0 TFSI S Tronic

Quantity	Description	Unit Price	Amount
<u>Parts</u>			
1	Bracket for connector housing <i>na</i>	\$ 11.00	
2	Radiator seal outer RHS <i>X</i>	\$ 6.00	

TOTAL \$ 17.00

For Premium Automobiles Pte Ltd

Authorised Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 21720

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/1431/2019/NS
Date : 4-Dec-19

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Trevor Vail
Address : 23 Claymore Road
#22-03
Singapore 229546
Telephone : (HP) +65 82332814
Type of Claim : Own Damage Claims
Policy No. : 1800003116-01
Vehicle No : **SGU 5056 M**
Model Code : Audi Q2 1.0 TFSI S Tronic
Model / Year : 16/1/2018
Engine No : CHZ 598948
Chassis No : WAUZZZGA2JA041528
Mileage : 10507
Date In : 4-Dec-19
Estimated By : Johnny Boo / Allan Wu
Accident Date : 4-Dec-19
Place of Accident : Outside Bukit Timah Police Station

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SGU 5056 M

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
1	To tow and recover vehicle from scene of accident.	S/N \$ 280.00 ✓	
2	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N \$ 360.00 ✓	
3	To remove and renew aircond condenser, radiator and additional radiatore. Check electrical fans and control unit. Pressurise cooling sytem. To carry out vacuum and regas.	S/N \$ 1,400.00 ✓	
4	To renew front windscreen.	S/N \$ 480.00 ✓	
5	To install front windscreen solar film.	S/N \$ 400.00 ✓	
SUB TOTAL LABOUR CHARGES		: \$ 2,920.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SGU 5056 M

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendations
6	To dislodge and reinstall lhs A-pillar and rhs front door harness.	S/N \$	1,200.00	X
7	To remove and reinstall lhs front assy, ABCD pillar trims, carpets, electronic components and fuse trays.	S/N \$	1,800.00	X
8	To dismantle and renew front bumper, bonnet, both front fenders, and both headlights. To cut out and reweld lhs upper A-pillar. To renew front lock carrier and align to position. Re-organise crash management components. Reinstall all parts removed.	\$	9,600.00	3750
9	To respray front bumper, bonnet, hinges, both front fenders and both front upper A-pillars.	\$	6,300.00	2750
10	To carry out diagnostic check.	S/N \$	192.00	/
TOTAL LABOUR CHARGES		:	\$ 22,012.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SGU 5056 M

S/N	Parts Description	Damaged Parts & Prices		Remarks
		S/Nett		
1	FRONT BUMPER / DP	\$	1,706.00	
2	FRONT BUMPER FIXING PARTS / MC	\$	314.00	
3	HEADLIGHT WASHER COVER CAP X	\$	104.00	
4	FRON BUMPER TOWING EYE COVER X	\$	36.00	
5	FRONT BUMPER GRILLE - CENTRE X	\$	179.00	
6	FRONT BUMPER AIR GUIDE GRILLE - LH / RH X	2 \$	308.00	
7	FRONT BUMPER END CAP - LH / RH X	2 \$	62.00	
8	FRONT BUMPER SPOILER X	\$	273.00	
9	FRONT BUMPER CLOSING ELEMENT X	\$	142.00	
10	FRONT WHEEL SPOILER - LH / RH X	2 \$	62.00	
11	FRONT BUMPER ADAPTER - LH X	\$	32.00	
12	FRONT BUMPER ADAPTER - RH X	\$	38.00	
13	RADIATOR GRILLE / BR	\$	1,301.00	
14	RADIATOR GRILLE STRIKER PLATE / BR	\$	114.00	
15	FRONT BUMPER CARRIER / BT	\$	625.00	
16	FRONT BUMPER GUIDE SECTION - LH / RH ?	2 \$	64.00	
17	FRONT BUMPER COVER / CHT	\$	91.00	
18	FRONT BUMPER FOAM FILLER PIECE ? or	\$	71.00	
19	FRONT BUMPER DISTANCE PIECE ?	\$	12.00	
20	CAUTION SIGN STICKER / MC	NEC \$	13.00	

SUB TOTAL SPARE PARTS

: \$ 5,547.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SGU 5056 M

S/N	Parts Description	Damaged Parts & Prices		Remarks
		S/Nett		
21	AIRCON STICKER / <i>MC</i>	NEC	\$ 7.00	
22	HORN - LH LOW TONE X	\$	262.00	
23	SIGNAL HORN - RH HIGH TONE X	\$	180.00	
24	SPRING SHACKLE - LH / RH X	2 \$	58.00	
25	FRONT FENDER - LH / RH / <i>DD</i>	2 \$	2,094.00	
26	FRONT FENDER ATTACHMENT PARTS / <i>MC</i>	\$	36.00	
27	FRONT FENDER BRACKET - LH / RH / <i>MC</i>	2 \$	28.00	
28	FRONT FENDER BRACKET - LH / RH / <i>MC</i>	2 \$	86.00	
29	FRONT FENDER BRACKET - LH / RH / <i>MC</i>	2 \$	28.00	
30	FRONT FENDER BRACE - LH / RH ?	2 \$	58.00	
31	FRONT FENDER CLOSING ELEMENT - LH / RH ?	2 \$	60.00	
32	FRONT FENDER INSULATION - LH / RH ?	2 \$	138.00	
33	FRONT FENDER INSULATION BRACKET - LH / RH ?	2 \$	42.00	
34	FRONT WHEEL HOUSING LINER - LH / RH X	2 \$	366.00	
35	WHEEL HOUSING LINER ATTACHMENT PARTS X	\$	52.00	
36	BONNET / <i>DD</i>	\$	2,549.00	
37	BONNET ATTACHMENT PARTS / <i>MC</i>	\$	149.00	
38	BONNET LID HINGE - LH / RH / <i>DT</i>	2 \$	112.00	
39	BONNET GAS FILLED STRUT X	\$	93.00	
40	GAS FILLED STRUT BRACKET - RH X	\$	31.00	
SUB TOTAL SPARE PARTS		:	\$ 6,429.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SGU 5056 M

S/N	Parts Description	Damaged Parts & Prices		Remarks
		S/Nett		
41	BONNET STRIKER - LH / RH ✓ BT	2	\$	200.00
42	BONNET SOUND ABSORBER ✓ MC		\$	201.00
43	BONNET IMPACT PROTECTION - CENTRE ✓ MC		\$	27.00
44	BONNET IMPACT PROTECTION - LH ✓ MC		\$	28.00
45	BONNET IMPACT PROTECTION - RH ✓ MC		\$	27.00
46	BONNET COVER - LH / RH X	2	\$	74.00
47	BONNET COVER - LH / RH X	2	\$	28.00
48	PLENUM CHAMBER COVER - FRONT ✓ CH		\$	144.00
49	WATER BOX X		\$	124.00
50	BONNET LID LOCK ? BT ✓	2	\$	367.00
51	BONNET BOWDEN CABLE - CENTRE ✓ TN		\$	53.00
52	BONNET LID LOCK CABLE ✓ TN		\$	67.00
53	BONNET RELEASE ELEMENT ? CR ✓		\$	53.00
54	BONNET RELEASE LEVER ? Jm ✓		\$	12.00
55	BONNET BOWDEN CABLE - LH / RH ✓ TN	2	\$	106.00
56	HEADLIGHT MOUNTING - LH / RH ✓ CR ✓ DR	1/2	\$	214.00
57	LED HEADLIGHT - LH / RH ✓ CR ✓ DR	1/2	\$	8,982.00
58	MAIN LIGHT ELECTRONICS POWER MODULE ?	2	\$	1,385.00
59	LIGHT CONTROL UNIT ?	2	\$	1,015.00
60	LED WITH HEAT SINK - LH / RH ?	2	\$	1,332.00

SUB TOTAL SPARE PARTS

: \$ 14,439.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SGU 5056 M

S/N	Parts Description	Damaged Parts & Prices		Remarks
		S/Nett		
61	HEADLIGHT HOSE - LH / RH ?	2	\$	52.00
62	LIFT CYLINDER - LH / RH ?	2	\$	256.00
63	HEADLIGHT HOSE - LH / RH ?		\$	170.00
64	HEADLIGHT DISTRIBUTOR ?		\$	27.00
65	HEADLIGHT PUMP ?		\$	147.00
66	HEADLIGHT WASH WATER RESERVOIR ✓ CRH		\$	156.00
67	FRONT WHEEL COVER - LH / RH ✓ RLC	2	\$	588.00
68	LOCK CARRIER ✓ BR		\$	907.00
69	AIRCON CONDENSER ?		\$	503.00
70	REFRIGERANT LINE ?		\$	461.00
71	REFRIGERANT LINE ?		\$	601.00
72	REFRIGERANT LINE ?		\$	461.00
73	REFRIGERANT LINE BRACKET ?		\$	25.00
74	DUAL CLIP ?		\$	28.00
75	RADIATOR ?		\$	878.00
76	ADDITIONAL RADIATOR ?		\$	837.00
77	READY MIX COOLANT ?	4	\$	84.00
78	RADIATOR BRACKET - UPPER ✓ BR	2	\$	77.00
79	RADIATOR BUSH - LOWER ✓ RLC	2	\$	18.00
80	RADIATOR SEALING STRIP - RH ALH ? CRH ✓	2	\$	32.00
SUB TOTAL SPARE PARTS		:	\$	<u>6,308.00</u>