

Khachang



## Prime Auto Claims Service Pte Ltd

GST Reg. No : 201606560M

6 Benoi Place Singapore 629927

Tel: 6861 0908 Fax: 6515 2948

Date: 05.12.2019

China Taiping Insurance (S) Pte Ltd  
2 Anson Road #16-00  
Springleaf Tower  
Singapore 079909

Steve (LKK) with MML 5/12/19, 2.15pm  
L/S

Ry AC spy  
3 days

Attn: Motor Claims Dept

### RE: ESTIMATE COST OF REPAIR TO VEHICLE SHD2306P TOYOTA AXIO HYBRID (2016)

#### To Supply

|     |     |                                |        |    |        |   |
|-----|-----|--------------------------------|--------|----|--------|---|
| 1 ) | 1pc | Rear bumper                    | / DD   | \$ | 700.00 | / |
| 2 ) | 1pc | Rear bumper left side retainer | / RR   | \$ | 60.00  | / |
| 3 ) | 1pc | Rear end panel                 | X R    | \$ | 380.00 | X |
| 4 ) | 1pc | Rear end panel top garnish     | X NM   | \$ | 180.00 | X |
| 5 ) | 1pc | Left tail lamp                 | / RR   | \$ | 450.00 | / |
| 6 ) | 1pc | Left tail lamp lower bracket   | ? X NM | \$ | 90.50  | X |

|                    |    |          |          |
|--------------------|----|----------|----------|
| Sub total Parts    | \$ | 1,860.50 | 1210.00  |
| Less: 25% discount | \$ | 465.12   | - 302.50 |
|                    | \$ | 1,395.38 | 907.50   |

#### To Supply S.Nett Parts

|     |      |                                  |      |    |       |   |
|-----|------|----------------------------------|------|----|-------|---|
| 1 ) | 1set | Rear bumper clips                | / MC | \$ | 30.00 | / |
| 2 ) | 1set | Rear end panel top garnish clips | X NM | \$ | 40.00 | X |

|                        |    |       |       |
|------------------------|----|-------|-------|
| Sub total S.Nett Parts | \$ | 70.00 | 30.00 |
|------------------------|----|-------|-------|

#### L/charges

|     |                                                                                                                                               |    |        |     |
|-----|-----------------------------------------------------------------------------------------------------------------------------------------------|----|--------|-----|
| 1 ) | To cut/welding rear end panel, remove rear bumper & left tail lamp.<br>Replace the above parts. Align & adjust rear bumper & left rear fender | \$ | 400.00 | 300 |
| 2 ) | To putty, respray painting rear bumper & rear end panel. To polish                                                                            | \$ | 500.00 | 400 |

|                       |    |          |         |
|-----------------------|----|----------|---------|
| Sub total L/charges   | \$ | 900.00   | 700.00  |
| Estimated Grand Total | \$ | 2,365.38 | 1637.50 |

less: 20% / 45  
L/S = 1300  
- 307.50  
1310.00