

TRANS EUROKARS PTE LTD

ESTIMATE COST OF REPAIRS

(5) EUROKARS GROUP

AIG ASIA PACIFIC INSURANCE P/L

NAME:

Mr Shivashanker S/O Ragavel

15457

78 SHENTON WAY

ADDRESS :

970 Hougang Street 91

EXCESS:

#07-16 CHARTIS BUILDING

#15-152

30-Nov-19 DATE:

SINGAPORE 079120

Singapore 530970

TEL:

ATTN.:

MOTOR CLAIMS

FAX:

87176166

VEH NO :	SMP7477Z	DATE IN :		CONTACT PERSON :	Ronald 63957875		
CHASSIS NO :	JM6DK2W7AK0416187	MILEAGE :		TYPE OF CLAIM:	THIRD PARTY CLAIM		
MODEL:	CX3IPM	DATE REG.:	29-Aug-19	POLICY NO. :			

NATURE OF WORKS **Parts Description**

			Parts Description	<u>on</u>		
NO			QTY		REVISED	PRICES
1	REAR BUMPER		1	MDHYF-50-22XABB	100/Qe/	\$ 1,040.10
2	STAY, REAR BUN	1PER	2	MD10J-50-271	17X	\$ 52.20
3	GUARD CENTER,	REAR BUMPER	1	MD10J-50-371	11 X	\$ 17.10
4	REAR REINFORCE	EMENT	1	MDB2P-50-260A	MX	\$ 362.8
5	RETAINER CENTE	ER, SENSOR	2	MGHP9-67-UC5	MX	\$ 22.6
6	SENSOR CENTER	, ULTRASONIC	2	MGMC8-67-UC1	?	\$ 401.0
7	PAD PROTECTOR	R, SENSOR	2	MG001-67-061	nec-	\$ 15.6
8	FASTENER, REAR	BUMPER	10	MB45A-56-146A	ms	\$ 30.0
9	CLIP, REAR BUM	PER	6	MBGV4-56-145	m/	\$ 17.4
10	GROMMET, REA	R BUMPER	6	MBHN1-50-0Z1A	nu/	\$ 16.2
11	PIN LOCATOR, RI	EAR BUMPER	1	MD10J-50-1K5	nu-	\$ 3.9
				TOTAL PARTS		\$ 1,978.9
				LESS 10%		\$ 197.8
				TOTAL PARTS COST		\$ 1,781.0
			Labour Descript	ion		
1	MZ-BR-REAR02 TO REPLACE REAR BUMPER AND REAR REINFORCEMENT. REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.			630	\$ 1,260.0	
2	MZ-SP-SREAR2	Z-SP-SREAR2 TO RESPRAY REAR BUMPER AND REAR REINFORCEMENT.			600	\$ 1,200.0
3	MZ-BR-REVSEN	TO TRANSFER REVERSE SENSORS	i.	180	NETT	\$ 315.0
4	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRES	SERVATION.		11 X	\$ 250.0
5	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FO	OR PROPER FUNCTION	DNING.	120	\$ 250.0

6	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.		1.	SV	\$	350.00
7		TO SUPPLY BRILA PREMIUM COATING. (Sole quel.		0	JETT	\$	150.00
8	MZ-BR-SUNDRI	SUNDRIES.	M 20	N	IETT	\$	100.00
		The second second second	TOTAL LABOUR	\$		\$	3,875.00
			TOTAL PARTS	\$	-	\$	1,781.01
			TOTAL	\$		\$	5,656.01
			LESS EXCESS	\$	-	\$	-
			TOTAL AFTER EXCESS	\$			
			GST 7%	\$		\$	-
			GRAND TOTAL	¢		4	

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$400 WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

TRANS EUROKARS PTE LTD

Authorised Signature

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- . To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- . Third party survey is on a "Without Prejudice" basis
- · No illeg il modification(s) is allowed
- Supplementary item(s) must be resurveyed <u>and</u> is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: