

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E
BEDOK NORTH AVE 4,
#01-2008/10/12 SINGAPORE 489977
TEL : 6441 5655 FAX : 6441 5355/6243 8121
R.O.C No : 200104141D GST Reg. No. 20-0104141-D

TO : SXXX4716E

LEE HUI LUN

BLK 5 BEDOK RESERVOIR VIEW

05-04

SINGAPORE 478928

TEL : FAX :

PH : 98548818

ATTN :

Term:

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

ESTIMATE BILL

Number : EB00005352

Date : 04/12/2019

Case No : AD00010831

Vehicle No : SLD2616Y

Chassis : JHMGE67509S205827

Year of Mfr 2008

Policy No

Model : HONDA JAZZ 1.3

Sn	DESCRIPTION	QTY	U PRICE	DISC	AMOUNT
1	TAILGATE <i>✓ bn</i>	1.0	680.50	20	544.40
2	REAR BUMPER <i>✓ cut</i>	1.0	472.30	20	377.84
3	REAR BUMPER RETAINER LH <i>✓ BR</i>	1.0	17.50	20	14.00
4	REAR BUMPER RETAINER RH <i>✓ svc</i>	1.0	17.50	20	14.00
5	TAILGATE WINDSCREEN GLASS MOULDING <i>✓ Nec</i>	1.0	85.10	20	68.08
List Price - Parts Sub Total					1,018.32
6	REVERSE SENSOR <i>✓ svc</i>	1.0	280.00	0	280.00
7	REAR BUMPER SPOILER <i>✓ bn</i>	1.0	680.00	0	680.00
8	WINDSCREEN SEALANT <i>✓ Nec</i>	2.0	24.00	0	48.00
9	END PANEL - REPAIR <i>✓ R</i>	1.0			
Special Nett Price - Parts Sub Total					1,008.00
Parts Total					2,026.32
10	LABOUR TO REMOVE & REFIT NECESSARY PARTS	1.0	600.00	0	600.00
11	SPRAY PAINT ON THE AFFECTED AREAS	1.0	700.00	0	700.00
12	ANTI-RUST COATING	1.0	180.00	0	180.00
13	TO REMOVE & REFIT WINDSCREEN	1.0	180.00	0	180.00
14	TO REMOVE & REFIT REVERSE SENSOR	1.0	150.00	0	150.00
Labour 1 Sub Total					1,810.00
SINGAPORE DOLLARS : FOUR THOUSAND ONE HUNDRED FOUR AND CENTS EIGHTY-SIX ONLY					
Less Excess					0.00
SUBTOTAL					3,836.32
GST 7.00%					268.54
TOTAL					4,104.86

Repair days - 7 days
Lump Sum
After paint photo

Date of accident : 25/11/2019 02:00 PM. Place : KALLANG BAHRU SLIP ROAD TURN INTO LAVENDER STREET

E. & O. E.

Sun Pin (LKK)

HOCK WAH MOTOR WORKSHOP PTE LTD

19/12/2019.

TP without prejudice.

sunpin@lkkauto.com

CUSTOMER SIGNATURE

AUTHORISED SIGNATURE