

MBM WHEELPOWER PTE. LTD.

YOUR REF.:

OUR REF.: SMC4625B

TO: AIG

CC: MOTOR CLAIMS DEPARTMENT

FAX:

DATE: 27/11/2019

FROM: Eryx Tan

FAX: 6452 5333

CONTACT: 8138 7188

MAKE & MODEL: CLA180 AMG LINE AUTO

CHASSIS NO.: WDD1173422N653563

ENGINE NO.: 27091031614001

YEAR MADE: 2019

ACCIDENT DATE: 26 November 2019

ESTIMATE FOR VEHICLE NO.: SMC4625B

NO.	DESCRIPTION	PART NO.	QTY.	LIST PRICE
1	REAR BUMPER	A 117 880 45 01	1	\$ 2,200.00 ✓
2	REAR BUMPER TRIM	A 117 885 00 01	1	\$ 130.00 ✓
3	REAR BUMPER LOWER GARNISH	A 117 885 95 00	1	\$ 450.00 ✓
4	REAR BUMPER SIDE GARNISH LH	A 117 885 00 53	1	\$ 48.00 ✓
5	REAR BUMPER SIDE GARNISH RH	A 117 885 02 53	1	\$ 48.00 ✓
6	REAR BUMPER BOTTOM TRIM	A 117 885 99 00	1	\$ 380.00 ✓
7	REAR BUMPER TOWING COVER	A 117 885 98 00	1	\$ 55.00 ✓
8	REAR BUMPER BAND	A 220 885 00 59	1	\$ 8.00 ?
9	REAR BUMPER RETAINER	A 117 885 09 65	1	\$ 135.00 ✓
10	REAR BUMPER SIDE BRACKET LH	A 117 885 39 00	1	\$ 45.00 ✓
11	REAR BUMPER SIDE BRACKET RH	A 117 885 40 00	1	\$ 45.00 ✓
12	REAR BUMPER SIDE RETAINER LH	A 117 885 00 14	1	\$ 90.00 ✓
13	REAR BUMPER SIDE RETAINER RH	A 117 885 05 14	1	\$ 90.00 ✓
14	REAR BUMPER SIDE MOUNTING RAIL LH	A 117 885 03 21	1	\$ 35.00 ✓
15	REAR BUMPER SIDE MOUNTING RAIL RH	A 117 885 04 21	1	\$ 35.00 ✓
16	REAR BUMPER BASIC CARRIER LH	A 117 885 07 65	1	\$ 45.00 ?
17	REAR BUMPER BASIC CARRIER RH	A 117 885 08 65	1	\$ 45.00 ?
18	REAR SENSOR DECOUPLING RING	A 000 542 12 51	4	\$ 36.00 ✓
19	REAR DISTANT SENSOR	A 000 905 55 04	✓ 2	\$ 1,200.00 ✓
20	REAR BUMPER MOUNTING PLATE	A 000 885 04 11	1	\$ 10.00 ✓
21	REAR BUMPER WIRING HARNESS	A 117 540 26 01	1	\$ 220.00 ?
22	REAR BUMPER EXPANSION RIVET	A 124 990 04 92	12	\$ 84.00 ✓
23	REAR SIDE WALL DAMPING LH	A 117 682 03 30	1	\$ 45.00 ?
24	REAR SIDE WALL DAMPING RH	A 117 682 04 30	1	\$ 45.00 ?
25	REAR BUMPER RIVET	A 003 990 94 97	30	\$ 180.00 ✓
26	REAR FENDER LH	A 117 630 01 21	1	\$ 3,100.00 ✓
27	REAR FENDER RH	A 117 630 02 21	1	\$ 3,100.00 ✓

SPECIAL NETT

BODY SEALANT	1	\$	80.00	✓
WINDSCREEN SEALANT	1	\$	<i>Mr 405n</i> 150.00	
REAR NUMBER PLATE WITH HOLDER	1	\$	<i>nd 455n</i> 80.00	
REVERSE SENSOR (1 SET)	1	\$	<i>Repair</i> 300.00	X

LABOUR

TO REMOVE, REFIT & REPAIR AFFECTED DAMAGED PARTS, INCLUDING TO KNOCK-OUT, WELD & STRAIGHTEN ON THE AFFECTED PARTS	\$	1,600.00
TO CHECK & RECONNECT ALL NECESSARY WIRING	\$	120.00
TO APPLY ANTI RUST COATING	\$	250.00
TO REMOVE & REFIT REAR WINDSCREEN	\$	150.00
TO CONDUCT CHASSIS ALIGNMENT	\$	120.00
TO REMOVE & INSTALL REVERSE SENSOR	\$	80.00
TO REMOVE, REFIT & UPHOLSTERY TO FACILITATE REPAIRS	\$	150.00
TO MOUNT UP TO CAR-O-LINER TO STRAIGHTEN REAR MAIN CHASSIS	\$	600.00
TO SPRAY PAINT ON THE AFFECTED AREAS	\$	1,600.00
TOTAL:	\$	35,197.80
7% GST:	\$	2,463.85
GRAND TOTAL:	\$	37,661.65

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: