

NGS MOTORSPORT PTE LTD

Blk 10 Ang Mo Kio Industrial Park 2A #02-01 AMK AutoPoint Singapore 568047

Tel :9695 5547 Fax: 6481 5727 e-mail : ngsmotorsportpteltd@gmail.com

Reg No: 201812604N

05/12/2019

AXA Ins Singapore Pte Ltd

Attn: Motor Claims Dept

Dear Sir,

RE: ACCIDENT ON 28/11/2019 @14:10HRS
INVOLVING VEH NO.: SJU7931M & SGS5470K
CLAIMS AGAINST SGS5470K
CLAIM REF: S9M028LGMC/LK

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

We submit herewith our direct claim estimate quotation as follow:-

Replacement parts: Ty Vios

1	Rear Bumper	Repair	\$	385.32
1	Rear Bumper Retainer	X NN	\$	59.84
1	Rear Fender RH	X Repair	\$	935.38
1	Rear Rim RH- Repair	X Repair	\$	200.00 100
1	Rear Door RH- Repair	X	\$	789.62
1	Rear Door Protector RH	X MC	\$	83.14 50 (SAV)

Less 25% \$ 2,453.30
\$ 613.33

6	Clips, Fender Lining @\$4.00	X S.Nett	\$	24.00
1	Rear Tyre RH	X S.Nett	\$	150.00

To remove all damaged parts with all necessary component/attachment
straighten chassis member, cut & weld panel, repair/reshape dented body panel,
replace damaged parts, refit into position \$ 800.00 400

Spray Painting \$ 800.00 600

Check wiring/proper function on lights and etc. \$ 50.00
\$ 3,663.97

Any other parts which necessitate repair or renewal will incur additional charged.

Please contact our Ms Evelyn @HP96955547 to arrange for survey. Thank you 1150

Yours faithfully.

NGS MOTORSPORT PTE LTD
EVELYN NG

3 Days - 05/12/19
P/P After repair photos
Gmo Qiap - 82880282
Gmo Qiang @ lkkauto.com