

P
A09

VEHICLE NO SLE 2837X HONDA VEZEL

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(\$\$)	SURVEYOR'S ADJUSTMENT
	PARTS (LIST ITEMS)			
1	LHS Front Fender	762	2 980.00	X
1	LHS Front Fender wheel arch garnish		garnish 283.00	X
1	LHS Front Fender Inner splash Shield		17 267.00	X
1	Front Bumper		Deep cut 1428.00	X
1	Front Bumper fog lamp cover LHS		scr 244.00	X
1	Front Bumper fog lamp LHS		17 428.00	X
1	Front Bumper lower skirt		garnish 780.00	X
2	Front Bumper side retainers RHS & LHS		17 142.00	X
1	LHS Headlamp		CNE 1280.00	X
1	LHS Headlamp lower bracket		17 248.00	X
			6080.00	
		less 20%	1216.00	20%
			4864.00	
	SPECIAL NETT ITEMS			
1SET	LHS Front fender inner shield clips		17 50.00	X
1SET	Front bumper clips		scr 60.00	50
1set	Front fender wheel arch LH clips		17 60.00	X
1	LHS Front sports rim		17 980.00	X
	TOTAL PARTS		6014.00	

not Allowed
2/s 2100?
3 day
Wheel Alignment
5/12/19

P-2806.00
502
P-1403.00
S.W-50.00
L-670.00
2123.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

VEHICLE NO SLE 2837X HONDA VEZEL

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (\$)	SURVEYOR'S ADJUSTMENT
	LABOUR		
1	To remove the affected parts & fittings to commence repairs; replace damaged parts and components	1000.00 —	250
2	To supply paint materials, expandable items & putty, respray paint on parts replaced (PEARL WHITE)	600.00 —	400
3	To check wiring and focus headlamp beam	150.00 —	20
4	To carry out anti rust treatment on affected areas	120.00 —	11X
5	To conduct full computerised wheel alignment test	120.00 —	11X
	Labour Total :	1990.00	
	TOTAL (PARTS & LABOUR):	8004.00	

NOTE: The parts listed in this preliminary estimate will be checked for damage after the vehicle is disassembled (dismantle). Additional damaged parts (if any) will be submitted as supplementary parts