

# AUBURN AUTO PTE LTD

176 Sin Ming Drive #04-18 Sin Ming Autocare, Singapore 575721

Tel : +65 9787 5558

Email: auburnauto.claim@gmail.com

Vehicle No: SFM2001U

Model: Toyota Wish

| QTY | Description                                | Repairer's Estimate |
|-----|--------------------------------------------|---------------------|
|     | <b>Spare Parts - List Items</b>            |                     |
| 1   | Front bumper side grille (LH) / CUT        | \$ 180.00 /         |
| 1   | Front bonnet lock X NAI                    | \$ 380.00 X         |
| 1   | Front bonnet inner rubber X NAI            | \$ 68.20 X          |
| 1   | Front bonnet outer rubber X NAI            | \$ 86.20 X          |
| 1   | Front bumper inner sponge X NAI            | \$ 135.90 X         |
| 1   | Front bumper side retainers / BR (LH & RH) | \$ 145.20 /         |
| 1   | Front headlamp lower bracket X NAI         | \$ 186.00 X         |
| 1   | Front grille chrome moulding X NAI         | \$ 285.90 X         |
| 1   | Front grille logo X NAI                    | \$ 188.80 X         |
| 1   | Front grille X NAI                         | \$ 628.60 X         |
| 2   | Front bumper reinforcement X NAI           | \$ 680.60 X         |
| 1   | L/H Mud Flap X NAI                         | \$ 160.00 X         |
| 1   | L/H Headlight / CUT                        | \$ 660.00 /         |
| 1   | Bonnet X R                                 | \$ 950.00 X         |
| 1   | Front bumper / BR                          | \$ 880.00 530 /     |
| 1   | Car Plate and Carplate Holder X NAI        | \$ 190.00 X         |
| 1   | Front support panel X R                    | \$ 1,670.00 X       |

Supp  
 FM Fend LH / 00 \$837.60 /  
 FH LH in fnd / TN \$165.93 /

\$ 7,475.40

2618.73  
 - 25%  
 1964.94

c/f: \$ 9,616.90

| S/N. | Labour Charges                                     |    |            |
|------|----------------------------------------------------|----|------------|
| 1    | To establish mirror motor & reset wiring focussing | \$ | 210.00 30  |
| 2    | To check wiring and reset headlamps focussing.     | \$ | 320.00 X   |
| 3    | To apply tuff kote.                                | \$ | 330.00 30  |
| 4    | Panel beating.                                     | \$ | 800.00 500 |
| 5    | To sand-down, patch-work, re-spray paint.          | \$ | 800.00 600 |
|      |                                                    | \$ | 2,460.00   |

Total Repair Cost: \$ 9,935.40 1160

P- 1964.94  
L- 1160  
3124.94  
L/S- 2499.75  
= 2590  
10,938.93#

Survey: 1st / 2nd / 3rd (delete accordingly)

Surveyor Details:

(Name) Steve (LKK)  
(Contact) 8322 8873  
(Email)  
(Signature)  
(Date/Time) 6/12/19, 3.00pm

5 days  
Wah Apple  
L/S

**LINK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Pay 2 Agree" basis
- No illegal modifications are allowed
- Supplementary items must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: