

AUBURN AUTO PTE LTD

176 Sin Ming Drive #04-18 Sin Ming Autocare, Singapore 575721

Tel : +65 9787 5558

Email: auburnauto.claim@gmail.com

Vehicle No: SFM2001U

Model: Toyota Wish

QTY	Description	Repairer's Estimate	
Spare Parts - List Items			
1	Front bumper side grille (LH) / CUT	\$	180.00
1	Front bonnet lock X	\$	380.00
1	Front bonnet inner rubber X	\$	68.20
1	Front bonnet outer rubber X	\$	86.20
1	Front bumper inner sponge X	\$	135.90
1	Front bumper side retainers / BR	\$	145.20
1	Front headlamp lower bracket X	\$	186.00
1	Front grille chrome moulding X	\$	285.90
1	Front grille logo X	\$	188.80
1	Front grille X	\$	628.60
2	Front bumper reinforcement X	\$	680.60
1	L/H Mud Flap X	\$	160.00
1	L/H Headlight / CUT	\$	660.00
1	Bonnet X R	\$	950.00
1	Front bumper / BR	\$	880.00
1	Car Plate and Carplate Holder X	\$	190.00
1	Front support panel X	\$	1,670.00

Supp
 FM Fend LH / DD
 FY LH Lin Fend / TN

\$ 7,475.40

c/f: \$ 9,616.90

S/N. Labour Charges

1	To establish mirror motor & reset wiring focussing	\$	210.00 30
2	To check wiring and reset headlamps focussing.	\$	320.00 X
3	To apply tuff kote.	\$	330.00 30
4	Panel beating.	\$	800.00 400
5	To sand-down, patch-work, re-spray paint.	\$	800.00 600
		\$	<u>2,460.00</u>

Total Repair Cost: \$ 9,935.40

Survey: 1st / 2nd / 3rd (delete accordingly)

Surveyor Details:

(Name) Steve (LKK)
(Contact) 8322 8873
(Email) _____
(Signature) 
(Date/Time) 6/12/19, 3.00pm

5 days
NAH Nigel
L/S

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: