




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CC4/FCI19021525/Dea3q2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 30-07-2020	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SH 8896L	Veh. Inspected	FBM 5464U	
Policy No.	D-19092580MFSH	Coverage (\$)	0.00	
Claim No.	D19007678MFSH	Excess (\$)	0.00	
Assign From	KAREN TAN	Assign Date	05/12/2019	
2. Vehicle Particulars & Condition				
Make & Model	HONDA CB150R	c.c	149	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	MLHKC2883J5004809	Colour	GREEN/BLACK	
Odometer	-	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	110/70 R17	BRIDGESTONE	2 mm	
L/H Front Tyre			mm	
R/H Rear Tyre	140/70 R17	BRIDGESTONE	2 mm	
L/H Rear Tyre			mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION AND O/S & N/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	30/11/2019	Inspection Date	05/12/2019	
Survey held at	S9 MOTOR TRADING PTE LTD 4001 ANG MO KIO INDUSTRIAL PARK 1 #01-21 ANG MO KIO INDUSTRIAL PARK 1 SINGAPORE 569622			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		