

S9 MOTOR TRADING PTE LTD

4001, Ang Mo Kio Industrial Park 1 #01-21 SINGAPORE 569622

Tel: 6452 4898 Fax: 6452 4868

Email: sg_motor_enterprise@yahoo.com.sg

Date: 6 December 2019

To : LKK

By Fax: 6256-4315

Attn : Bryan Ang

Tel: 97237799

VEHICLE NO : FBM 5464U

CB150R Honda

ACCIDENT DATE: 30 November 2019

Description	Qty	Quotation \$
1 Front RH Signal <i>Cut</i>	1	75.00 ✓
2 Handle Bar <i>1st</i>	1	80.00 ✓
3 Clutch Lever <i>Cut</i>	1	65.00 ✓
4 Handle Bar Extension Bracket <i>1st / broken</i>	1	50.00 ✓
5 Balancer - Bar-end <i>1st</i>	1	35.00 ✓
6 Head Lamp Assy <i>Scratched</i>	1	360.00 ✓
7 Head Lamp Holder <i>Scratched</i>	1	50.00 ✓
8 Front Mudguard <i>broken</i>	1	80.00 ✓
9 Front Rim <i>Dented</i>	1	360.00 ✓
10 Brake Disc <i>Scratched</i>	1	160.00 ✓
11 Fork Tube <i>1st</i>	1 set	1,040.00 ✓
12 Fork Under Bracket <i>Dam</i>	1	160.00 ✓
13 Front Side Cover L/RH <i>Cut / broken</i>	1	70.00 ✓
14 Tank Cover <i>broken</i>	2	90.00 ✓
15 Fuel Tank <i>Dented</i>	1	600.00 ✓
16 Radiator Assy <i>1st</i>	1	350.00 ✓
17 Fan Motor Assy <i>broken</i>	1	150.00 ✓
18 Rear LH Side Panel <i>broken</i>	1	65.00 ✓
19 RH Frame Centre Cover <i>broken / cut</i>	1	65.00 ✓
20 RH Engine Lower Cover <i>broken / cut</i>	1	55.00 ✓
22 Signal light holder <i>broken</i>	1	78.00 ✓

Sub-Total 3,960.00

Less 10% 396.00

Sub-Total 3,564.00

Acknowledged by Repaired
Signature:
Date:

LKK Auto Centre (Pte) Ltd. hereby notifies the Repaired of the following:
• To ensure the safety of the repaired vehicle during the repair process.
• Parts prices are subject to confirmation.
• Third party survey is on a "Without Prejudice" basis.
• No (legal) modification is allowed.
• Supplementary details must be received and is subject to final approval from insurance company.

VEHICLE NO : FBM 5464U

CB150R Honda

Nett Items

- | | |
|--|-------------------------|
| 1 Towing fee <i>N/A</i> | 40.00 X |
| 2 Re-align body alignment | 350.00 80/- |
| 3 Remove & replace necessary parts, align & etc | 280.00 200/- |
| 4 Remove & replace fork assy, brake disc, front rim & re-align & etc | 250.00 80/- |
| 5 Re-check harness wiring | 60.00 30/- |
| 6 To respray & touch up paint work | 250.00 150/- |
| 7 Front number place <i>missing</i> | 15.00 ✓ |

Special Nett Items

- | | |
|--------------------------------|---------------------|
| 1 Meter Assy <i>cut/broken</i> | 520.00 ✓ |
|--------------------------------|---------------------|

Sub-Total 1,665.00


Nett Total 5,229.00

Remove & refit engine to facilitate repair to body alignment — at 200/- NW

NB: This estimate was made from a visual inspection only, any other damage parts or labour require when repair commences, we will advise you and submit supplementary item to you accordingly.

Kindly revert upon completion.

Thank you




S9 MOTOR TRADING PTE LTD

:LG

05/12/2011 @ 1800h

Not Author

2 hour 5 days.



2 KRC Auto



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: