

ASS. REC. BY: Surveyor GQ REF: CS / FCI 1902153A / G190302 Special Instructions: _____

(CWS)

From (Person): Jason Teo chee kiat of FCI Date/Time: 6.12.19 8.25am

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLK 37424 Insured: SHA 4969D

at Workshop m/s Yee Auto Tel: 64575768 / 2625

of 160 Sin Ming Drive #02-17

Policy No: _____ Claim No: D19067669MFSH

Sum Insured: _____ Excess: _____

Make of Vch: _____ D.O.A. 2.12.19

(Client's Record) CA / REV / REP. / REV 24 HRS rev

Date/Time: 6.12.19 9.49am Person Contacted: chan H.O.D. Endorsement: _____

Vehicle IN / OUT

Date/Time Action/Instruction (✓) Estimate

SHA 4969D - NA/INC/REV/WS/1/3 DOA-02/12/2019

SLK 37424 NA/INC/REV/WS/1/3 DOA-02/12/2019

6/12/19 @ 3.59pm revised to Jason Teo by email.

16/1/20 @ 12.28pm confirmed with Ms Phang LS @ 750, 3 day, by email.

called @ 6.543.20, 72%

ASS. REC. BY:

BRL

REF: FCI

ASSIGNMENT

From:

Date:

6.12.2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

SLK 37424

at Workshop n/s

Yu Auto

of

160 Sin ming Drive #02-17

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

3

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

np''

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SLK37424

Yr Recd:

13 Jan 2017

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Vezel

C.C.

1496

Colour:

Blue

A/C:

Insured / Std / NI / NA

Sp. Reading

77494

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

RUH204134

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

225/50 R18

R:

U

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Continental

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

06-12-19

Survey held at

w/s

11:20

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Follow 2500

RECEIVED 10 JAN 2020

Date/Time, File Pass to?

☐

: Prel. Report

14/1, 11:20

☐

: Final Report

Date/Time, File Return to?

3

Days Of Repair:

3

Resurvey No. of Trip:

1

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Wheel end (\$

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

170
50
50
38
308

Rep. Format:

TP

Lump Sum / 1 Day:

2500



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19007669MFSH

Date: 10 December 2019

Our Ref: CS/FC119021534/Gqf3

The Motor Claims Department
MS First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SLK 3742Y

Please be informed that we had conducted the inspection of the abovementioned vehicle on 06/12/2019 at the premises of M/s YEE AUTO, and have the following to report:-

Workshop Estimate Amount	: S\$ 9,043.20
Revised Estimate Amount	: S\$ 3,156.72
"Check" Items Amount	: S\$ -
Market Value	: S\$ -
LTA Reimbursement Value	: S\$ -
Nett Value	: S\$ -

Description of Damage:

The vehicle sustained damages at the front portion.



Yours faithfully

Guo Qiang
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	04-12-2019	Our Ref No. D19007669MFSH
Accident Date	02-12-2019	Claim Type. Third Party
Insured Vehicle	SHA4969D	Third Party Vehicle. SLK3742Y
Survey Location	160 SIN MING DRIVE #02-17 SIN MING AUTOCITY	
Contact Person.	JUNE	
Contact No.	6457 5768/ 0	Fax No. 0
Survey Type	WITHOUT PREJUDICE: CASE FROM SOLICITORS. SURVEY ON WP BASIS.	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	YEE AUTO PTE LTD	Attention. NIL
Cc : TP Solicitor	BONNIE KWOK LLC	TP Solicitor Fax No. NA
Officer Incharge	JASON TEA CHEE KIAT	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Shiau Chan (LKKAUTO)

From: yeeauto pteltd <yeeautopteltd@gmail.com>
Sent: Thursday, 16 January 2020 12:27 PM
To: Shiau Chan (LKKAUTO)
Subject: Re: FINALISE OF TP VEHICLE SLK 3742Y (DOA: 02/12/2019)

Hi Shiau Chan,

We accept amount S\$2500/- (bf GST) and 03 repair days.

Thanks & Regards

Ms Phang

Yee Auto Pte Ltd

160 Sin Ming Drive

#02-17 Sin Ming AutoCity

Singapore 575722

ROC & GST No.: 201719251W

email: yeeautopteltd@gmail.com

Contact No: 6457 2625 Fax: 6252 8459

On Tue, 14 Jan 2020 at 15:50, Shiau Chan (LKKAUTO) <siewsc@lkkauto.com> wrote:

Dear Kai Xin,

As spoken.

WITHOUT PREJUDICE

Offer Lump Sum \$2,500.00 before GST and 3 repair days.

Kindly check and confirm.

Wishing you a Happy and prosperous Lunar New Year

Best Regards,

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Tuesday, 10 December 2019 3:59 PM
To: 'CWS Motor Claims'; assignments; SUR
Cc: 'Jason Tea'
Subject: RE: SURVEY ASSESSMENT - D19007669MFSH/1
Attachments: CSFCI19021534Gqf3.pdf

Dear Jason,

Enclosed herewith preliminary advice of SLK 3742Y.

Best Wishes for Merry Christmas & Happy New Year 2020

Best Regards,

Shiau Chan (Ms) | Case Handler
LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO) <admin-d@lkkauto.com>
Sent: Friday, 6 December 2019 9:51 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: 'Jason Tea' <JasonTea@msfirstcapital.com.sg>
Subject: RE: SURVEY ASSESSMENT - D19007669MFSH/1

Dear Sir/Madam,

Thank you for your assignment.

Best Regards,

Summer Lee | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>
Sent: Friday, 6 December, 2019 8:25 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Jason Tea <JasonTea@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19007669MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	727A
Vehicle No.:	SLK3742Y
Vehicle to be Exported:	No
Intended Deregistration Date:	08 Dec 2019
Vehicle Make:	HONDA
Vehicle Model:	VEZEL 1.5X SENSING CVT ABS D/AIRBAG 2WD
Primary Colour:	Blue
Manufacturing Year:	2016
Engine No.:	L15B4404135
Chassis No.:	RU11204134
Maximum Power Output:	96.0 kW (128 bhp)
Open Market Value:	\$22,375.00
Original Registration Date:	13 Jan 2017
First Registration Date:	13 Jan 2017
Transfer Count:	0
Actual ARF Paid:	\$13,325.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	12 Jan 2027
PARF Rebate Amount:	\$9,993.00
COE Expiry Date:	12 Jan 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$50,101.00
COE Rebate Amount:	\$35,542.00
Total Rebate Amount:	\$45,535.00

The information contained herein is correct as at 08 Dec 2019

OK



YEE AUTO PTE LTD

160 Sin Ming Drive #02-17/#07-12 Sin Ming AutoCity Singapore 575722
 Tel: 6457 5768 Fax: 6252 8459 Mobile: 9687 4031
 Email: yeeautopteitd@gmail.com
 Registration No: 201719251W GST No: 201719251W

M/S: First Capital Insurance Ltd
 36 Robinson Road
 #16-01 City House
 Singapore 068877

ATTN: Motor Claim Department

Your Ref No: -
 Claim Type: Third Party
 Accident Date: 02/12/2019
 TP Veh Reg No: SHA4969D

Estimate No: ES1900139
 Date: 05 Dec 2019
 Policy No:
 Veh Reg No: SLK3742Y
 Make/Model: HONDA VEZEL 1.5X
 SENSING CVT ABS
 D/AIRBAG 2WD
 Chassis No: RU11204134
 Engine No: L15B4404135
 Reg. Date: 13/01/2017

Estimate Repair Cost to Vehicle No :SLK3742Y

Description	U/Price	Quantity	List Price SS	Amount SS
Net Price				
1 FRONT NUMBER PLATE	60.00	1 PC	60.00 X 1	60.00
Spare Parts				
2 FRONT BUMPER / <i>le</i>	1,227.70	1 PC	1,227.70	801.7
3 FRONT BUMPER AIR GRILLE CENTRAL	177.50	1 PC	177.50	
4 FRONT BUMPER BRACKET - LH	64.30	1 PC	64.30	35
5 FRONT BUMPER BRACKET - RH	64.30	1 PC	64.30	
6 FRONT BUMPER CLIPS	60.00	1 SET	60.00	30
7 FRONT BUMPER FOG LAMP - LH	527.40	1 PC	527.40	
8 FRONT BUMPER FOG LAMP BRACKET - LH	99.40	1 PC	99.40	
9 FRONT BUMPER FOG LAMP COVER - LH	198.30	1 PC	198.30	45
10 FRONT BUMPER LOWER SPOILER	681.40	1 PC	681.40	451.6
11 FRONT BUMPER LOWER SPOILER CLIPS	60.00	1 SET	60.00	20
12 FRONT BUMPER NUMBER PLATE INNER GRILLE	285.00	1 PC	285.00	
13 FRONT BUMPER REINFORCEMENT	521.40	1 PC	521.40	421
14 FRONT BUMPER SIDE RETAINER - LH	52.60	1 PC	52.60	
15 FRONT BUMPER SIDE RETAINER - RH	52.60	1 PC	52.60	
16 FRONT FENDER - LH	780.40	1 PC	780.40	
17 FRONT GRILLE OUTER	265.50	1 PC	265.50	
18 FRONT GRILLE CHROME MOULDING	138.50	1 PC	138.50	
19 FRONT GRILLE INNER	205.10	1 PC	205.10	
20 FRONT GRILLE LOGO	95.50	1 PC	95.50	
21 FRONT HEADLAMP - LH	1,450.80	1 PC	1,450.80	
22 FRONT BUMPER CENTRE CHROME MOULDING	195.50	1 PC	195.50	
				3295.1
				20% 2604.08
				7,203.20
Labour				
23 TO DISMANTLE & REPLACE DAMAGED PARTS, PANEL, BEAT WHERE NECESSARY.	850.00	1 JOB	850.00	250
24 TO PUTTY, APPLY PRIMER & SPRAY-PAINT ON THE AFFECTED PORTION.	850.00	1 JOB	850.00	250
25 TO CHECK WIRING FUNCTIONS.	80.00	1 JOB	80.00	30
				1,780.00
				1,780.00

530



YEE AUTO PTE LTD

160 Sin Ming Drive #02-17/#07-12 Sin Ming AutoCity Singapore 575722
Tel: 6457 5768 Fax: 6252 8459 Mobile: 9687 4031
Email: yeeautopteLtd@gmail.com
Registration No: 201719251W GST No: 201719251W

M/S: First Capital Insurance Ltd
36 Robinson Road
#16-01 City House
Singapore 068877

ATTN: Motor Claim Department

Your Ref No: -
Claim Type: Third Party
Accident Date: 02/12/2019
TP Veh Reg No: SHA4969D

Estimate No: ES1900139
Date: 05 Dec 2019
Policy No:
Veh Reg No: SLK3742Y
Make/Model: HONDA VEZEL 1.5X
SENSING CVT ABS
D/AIRBAG 2WD
Chassis No: RU11204134
Engine No: L15B4404135
Reg. Date: 13/01/2017

Estimate Repair Cost to Vehicle No :SLK3742Y

Description	U/Price	Quantity	List Price	Amount
			<u>SS</u>	<u>SS</u>
			Total	SS 9,043.20
			Add GST @ 7%	633.02
			Total Amount Payable	SS 9,676.22

TOTAL: SINGAPORE DOLLAR NINE THOUSAND SIX HUNDRED SEVENTY SIX AND CENTS TWENTY TWO ONLY

For Yee Auto Pte Ltd

AUTHORISED SIGNATURE

3/24/08
20% : 2500

10/12/19
2 Days.
Lumpsum Repair.
After repair photos.
Gua Qip - 82880282
06/12/19.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary part(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19021534/Gqf3n2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 17-01-2020		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 4969D	Veh. Inspected	SLK 3742Y	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19007669MFSH	Excess (\$)	0.00	
Assign From	JASON TEA CHEE KIAT	Assign Date	06/12/2019	
2. Vehicle Particulars & Condition				
Make & Model	HONDA VEZEL	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	RU11204134	Colour	BLUE	
Odometer	77494	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/50 R18	CONTINENTAL	6 mm	
L/H Front Tyre	225/50 R18	CONTINENTAL	6 mm	
R/H Rear Tyre	225/50 R18	CONTINENTAL	6 mm	
L/H Rear Tyre	225/50 R18	CONTINENTAL	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	02/12/2019	Inspection Date	06/12/2019	
Survey held at	160 SIN MING DRIVE #02-17			
Repairer	YEE AUTO SERVICE			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLK 3742Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BUMPER	DEFORMED	1,227.70	801.70
1	FRONT BUMPER AIR GRILLE CENTRAL	NOT NECESSARY	177.50	-
1	FRONT BUMPER BRACKET-LH	BROKEN	64.30	35.00
1	FRONT BUMPER BRACKET-RH	NOT NECESSARY	64.30	-
1	SET FRONT BUMPER CLIPS	NECESSARY	60.00	30.00
1	FRONT BUMPER FOG LAMP-LH	NOT NECESSARY	527.40	-
1	FRONT BUMPER FOG LAMP BRACKET-LH	NOT NECESSARY	99.40	-
1	FRONT BUMPER FOG LAMP COVER-LH	DEFORMED	198.30	45.00
1	FRONT BUMPER LOWER SPOILER	CUT	681.40	451.60
1	SET FRONT BUMPER LOWER SPOILER CLIPS	NECESSARY	60.00	20.00
1	FRONT BUMPER NUMBER PLATE INNER GRILLE	NOT NECESSARY	285.00	-
1	FRONT BUMPER REINFORCEMENT	BENT	521.40	421.00
1	FRONT BUMPER SIDE RETAINER-LH	NOT NECESSARY	52.60	-
1	FRONT BUMPER SIDE RETAINER-RH	NOT NECESSARY	52.60	-
1	FRONT FENDER-LH	NOT NECESSARY	780.40	-
1	FRONT GRILLE OUTER	NOT NECESSARY	265.50	-
1	FRONT GRILLE CHROME MOULDING	NOT NECESSARY	138.50	-
1	FRONT GRILLE INNER	NOT NECESSARY	205.10	-
1	FRONT GRILLE LOGO	NOT NECESSARY	95.50	-
1	FRONT HEADLAMP-LH	CRACKED	1,450.80	1,450.80
1	FRONT BUMPER CENTRE CHROME MOULDING	NOT NECESSARY	195.50	-
	LESS 20% DISCOUNT		-	-651.02
			7,203.20	2,604.08
SPECIAL NETT ITEMS				
1	FRONT NUMBER PLATE (SN)	NOT NECESSARY	60.00	-
			60.00	-
LABOUR				
	TO DISMANTLE & REPLACE DAMAGED PARTS.PANEL BEAT WHERE NECESSARY.		850.00	250.00
	TO PUTTY,APPLY PRIMER & SPRAY-PAINT ON THE AFFECTED PORTION.		850.00	250.00

Report Ref No. CS/FCI19021534/Gqf3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO CHECK WIRING FUNCTIONS.		80.00	30.00
			1,780.00	530.00
GRAND TOTAL			9,043.20	3,134.08
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,500.00

Report Ref No. CS/FCI19021534/Gqf3n2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.