

INS. CASE OWNER:

Ruchel

CC4/FCI19021936 / K2.93/1

LKK:

IDAC:

Surveyor:

Kenneth

DOI:

ASSIGNMENT

9/12/19

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SHC 8658 P

Claim No.:

019007674mfs11

Name of Insured:

CH

Policy No.:

Insured Tel No.:

HP:

Make / Model:

Excess Sec II :\$S

D.O.A: 02/12/2019

Place of Accident:

Is driver the owner?

( YES / NO )

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No

SFW 40 S



INSRS:  
WSP: HUIYANG MOTOR  
Tel:  
Liability:  
RMKS:



INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:



INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:



INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:

| Date/Time | STAGE                                                                                                                                                                | DATE / PIC                                                              |
|-----------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------|
|           | Non-Reporting ltr (1st):                                                                                                                                             |                                                                         |
|           | Non-Reporting ltr (2nd):                                                                                                                                             |                                                                         |
|           | Non-Reporting ltr (Final):                                                                                                                                           |                                                                         |
|           | Notification ltr (if non-pickup):                                                                                                                                    |                                                                         |
|           | Call OI:                                                                                                                                                             |                                                                         |
|           | After call ltr to OI:                                                                                                                                                |                                                                         |
|           | Documentation Check List: Handler Typist                                                                                                                             |                                                                         |
|           | Notification ltr (if non-pickup)                                                                                                                                     |                                                                         |
|           | After call ltr to OI:                                                                                                                                                |                                                                         |
|           | Authorisation To Act:                                                                                                                                                |                                                                         |
|           | Release Voucher:                                                                                                                                                     |                                                                         |
|           | Final Repair Bill:                                                                                                                                                   |                                                                         |
|           | Car Rental Invoice:                                                                                                                                                  |                                                                         |
|           | Towing Invoice:                                                                                                                                                      |                                                                         |
|           | LTA / GIA:                                                                                                                                                           |                                                                         |
|           | Medical Bill:                                                                                                                                                        |                                                                         |
|           | PIR:                                                                                                                                                                 |                                                                         |
|           | Mandate/Reject Instruction:                                                                                                                                          |                                                                         |
|           | LOD:                                                                                                                                                                 |                                                                         |
|           | Payment Breakdown Form:                                                                                                                                              |                                                                         |
|           | Post-Repair Photos:                                                                                                                                                  |                                                                         |
|           | Others:                                                                                                                                                              |                                                                         |
|           | PRELIMINARY ADVICE Date/Time:                                                                                                                                        | Sent By:                                                                |
|           | FINALIZATION Date/Time:                                                                                                                                              | Confirm with:                                                           |
|           | Repair Cost: \$S 1,300 ( 4 days) Reduction: 46 %                                                                                                                     | Confirm by: RSC                                                         |
|           | FINAL SETTLEMENT Date/Time: 05-03-20                                                                                                                                 | Confirm with: B&L                                                       |
|           | Final Liability: % 100 (Agreed / Assessed) BOLA S/N No. : 21                                                                                                         | Email <input checked="" type="checkbox"/> Call <input type="checkbox"/> |
|           | Repair Cost: \$S 1,811.00                                                                                                                                            | If NO or B 28, Ass. Lia:                                                |
|           | Loss of Rental (LOR): \$S - ( days)                                                                                                                                  |                                                                         |
|           | Loss of Use (LOU): \$S 180.00 (\$60 x 3 days)                                                                                                                        |                                                                         |
|           | Loss of Income (LOI): \$S - (\$ x days)                                                                                                                              |                                                                         |
|           | LOR only <input type="checkbox"/> LOU only <input checked="" type="checkbox"/> LOR + LOU <input type="checkbox"/> LOR + LOI <input type="checkbox"/> (Tick only one) |                                                                         |
|           | GIA/LTA Search \$S -                                                                                                                                                 |                                                                         |
|           | Medical: \$S -                                                                                                                                                       |                                                                         |
|           | Disbursement: \$S - (e.g. Tow/ Independent )                                                                                                                         |                                                                         |
|           | Legal Cost: \$S -                                                                                                                                                    |                                                                         |
|           | Total: \$S 1,991.00 Global Sum \$S:                                                                                                                                  |                                                                         |
|           | FINAL PAYMENT Date/Time: 05-03-20                                                                                                                                    | Confirm with: B&L                                                       |
|           | Payee 1: \$S 1,991.00                                                                                                                                                | Email <input checked="" type="checkbox"/> Call <input type="checkbox"/> |
|           | Payee 2: (Strike if N.A.) \$S                                                                                                                                        | Name 1: HUIYANG MOTOR PTE LTD                                           |
|           | Payee 3: (Strike if N.A.) \$S                                                                                                                                        | Name 2:                                                                 |
|           |                                                                                                                                                                      | Name 3:                                                                 |

COPY SENT 30/3/2020

ASS. REC. BY:

REF: CS/FC19021536/Kf3

Special Instruction:

Survivor: Kenneth

ASSIGNMENT (Office)

From (Person): Rachel Lin

of FC1

Date/Time: 5.12.19 6.51p.m

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SPW 405

Insured: SHC 8658P

at Workshop m/s Hui Yang motor

Tel: 64515752

of BIK 176 Shing ming Ave #104-02

Policy No:

Claim No: D19007674 MP54

Sum Insured:

Excess:

Make of Veh:

D.O.A. 2.12.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 6.12.19 9.40a.m

Person Contacted: Sandra

Vehicle IN / OUT

| Date/Time | Action/Instruction ( ✓ ) Estimate      |
|-----------|----------------------------------------|
|           | SHC 8658P CS/FC19021536/Kf3 28/10/2019 |
|           | SPW 405 X                              |
|           |                                        |
|           |                                        |
|           |                                        |
|           |                                        |
|           |                                        |

ASS. REC. BY:

REF: FC1

## ASSIGNMENT

From:

Date

9.12.2019

Estimated Cost:

OD / TP / INS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

SPW 405

at Workshop m/s

Hui Yang Motor

of

Blk 176 Sun Ming Drive # 0402

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:


(Client's Record)

Make of Vch:

Aper 10.30 a.m

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.



Bal. or Market Value:

88115

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4-5 days

Res.: Yes or No

Lum Sum:

1.81 %

3 Val: Yes or No

CA / REV / REP. / 24 HRS

sup

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No

SPW 405

Yr Regn:

12, 17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Perant Sceniz

C.C.

1461

Colour:

M. Brown

A/C:

Insured / Std / NI / NA

Sp. Reading

36294

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

VI-IRI-A 00658596329

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / SJ/Rim / STD A/Rim or

Tyre Size:

F:

R:

195/55 R 20

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or

Front

Rear

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

2/12/19

D.O.L.

9/12/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

4.1.1300 (RIS: 14,390-86 66%)

Date/Time, File Pass to?



: Preli. Report

1)



: Final Report

Date/Time, File Return to?

2)

Rep. Format:

Lump Sum / F.R. / F.C.

Days Of Repair:

Resurvey No. of Trip:

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Invs (\$



: Weekend (\$

Survey Fee:

Transportation:

S + RS. \$

Photos:

Notes:

TOTAL



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D19007674MFSH  
Our ref: CC4/FCI19021536/Kea3

Date: 16/12/2019

The Motor Claims Department  
MS FIRST CAPITAL INSURANCE LTD

Dear Sir/Madam,

**PRELIMINARY ADVICE OF VEHICLE NO.**

**SFW 40S**

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 09-12-2019 at the premises of M/s Hui Yang Motor Pte Ltd and have the following to report:-

|                               |       |           |
|-------------------------------|-------|-----------|
| Workshop Estimate Amount      | : S\$ | 21,690.86 |
| Revised Estimate Amount       | : S\$ | 6,588.80  |
| "Check" Items Amount          | : S\$ | 11,049.54 |
| Total (Including Check Items) | : S\$ | 17,638.34 |

|                         |       |   |        |
|-------------------------|-------|---|--------|
| Market Value            | : S\$ | - | (est.) |
| LTA Reimbursement Value | : S\$ | - | (est.) |
| Nett Value              | : S\$ | - | (est.) |

**Description of Damage:**

The vehicle sustained damages at the  
Rear Portion



**Comments/Present Status:**

Damages Consistent

Estimated normal period for repairs: 4-5 day

Yours faithfully,

KENNETH KONG  
Licensed Appraiser

He

max 09/12  
LEK

# 輝陽汽車有限公司

## HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721

Tel: 64515752 (2 Lines) . Fax: 64514658

GST Reg No. 201629438M

02/12/2019

Owner: ANG KOH BOON

11mp B7300h

Not Authorised

Referring B4 print  
4-141

### ESTIMATE TO REPAIR RENAULT SCENIC - SFW40S

|       |                                             |        |          |   |
|-------|---------------------------------------------|--------|----------|---|
| 1pc   | rear tailgate                               | Rs     | 2,850.00 | X |
| 1pc   | rear tailgate "RENAULT" logo                | Rs     | 85.50    | X |
| 1pc   | rear tailgate "RENAULT" emblem              | Rs     | 80.50    | X |
| 1pc   | rear tailgate "SCENIC" emblem               | Rs     | 80.50    | X |
| 1pc   | rear tailgate windscreen moulding           | Rs     | 250.80   | X |
| 1pc   | rear tailgate outer garnish                 | my CMA | 485.50   | X |
| 1pc   | rear tailgate inner rubber                  | Rs     | 392.50   | X |
| 1pc   | rear tailgate inner lock                    | Rs     | 485.20   | X |
| 8pcs  | rear tailgate inner clip @\$25.00           | Rs     | 200.00   | X |
| 1pc   | rear bumper                                 | Bu S   | 1,950.80 | X |
| 1pc   | rear bumper centre bracket                  | CMS    | 385.20   | X |
| 2pcs  | rear bumper side bracket @\$295.50          | Rs     | 591.00   | X |
| 2pcs  | rear bumper side retainer @\$195.20         | Rs     | 390.40   | X |
| 1pc   | rear bumper towing cover                    | Rs     | 98.25    | X |
| 2pcs  | rear bumper parking sensor @\$358.50        | Char S | 717.00   | X |
| 2pcs  | rear bumper parking sensor rubber @\$58.50  | Rs     | 117.00   | X |
| 2pcs  | rear bumper parking sensor bracket @\$65.85 | Rs     | 131.70   | X |
| 1pc   | rear bumper parking sensor hardness         | Rs     | 1,280.00 | X |
| 1pc   | rear bumper diffuser                        | Bu S   | 1,250.20 | X |
| 1pc   | rear bumper diffuser garnish                | my RS  | 1,155.50 | X |
| 10pcs | rear bumper diffuser clip @\$25.00          | Rs     | 250.00   | X |
| 2pcs  | rear bumper reflector @\$285.50             | Rs     | 571.00   | X |
| 2pcs  | rear bumper lower bracket @\$150.20         | CM PS  | 300.40   | X |
| 1pc   | rear bumper reinforcement                   | Rs     | 780.50   | X |
| 1pc   | rear end panel                              | Rs     | 1,350.00 | X |
| 1pc   | rear end panel inner garnish                | Rs     | 485.00   | X |
| 1pc   | rear floor panel                            | CM S   | 1,850.50 | X |
| 1pc   | rear floor panel inner garnish              | Rs     | 785.50   | X |
| 1pc   | rear floor panel sponge                     | Rs     | 450.50   | X |

less 10%

balance c/f

LEK Auto Components hereby certify the Repair of the following:

- To ensure safety and reliability
- To ensure quality and consistency
- To ensure the vehicle is in good condition
- To ensure the vehicle is in good condition
- To ensure the vehicle is in good condition
- To ensure the vehicle is in good condition
- To ensure the vehicle is in good condition
- To ensure the vehicle is in good condition

\$ 19,800.95  
\$ 1,980.10  
\$ 17,820.86



輝陽汽車有限公司  
HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721

Tel: 64515752 (2 Lines) . Fax: 64514658

GST Reg No. 201629438M

02/12/2019

Owner: ANG KOH BOON

ESTIMATE TO REPAIR RENAULT SCENIC - SFW40S

|       |                                      |           |                        |
|-------|--------------------------------------|-----------|------------------------|
|       | balance b/f                          |           | \$ 17,820.86           |
| 1 set | rear number plate & casing           | s.nett    | \$ 50.00 <i>45.00</i>  |
|       | remove & refit rear windscreen glass | <i>nn</i> | \$ 120.00 <i>X</i>     |
|       | tuffkote                             | <i>nn</i> | \$ 200.00 <i>X</i>     |
|       | sealant                              | <i>nn</i> | \$ 120.00 <i>X</i>     |
|       | wiring                               |           | \$ 180.00 <i>201</i>   |
|       | spray painting                       |           | \$ 1,600.00 <i>600</i> |
|       | labour charges                       |           | \$ 1,600.00 <i>500</i> |
|       | Total                                |           | <u>\$ 21,690.86</u>    |



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No supplementary work is allowed
- Supplementary work must be authorised and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature: \_\_\_\_\_  
Date: \_\_\_\_\_

### MOTOR SURVEY ASSIGNMENT

|                           |                                                             |                                    |
|---------------------------|-------------------------------------------------------------|------------------------------------|
| <b>Date</b>               | 04-12-2019                                                  | <b>Our Ref No.</b> D19007674MFSH   |
| <b>Accident Date</b>      | 02-12-2019                                                  | <b>Claim Type.</b> Third Party     |
| <b>Insured Vehicle</b>    | SHC8658P                                                    | <b>Third Party Vehicle.</b> SFW40S |
| <b>Survey Location</b>    | BLK 176 SIN MING DRIVE #04-02 SIN MING AUTOCARE             |                                    |
| <b>Contact Person.</b>    | SANDRA                                                      |                                    |
| <b>Contact No.</b>        | 6451 5752/ 0                                                | <b>Fax No.</b> 6451 4658           |
| <b>Survey Type</b>        | WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED: |                                    |
| <b>Appointed Surveyor</b> | LKK AUTO CONSULTANTS PTE LTD                                |                                    |
| <b>Contact Person</b>     | NA                                                          | <b>Fax No.</b> 68416315            |
| <b>Contact Number.</b>    | NA                                                          |                                    |

### FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

### THIRD PARTY SURVEY REQUEST

|                          |                        |                                |
|--------------------------|------------------------|--------------------------------|
| <b>Cc : Workshop</b>     | HUI YANG MOTOR PTE LTD | <b>Attention.</b> NIL          |
| <b>Cc : TP Solicitor</b> | NA                     | <b>TP Solicitor Fax No.</b> NA |
| <b>Officer Incharge</b>  | RACHELWU LIMEI         |                                |

### IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.  
 This is a computer generated letter, no signature required.

# 輝陽汽車有限公司 HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721  
Tel: 64515752 (2 Lines) . Fax: 64514658  
GST Reg No. 201629438M

02/12/2019

Owner: ANG KOH BOON

## ESTIMATE TO REPAIR RENAULT SCENIC - SFW40S

|       |                                             |    |             |   |
|-------|---------------------------------------------|----|-------------|---|
| 1pc   | rear tailgate                               | \$ | 2,850.00    | ? |
| 1pc   | rear tailgate "RENAULT" logo                | re | \$ 85.50    | ? |
| 1pc   | rear tailgate "RENAULT" emblem              | re | \$ 80.50    | ? |
| 1pc   | rear tailgate "SCENIC" emblem               | re | \$ 80.50    | ? |
| 1pc   | rear tailgate windscreen moulding           | \$ | 250.80      | ? |
| 1pc   | rear tailgate outer garnish                 | re | \$ 485.50   | X |
| 1pc   | rear tailgate inner rubber                  | re | \$ 392.50   | X |
| 1pc   | rear tailgate inner lock                    | re | \$ 485.20   | X |
| 8pcs  | rear tailgate inner clip @\$25.00           | re | \$ 200.00   | ? |
| 1pc   | rear bumper                                 | re | \$ 1,950.80 | ? |
| 1pc   | rear bumper centre bracket                  | \$ | 385.20      | ? |
| 2pcs  | rear bumper side bracket @\$295.50          | \$ | 591.00      | ? |
| 2pcs  | rear bumper side retainer @\$195.20         | re | \$ 390.40   | X |
| 1pc   | rear bumper towing cover                    | re | \$ 98.25    | X |
| 2pcs  | rear bumper parking sensor @\$358.50        | re | \$ 717.00   | ? |
| 2pcs  | rear bumper parking sensor rubber @\$58.50  | re | \$ 117.00   | ? |
| 2pcs  | rear bumper parking sensor bracket @\$65.85 | \$ | 131.70      | ? |
| 1pc   | rear bumper parking sensor hardness         | \$ | 1,280.00    | ? |
| 1pc   | rear bumper diffuser                        | re | \$ 1,250.20 | ? |
| 1pc   | rear bumper diffuser garnish                | \$ | 1,155.50    | ? |
| 10pcs | rear bumper diffuser clip @\$25.00          | re | \$ 250.00   | ? |
| 2pcs  | rear bumper reflector @\$285.50             | re | \$ 571.00   | X |
| 2pcs  | rear bumper lower bracket @\$150.20         | \$ | 300.40      | ? |
| 1pc   | rear bumper reinforcement                   | \$ | 780.50      | ? |
| 1pc   | rear end panel                              | \$ | 1,350.00    | ? |
| 1pc   | rear end panel inner garnish                | \$ | 485.00      | ? |
| 1pc   | rear floor panel                            | CM | \$ 1,850.50 | ? |
| 1pc   | rear floor panel inner garnish              | re | \$ 785.50   | X |
| 1pc   | rear floor panel sponge                     | \$ | 450.50      | ? |

less 10%

balance c/f

|    |           |
|----|-----------|
| \$ | 19,800.95 |
| \$ | 1,980.10  |
| \$ | 17,820.86 |



Not Authar  
Perry B4 print  
4-5 days

msd cap  
mon 09/12  
LKK

輝陽汽車有限公司  
HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721

Tel: 64515752 (2 Lines) . Fax: 64514658

GST Reg No. 201629438M

02/12/2019

Owner: ANG KOH BOON

ESTIMATE TO REPAIR RENAULT SCENIC - SFW40S

balance b/f \$ 17,820.86

1 set rear number plate & casing

s.nett \$ <sup>pd</sup> 50.00 <sup>45rn</sup>

remove & refit rear windscreen glass

\$ 120.00 ?

tuffkote

\$ 200.00 ?

sealant

\$ 120.00 ?

wiring

\$ 180.00 201

spray painting

\$ 1,600.00 600

labour charges

\$ 1,600.00 ?

Total

\$ 21,690.86



LKCAuto Consultants hence notify the Repairer of the following:

- To survey before/after spray painting
- To display damaged panel during survey
- Patch points are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No legal modification(s) allowed
- Supplementary items must be arranged and is subject to final approval from Insurance Company

Acknowledged by Repairer:  
Signature:  
Date:



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                                                                      |                                                                                                    |                              |                    |                                                                                     |
|----------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------|------------------------------|--------------------|-------------------------------------------------------------------------------------|
| MS FIRST CAPITAL INSURANCE LTD                                                                                                         |                                                                                                    | Ref : CC4/FCI19021536/Kea3q2 |                    |                                                                                     |
| 36 ROBINSON ROAD<br>#16-01 CITY HOUSESINGAPORE 068877                                                                                  |                                                                                                    | Date : 01-04-2020            |                    |  |
|                                                                                                                                        |                                                                                                    | Code : FCI2                  |                    |                                                                                     |
| 1. Policy Particulars :- THIRD PARTY CLAIM                                                                                             |                                                                                                    |                              |                    |                                                                                     |
| Insured Veh.                                                                                                                           | SHC 8658P                                                                                          | Veh. Inspected               | SFW 40S            |                                                                                     |
| Policy No.                                                                                                                             | D-18088938MFSH                                                                                     | Coverage (\$)                | 0.00               |                                                                                     |
| Claim No.                                                                                                                              | D19007674MFSH                                                                                      | Excess (\$)                  | 0.00               |                                                                                     |
| Assign From                                                                                                                            | RACHEL WJ LIMEI                                                                                    | Assign Date                  | 05/12/2019         |                                                                                     |
| 2. Vehicle Particulars & Condition                                                                                                     |                                                                                                    |                              |                    |                                                                                     |
| Make & Model                                                                                                                           | RENAULT SCENIC (A)                                                                                 | c.c                          | 1461               |                                                                                     |
| Engine No.                                                                                                                             | HIDDEN                                                                                             | Year of Reg.                 | 2017               |                                                                                     |
| Chassis No.                                                                                                                            | VF1RFA00658596329                                                                                  | Colour                       | METALLIC BROWN     |                                                                                     |
| Odometer                                                                                                                               | 36294                                                                                              | Steering                     | IN ORDER           |                                                                                     |
| Brakes                                                                                                                                 | IN ORDER                                                                                           | Modification                 | STANDARD ALLOY RIM |                                                                                     |
| General                                                                                                                                | GOOD                                                                                               |                              |                    |                                                                                     |
| 3. Conditions of Tyres                                                                                                                 |                                                                                                    |                              |                    |                                                                                     |
|                                                                                                                                        | Size                                                                                               | Make                         | Balance            |                                                                                     |
| R/H Front Tyre                                                                                                                         | 195/55 R20                                                                                         | GOODYEAR                     | 8 mm               |                                                                                     |
| L/H Front Tyre                                                                                                                         | 195/55 R20                                                                                         | GOODYEAR                     | 8 mm               |                                                                                     |
| R/H Rear Tyre                                                                                                                          | 195/55 R20                                                                                         | GOODYEAR                     | 8 mm               |                                                                                     |
| L/H Rear Tyre                                                                                                                          | 195/55 R20                                                                                         | GOODYEAR                     | 8 mm               |                                                                                     |
| 4. Description of Damages                                                                                                              |                                                                                                    |                              |                    |                                                                                     |
| THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.<br>DAMAGES SEE DETAILS.                                                             |                                                                                                    |                              |                    |                                                                                     |
| 5. General Information                                                                                                                 |                                                                                                    |                              |                    |                                                                                     |
| Accident Date                                                                                                                          | 02/12/2019                                                                                         | Inspection Date              | 09/12/2019         |                                                                                     |
| Survey held at                                                                                                                         | HUI YANG MOTOR PTE LTD<br>BLOCK 176 SIN MING DRIVE<br>#04-02 SIN MING AUTOCARE<br>SINGAPORE 575721 |                              |                    |                                                                                     |
| 5a. Remarks                                                                                                                            |                                                                                                    |                              |                    |                                                                                     |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                                                                                    |                              |                    |                                                                                     |
| 5b. Estimate Days of Repair                                                                                                            |                                                                                                    |                              |                    |                                                                                     |
| ESTIMATED NORMAL PERIOD FOR REPAIR:                                                                                                    |                                                                                                    | 4 Working Days               |                    |                                                                                     |

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

**ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SFW 40S**

| Qty | Description of Parts                        | Condition            | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|---------------------------------------------|----------------------|---------------------------|-------------------|
|     | <b>REPLACEMENT OF PARTS</b>                 |                      |                           |                   |
| 1   | REAR TAILGATE "RENAULT" LOGO                | NECESSARY            | 85.50                     | 85.50             |
| 1   | REAR TAILGATE                               | TO REPAIR SEE LABOUR | 2,850.00                  | -                 |
| 1   | REAR TAILGATE "RENAULT" EMBLEM              | NECESSARY            | 80.50                     | 80.50             |
| 1   | REAR TAILGATE "SCENIC" EMBLEM               | NECESSARY            | 80.50                     | 80.50             |
| 1   | REAR TAILGATE WINDSCREEN MOULDING           | NOT NECESSARY        | 250.80                    | -                 |
| 1   | REAR TAILGATE OUTER GARNISH                 | MTG CRACKED          | 485.50                    | 485.50            |
| 1   | REAR TAILGATE INNER RUBBER                  | SERVICEABLE          | 392.50                    | -                 |
| 1   | REAR TAILGATE INNER LOCK                    | TO REPAIR SEE LABOUR | 485.20                    | -                 |
| 8   | REAR TAILGATE INNER CLIP @\$25.00           | NECESSARY            | 200.00                    | 200.00            |
| 1   | REAR BUMPER                                 | BUCKLED              | 1,950.80                  | 1,950.80          |
| 1   | REAR BUMPER CENTRE BRACKET                  | CRACKED              | 385.20                    | 385.20            |
| 2   | REAR BUMPER SIDE BRACKET @\$295.50          | TO REPAIR SEE LABOUR | 591.00                    | -                 |
| 2   | REAR BUMPER SIDE RETAINER @\$195.20         | SERVICEABLE          | 390.40                    | -                 |
| 1   | REAR BUMPER TOWING COVER                    | SERVICEABLE          | 98.25                     | -                 |
| 2   | REAR BUMPER PARKING SENSOR @\$358.50        | SHORTED              | 717.00                    | 717.00            |
| 2   | REAR BUMPER PARKING SENSOR RUBBER @\$58.50  | NECESSARY            | 117.00                    | 117.00            |
| 2   | REAR BUMPER PARKING SENSOR BRACKET @\$65.85 | SERVICEABLE          | 131.70                    | -                 |
| 1   | REAR BUMPER PARKING SENSOR HARDNESS         | SERVICEABLE          | 1,280.00                  | -                 |
| 1   | REAR BUMPER DIFFUSER                        | BUCKLED              | 1,250.20                  | 1,250.20          |
| 1   | REAR BUMPER DIFFUSER GARNISH                | MTG CRACKED          | 1,155.50                  | 1,155.50          |
| 10  | REAR BUMPER DIFFUSER CLIP @\$25.00          | NECESSARY            | 250.00                    | 250.00            |
| 2   | REAR BUMPER REFLECTOR @\$285.50             | SERVICEABLE          | 571.00                    | -                 |
| 2   | REAR BUMPER LOWER BRACKET @\$150.20         | CRACKED              | 300.40                    | 300.40            |
| 1   | REAR BUMPER REINFORCEMENT                   | TO REPAIR SEE LABOUR | 780.50                    | -                 |
| 1   | REAR END PANEL                              | TO REPAIR SEE LABOUR | 1,350.00                  | -                 |
| 1   | REAR END PANEL INNER GARNISH                | SERVICEABLE          | 485.00                    | -                 |
| 1   | REAR FLOOR PANEL                            | CRACKED              | 1,850.50                  | 1,850.50          |

Report Ref No. CC4/FCI19021536/Kea3q2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

| Qty | Description of Parts                                                                                                                                     | Condition     | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|----------------------------------------------------------------------------------------------------------------------------------------------------------|---------------|---------------------------|-------------------|
| 1   | REAR FLOOR PANEL INNER GARNISH                                                                                                                           | SERVICEABLE   | 785.50                    | -                 |
| 1   | REAR FLOOR PANEL SPONGE                                                                                                                                  | SERVICEABLE   | 450.50                    | -                 |
|     | LESS 10% DISCOUNT                                                                                                                                        |               | -1,980.10                 | -890.86           |
|     |                                                                                                                                                          |               | 17,820.85                 | 8,017.74          |
|     | <b><u>SPECIAL NETT ITEMS</u></b>                                                                                                                         |               |                           |                   |
| 1   | SET REAR NUMBER PLATE & CASING (SN)                                                                                                                      | DENTED        | 50.00                     | 45.00             |
| 1   | SEALANT (SN)                                                                                                                                             | NOT NECESSARY | 120.00                    | -                 |
|     |                                                                                                                                                          |               | 170.00                    | 45.00             |
|     | <b><u>LABOUR</u></b>                                                                                                                                     |               |                           |                   |
|     | REMOVE & REFIT REAR WINDSCREEN GLASS.                                                                                                                    | NOT NECESSARY | 120.00                    | -                 |
|     | TUFFKOTE.                                                                                                                                                | NOT NECESSARY | 200.00                    | -                 |
|     | WIRING.                                                                                                                                                  |               | 180.00                    | 20.00             |
|     | SPRAY PAINTING.                                                                                                                                          |               | 1,600.00                  | 600.00            |
|     | LABOUR CHARGES. INCLUSIVE OF THE REPAIR OF REAR TAILGATE,REAR TAILGATE INNER LOCK,REAR BUMPER SIDE BRACKET,REAR BUMPER REINFORCEMENT AND REAR END PANEL. |               | 1,600.00                  | 500.00            |
|     |                                                                                                                                                          |               | 3,700.00                  | 1,120.00          |
|     | <b>GRAND TOTAL</b>                                                                                                                                       |               | <b>21,690.85</b>          | <b>9,182.74</b>   |
|     | <b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>                                                                              |               |                           | <b>7,300.00</b>   |

Report Ref No. CC4/FCI19021536/Kea3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.