

Ke mon 09/12 LKK 輝陽汽車有限公司 HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721

Tel: 64515752 (2 Lines) . Fax: 64514658

GST Reg No. 201629438M

02/12/2019

Owner: ANG KOH BOON

11 Emp B4 300h

Not Notarized
Referring B4 print
4- days

ESTIMATE TO REPAIR RENAULT SCENIC - SFW40S

1pc	rear tailgate	R	\$ 2,850.00	X
1pc	rear tailgate "RENAULT" logo	R	\$ 85.50	X
1pc	rear tailgate "RENAULT" emblem	R	\$ 80.50	X
1pc	rear tailgate "SCENIC" emblem	R	\$ 80.50	X
1pc	rear tailgate windscreen moulding	R	\$ 250.80	X
1pc	rear tailgate outer garnish	my CMA	\$ 485.50	X
1pc	rear tailgate inner rubber	Sn	\$ 392.50	X
1pc	rear tailgate inner lock	R	\$ 485.20	X
8pcs	rear tailgate inner clip @\$25.00	R	\$ 200.00	X
1pc	rear bumper	Bu	\$ 1,950.80	X
1pc	rear bumper centre bracket	CMA	\$ 385.20	X
2pcs	rear bumper side bracket @\$295.50	R	\$ 591.00	X
2pcs	rear bumper side retainer @\$195.20	Sn	\$ 390.40	X
1pc	rear bumper towing cover	Sn	\$ 98.25	X
2pcs	rear bumper parking sensor @\$358.50	Shas	\$ 717.00	X
2pcs	rear bumper parking sensor rubber @\$58.50	R	\$ 117.00	X
2pcs	rear bumper parking sensor bracket @\$65.85	R	\$ 131.70	X
1pc	rear bumper parking sensor hardness	R	\$ 1,280.00	X
1pc	rear bumper diffuser	Bu	\$ 1,250.20	X
1pc	rear bumper diffuser garnish	my CMA	\$ 1,155.50	X
10pcs	rear bumper diffuser clip @\$25.00	R	\$ 250.00	X
2pcs	rear bumper reflector @\$285.50	Sn	\$ 571.00	X
2pcs	rear bumper lower bracket @\$150.20	CMA Bu	\$ 300.40	X
1pc	rear bumper reinforcement	R	\$ 780.50	X
1pc	rear end panel	R	\$ 1,350.00	X
1pc	rear end panel inner garnish	R	\$ 485.00	X
1pc	rear floor panel	CMA	\$ 1,850.50	X
1pc	rear floor panel inner garnish	Sn	\$ 785.50	X
1pc	rear floor panel sponge	Sn	\$ 450.50	X

less10%
balance c/f


LKK Auto Consultants hence notify the Repairer of the following:

• To resurvey before after spray painting	
• To display damage on car after resurvey	\$ 19,800.95
• Parts prices are subject to confirmation	
• Third party survey is done "Without Prejudice" basis	\$ 1,980.10
• No illegal employment of staff is allowed	
• Supplementary details will be resurveyed and is subject to final spot check from Insurance Company	\$ 17,820.86

Acknowledged by Repairer

Signature:

Date:



輝陽汽車有限公司
HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721

Tel: 64515752 (2 Lines) . Fax: 64514658

GST Reg No. 201629438M

02/12/2019

Owner: ANG KOH BOON

ESTIMATE TO REPAIR RENAULT SCENIC - SFW40S

balance b/f \$ 17,820.86

1 set rear number plate & casing

s.nett \$ nd 50.00 ^{45m}

remove & refit rear windscreen glass

~~nn~~ \$ 120.00 ~~X~~

tuffkote

~~nn~~ \$ 200.00 ~~X~~

sealant

~~nn~~ \$ 120.00 ~~X~~

wiring

\$ 180.00 ²⁰¹

spray painting

\$ 1,600.00 ⁶⁰⁰

labour charges

\$ 1,600.00 ⁵⁰⁰

Total

\$ 21,690.86



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: