

輝陽汽車有限公司 HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721

Tel: 64515752 (2 Lines) . Fax: 64514658

GST Reg No. 201629438M

02/12/2019

Owner: ANG KOH BOON

ESTIMATE TO REPAIR RENAULT SCENIC - SFW40S

1pc	rear tailgate	\$ 2,850.00	?
1pc	rear tailgate "RENAULT" logo	\$ 85.50	✓
1pc	rear tailgate "RENAULT" emblem	\$ 80.50	✓
1pc	rear tailgate "SCENIC" emblem	\$ 80.50	✓
1pc	rear tailgate windscreen moulding	\$ 250.80	✓
1pc	rear tailgate outer garnish	\$ 485.50	X
1pc	rear tailgate inner rubber	\$ 392.50	X
1pc	rear tailgate inner lock	\$ 485.20	X
8pcs	rear tailgate inner clip @\$25.00	\$ 200.00	✓
1pc	rear bumper	\$ 1,950.80	✓
1pc	rear bumper centre bracket	\$ 385.20	?
2pcs	rear bumper side bracket @\$295.50	\$ 591.00	?
2pcs	rear bumper side retainer @\$195.20	\$ 390.40	X
1pc	rear bumper towing cover	\$ 98.25	X
2pcs	rear bumper parking sensor @\$358.50	\$ 717.00	✓
2pcs	rear bumper parking sensor rubber @\$58.50	\$ 117.00	✓
2pcs	rear bumper parking sensor bracket @\$65.85	\$ 131.70	?
1pc	rear bumper parking sensor hardness	\$ 1,280.00	?
1pc	rear bumper diffuser	\$ 1,250.20	✓
1pc	rear bumper diffuser garnish	\$ 1,155.50	?
10pcs	rear bumper diffuser clip @\$25.00	\$ 250.00	✓
2pcs	rear bumper reflector @\$285.50	\$ 571.00	X
2pcs	rear bumper lower bracket @\$150.20	\$ 300.40	?
1pc	rear bumper reinforcement	\$ 780.50	?
1pc	rear end panel	\$ 1,350.00	?
1pc	rear end panel inner garnish	\$ 485.00	?
1pc	rear floor panel	\$ 1,850.50	✓
1pc	rear floor panel inner garnish	\$ 785.50	X
1pc	rear floor panel sponge	\$ 450.50	?

less 10%

balance c/f

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications is allowed
- Supplementary items must be resurveyed and is subject to final approval from Insurance Company

\$	19,800.95
\$	1,980.10
\$	17,820.86

Acknowledged by Repairer

Signature:

Date:



mon 09/12
LKK

Not Authorised
Repair by paint
4-5 days

輝陽汽車有限公司
HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721

Tel: 64515752 (2 Lines) . Fax: 64514658

GST Reg No. 201629438M

02/12/2019

Owner: ANG KOH BOON

ESTIMATE TO REPAIR RENAULT SCENIC - SFW40S

	balance b/f		\$ 17,820.86
1 set	rear number plate & casing	s.nett	\$ <i>pu</i> 50.00 <i>45.00</i>
	remove & refit rear windscreen glass	\$	120.00 <i>?</i>
	tuffkote	\$	200.00 <i>?</i>
	sealant	\$	120.00 <i>?</i>
	wiring	\$	180.00 <i>201</i>
	spray painting	\$	1,600.00 <i>600</i>
	labour charges	\$	1,600.00 <i>?</i>
	Total	\$	<u>21,690.86</u>



LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: