辉陽汽車有限公司 HUI YANG MOTOR PTE. LTD.

Contact Add: SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721 Tel: 64515752 (2 Lines) . Fax: 64514658 GST Reg No. 201629438M

Date: 02/01/2020

MS First Capital Insurance Ltd

Motor Claims Department 36 Robinson Road #16-01 City House Singapore 068877

RE: ACCIDENT INVOLVING SFW40S & SHC8658P ON 02/12/2019
ALONG BUKIT TIMAH ROAD (BETWEEN NAMELY AVE & FIRST AVE)

SETTLEMENT OF OUR CLAIM FOR SFW40S

 Lump Sum repair cost as recommended by surveyor (TP0791)
 \$ 7,811.00

 03 Days Loss of Use @ \$80.00 per day
 \$ 240.00

 Total
 \$ 8,051.00

*The above claim applies only to vehicle damage and expressly exclude all personal injuries and other consequential loss.

Please let us have your reply soonest possible, thank you.

Best Regards, Marco Neo HUI YANG MOTOR PTE LTD

DID: 64515752 Fax: 64514658

email: hui_yang_motor@hotmail.com

AUTHORIZATION LETTER

TO WHOM IT MAY CONCERN	
I/We, Ang koh Boon	hereby declare and agree to use the
address of Hui Yang Motor Pte Ltd, that is at Blk 176	
Autocare Singapore 575721 in all my correspondences	with any party in connection with my
claim.	
Arising from an accident involving my motor vehicle	registration number SFW40S
and other vehicles registration number	ρ
along Bukit Timah Road (Between Namly Ave & First Ave)	on on
02 12 2019	
I/We, further grant authority to Messrs Hui Yang representatives to negotiate my/our claim on my/our voucher / indemnity forms and all necessary documents above accident claim.	behalf and to execute, sign discharge s in connection with and arising of the
I/We wish to inform you that you could issue the chequ	e payment in favour of my/our repairer
Messrs Hui Yang Motor Pte Ltd.	
Signature of registered owner and/or Company's stamp	

HUI YANG MOTOR PTE LTD

Bill To:

TAX INVOICE

MS First Capital Insurance Ltd

Motor Claims Department

36 Robinson Road

#16-01 City House

Singapore 068877

TP Claim Invoice No:

TP0791

Bill Date:

02/01/2020

Description	Amount
Date of Accident: 02/12/2019	
Owner : ANG KOH BOON	
Vehicle No : SFW40S	
Make & Model : RENAULT SCENIC	
Lump Sum repair cost as recommended by surveyor	\$ 7,300.00
4	
Sub-Total:	\$ 7,300.00
Add 7% GST:	\$ 511.00
Total Amount SGD :	\$ 7,811.00

Reg No.:201629438M GST No:201629438M

HUI YANG MOTOR PTE LTD



Authorised Signature

Hui Yang Motor Pte Ltd

Sin Ming Autocare Blk 176 Sin Ming Drive

#04-02 Singapore 575721

Email: hui_yang_motor@hotmail.com

H/P: 98625891 Office: 64515752 Fax: 64514658