

22/03/2002

ASS. REC. BY:

REF:

CS/AIG 19021545 109f302

Special Instruction:

Survivor: Marcus

ASSIGNMENT (Office)

From (Person):

Hor Ymm T

of

AIG

Date/Time:

6.12.19 1449.m

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLU 6912B

Insured:

SJT 7865

at Workshop m/s

Euro Success

Tel:

98289277

of

1 Kaki Bukit Ave 6 1102-03 Autobay

Policy No:

Claim No:

521271132756

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

5.12.2019

CA / REV / REP. / REV 24 HRS

Date/Time:

6.12.19 10.38a.m

Person Contacted:

Ah Huat

H.O.D. Endorsement:

Vehicle IN OUT

Date/Time

Action/Instruction (

✓)

Estimate

SJT 7865 : X

SLU 6912B : X

ASS. REC. BY:

REF: **AIG****Marcus****ASSIGNMENT**

From:

Date: **9.12.2019**

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: **SLU 6912B**at Workshop m/s **Euro Success**of **1 Kaki Bukit Ave 6 #102-03 Autobay**

Insured:

Policy No.:

Claims No.:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

18

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SLU 6912B

Yr Regn:

13/4/11Type: ☒ M.Car / ☐ M.Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or

Make:

Volkswagen Scirocco R 1984

Colour:

whiteA/C: ☒ Insured / ☐ Std / ☐ NI / ☐ NA

Sp. Reading

131756T/Radio: ☒ Insured / ☐ Std / ☐ NI / ☐ NA

Eng/No:

C/No:

WVWZZZ1383V026568Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ BurntSteering: ☒ Inorder / ☐ Jammed / ☐ Leaked / ☐ Burnt orBrake: ☒ Inorder / ☐ Jammed / ☐ Leaked / ☐ Burnt orModl: ☒ Nil / ☐ S/Rim / ☐ STD A/Rim or

Tyre Size:

F:

245/40 ZR18

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

6

mm

Rear

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

5/12/19

D.O.I.

9/12/19

Survey held at

Des. of Damages: ☐ Frt / ☐ Rear / ☐ O/S / ☐ N/S / ☐ U/C / ☐ Rooftop or**Rear & L.L.**

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Rep 18th**LTA 24534****1/15 4th.****30/12/19****6/5 * 16.000 confirmed with AM Insur.
(led to 43172.74, 73%)**

Date/Time, File Pass to?

☐

: Preli. Report

1) **30/12/19**☐

: Final Report

Date/Time, File Return to?

2)

Rep. Format:

MER-TP

Lump Sum / H.R. /

16000

Days Of Repair:

18

Resurvey No. of Trip:

1

Add Fee:

☐

: Site Insp (\$)

☐

: Interview (\$)

☐

: Tech. Invs (\$)

☐

: Weekend (\$)

Survey Fee:

250

Transportation:

S + RS, SI

Photos

Others

11

TOTAL

261

Your password will expire in 6 days. [Click here to change it.](#)

PRE-REPAIR INSPECTION REQUEST – SLU6912B vs SJT786S (OI) on D.O.A.: 05/12/2019

From: Hor, Yinrul
 To: 'assignments@lkkauto.com', Admin A (admin-a@lkkauto.com)
 Cc: Fong, Andy-SY, Chan, Jennifer-WM, Abu Kassim, Noor Mariesa, Azlan, Syazairdina, Chan, Yoke Shi, Lim, Sheng Yang, Mithoosingh, Aashweenjeetkaur, Parthiban, Theerthan, Subramaniam,
 Sent: Friday, 6 December, 2019 10:14:12 AM

Hi,

Please refer to the enclosed request from **Hin Tat Augustine & Partners**.
 Kindly carry out Policy coverage verification first before conducting the pre-repair inspection within 48 hours

If you have any queries/concerns, please let us know.
 Kindly assist to assign **Marcus Chua** as Single Joint Expert as requested.

Thanks & Regards,

Hor Yin Rul (Viviane)
 AIG
 FNOL Adjuster I
 Singapore AUTO Claims

Tel: 8001206556 | Ext: 1002208

Yinrul.Hor@aig.com | www.aig.sg

From: Ruby Ong <ruby@htapartners.com.sg>
 Sent: Friday, December 6, 2019 9:51 AM
 To: Hor, Yinrul <Yinrul.Hor@aig.com>
 Cc: Fong, Andy-SY <Andy-SY.Fong@aig.com>; Chan, Jennifer-WM <Jennifer-WM.Chan@aig.com>; Abu Kassim, Noor Mariesa <NoorMariesa.AbuKassim@aig.com>; Azlan, Syazairdina <Syazairdina.Azlan@aig.com>; Chan, Yoke Shi <yokeshi.chan@aig.com>; Lim, Sheng Yang <ShengYang.Lim@aig.com>; Mithoosingh, Aashweenjeetkaur <Aashweenjeetkaur.Mithoosingh@aig.com>; Parthiban, Theerthan <Theerthan.Parthiban@aig.com>; Subramaniam, Divyashni <Divyashni.Subramaniam@aig.com>
 Subject: [EXTERNAL] RE: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SJT786S AND SLU6912B ON 05/12/2019
 Importance: High

This message is from an external sender; be cautious with links and attachments.

SAVE AS TO COSTS

Dear Sir

We refer to your email of even date.

Our client is agreeable to appoint LKK Auto Consultants, Marcus Chua (East Area) from your list to conduct the joint pre-repair survey as a single joint expert for our client's vehicle no **SLU 6912B**.

Please make the necessary arrangements with the contact person. The details are as follows :

Venue : EURO SUCCESS SERVICES PTE LTD
 1 Kaki Bukit Avenue 6
 #02-03 Autobay
 Singapore 417883

Contact Person : Ah Huat (Tel. 9828 9277 / 6742 6231)

If you fail to conduct the pre-repair survey within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference.

Best regards,
 Ruby Ong
 Secretary
 M/s Hin Tat Augustine & Partners
 20 Upper Circular Road
 #02-10/12 The Riverwalk
 Singapore 058416
 Tel : 6533 0212 ext 278
 Fax : 6338 3536 / 6533 0313
www.htapartners.com.sg

Privileged/Confidential information is contained in this message. If you are not the addressee indicated in this message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email.

From: Hor, Yinrul <Yinrul.Hor@aig.com>
 Sent: Friday, 6 December 2019 9:19 AM
 To: Ruby Ong <ruby@htapartners.com.sg>
 Cc: Fong, Andy-SY <Andy-SY.Fong@aig.com>; Chan, Jennifer-WM <Jennifer-WM.Chan@aig.com>; Abu Kassim, Noor Mariesa <NoorMariesa.AbuKassim@aig.com>; Azlan, Syazairdina <Syazairdina.Azlan@aig.com>; Chan, Yoke Shi <yokeshi.chan@aig.com>; Lim, Sheng Yang <ShengYang.Lim@aig.com>; Mithoosingh, Aashweenjeetkaur <Aashweenjeetkaur.Mithoosingh@aig.com>; Parthiban, Theerthan <Theerthan.Parthiban@aig.com>; Subramaniam, Divyashni <Divyashni.Subramaniam@aig.com>
 Subject: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SJT786S AND SLU6912B ON 05/12/2019



This is a secure, encrypted message. To read it, open the attachment.

* Este es un mensaje cifrado y seguro. Para leerlo, abra el archivo adjunto.

Esta é uma mensagem criptografada segura. Para lê-lo, abra o anexo.

Ceci est une sécurité, un message crypté. Pour le lire, ouvrez la pièce jointe.

これは暗号化された電子メールです。閲覧には添付ファイルを開いてください。

[Click here](#) by 2019-12-12 19:19 CST to read your message.
After that, open the attachment.

[More Info](#)

Disclaimer: This email and its content are confidential and intended solely for the use of the addressee. Please notify the sender if you have received this email in error or simply delete it.

Secured by Proofpoint Encryption, Copyright © 2009-2017 Proofpoint, Inc. All rights reserved.

From: Yinnul.Hor@aig.com
To: ruby@htapartners.com.sg
Cc: Andy-SY.Fong@aig.com ,Jennifer-VM.Chan@aig.com ,NoorMariessa.AbuKassim@aig.com ,Syazairdina.Azlan@aig.com ,yokeshi.chan@aig.com ,ShengYang.Lim@aig.com ,Aashweenjeetkaur.Mithoosingh@aig.com ,Theerthan.Parthib
Subject: aigencrypt PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SJT786S AND SLU6912B ON 05/12/2019
Date: Fri, 6 Dec 2019 01:19:06 +0000
Without Prejudice

Your Reference : TCL.GCN.RO.50749.19.ESS
Our Reference : SJT786S

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert:

Name of Surveyor	Company Name
AIG In House Surveyor	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon HanXin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thanks & Regards,

Hor Yin Rul (Viviane)
AIG
FNOL Adjuster I
Singapore AUTO Claims

Tel: 6001206556 | Ext: 1002208
Yinnul.Hor@aig.com | www.aig.sg

From: Ruby Ong <ruby@htapartners.com.sg>
Sent: Thursday, December 5, 2019 5:02 PM
To: Hor, Yinnul <Yinnul.Hor@aig.com>
Subject: [EXTERNAL] REQUEST FOR PRE-REPAIR SURVEY PROTOCOL FOR SLU 6912B [OUR REF. TCL.GCN.RO.50749.19.ESS]
Importance: High

This message is from an external sender; be cautious with links and attachments.

Your ref: SJT 786S
Our ref: TCL.GCN.ro.50749.19.ess

WITHOUT PREJUDICE

5 December 2019

AIG Asia Pacific Insurance Pte. Ltd.
Motor Claims Department
8 Shenton Way
#08-16 AIG Building
Singapore 068811

By Email Only

VERY URGENT

Dear Sirs,

CLAIMANT: TAN CHOR KOON

NOTICE OF ACCIDENT AND PRE-REPAIR SURVEY - ACCIDENT INVOLVING SLU 6912B, SJT 786S & SLA 3088B ALONG GEYLANG ROAD ON 5 DECEMBER 2019 @ 0905HRS

We are instructed by Tan Chor Koon to notify you of a road traffic accident on 5 December 2019 at about 0905hrs along Geylang Road involving our client's vehicle registration number SLU 6912B and vehicle registration number SJT 786S driven by your insured's driver at the material time.

As a result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurers would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without reference to you.

Best regards,
Ruby Ong
Secretary
M/s Hin Tat Augustine & Partners
20 Upper Circular Road
#02-10/12 The Riverwalk
Singapore 058416
Tel : 6533 0212 ext 278
Fax : 6338 3536 / 6533 0313
www.htapartners.com.sg

Privileged/Confidential information is contained in this message. If you are not the addressee indicated in this message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email.

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 359A

Vehicle Details

Vehicle No.: SLU6912B

Vehicle to be Exported: No

Intended Deregistration Date: 09 Dec 2019

Vehicle Make: VOLKSWAGEN

Vehicle Model: SCIROCCO R 2.0L AT 137RX3

Primary Colour: White

Manufacturing Year: 2011

Engine No.: CDL045617

Chassis No.: WWZZZ13ZBV026568

Maximum Power Output: 188.0 kW (252 bhp)

Open Market Value: \$34,168.00

Original Registration Date: 13 Apr 2011

First Registration Date: 13 Apr 2011

Transfer Count: 3

Actual ARF Paid: \$34,168.00 *17084*

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 12 Apr 2021

PARF Rebate Amount: \$18,792.00

Intended COE Rebate Details

COE Expiry Date: 12 Apr 2021

COE Category: B - Car (1601cc & above)

COE Period(Years): 10

QP Paid: \$42,801.00

COE Rebate Amount: \$5,742.00

Total Rebate Amount: \$24,534.00

The information contained herein is correct as at 09 Dec 2019

OK

Scirocco R 2.0A

Price Range

Depreciation

2011

Vehicle Type

Submit

Advanced Search

Home » Used Cars » Car Source Pte Ltd » Volkswagen Scirocco R 2.0A

Volkswagen Scirocco R 2.0A

- Overview
- Financial
- Insurance
- Accessories
- Similar
- Research
- Photos
- Map

Price	\$40,800		
Depreciation	\$18,690 /yr View models with similar depre	Reg Date	07-Mar-2011 (1yr 2mths 25days COE left)
Mileage	119,000 km (13.6k /yr)	Manufactured	2010
Road Tax	\$1,194 /yr	Transmission	Auto
Dereg Value	\$23,822 as of today (change)	OMV	\$35,209
COE	\$35,909	ARF	\$35,209
Engine Cap	1,984 cc	Power	188.0 kW (252 bhp)
Curb Weight	1,364 kg	No. of Owners	3
Type of Vehicle	Sports Car		

Features
Powerful 2.0L Turbocharged Engine, 252 Bhp, 6 Speed DSG Gearbox, 4 Airbags, Bi-Xenon Headlights, Side Mirror Indicators, Rain Sensing Wiper. View specs of the Volkswagen Scirocco (2009-2017)

Accessories
Pioneer Touch Screen Player, Bluetooth, Black Leather Seats, 18 Inch Sport Rims, Multi Steering Control, Remote Boot Release, Driver's Electric Seat.

Description
Well Maintained By Owner, Front Brembo Brake, 4 New Brake Pad, Parts Was Replaced Whenever It Was Detected Faulty, Buy Direct From The Owner, Get To Know The Maintenance History, Test Drive To Evaluate The Condition, Consignment Unit.

Category
PARF Car

Status
Available

Resources

- STA

Vehicle Evaluation
Afraid of lemons? Request to have this car evaluated professionally. Find out more
- Car Valuation - Free
Find out the market value of your existing car for free. Get started



- Shortlist
- Compare
- Add note
- Report Error
- More Actions

Seller Information

Car Source Pte Ltd

1 vehicles for sale. 11 sold in past 3 mths

118 Aljunied Avenue 2 #02-134

Tel: 69099744

Search cars nearby

Andy

98558318

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	06/12/2019 13:26
Date Of Accident	05/12/2019 09:05
Exact Location Of Accident	GEYLANG ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLU6912B
Insured/Policyholder	
Name Of Registered Owner	TAN CHOR KOON
NRIC No	S1431359A
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-94838269
Alternative Phone No	OTHERS-94838269

Vehicle Particulars

Manufacturer	VOLKSWAGEN
Model	SCIROCCO R 2.0L AT 137RX3
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA305846/1
Cover Note Number	

Driver

Name of Driver	JERVIS SEET
NRIC No	S9726332I
Date Of Birth	05/08/1997
Occupation	INDOOR
Date Of Driving Pass	15/01/2016
Driving Experience	3 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-86121055
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	179 WOODLANDS STREET 13 #03-267 SPORE 730179
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	CHILDREN
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	3
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	TRAFFIC POLICE DIVISION HQ - SINGAPORE CITY
Police Station Address	ROAD: 10 UBI AVENUE 3 , POSTCODE: 408865 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 65470000 - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO SKETCH PLAN/POLICE REPORT

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJT786S
Vehicle Make/Model/Colour	MERCEDES BENZ / GLC200 (R18 LED)
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SLA3088E
Vehicle Make/Model/Colour	MERCEDES BENZ / E200 SEDAN AVG (R18 LED)
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF INJURED PERSON 1

Name	JERVIS SEET
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	SLU6912B
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Remedy Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the withholding of this report of the police and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**
 - (i) I understand, acknowledge, agree and consent that:
 - (i) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police) for the purposes of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law or administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
 - (ii) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (iii) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms) which may be sited outside of Singapore, for one or more of the above Purposes;
 - (iv) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
 - (v) the information so collected under (i) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders;



Tan

Policyholder's Signature
Date & Time:



[Signature]


Driver's Signature
(if driver is not the policyholder)
Date & Time:

[Signature]

Reporting Centre Personnel's Signature
Name: **SUNAIMI**
NRIC/FIN No.: **58040377A**
Date:

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On the above stated date and time, my vehicle was stationary when suddenly vehicle B came from the rear and collided on to my vehicle rear portion. Due to the impact my vehicle got pushed forward and touched vehicle C.

DECLARATION

I/We declare the foregoing particulars to be true in every respect



tan

Policyholder's Signature
Date & Time



Jey

Driver's Signature
(if driver is not the policyholder)
Date & Time

[Signature]

Reporting Centre Personnel's Signature
Name: **SUMAIMI**
NRIC/FIN No.: **58040377A**
Date:

EURO SUCCESS SERV PTE. LTD

Blk 1 Kaki Bukit 6, #02-03 Singapore 417883

TEL: 67426231

FAX: 67411019

H/P: 98289277 (AH HUAT)

Vehicle No: SLU6912B

Model: VOLKSWAGEN SCIROCCO R

not Authorised
1/5 16,000
Thangphat Attorneys
18th.

QTY	List Items	Price \$
1	FRONT BONNET	Buc 1260.20
1	FRONT BONNET LOCK	1m 130.90
1	FRONT BONNET LOGO	NF 89.95 X
1	FRONT BONNET LOCK STRIKER	NN 72.20 X
2	FRONT L-R BONNET HINGES @65	11 130.00 X
1	FRONT BONNET INSULATOR	11 201.35 X
10	FRONT BONNET INSULATOR CLIPS @4.5	11 45.00 X
1	FRONT BUMPER	80/70.11 1180.65
1	FRONT BUMPER CTR GRILLE	11 234.63 X
1	FRONT BUMPER TOW COVER	11 82.20 X
2	FRONT BUMPER LED LIGHT L-R @181.6	11 363.20 X
1	FRONT BUMPER LOWER EXTENSION	11 421.60 X
2	FRONT BUMPER FOG LAMPS L-R @273.85	11 547.70 X
2	FRONT BUMPER FOG LAMP COVER L-R @99.15	11 198.30 X
1	FRONT BUMPER SPONGE	70.11 196.62
1	FRONT BUMPER REINFORCEMENT	11 611.65
2	FRONT BUMPER SIDE RETAINERS L-R @35	11 70.00 X
2	FRONT FENDER L-R @681.5	11 1363.00 X
2	FRONT FENDER INNER SHIELD L-R @154.4	11 308.80 X
30	FRONT FENDER INNER SHIELD CLIPS @ 4.5	11 135.00 X
1	FRONT GRILLE FRAME	11 228.42
1	FRONT GRILLE BASE	11 248.92
1	FRONT GRILLE MOULDING	11 281.60 X
1	FRONT HEADLAMP L-R @891.65	11 1783.30
2	FRONT HEAD LAMP TOP BRACKET @68.5	11 137.00 X
2	FRONT HEAD LAMP LOWER BRACKET @48.6	11 97.20 X
1	FRONT SUPPORT PANEL	11 1015.00
1	FRONT SUPPORT PANEL TOP GARNISH	11 121.60 X
2	HORNS @89.5	11 179.00 X
1	AIR CON CONDENSER	11 895.60
1	AIR CON DISCHARGE PIPE	11 341.20 X
1	AIR CON SUCTION PIPE	11 315.60 X
1	AIR CLEANER INTAKE DUCT	11 102.60
1	AIR CLEANER BOX ASSY	11 441.50 X
1	ALTERNATOR	11 1265.60 X
1	AIR INTER COOLER	11 841.50 X
1	RADIATOR ASSY	11 831.10 X
1	RADIATOR TOP HOSE	11 142.20 X
1	RADIATOR BOTTOM HOSE	11 155.60 X
1	RADIATOR AUXILIARY FAN ASSY	11 899.50 X
1	EXHAUST MANIFOLD COVER	11 210.20 X
1	ENGINE MOUNTING R/H	11 281.60 X

1	ENGINE MOUNTING L/H	17	265.50	X
1	TAILGATE	solg m	1644.66	—
1	TAILGATE LOGO	nu	105.23	—
1	TAILGATE INNER LOCK	jm	147.36	—
1	TAILGATE INNER TRIM	75	187.20	—
1	TAILGATE LOCK STRIKER	17	85.65	X
1	TAILGATE W/ STRIP	7m	155.36	—
2	TAILGATE DAMPERS L-R @105.54	17	211.08	X
2	TAILLAMP L-R @388.59	3no / crn	777.18	—
2	TAILLAMP LOWER BRACKET @162.38	17	325.76	X
2	TAILLAMP PANELS @68.55	Bunt/Sec	137.10	—
1	REAR TAILGATE GLASS	stathb	800.00	—
1	REAR FENDER O/S	solg m/sec	1562.00	—
2	REAR L-R FENDER 1/4 GLASS MOULDING @780	17	1560.00	X
2	REAR FENDER INNER TOP TRIM L-R @352	o/s 75	704.00	IPC
2	REAR FENDER INNER TRIM BOARD L-R @791	o/s 75	1582.00	IPC
2	REAR FENDER WHEEL HOUSING L-R @1151	o/s solg m	2302.00	IPC
2	REAR FENDER AIR VENTS L-R @104	o/s crn	208.00	IPC
1	REAR ROOF	17	2000.00	X
2	REAR L-R splash shield @ 640	285.00	1280.00	IPC
2	REAR L-R KNUCKLE ARM @1005	17	2010.00	X
2	REAR L-R KNUCKLE ABS SENSOR @905	17	1810.00	X
2	REAR L-R KNUCKLE WHEEL BEARING @835	17	1670.00	X
2	REAR L-R DRY SUP @545	17	1090.00	X
2	REAR L-R UPPER ARM @450	17	900.00	X
2	REAR L-R TRIM ARM @495	17	990.00	X
2	REAR L-R ABSORBER MOUNTING HOUSING @320	17	640.00	X
2	REAR L-R SHOCK ABSORBER @650	17	1300.00	X
1	REAR w. abs screen wiper arm & motor 680	crn/jm	1819.00	—
1	REAR BUMPER	75	1121.24	—
2	REAR BUMPER REFLECTOR L-R @89.95	17	179.90	X
1	REAR BUMPER REINFORCEMENT	75	570.20	—
2	REAR BUMPER SIDE RETAINERS L-R @84.45	o/s crn	168.90	IPC
1	REAR BUMPER CTR GUIDE	crn	142.65	—
1	REAR END PANEL	3.0 bps	933.20	—
1	REAR END PANEL INNER MEMBER	3.0 bps	442.60	—
1	REAR END PANEL INNER TRIM	75	221.76	—
1	REAR FLOOR BOARD	7m	653.11	—
1	REAR FLOOR PANEL	crnph/bac	953.01	—
1	REAR EXHAUST INSULATOR	sec	122.60	—
1	REAR SMART KEYLESS ANTENNA	17	189.92	X
1	REAR EXHAUST MOUNTING	svl	37.20	X
TOTAL			\$52,464.16	
LESS 10%			\$5,246.41	
TOTAL			\$47,217.74	
Special Nett Items				
1	FRONT NO. PLATE WITH HOLDER	crn	60.00	40
1	AIRCON OIL	nu	65.00	30

2011.8.5.2

1	RADIATOR COOLANT
1	TAILGATE GLASS SEALANT
1	REAR NO. PLATE WITH HOLDER
1	REAR REVERSE SENSOR
1	REAR SPORT EXHAUST MUFFLER
2	REAR L-R SPORT RIM @750
1 set	REAR reverse camera

NA	60.00	X
NA	80.00	60
SAG	60.00	40
SHOPS	280.00	200
1	2000.00	X
11	1500.00	X
SHOPS	750.00	350

\$4,855.00

Labour Charges

TOWING	200.00	100
TO CHECK FRONT AND REAR ELECTRICAL WIRING	120.00	50
TO REMOVE AND REFIX TAILGATE GLASS	180.00	120
TO REMOVE AND REFIX A/C CONDENSER AND REFILL A/C GAS	200.00	100
TO REMOVE AND REFIX REAR INTERIOR TRIMS TO ASSIST REPAIR	250.00	100
TO REMOVE AND REFIX REAR EXHAUST SYSTEM	250.00	80
TO RESPRAY UNDER COATING	350.00	120
TO REMOVE AND REFIX REAR REVERSE SENSOR	150.00	50
TO RESPRAY PAINTING AND ETC	2200.00	1800
TO PANEL BEATING, CUT , WELD REMOVE AND REPLACING ABOVE PARTS	3200.00	2600

\$7,100.00

ESTIMATE PARTS AND LABOUR GRAND TOTAL

\$59,172.74

2382666

LKK Auto Consultants hence forth

15141.

1. To ensure the accuracy of the estimate, the following information must be provided by the client:

2. The estimate is based on the information provided and is subject to change without prejudice on basis of the actual condition of the vehicle.

3. The estimate is valid for 30 days from the date of issue.

4. The estimate must be reviewed and approved by the client and the insurance company.

5. The estimate is not valid if the vehicle is not in the possession of the client.

6. The estimate is not valid if the vehicle is not in the possession of the client.

7. The estimate is not valid if the vehicle is not in the possession of the client.

8. The estimate is not valid if the vehicle is not in the possession of the client.

9. The estimate is not valid if the vehicle is not in the possession of the client.

10. The estimate is not valid if the vehicle is not in the possession of the client.

Signature: _____

Date: _____

...CLAIM SUBFOLDER...(Pending for Survey Report)
























































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	06 Dec 2019 Edit Reg		06 Dec 2019 00:00 Edit Adj Rpt	S\$16,000.00 Edit Estimates	S\$16,000.00 View Rpt		Pending for Survey Report Cancel Case























































Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------























































CLAIM SUBFOLDER DETAILS				[Created by adjuster]					
Insured:	MOHAMED HANEEFA IQBAL, Co. Reg. No.: -								
Main Claimant:	TAN CHOR KOON, ID: S1431359A								
Vehicle Reg. No.:	SLU6912B	Date of Loss:	05/12/2019 09:00 - :59 [103 Months and 22 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 5212711327SG	Policy/Cover Note No.:	(Comprehensive)						
Vehicle Reg. No. (Insured):	SJT786S	Policy No. (Claimant):							
		Excess:							
Repairer:	Euro Success Services Pte Ltd (HQ) 1 KAKI BUKIT AVENUE 6 #02-03 AUTOBAY, 417883 Kaki Bukit - Tel:								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Foo, Chit Yan] Chityan.Foo@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 18/12/2019]								
ASSOCIATED MAIL RECEIVED				View All Compose Case Mail					
There are no mail for this case.									
ALL ASSOCIATED TASKS				View All Search Tasks Create New Task Complete					
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									





***SLU6912B (5212711327SG)**
[SJT786S]
TP
TAN CHOR KOON
Dec 5 2019 9:00AM
[MOHAMED HANEEFA IQBAL]
Euro Success Services Pte Ltd

<https://singapore.merimen.com/claims/index.cfm?fusebox=MTRdoc&fuseaction=dsp> d... 6/1/2020

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
				<input checked="" type="checkbox"/>
41	09/12/19 18:07	General View	 Load JPG	<input checked="" type="checkbox"/>
42	09/12/19 18:07	General View	 Load JPG	<input checked="" type="checkbox"/>
43	09/12/19 18:07	General View	 Load JPG	<input checked="" type="checkbox"/>
44	09/12/19 18:07	General View	 Load JPG	<input checked="" type="checkbox"/>
45	09/12/19 18:07	General View	 Load JPG	<input checked="" type="checkbox"/>
46	09/12/19 18:07	General View	 Load JPG	<input checked="" type="checkbox"/>
47	09/12/19 18:07	General View	 Load JPG	<input checked="" type="checkbox"/>
48	09/12/19 18:07	General View	 Load JPG	<input checked="" type="checkbox"/>
49	09/12/19 18:07	General View	 Load JPG	<input checked="" type="checkbox"/>
50	09/12/19 18:07	General View	 Load JPG	<input checked="" type="checkbox"/>
51	09/12/19 18:07	General View	 Load JPG	<input checked="" type="checkbox"/>
52	09/12/19 18:07	General View	 Load JPG	<input checked="" type="checkbox"/>
53	09/12/19 18:07	General View	 Load JPG	<input checked="" type="checkbox"/>
54	09/12/19 18:07	General View	 Load JPG	<input checked="" type="checkbox"/>
55	09/12/19 18:07	General View	 Load JPG	<input checked="" type="checkbox"/>
56	09/12/19 18:07	General View	 Load JPG	<input checked="" type="checkbox"/>
57	09/12/19 18:07	General View	 Load JPG	<input checked="" type="checkbox"/>
58	09/12/19 18:07	General View	 Load JPG	<input checked="" type="checkbox"/>
59	09/12/19 18:07	General View	 Load JPG	<input checked="" type="checkbox"/>
60	09/12/19 18:07	General View	 Load JPG	<input checked="" type="checkbox"/>
61	09/12/19 18:07	General View	 Load JPG	<input checked="" type="checkbox"/>
62	09/12/19 18:07	General View	 Load JPG	<input checked="" type="checkbox"/>
63	09/12/19 18:07	General View	 Load JPG	<input checked="" type="checkbox"/>
64	09/12/19 18:07	General View	 Load JPG	<input checked="" type="checkbox"/>
65	09/12/19 18:07	General View	 Load JPG	<input checked="" type="checkbox"/>
66	09/12/19 18:07	General View	 Load JPG	<input checked="" type="checkbox"/>
67	09/12/19 18:07	General View	 Load JPG	<input checked="" type="checkbox"/>
68	09/12/19 18:07	General View	 Load JPG	<input checked="" type="checkbox"/>
69	09/12/19 18:07	General View	 Load JPG	<input checked="" type="checkbox"/>
70	09/12/19 18:07	General View	 Load JPG	<input checked="" type="checkbox"/>
71	09/12/19 18:07	General View	 Load JPG	<input checked="" type="checkbox"/>
72	09/12/19 18:07	General View	 Load JPG	<input checked="" type="checkbox"/>
73	09/12/19 18:07	General View	 Load JPG	<input checked="" type="checkbox"/>
74	09/12/19 18:07	General View	 Load JPG	<input checked="" type="checkbox"/>
75	09/12/19 18:08	General View	 Load JPG	<input checked="" type="checkbox"/>
76	09/12/19 18:08	General View	 Load JPG	<input checked="" type="checkbox"/>
77	09/12/19 18:08	General View	 Load JPG	<input checked="" type="checkbox"/>
78	09/12/19 18:08	General View	 Load JPG	<input checked="" type="checkbox"/>
79	09/12/19 18:08	General View	 Load JPG	<input checked="" type="checkbox"/>
80	09/12/19 18:08	General View	 Load JPG	<input checked="" type="checkbox"/>
81	09/12/19 18:08	General View	 Load JPG	<input checked="" type="checkbox"/>
82	09/12/19 18:08	General View	 Load JPG	<input checked="" type="checkbox"/>
83	09/12/19 18:08	General View	 Load JPG	<input checked="" type="checkbox"/>
84	09/12/19 18:08	General View	 Load JPG	<input checked="" type="checkbox"/>
85	09/12/19 18:08	General View	 Load JPG	<input checked="" type="checkbox"/>
86	09/12/19 18:08	General View	 Load JPG	<input checked="" type="checkbox"/>
87	09/12/19 18:08	General View	 Load JPG	<input checked="" type="checkbox"/>
88	09/12/19 18:08	General View	 Load JPG	<input checked="" type="checkbox"/>
89	09/12/19 18:08	General View	 Load JPG	<input checked="" type="checkbox"/>
90	09/12/19 18:08	General View	 Load JPG	<input checked="" type="checkbox"/>
91	09/12/19 18:08	General View	 Load JPG	<input checked="" type="checkbox"/>
92	09/12/19 18:08	General View	 Load JPG	<input checked="" type="checkbox"/>
93	09/12/19 18:08	General View	 Load JPG	<input checked="" type="checkbox"/>
94	09/12/19 18:08	General View	 Load JPG	<input checked="" type="checkbox"/>
95	09/12/19 18:08	General View	 Load JPG	<input checked="" type="checkbox"/>

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
96	09/12/19 18:08	General View	 Load JPG	<input checked="" type="checkbox"/>
97	09/12/19 18:08	General View	 Load JPG	<input checked="" type="checkbox"/>
98	09/12/19 18:08	General View	 Load JPG	<input checked="" type="checkbox"/>
99	09/12/19 18:08	General View	 Load JPG	<input checked="" type="checkbox"/>
100	09/12/19 18:08	General View	 Load JPG	<input checked="" type="checkbox"/>
101	09/12/19 18:08	General View	 Load JPG	<input checked="" type="checkbox"/>
102	09/12/19 18:08	General View	 Load JPG	<input checked="" type="checkbox"/>
103	09/12/19 18:08	General View	 Load JPG	<input checked="" type="checkbox"/>
104	09/12/19 18:08	General View	 Load JPG	<input checked="" type="checkbox"/>
105	09/12/19 18:08	General View	 Load JPG	<input checked="" type="checkbox"/>
106	09/12/19 18:08	General View	 Load JPG	<input checked="" type="checkbox"/>
107	09/12/19 18:08	General View	 Load JPG	<input checked="" type="checkbox"/>
108	09/12/19 18:08	General View	 Load JPG	<input checked="" type="checkbox"/>
109	09/12/19 18:08	General View	 Load JPG	<input checked="" type="checkbox"/>
110	09/12/19 18:08	General View	 Load JPG	<input checked="" type="checkbox"/>
111	09/12/19 18:08	General View	 Load JPG	<input checked="" type="checkbox"/>
112	09/12/19 18:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
113	09/12/19 18:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
114	09/12/19 18:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
115	09/12/19 18:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
116	09/12/19 18:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
117	09/12/19 18:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
118	09/12/19 18:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
119	09/12/19 18:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
120	09/12/19 18:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
121	09/12/19 18:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
122	09/12/19 18:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
123	09/12/19 18:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
124	09/12/19 18:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
125	09/12/19 18:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
126	09/12/19 18:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
127	09/12/19 18:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
128	09/12/19 18:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
129	09/12/19 18:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
130	09/12/19 18:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
131	09/12/19 18:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
132	09/12/19 18:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
133	09/12/19 18:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
134	09/12/19 18:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
135	09/12/19 18:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
136	09/12/19 18:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
137	09/12/19 18:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
138	09/12/19 18:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
139	09/12/19 18:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
140	09/12/19 18:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
141	09/12/19 18:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
142	09/12/19 18:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
143	09/12/19 18:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
144	09/12/19 18:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
145	09/12/19 18:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
146	09/12/19 18:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
147	09/12/19 18:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
148	09/12/19 18:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
149	09/12/19 18:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
150	09/12/19 18:10	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
151	09/12/19 18:10	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
152	09/12/19 18:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
153	09/12/19 18:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
154	09/12/19 18:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
155	09/12/19 18:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
156	09/12/19 18:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
157	09/12/19 18:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
158	09/12/19 18:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
159	09/12/19 18:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
160	09/12/19 18:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
161	09/12/19 18:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
162	09/12/19 18:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
163	09/12/19 18:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
164	09/12/19 18:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
165	09/12/19 18:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
166	09/12/19 18:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
167	09/12/19 18:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
168	09/12/19 18:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
169	09/12/19 18:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
170	09/12/19 18:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
171	09/12/19 18:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
172	09/12/19 18:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
173	09/12/19 18:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
174	09/12/19 18:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
175	09/12/19 18:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
176	09/12/19 18:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
177	09/12/19 18:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
178	09/12/19 18:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
179	09/12/19 18:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
180	09/12/19 18:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
181	09/12/19 18:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
182	09/12/19 18:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
183	09/12/19 18:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
184	09/12/19 18:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
185	09/12/19 18:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
186	09/12/19 18:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
187	09/12/19 18:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
188	09/12/19 18:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
189	09/12/19 18:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
190	09/12/19 18:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
191	09/12/19 18:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
192	09/12/19 18:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
193	09/12/19 18:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
194	09/12/19 18:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
195	09/12/19 18:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
196	09/12/19 18:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
197	09/12/19 18:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
198	09/12/19 18:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
199	09/12/19 18:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
200	09/12/19 18:11	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
201	09/12/19 18:11	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
202	09/12/19 18:11	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
203	09/12/19 18:11	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
204	09/12/19 18:11	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
205	09/12/19 18:11	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
206	09/12/19 18:11	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
207	09/12/19 18:11	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>

Video				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
208	09/12/19 18:11	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
209	09/12/19 18:11	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
210	09/12/19 18:11	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
211	09/12/19 18:11	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	10/12/19 11:03	TP GIA REPORT		Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
1	10/12/19 11:14	OI GIA REPORT		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>				
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>				

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIG19021545/UQF3E2

Date: 06/01/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant

Vehicle No : SLU6912B

Insured Vehicle No : SJT786S

Date of Loss: 05/12/2019

Nature of Claim: TP

Claim No: 5212711327SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLU6912B

Make & Model: VOLKSWAGEN SCIROCCO R, 2.0 L AT 137RX3 (A)

Engine No: CDL045617

Reg. Date: 13/04/2011 (Man. Year: 2011)

Chassis No: WWZZZ13ZBV026568

Colour: White

Odometer: 131756 km

Engine Capacity: 1984 cc

Market Value/New Car

N/A

Price:

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/40Z R18

Rear Tyre Size:

245/40Z R18

Front Left Side: Goodyear 6 mm

Rear Left Side:

Goodyear 6 mm

Front Right Side: Goodyear 6 mm

Rear Right Side:

Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	52,072.74	18,806.67	33,266.07	63.88
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,100.00	5,120.00	1,980.00	27.89
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	59,172.74	23,926.67	35,246.07	59.56
Approved Total (Overridden) (S\$)		16,000.00		
Nett Amount (S\$)	59,172.74	16,000.00	43,172.74	72.96

INSPECTION

Date of Assignment: 06/12/2019

Date Inspected: 09/12/2019 Inspected At:

Euro Success Services Pte Ltd (HQ)
1 KAKI BUKIT AVENUE 6 #02-03
AUTOBAY
Singapore 417883

Estimated Period of Repair: 18.0 days

Adjuster: MARCUS CHUA

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Buckled	1,260.20 FL	*1,260.20 FL
2	1		*FRONT BONNET LOCK	Twisted	130.90 FL	*130.90 FL
3	1		*FRONT BONNET LOGO	Not fitted	89.95 FL	*- FL
4	1		*FRONT BONNET LOCK STRIKER	Not Necessary	72.20 FL	*- FL
5	2		*FRONT L-R BONNET HINGE	Not Necessary	130.00 FL	*- FL
6	1		*FRONT BONNET INSULATOR	Not Necessary	201.35 FL	*- FL
7	10		*FRONT BONNET INSULATOR CLIPS	Not Necessary	45.00 FL	*- FL
8	1		*FRONT BUMPER	Dented / Torn	1,180.65 FL	*1,180.65 FL
9	1		*FRONT BUMPER CTR GRILLE	Not Necessary	234.63 FL	*- FL
10	1		*FRONT BUMPER TOW COVER	Not Necessary	82.20 FL	*- FL
11	2		*FRONT BUMPER LED LIGHT L-R	Not Necessary	363.20 FL	*- FL
12	1		*FRONT BUMPER LOWER EXTENSION	Not Necessary	421.60 FL	*- FL
13	2		*FRONT BUMPER FOG LAMPS L-R	Not Necessary	547.70 FL	*- FL
14	2		*FRONT BUMPER FOG LAMP COVER L-R	Not Necessary	198.30 FL	*- FL
15	1		*FRONT BUMPER SPONGE	Torn	196.62 FL	*196.62 FL
16	1		*FRONT BUMPER REINFORCEMENT	Dented	611.65 FL	*611.65 FL
17	2		*FRONT BUMPER SIDE RETAINERS L-R	Not Necessary	70.00 FL	*- FL
18	2		*FRONT FENDER L-R	Repair	1,363.00 FL	*- FL
19	1		*FRONT FENDER INNER SHIELD CLIPS (30PCS)	Not Necessary	135.00 FL	*- FL
20	1		*FRONT GRILLE FRAME	Cracked	228.42 FL	*228.42 FL
21	1		*FRONT GRILLE BASE	Cracked	248.92 FL	*248.92 FL
22	1		*FRONT GRILLE MOULDING	No such part	281.60 FL	*- FL
23	1		*FRONT HEADLAMP L-R	N/S Cracked	1,783.30 FL	*891.65 FL
24	2		*FRONT HEAD LAMP TOP BRACKET	Not Necessary	137.00 FL	*- FL
25	2		*FRONT HEAD LAMP LOWER BRACKET	Not Necessary	97.20 FL	*- FL
26	1		*FRONT SUPPORT PANEL	Cracked	1,015.00 FL	*1,015.00 FL
27	1		*FRONT SUPPORT PANEL TOP GARNISH	Not Necessary	121.60 FL	*- FL
28	2		*HORNS	Not Necessary	179.00 FL	*- FL
29	1		*AIR CON CONDENSER	Bent / Punctured	895.60 FL	*895.60 FL
30	1		*AIR CON DISCHARGE PIPE	Not Necessary	341.20 FL	*- FL
31	1		*AIR CON SUCTION PIPE	Not Necessary	315.60 FL	*- FL
32	1		*AIR CLEANER INTAKE DUCT	Cracked	102.60 FL	*102.60 FL
33	1		*AIR CLEANER BOX ASSY	Not Necessary	441.50 FL	*- FL
34	1		*ALTERNATOR	Not Necessary	1,265.60 FL	*- FL
35	1		*AIR INTER COOLER	Not Necessary	841.50 FL	*- FL
36	1		*RADIATOR ASSY	Serviceable	831.10 FL	*- FL
37	1		*RADIATOR TOP HOSE	Not Necessary	142.20 FL	*- FL
38	1		*RADIATOR BOTTOM HOSE	Not Necessary	155.60 FL	*- FL
39	1		*EXHAUST MANIFOLD COVER	Not Necessary	210.20 FL	*- FL
40	1		*ENGINE MOUNTING R/H	Not Necessary	281.60 FL	*- FL
41	1		*ENGINE MOUNTING L/H	Not Necessary	265.50 FL	*- FL
42	1		*TAILGATE	Badly Dented	1,644.66 FL	*1,644.66 FL
43	1		*TAILGATE LOGO	Necessary	105.23 FL	*105.23 FL
44	1		*TAILGATE INNER LOCK	Jammed	147.36 FL	*147.36 FL
45	1		*TAILGATE INNER TRIM	Distorted	187.20 FL	*187.20 FL
46	1		*TAILGATE LOCK STRIKER	Not Necessary	85.65 FL	*- FL
47	1		*TAILGATE W/STRIP	Twisted	155.36 FL	*155.36 FL
48	2		*TAILGATE DAMPERS L-R	Not Necessary	211.08 FL	*- FL
49	2		*TAILLAMP L-R	Broken / Cracked	777.18 FL	*777.18 FL
50	2		*TAILLAMP LOWER BRACKET	Not Necessary	325.76 FL	*- FL
51	2		*TAILLAMP PANELS	Bent / Buckled	137.10 FL	*137.10 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
52	1		*REAR TAILGATE GLASS	Shattered	800.00 FL	*800.00 FL
53	1		*REAR FENDER O/S	Badly Dented / Buckled	1,562.00 FL	*1,562.00 FL
54	2		*REAR L-R FENDER 1/4 GLASS MOULDING	Not Necessary	1,560.00 FL	*- FL
55	1		*REAR FENDER INNER TOP TRIM L-R	O/S Distorted	704.00 FL	*352.00 FL
56	1		*REAR FENDER INNER TRIM L-R	O/S Distorted	1,582.00 FL	*466.00 FL
57	1		*REAR FENDER WHEEL HOUSING L-R	O/S Badly Dented	2,302.00 FL	*1,151.00 FL
58	1		*REAR FENDER AIR VENTS L-R	O/S Cracked	208.00 FL	*104.00 FL
59	1		*REAR ROOF	Repair	2,000.00 FL	*- FL
60	1		*REAR L-R SPLASH SHIELD	O/S Torn	1,280.00 FL	*285.00 FL
61	2		*REAR L-R KNUCKLE ARM	Not Necessary	2,010.00 FL	*- FL
62	2		*REAR L-R KNUCKLE ABS SENSOR	Not Necessary	1,810.00 FL	*- FL
63	2		*REAR L-R KNUCKLE WHEEL BEARING	Not Necessary	1,670.00 FL	*- FL
64	2		*RAER L-R DRY SUP	Not Necessary	1,090.00 FL	*- FL
65	2		*REAR L-R UPPER ARM	Not Necessary	900.00 FL	*- FL
66	2		*REAR L-R TRIM ARM	Not Necessary	990.00 FL	*- FL
67	2		*REAR L-R ABSORBER MOUNTING HOUSING	Not Necessary	640.00 FL	*- FL
68	2		*REAR L-R SHOCK ABSORBER	Not Necessary	1,300.00 FL	*- FL
69	1		*SET REAR WINDSCREEN WIPER ARM & MOTOR	Cracked / Jammed	1,819.00 FL	*680.00 FL
70	1		*REAR BUMPER	Distorted	1,121.24 FL	*1,121.24 FL
71	2		*REAR BUMPER REFLECTOR L-R	Not fitted	179.90 FL	*- FL
72	1		*REAR BUMPER REINFORCEMENT	Distorted	570.20 FL	*570.20 FL
73	1		*REAR BUMPER SIDE RETAINERS L-R	O/S Cracked	168.90 FL	*84.45 FL
74	1		*REAR BUMPER CTR GUIDE	Cracked	142.65 FL	*142.65 FL
75	1		*REAR END PANEL }	Badly Dented	933.20 FL	*933.20 FL
76	1		*REAR END PANEL INNER MEMBER }		442.60 FL	*- FL
77	1		*REAR END PANEL INNER TRIM	Distorted	221.76 FL	*221.76 FL
78	1		*REAR FLOOR BOARD	Torn	653.11 FL	*653.11 FL
79	1		*REAR FLOOR PANEL	Crumpled / Buckled	953.01 FL	*953.01 FL
80	1		*REAR EXHAUST INSULATOR	Bent	122.60 FL	*122.60 FL
81	1		*REAR SMART KEYLESS ANTENNA	Not Necessary	189.92 FL	*- FL
82	1		*REAR EXHAUST MOUNTING	Serviceable	37.20 FL	*- FL
83	1		*FRONT NO. PLATE WITH HOLDER	Cracked	60.00 FS	*40.00 FS
84	1		*AIRCON OIL	Necessary	65.00 FS	*30.00 FS
85	1		*RADIATOR COOLANT	Not Necessary	60.00 FS	*- FS
86	1		*TAILGATE GLASS SEALANT	Necessary	80.00 FS	*40.00 FS
87	1		*REAR NO. PLATE WITH HOLDER	Broken	60.00 FS	*40.00 FS
88	1		*REAR REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS
89	1		*REAR SPORT EXHAUST MUFFLER	Repair	2,000.00 FS	*- FS
90	2		*REAR L-R SPORT RIM	Not Necessary	1,500.00 FS	*- FS
91	1		*SET REAR REVERSE CAMERA	Shorted	750.00 FS	*350.00 FS
92	2		*FRONT FENDER INNER SHIELD L-R	Not Necessary	308.80 FL	*- FL
93	1		*RADIATOR AUXILIARY FAN ASSY	Not Necessary	899.50 FL	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) **57,319.16** **20,818.52**
- List Item Discount on L Items 10.00/10.00% (\$\$) 5,246.42 2,011.85

Total Parts (\$\$) **52,072.74** **18,806.67**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING	New	200.00	100.00
2	TO CHECK FRONT AND REAR ELECTRICAL WIRING	New	120.00	50.00
3	TO REMOVE AND REFIX TAILGATE GLASS	New	180.00	120.00
4	TO REMOVE AND REFIX REAR INTERIOR TRIMS TO ASSIST REPAIR	New	250.00	100.00
5	TO REMOVE AND REFIX REAR EXHAUST SYSTEM	New	250.00	80.00
6	TO RESPRAY UNDER COATING	New	350.00	120.00
7	TO REMOVE AND REFIX REAR REVERSE SENSOR	New	150.00	50.00
8	TO RESPRAY PAINTING AND ETC	New	2,200.00	1,800.00
9	TO PANEL BEATING, CUT, WELD REMOVE AND REPLACING ABOVE PARTS	New	3,200.00	2,600.00
10	TO REMOVE AND REFIX A/C CONDENSER AND REFILL A/C GAS	New	200.00	100.00
Gross Labour Cost (S\$)			7,100.00	5,120.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >