

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHC 8506U

DATE 5/12/2019 16:00

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Rear Bumper <i>x(R)</i>			\$ 553.00	
	Rear Bumper Clip 10 pcs <i>xun</i>			\$ 22.00	
	Rear Bumper Bracket <i>xun</i>		\$ 35.60	\$ 71.20	
	Rear Bumper Under Cover <i>xun</i>			\$ 228.00	
	Rear Bumper Reflector Lamp (RH) <i>xun</i>			\$ 30.60	
	SUB TOTAL			\$ 904.80	
	LESS 20%			\$ 180.96	
	DISCOUNTED TOTAL			\$ 723.84	
	Rear Bumper Reverse Sensor <i>xun</i>			\$ 135.70	Nett
	Rear Bumper Rubber Mat <i>xun</i>			\$ 50.00	Nett
				\$ 185.70	
	Labour Charge				
	Panel Beating			\$ 350.00	<i>\$240</i>
	Spray Painting Charge			\$ 250.00	<i>\$200</i>
	Wiring Charge			\$ 50.00	<i>xm</i>
	Remove/Refix Reverse Sensor			\$ 80.00	<i>xm</i>
	TOTAL LABOUR			\$ 730.00	
	ESTIMATE TOTAL			\$ 1,639.54	
<div style="border: 1px solid black; padding: 5px; margin: 10px;"> <p>LKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company <p>Acknowledged by Repairer Signature: _____ Date: _____</p> </div>					
<p>This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.</p>					

(LKK)

BIG-Ju

Lgum

Parasurama@LKKauto.com
\$ 6/12/19 12:00h
2 repair jobs
as + repair photo
(15)