

趙 源 摩 哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

To: India International Insurance Pte Ltd

Accident Date : 03.12.2019

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Third Party

Acknowledged by Repairer

Signature:

Date:

Date:

05.12.2019

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货 名 DESCRIPTION	单 价 Unit Price	银 Amount 额 \$ cts.
Estimate Cost of Repair to "Nissan Sylphy" Reg. No. SKQ772K Claiming Against Your Insured Veh. No. SHC2644T			
1pc	Rear Bumper	2.60	574.3 687.00 N
12pcs	Rear Bumper Clips		✓ 31.20 N
1pc	Rear Bumper Bracket RH		78.5 96.10 N
1pc	Rear Bumper Sponge (Center)		78.6 146.00 N
1pc	Rear Bumper Sponge (Side)		68 85.10 N
1pc	Rear Bumper Reinforcement		X 385.00 N
1pc	Rear Bumper Reflector RH		45 102.00 N
1pc	Rear Bumper Auto Boot Sensor		155.9 245.00 N
1pc	Boot Emblem		45 110.00 N
1pc	Boot Badge Sylphy		42 95.60 N
1pc	Boot Xtronic CVT		45.6 89.80 N
1pc	Boot Outer Lower Moulding		120 350.00 N
	Less 10%	1284.1	2,422.80
		1155.69	242.28
			2,180.52
1pc	Boot Outer Lower Moulding		X 165.00 SN
1pc	Rear Bumper Reverse Sensor		200 280.00 SN
	To Conduct Front Electrical Check, Replace Reverse Sensor, Module, Rewiring etc		40 120.00
	Labour Charge - Panel Beating, Repairing Of Boot, End Panel, and Parts Replacement		200 450.00
	To Spray Paint Affected Areas	640	400 600.00
	3 Days. p/p before paint photos. Gao Qrp. 05/12/19.	Total :	3,795.52
			1995.69