

ASS. REC. BY:

REF: CS/CT119021571/GBF3065 Special Instruction:

SURVIVOR: GA

ASSIGNMENT (Office)

From (Person): Tan Kah Leong of CT1 Date/Time: 06/12/19 @ 2.07pm

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SMJ 4081H Insured: GBF 73065

at Workshop m/s KAH MOTOR Tel: 90721766 Ruben

of 15 UBI RD 4

Policy No: Claim No: SNM19D205791

Sum Insured: Excess:

Make of Veh: D.O.A. 04/12/19
(Client's Record)

CA / REV / REP. / REV 24 HRS my 9.12.2019

Date/Time: 6.12.19 2.15p.m. Person Contacted: Joshuruben H.O.D. Endorsement:

Vehicle IN OUT

Date/Time	Action/Instruction (✓) Estimate
	SMJ 4081H-X
	GBF 73065-X
	Part by Part \$33,127.38 (Red: 7655.15; 187%)

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / ☒ WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

22 days

Res.:

Yes or No

Lum Sum:

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SMJ 4081 H

Regn:

04 Mar 2019

Type: ☒ M.Cat / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Jazz 1.3 c.c 1318

Colour:

Blue

A/C:

Insured / Std / NI / NA

Sp. Reading

21387

T/Radio:

Insured / Std / NI / NA

Engl/No:

C/No:

JHMGK3850K5207772

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

185/65 R15

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Habilead

Front

Rear

R/Bal.

7

mm

R/Bal.

7

mm

L/Bal.

7

mm

L/Bal.

7

mm

D.O.A.

D.O.I.

09-12-19

Survey held at

w/s

Des. of Damages ☒ Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

COT: 26228

Net = 36K

New car: 74K.

30/1/2020

RECEIVED 30 JAN 2020

Date/Time, File Pass to?

30/1/2020 Typist

Date/Time, File Return to?

9

Report Format

Long Sum / Update 33.121.38



Prel. Report



Final Report

Days Of Repair: 22

Resurvey No. of Trip: 2

Add Fee:



Site Insp (\$)



Interview (\$)



Tech. Insp (\$)



Material (\$)

Survey Fee:

Transportation:

S + RS \$

Photos

Notes

TOTAL

220

220

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	05 Dec 2019		06 Dec 2019 14:11 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:									
Main Claimant: NEO CHIN CHYE , ID: S7308927A									
Vehicle Reg. No.: SMJ4081H		Date of Loss:	04/12/2019 21:00 - :59						
Claim Type: TP / SNM19D205791C02		Policy/Cover Note No.:	DMCVSN30106419000						
Vehicle Reg. No. (Insured): GBF7306S		Policy No. (Claimant):	19-MS001788-R00						
		Excess:	S\$350.00						
Repairer: Kah Motor Co Sdn Bhd (Ubi) 15 Ubi Road 4, 408610 Ubi - Tel: 68465671									
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Tan Kah Leong - 63896193]									
Claimant's Insurer: Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 17/12/2019]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
 ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Summer Lee (LKK Auto)

From: Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>
Sent: Friday, 6 December, 2019 2:07 PM
To: Jeshurueben Rao Thomas; assignments
Subject: RE: OUR REF: SNM19D205791/GBF7306S/TKL - DIRECT SETTLEMENT OF VEHICLE NO.SMJ4081H AGAINST GBF7306S (CNT)

WITHOUT PREJUDICE

Dear Rueben,

We refer to your email dated 06.12.2019.

We will be assigning M/s LKK Auto Consultants to survey your client's vehicle on a without prejudice basis.

Aside to LKK,

Please refer to the email below & proceed to survey the third party vehicle.

Thank you.

Regards

Tan Kah Leong
Assistant Executive
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #15-00 Springleaf Tower Singapore 079909
DID: (65) 6389 6193 | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Jeshurueben Rao Thomas [mailto:jeshurueben@honda.com.sg]
Sent: Friday, December 6, 2019 2:00 PM
To: Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>
Subject: RE: OUR REF: SNM19D205791/GBF7306S/TKL - DIRECT SETTLEMENT OF VEHICLE NO.SMJ4081H AGAINST GBF7306S (CNT)

Dear Kah Leong,

We would like to select the surveyor as below:-

5. XING QUO QIANG

Thank You

Warmest Regards

Jeshurueben Rao Thomas (Rueben)

Bodyshop Service Advisor
Kah Motor Body Repair Centre
15, Ubi Road 4
Singapore 408610
Tel : 68465672
Hp : 90721766

From: Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>
Sent: Friday, 6 December 2019 1:49 PM
To: Jeshurueben Rao Thomas <jeshurueben@honda.com.sg>
Subject: RE: OUR REF: SNM19D205791/GBF7306S/TKL - DIRECT SETTLEMENT OF VEHICLE NO.SMJ4081H AGAINST GBF7306S (CNT)

Without Prejudice

Dear Rueben,

We refer to your email below.

Please see attached and let us know if you agree with SJE.

Thank you.

Regards

Tan Kah Leong
Assistant Executive
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #15-00 Springleaf Tower Singapore 079909
DID: (65) 6389 6193 | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Claims Dept of CTI
Sent: Thursday, December 5, 2019 5:47 PM
To: Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>; Chee So Chow <sochow.chee@sg.cntaiping.com>; jeshurueben@honda.com.sg
Subject: OUR REF: SNM19D205791/GBF7306S/TKL - DIRECT SETTLEMENT OF VEHICLE NO.SMJ4081H AGAINST GBF7306S (CNT)

Dear Kah Leong,

Please conduct PRS for SMJ4081H.

Note: officer in charge – Kah Leong 63896193.

***** Kindly quote our reference number when replying.**

Regards,

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #15-00 Springleaf Tower Singapore 079909
T: (65) 63896116 | F: (65) 62247175

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Jeshurueben Rao Thomas [<mailto:jeshurueben@honda.com.sg>]
Sent: Thursday, 5 December, 2019 4:22 PM
To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>
Subject: DIRECT SETTLEMENT OF VEHICLE NO.SMJ4081H AGAINST GBF7306S (CNT)

To The Officer In Charge,

Please Refer The Above Attachment For Your Reference.

Kindly Help To Arrange Surveyor To Survey This Vehicle SMJ4081H. *VEHICLE IS IN*

Your Insured vehicle number is GBF7306S, Accident Date 04/12/2019.

Thank You

Warmest Regards

Jeshurueben Rao Thomas (Rueben)
Bodyshop Service Advisor
Kah Motor Body Repair Centre
15, Ubi Road 4
Singapore 408610
Tel : 68465672
Hp : 90721766



Confidential Note: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you.

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>



Confidential Note: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you.

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	05/12/2019 13:52
Date Of Accident	04/12/2019 21:30
Exact Location Of Accident	PIE TOWARDS CTE EXIT (LAMPPOST 665F)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMJ4081H
Insured/Policyholder	
Name Of Registered Owner	NEO CHIN CHYE
NRIC No	S7308927A
Email Address	JIM.NEO@SG.MCD.COM
Mobile Phone No	(LOCAL) +65-91881838
Alternative Phone No	OFFICE-91881838

Vehicle Particulars

Manufacturer	HONDA
Model	JAZZ-1.3 LX (GE6) (A)
Exact Purpose for which vehicle was being used at time of accident	GOING HOME
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	TOKIO MARINE INSURANCE SINGAPORE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	19-MS001788-R00
Cover Note Number	

Driver

Name of Driver	NEO CHIN CHYE
NRIC No	S7308927A
Date Of Birth	11/03/1973
Occupation	INDOOR
Date Of Driving Pass	08/03/2002
Driving Experience	17 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91881838
Fax Number	
Contact Number	OFFICE-91881838
Email Address	JIM.NEO@SG.MCD.COM

Address	APT BLK 503B CANBERRA LINK #11-23
Postcode	752503
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	- - -
Insurance Company of Driver's Own Vehicle	- - -

General information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	3
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	3
Passenger 1	NAME: : WANG XIUMEI GENDER: : FEMALE
Passenger 2	NAME: : LOH YUANSAN GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHED STATEMENT - THIRD PARTY DIRECT SETTLEMENT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBF7306S
Vehicle Make/Model/Colour	TOYOTA/BLUE
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	NAGAMUTHU RAJAKUMAR
NRIC/Passport Number	G847653T
Contact Number	85233348
Address	
Postcode	

Insurance Company Name

CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

SKB1988C

Vehicle Make/Model/Colour

AUDI/BLACK

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

CHONG WEE LEE

NRIC/Passport Number

S7510608D

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan Pg. 1

Vehicle Number: SMJ 4081 H

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)** I understand, acknowledge, agree and consent that:
 - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
 - (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
 - (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time: 5/12/19 12:32 hr

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name

RHC/TPN No.:

Sketch Plan Pg. 2

Vehicle Number: SMJ 4081 H.

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 04/12/2019, At About 9:30pm. I WAS TRAVELLING ALONG PIE, HEADING TOWARDS CTE, WHEN I WAS AT THE EXTREME LEFT LANE, TRAFFIC IN FRONT SLOW DOWN TO A STOP. I SLOW DOWN ALMOST TO A STOP. SUDDENLY A LADY VEHICLE NO. GBF7306S CAME FROM THE BACK AND HIT MY VEHICLE AT THE REAR PORTION. THE IMPACT CAUSED MY VEHICLE TO PUSH FORWARD AND HIT INTO VEHICLE NO. SKB1982C.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time: 5/12/19. 12:32h.

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: [Signature]
NRIC/FIN No:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	927A
Vehicle Details	
Vehicle No.:	SMJ4081H
Vehicle to be Exported:	No
Intended Deregistration Date:	09 Dec 2019
Vehicle Make:	HONDA
Vehicle Model:	JAZZ 1.3 CVT
Primary Colour:	Blue
Manufacturing Year:	2019
Engine No.:	L13B14100238
Chassis No.:	JHMGK3850KS207772
Maximum Power Output:	73.0 kW (97 bhp)
Open Market Value:	\$15,963.00
Original Registration Date:	04 Mar 2019
First Registration Date:	04 Mar 2019
Transfer Count:	0
Actual ARF Paid:	\$5,963.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	03 Mar 2029
PARF Rebate Amount:	\$4,472.00
Intended COE Rebate Details	
COE Expiry Date:	03 Mar 2029
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$23,568.00
COE Rebate Amount:	\$21,756.00
Total Rebate Amount:	\$26,228.00

The information contained herein is correct as at 09 Dec 2019

OK

▶ Honda Jazz Used Vehicle List (6 vehicles)

Car Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Company	Availabl
Honda Jazz 1.3A	\$63,800	\$6,600 /yr	25-Feb-2019	1,318 cc	-	Pure Motors Pte Ltd	Availabl

1.98% Promo Interest. 1 Owner Only. As Good As New Car. 5 Years Unlimited Mileage Warranty By Kah Motors. Flexible Bank/In House Loan Available, 100% Loan Approval. Please Visit/Call Us Now For Further...

Office No. - 64633343

Reovin Soh - 91002154 | Gavin Tan - 86063619

Honda Jazz 1.3A LX (OPC)	\$52,000	\$5,270 /yr	03-Apr-2019	1,318 cc	4,500 km	Euro Performance Asia Pte Ltd	Availabl
--------------------------	----------	-------------	-------------	----------	----------	-------------------------------	----------

Kah Motors Unit. 5 Years Unlimited Mileage Warranty. 1 More Free Servicing. Fully Serviced And Maintained By Agent. Condition And Mileage As Good As New. Always Park Under Shelter. Trade In And Hig...

Office No. - 65330588 / 85009000

Sindy - 90602839 | Braden - 81501500 | Felix - 90906655

Honda Jazz 1.5A RS	\$75,800	\$7,130 /yr	16-May-2019	1,498 cc	14,000 km	First CarMart Motor	Availabl
--------------------	----------	-------------	-------------	----------	-----------	---------------------	----------

1 Owner 1.5 A Jazz From Kah Motor! Fully Serviced By Kah Motors Workshop With 5 Years Warranty. Very Well Taken Care. Fuel Efficient A Responsive Drive, Like New Condition. Great Buy / Saving! Plea...

Office No. - 67420070

Leslie Chong - 97431381 | Sebastian Yeo - 97477566

Honda Jazz 1.3A LX	\$67,800	\$6,880 /yr	17-May-2019	1,318 cc	1,740 km	Dickson Automobile	Availabl
--------------------	----------	-------------	-------------	----------	----------	--------------------	----------

We Provide Immediate Transfer For A Peace Of Mind, Huge Saving \$6,200 From New Car, Agent Warranty Till 5/2024, 3 Years Free Servicing Available, Road Tax Till 5/2020, Super Low Mileage, Smell & Feel ...

Office No. - 68447667

Ricky Eng - 91853390 | Grace Lua - 83946026 | Tank Ong - 85265670

Honda Jazz 1.3A	\$69,696	\$6,960 /yr	01-Jul-2019	1,318 cc	5,624 km	Karz Automobile & Leasing Pte Ltd	Availabl
-----------------	----------	-------------	-------------	----------	----------	-----------------------------------	----------

5 Years Unlimited Mileage Warranty, Huge Saving \$5,200 From New Car, Agent Warranty Till 7/2024, 3 Years Free Servicing Available, Super Low Mileage, Smell & Feel Exactly Like A Brand New Car, Facelifted Mo...

Office No. - -

Ryan - 87775736 | Sam - 88085168 | Roy - 87557531 | Vince - 87429379

Honda Jazz 1.3A	\$51,888	\$4,980 /yr	17-Sep-2019	1,318 cc	-	Automedic Holdings	Availabl
-----------------	----------	-------------	-------------	----------	---	--------------------	----------

Kah Motor Unit. 1 Owner. 5 Years Unlimited Mileage Warranty. Loan/Trade In Available. Call Us Now To Arrange A Viewing Appointment.

Office No. - 62843558

Daniel - 93802853 | Jack Chin - 98161909 | Tham - 87980670

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale even for COE cars, OPC cars, vans, trucks, hybrid cars, sports cars or station wagons. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. We have new car dealers comprising parallel importers, authorized car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions, and also motoring advice, car reviews & car news on the latest models. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

© 2004-2019 sgCarMart. All rights reserved.

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

SST Reg No: M200050223

Company Ref. No.: S60FC1380G

Customer	: CHINA TAIPING INSURANCE (S'PORE) PTE	Document No.	: SQT19005247	Page	1
	3 ANSON ROAD #16-00	Date	: 5. Dec 2019		
	SPRINGLEAF TOWER	Customer No.	: WZC008		
	SINGAPORE 079909	Svc Advisor	: RUEBEN THOMAS		
Registration No	: SMJ4081H	Engine No	: L13B14100238		
Chassis No	: JHMGK3850KS207772	Date Time	: 5. Dec 2019 10:03:09 AM		
Model	: JAZZ 1.3LXR CVT 19YM (EURO 6)	Surveyor Name	:		
Owner's Name	: NEO CHIN CHYE	Survey Date	:		
Ins Policy No.	:	Authorisation Date	:		
Date of Accident	: 4/12/2019				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount Incl GST
	TP DIRECT SETTLEMENT (J/NO: 73900)						
	OWNER: NEO CHIN CHYE						
	OWNER INSURER: TOKIO MARINE						
	ACC DATE: 04/12/2019						
	SURVEYED BY:						
	DATE:						
	REF NO:						
	TP INSURER: CHINA TAIPING INSURANCE						
	TP VEH: GBF7306S						
BO-NUM-COMP-L	NUMBER PLATE WITH CASING-L(N) <i>BT</i>	2	45.00		90.00	6.30	✓ 96.30
73211-T5A-J01	GLASS SETRR.WINDSHIELD <i>SM</i>	1	625.60	5	594.32	41.60	✓ 635.92
73127-TY0-000	RUBBER CWINDSHIELD DAMPER	1	11.70	5	11.11	0.78	✓ 11.89
73214-T5A-013	RUBBERWINDSHIELD DAMPER <i>acc.</i>	2	7.10	5	13.49	0.94	✓ 14.43
73226-SZW-000	DAMPERSTD 5X5	1	8.70	5	8.26	0.58	✓ 8.84
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	1	60.00		60.00	4.20	✓ 64.20
68100-T5A-U10ZZ	TAIL GATE COMP <i>Buc</i>	1	749.60	5	712.12	49.85	✓ 761.97
74440-T5A-003	WEATHERSTRIPTAILGATE <i>ini</i>	1	92.30	5	87.68	6.14	✓ 93.82
74801-T5S-K01	LOCK ASSY,TAILGATE <i>BT</i>	1	86.20	5	81.89	5.73	✓ 87.62
74830-T5A-000	CABLETAILGATE OPENER <i>X NN</i>	1	28.20	5	26.79	1.88	28.67
74870-T5A-003	STAY ASSY,L.TAILGATE OPEN <i>X NN</i>	1	96.40	5	91.58	6.41	97.99
74820-T5A-003	STAY ASSY,R.TAILGATE OPEN <i>X NN</i>	1	96.40	5	91.58	6.41	97.99
68210-T5A-023ZZ	HINGE COMP,TAILGATE <i>X NN</i>	2	31.40	5	59.66	4.18	✓ 63.84
74810-S6A-003	HANDLETAILGATE <i>Sm</i>	1	62.00	5	58.90	4.12	63.02
74890-T5A-A11	GARNISH ASSY,RR LICENCE <i>QA</i>	1	108.20	5	102.79	7.20	✓ 109.99
75701-T5A-000	EMBLEMH <i>X NN</i>	1	10.70	5	10.16	0.71	10.87
90301-ST0-003	NUTPUSH 3MM <i>X NN</i>	2	2.10	5	3.99	0.28	4.27
75722-T5L-T01	EMBLEMRR <i>acc.</i>	1	11.90	5	11.30	0.79	✓ 12.09
34100-S60-013	LIGHT ASSYLICENCE <i>QW</i>	2	35.00	5	66.50	4.66	✓ 71.16

Printed on 5/12/2019 4:16:34 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : CHINA TAIPING INSURANCE (S'PORE) PTE
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

Registration No : SMJ4081H

Chassis No : JHMGK3850KS207772

Model : JAZZ 1.3LXR CVT 19YM (EURO 6)

Owner's Name : NEO CHIN CHYE

Ins Policy No. :

Date of Accident : 4/12/2019

Document No. : SQT19005247 Page 2

Date : 5. Dec 2019

Customer No. : WZC008

Svc Advisor : RUEBEN THOMAS

Engine No : L13B14100238

Date | Time : 5. Dec 2019 10:03:09 AM

Surveyor Name :

Survey Date :

Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount Incid GST
34155-T5A-J01	LIGHT ASSYL.LID <i>CR</i>	1	89.20	5	84.74	5.93	90.67
34150-T5A-J01	LIGHT ASSYL.LID <i>CR</i>	1	89.20	5	84.74	5.93	90.67
33550-T5A-J02	TAILLIGHT ASSYL. <i>CR</i>	1	244.60	5	232.37	16.27	248.64
33500-T5A-J02	TAILLIGHT ASSY,R. <i>CR</i>	1	244.60	5	232.37	16.27	248.64
34270-T5A-J01	LIGHT ASSYHIGH MOUNT STOP <i>CR</i>	1	87.20	5	82.84	5.80	88.64
76710-T5A-003	MOTOR COMPRR.WINDSHIELD WIPER <i>Im</i>	1	88.50	5	84.07	5.88	89.95
76720-T5A-003	ARMRR.WIPER <i>cut</i>	1	43.70	5	41.51	2.91	44.42
76711-T5A-003	CAPPIVOT <i>scr</i>	1	5.50	5	5.22	0.37	5.59
76730-T5A-003	BLADERR.WINDSHIELD WIPER 350M <i>cut</i>	1	42.10	5	39.99	2.80	42.79
39530-T5A-J01	CAMERA ASSY,RR.VIEW <i>CR</i>	1	1089.50	5	1035.02	72.45	1107.47
NMDVR-IROADX9-2C	DVR, IROAD 2 CHANNEL <i>Mis</i>	1	429.90		429.90	30.09	459.99
04715-T5A-J50ZZ	FACE,RR.BUMPER <i>re</i>	1	492.70	5	468.06	32.76	500.82
91505-TM8-003	CLIP,BUMPER <i>MC</i>	7	2.30	5	15.29	1.07	16.36
71598-T5A-J50	SPACER,L,RR.BUMPER SIDE <i>MC</i>	1	17.30	5	16.43	1.15	17.58
71593-T5A-J50	SPACER,R,RR.BUMPER SIDE <i>MC</i>	1	17.30	5	16.43	1.15	17.58
71503-T5A-J50	COVER,RR.EXPI FIN <i>CR</i>	1	9.50	5	9.02	0.63	9.65
71505-T5A-J50	GARNISH,RR.BUMPER <i>cut</i>	1	39.20	5	37.24	2.61	39.85
71507-T5A-J60	COVER,L,RR.BUMPER <i>CR</i>	1	21.20	5	20.14	1.41	21.55
71502-T5A-J60	COVER,R,RR.BUMPER <i>CR</i>	1	21.20	5	20.14	1.41	21.55
NMRS-4P-TM3040L	4PCS ACT RR.SENSOR <i>DM</i>	1	320.00		320.00	22.40	342.40
66100-TAR-T00ZZ	PANEL COMPRR. <i>BT</i>	1	328.60	5	312.17	21.85	334.02
63720-T5A-900ZZ	GUTTER COMP,L,RR.PILLAR LOWER <i>BT</i>	1	91.00	5	86.45	6.05	92.50
63320-T5A-900ZZ	GUTTER COMP,R,RR.PILLAR <i>repairs</i>	1	91.00	5	86.45	6.05	92.50
04655-TAS-310ZZ	PANEL SET,RR.FLOOR <i>BT</i>	1	701.00	5	665.95	46.62	712.57
72841-SH3-315	OILSHEET <i>MC</i>	1	41.70	5	39.61	2.77	42.38
65590-T5A-N00ZZ	STIFFENER COMP,L,RR.SIDE <i>BT</i>	1	89.20	5	84.74	5.93	90.67
65540-T5A-N00ZZ	STIFFENER COMP,R,RR. <i>CR</i>	1	89.20	5	84.74	5.93	90.67
65619-T5A-300ZZ	FLANGERR.FRAME END <i>BT</i>	2	11.30	5	21.47	1.50	22.97
65662-T5A-300ZZ	FRAME BL,RR. <i>BT</i>	1	50.10	5	47.59	3.33	50.92

Printed on 5/12/2019 4:16:34 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.



QUOTATION

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : CHINA TAIPING INSURANCE (S'PORE) PTE
 3 ANSON ROAD #16-00
 SPRINGLEAF TOWER
 SINGAPORE 079909

Registration No : SMJ4081H

Chassis No : JHMGK3850KS207772

Model : JAZZ 1.3LXR CVT 19YM (EURO 6)

Owner's Name : NEO CHIN CHYE

Ins Policy No. :

Date of Accident : 4/12/2019

Document No. : SQT19005247 Page 3

Date : 5. Dec 2019

Customer No. : WZC008

Svc Advisor : RUEBEN THOMAS

Engine No : L13B14100238

Date | Time : 5. Dec 2019 10:03:09 AM

Surveyor Name :

Survey Date :

Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incl GST
75450-SAA-013	OUTLETRR AIR	1	25.90	5	24.60	1.72	26.32
04646-T5A-E50ZZ	PANEL SET,L.RR.OUTER	1	530.10	5	503.59	35.25	538.84
74592-T5B-003	FENDER,L.RR.INNER	1	81.00	5	76.95	5.39	82.34
73525-SYY-000	RUBBERRR QTR W/SHIELD	2	9.90	5	18.81	1.32	20.13
91501-T5A-901	CLIP A ,QUARTER WINDSHIELD	1	3.50	5	3.32	0.23	3.55
91502-T5A-901	CLIP B ,QUARTER WINDSHIELD	1	3.70	5	3.51	0.25	3.76
91503-TD4-003	CLIP C,QUARTER WINDSHIELD	1	2.50	5	2.37	0.17	2.54
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	1	60.00		60.00	4.20	64.20
64700-T5B-325ZZ	PANEL COMP,L.RR.	1	533.50	5	506.82	35.48	542.30
04645-TAR-320ZZ	PANEL SETL.FR.OUTSIDE	1	742.80	5	705.66	49.40	755.06
84640-T5A-003ZA	LINING ASSYRR.PANEL	1	60.80	5	57.76	4.04	61.80
84651-TAR-Z03ZA	LINING ASSYL.TRUNK	1	173.40	5	164.73	11.53	176.26
84601-TAR-Z03ZA	LINING ASSYL.TRUNK	1	173.40	5	164.73	11.53	176.26
84400-T5H-H02ZA	SHELF ASSY,RR.	1	228.90	5	217.45	15.22	232.67
84521-T5A-901ZA	LID ASSYSPARE TIRE	1	194.70	5	184.96	12.95	197.91
84550-T5A-J30	BOX ASSY,CARGO FLOOR GATE	1	120.50	5	114.47	8.01	122.48
84440-T5A-J02ZA	LINING ASSYTAILGATE LOWER	1	58.70	5	55.76	3.90	59.66
84441-T5A-003ZB	POCKETTAILGATE LINING PULL	1	5.60	5	5.32	0.37	5.69
67550-T5A-N10ZZ	PANEL COMP,L.RR.DOOR	1	736.20	5	699.39	48.96	748.35
67865-T5A-003	TAPELRR.DOOR SASH	1	15.40	5	14.63	1.02	15.65
72864-T5A-J01	SUB SEALL.RR.DOOR	1	7.00	5	6.65	0.47	7.12
72650-T5H-H01	LATCH ASSYL.RR.DOOR	1	180.10	5	171.09	11.98	183.07
60100-T5A-000ZZ	HOOD COMP	1	551.50	5	523.92	36.67	560.59
74120-T5A-J01	LOCK ASSYHOOD	1	43.70	5	41.51	2.91	44.42
04711-T5A-J50ZZ	FACE,FR.BUMPER	1	517.70	5	491.81	34.43	526.24
91505-TM8-003	CLIP,BUMPER	19	2.30	5	41.51	2.91	44.42
71198-T5A-000	SPACERL.FR.BUMPER	1	10.40	5	9.88	0.69	10.57
71193-T5A-000	SPACERR.FR.BUMPER	1	10.40	5	9.88	0.69	10.57
71190-T5A-J50	BEAM UPPER,L.FR.BUMPER	1	28.40	5	26.98	1.89	28.87

Printed on 5/12/2019 4:16:34 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : CHINA TAIPING INSURANCE (S'PORE) PTE
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

Registration No : SMJ4081H

Chassis No : JHMGK3850KS207772

Model : JAZZ 1.3LXR CVT 19YM (EURO 6)

Owner's Name : NEO CHIN CHYE

Ins Policy No. :

Date of Accident : 4/12/2019

Document No. : SQT19005247 Page 4

Date : 5. Dec 2019

Customer No. : WZC008

Svc Advisor : RUEBEN THOMAS

Engine No : L13B14100238

Date | Time : 5. Dec 2019 10:03:09 AM

Surveyor Name :

Survey Date :

Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
71140-T5A-J50	BEAM UPPER,R.FR.BUMPER	1	28.40	5	26.98	1.89	28.87
71102-T5L-T50	LOWER GRILLE ASSY,FR.	1	150.70	5	143.16	10.02	153.18
71145-TAR-T50	BASE,FR.LICENCE PLATE	1	50.30	5	47.78	3.34	51.12
71108-T5A-J50	GARNISH,L.FR.BUMPER	1	29.70	5	28.21	1.97	30.18
71103-T5A-J50	GARNISH,R.FR.BUMPER	1	29.70	5	28.21	1.97	30.18
71119-T5A-J50	GARNISH,L.FR.LOWER GRILLE	1	8.90	5	8.45	0.59	9.04
71114-T5A-J50	GARNISH,R.FR.LOWER GRI INT	1	8.90	5	8.45	0.59	9.04
71130-T5A-J50ZZ	BEAM COMP,FR.BUMPER	1	218.50	5	207.57	14.53	222.10
71121-T5A-J50	BASE,FR.GRILLE HOOK	1	233.30	5	221.63	15.51	237.14
71122-T5A-J50	MOLDING LOWER,FR.GRILLE	1	152.70	5	145.06	10.15	155.21
75700-T5A-000	EMBLEM H	1	16.40	5	15.58	1.09	16.67
90301-ST0-003	NUTPUSH 3MM	2	2.10	5	3.99	0.28	4.27
71123-T5A-J50	MOLDING UPPER,FR.GRILLE	1	127.30	5	120.93	8.47	129.40
71105-T5A-J50	COVER,FR.GRILLE	1	12.90	5	12.25	0.86	13.11
71124-T5A-J50	STAY,FR.GRILLE	1	13.00	5	12.35	0.86	13.21
71126-T5A-J50	EMBLEM BASE,FR.GRILLE	1	20.80	5	19.76	1.38	21.14
80100-T5B-003	CONDENSER ASSY	1	704.40	5	669.18	46.84	716.02
19010-5R1-901	RADIATOR COMP	1	1242.70	5	1180.56	82.64	1263.20
08CLA-P9911LK8	COOLANT ANTI-FREEZE TYPE 2	3	23.20	5	66.12	4.63	70.75
33150-T5A-J81	HEADLIGHT ASSY,L	1	492.10	5	467.49	32.72	500.21
33100-T5A-J81	HEADLIGHT ASSY,R	1	492.10	5	467.49	32.72	500.21
60400-T5B-J00ZZ	BULKHEAD COMP,FR.	1	391.70	5	372.11	26.05	398.16
Sum Item					16068.18	1,124.76	17,192.94

BO-R-COOL-RWS	SUPPLY & INSTALL SOLAR FILM ON REAR WINDSCREEN.	1	300.00		300.00	21.00	321.00
BO-WHEEL ALIGN X4	WHEEL ALIGNMENT X4	1	180.00		180.00	12.60	192.60
BO-TOW-SW	TOWING SERVICE	1	70.00		70.00	4.90	74.90
Sum Ext. Service					550.00	38.50	588.50

Printed on 5/12/2019 4:16:34 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATIONGST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer : CHINA TAIPING INSURANCE (S'PORE) PTE
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

Registration No : SMJ4081H

Chassis No : JHMGK3850KS207772

Model : JAZZ 1.3LXR CVT 19YM (EURO 6)

Owner's Name : NEO CHIN CHYE

Ins Policy No. :

Date of Accident : 4/12/2019

Document No. : SQT19005247 Page 5

Date : 5. Dec 2019

Customer No. : WZC008

Svc Advisor : RUEBEN THOMAS

Engine No : L13B14100238

Date | Time : 5. Dec 2019 10:03:09 AM

Surveyor Name :

Survey Date :

Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount Incl GST
BOSUN	SUNDRIES / <i>acc</i>	1	50.00	30 ✓	50.00	3.50	53.50
BML01I	INSPECT FR LIGHTING MECHANISMS & FOCUS	1	100.00	✓	100.00	7.00	107.00
BML02I	INSPECT RR LIGHTING MECHANISMS, PERFORM WATER	1	100.00	✓	100.00	7.00	107.00
BOJSE	BODY JOINT SEALANT. / <i>acc</i>	4	100.00	2 320 ✓	400.00	28.00	428.00
BOBC	BODY UNDERSIDE COATING (N)	1	100.00	✓	100.00	7.00	107.00
BP00R	APPLY BODY UNDERSIDE COATING (N).	1	250.00	✓	250.00	17.50	267.50
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	150.00	130 ✓	150.00	10.50	160.50
BMF00D	REMOVE & INSTALL FUEL TANK FUEL PIPES.(N)	1	250.00	✓	250.00	17.50	267.50
BG51D	REMOVE & INSTALL RR. L QTR GLASS.(N)	1	250.00	180 ✓	250.00	17.50	267.50
BC012R	RESET VEHICLE SMART ENTRY SYSTEM	1	350.00	300 ✓	350.00	24.50	374.50
BC011R	REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA	1	350.00	300 ✓	350.00	24.50	374.50
BMI03D	REMOVE & INSTALL REAR COMPARTMENT LININGS	1	350.00	✓	350.00	24.50	374.50
BMI01D	REMOVE & INSTALL ROOF LINING GARNISHES SEATS	1	560.00	✓	560.00	39.20	599.20
BG02D	REMOVE & INSTALL RR. WINDSCREEN.(N)	1	560.00	350 ✓	560.00	39.20	599.20
BC01R	REMOVE & INSTALL IN-CAR DASH CAMERA (N)	1	560.00	350 ✓	560.00	39.20	599.20
BKTG02R	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &	1	560.00	✓	560.00	39.20	599.20
BMU02R	REMOVE & REPLACE RR UNDERCARRIAGE PARTS. (N)	1	680.00	✓	680.00	47.60	727.60
BKRP22M	CUT RR PANEL, FLOOR AND RR L FENDER, RR L CHASSIS <i>560</i>	1	8000.00	7280 ✓	8000.00	560.00	8560.00
BP08R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (8P) <i>450</i>	1	3800.00	3600 ✓	3800.00	266.00	4066.00
BMC01D	REMOVE & INSTALL RADIATOR WITH FITTINGS.	1	230.00	✓	230.00	16.10	246.10
BMA01D	REMOVE & INSTALL A/C CONDENSER WITH FITTINGS.	1	280.00	✓	280.00	19.60	299.60
BKBH01R	REMOVE & RENEW BULKHEAD AND RENEW DAMAGED PARTS	1	2400.00	1960 ✓	2400.00	168.00	2568.00
BP05R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (5P)	1	2400.00	1800 ✓	2400.00	168.00	2568.00
Sum Labor					22730.00	1,591.10	24,321.10

Survey By _____

Printed on 5/12/2019 4:16:34 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.



KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)
Service and Body Repair
Tel: +65 6841 3838 Website: www.honda.com.sg
For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer : CHINA TAIPING INSURANCE (S'PORE) PTE
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909
Registration No : SMJ4081H
Chassis No : JHMGK3850KS207772
Model : JAZZ 1.3LXR CVT 19YM (EURO 6)
Owner's Name : NEO CHIN CHYE
Ins Policy No. :
Date of Accident : 4/12/2019

Document No. : SQT19005247 **Page** 6
Date : 5. Dec 2019
Customer No. : WZC008
Svc Advisor : RUEBEN THOMAS
Engine No : L13B14100238
Date | Time : 5. Dec 2019 10:03:09 AM
Surveyor Name :
Survey Date :
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
Date & Time	09/12/19				Total Amount	39,348.18	42,102.54
Excess					Total (Inclusive of GST)		42,102.54
Status							
Signature							

22 Days. 11/12/19
Guo Qiang - 82880282
before paint photos.

40782.53

40834.97

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Printed on 5/12/2019 4:16:34 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

© SERVICE PRE-INVOICEGST Reg No.: M200050223
Company Ref. No.: S60FC1380G

ATTN: GUO QIANG.

WD: 22 DAYS.

Customer: CU0090447 / CHINA TAIPING
Chassis No: JHMGK3850KS207772
License No: SMJ4081H
Mileage: 21837
Engine No: L13B14100238

Document No: SVO19079759
Printed By: JESHURUEBEN
Order Date: 11. December 2019
Order Time: 8:25:19 AM
Service Advisor: RUEBEN THOMAS

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	7% GST Amount	Incl GST
	TP DIRECT SETTLEMENT (J/NO: 73900)						
	OWNER: NEO CHIN CHYE						
	OWNER INSURER: TOKIO MARINE						
	ACC DATE: 04/12/2019						
	SURVEYED BY: GUO QIANG (LKK)						
	DATE: 09/12/2019						
	REF NO:						
	TP INSURER: CHINA TAIPING INSURANCE						
	TP VEH: GBF7306S						
35070	84181-TAR-T01ZB(GARNISH ASSY,L.QUARTER PILLAR)	1	66.40	5	63.08	4.42	67.50
	SUM EXCESS:				63.08	4.42	67.50
BO-NUM-COMP-L	NUMBER PLATE WITH CASING-L(N)	2	45.00		90.00	6.30	96.30
73211-T5A-J01	GLASS SETRR.WINDSHIELD	1	625.60	5	594.32	41.60	635.92
73127-TY0-000	RUBBER CWINDSHIELD DAMPER	1	11.70	5	11.11	0.78	11.89
73214-T5A-013	RUBBERWINDSHIELD DAMPER	2	7.10	5	13.49	0.94	14.43
73226-SZW-000	DAMPERSTD 5X5	1	8.70	5	8.26	0.58	8.84
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	1	60.00		60.00	4.20	64.20
68100-T5A-U10ZZ	TAIL GATE COMP	1	749.60	5	712.12	49.85	761.97
74440-T5A-003	WEATHERSTRIPTAILGATE	1	92.30	5	87.68	6.14	93.82
74801-T5S-K01	LOCK ASSY,TAILGATE	1	86.20	5	81.89	5.73	87.62
74810-S6A-003	HANDLETAILGATE	1	62.00	5	58.90	4.12	63.02
74890-T5A-A11	GARNISH ASSY,RR LICENCE	1	108.20	5	102.79	7.20	109.99
75722-T5L-T01	EMBLEMRR.	1	11.90	5	11.30	0.79	12.09
34100-S60-013	LIGHT ASSY,LICENCE	2	35.00	5	66.50	4.66	71.16
34155-T5A-J01	LIGHT ASSY,LID	1	89.20	5	84.74	5.93	90.67
33550-T5A-J02	TAILLIGHT ASSYL	1	244.60	5	232.37	16.27	248.64
33500-T5A-J02	TAILLIGHT ASSY,R.	1	244.60	5	232.37	16.27	248.64
76710-T5A-003	MOTOR COMPRR.WINDSHIELD WIPER	1	88.50	5	84.07	5.88	89.95
76720-T5A-003	ARMRR.WIPER	1	43.70	5	41.51	2.91	44.42
76711-T5A-003	CAPPIVOT	1	5.50	5	5.22	0.37	5.59
76730-T5A-003	BLADERR.WINDSHIELD WIPER 350M	1	42.10	5	39.99	2.80	42.79
NMDVR-IROADX9-2C	DVR, IROAD 2 CHANNEL	1	429.90		429.90	30.09	459.99
04715-T5A-J50ZZ	FACE,RR.BUMPER	1	492.70	5	468.06	32.76	500.82
91505-TM8-003	CLIP,BUMPER	7	2.30	5	15.29	1.07	16.36
71598-T5A-J50	SPACER,L,RR.BUMPER SIDE	1	17.30	5	16.43	1.15	17.58
71593-T5A-J50	SPACER,R,RR.BUMPER SIDE	1	17.30	5	16.43	1.15	17.58
71505-T5A-J50	GARNISH,RR.BUMPER	1	39.20	5	37.24	2.61	39.85
71507-T5A-J60	COVER,L,RR.BUMPER	1	21.20	5	20.14	1.41	21.55
NMRS-4P-TM3040L	4PCS ACT RR.SENSOR	1	320.00		320.00	22.40	342.40
66100-TAR-T00ZZ	PANEL COMPRR.	1	328.60	5	312.17	21.85	334.02
63720-T5A-900ZZ	GUTTER COMP,L,RR.PILLAR LOWER	1	91.00	5	86.45	6.05	92.50
04655-TAS-310ZZ	PANEL SET,RR.FLOOR	1	701.00	5	665.95	46.62	712.57
72841-SH3-315	OILSHEET	1	41.70	5	39.61	2.77	42.38
65590-T5A-N00ZZ	STIFFENER COMP,L,RR.SIDE	1	89.20	5	84.74	5.93	90.67
65619-T5A-300ZZ	FLANGERR.FRAME END	1	11.30	5	10.73	0.75	11.48
65662-T5A-300ZZ	FRAME BL,RR.	1	50.10	5	47.59	3.33	50.92
04646-TAR-330ZZ	PANEL SET,L,RR.OUTSIDE	1	585.30	5	556.03	38.92	594.95
74592-T5B-003	FENDER,L,RR.INNER	1	81.00	5	76.95	5.39	82.34
73525-SYY-000	RUBBERRR QTR W/SHIELD	2	9.90	5	18.81	1.32	20.13

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

© SERVICE PRE-INVOICEGST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer: CU0090447 / CHINA TAIPING
Chassis No: JHMGK3850KS207772
License No: SMJ4081H
Mileage: 21837
Engine No: L13B14100238

Document No: SVO19079759
Printed By: JESHURUEBEN
Order Date: 11. December 2019
Order Time: 8:25:19 AM
Service Advisor: RUEBEN THOMAS

91501-T5A-901	CLIP A ,QUARTER WINDSHIELD	1	3.50	5	3.32	0.23	3.55
91502-T5A-901	CLIP B ,QUARTER WINDSHIELD	1	3.70	5	3.51	0.25	3.76
91503-TD4-003	CLIP C,QUARTER WINDSHIELD	1	2.50	5	2.37	0.17	2.54
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	1	60.00		60.00	4.20	64.20
64700-T5B-325ZZ	PANEL COMP,L,RR.	1	533.50	5	506.82	35.48	542.30
84640-T5A-003ZA	LINING ASSYRR.PANEL	1	60.80	5	57.76	4.04	61.80
84651-TAR-Z03ZA	LINING ASSYL.TRUNK	1	173.40	5	164.73	11.53	176.26
84601-TAR-Z03ZA	LINING ASSYR.TRUNK	1	173.40	5	164.73	11.53	176.26
84400-T5H-H02ZA	SHELF ASSY,RR.	1	228.90	5	217.45	15.22	232.67
84521-T5A-901ZA	LID ASSYSPARE TIRE	1	194.70	5	184.96	12.95	197.91
84550-T5A-J30	BOX ASSY,CARGO FLOOR GATE	1	120.50	5	114.47	8.01	122.48
84440-T5A-J02ZA	LINING ASSYTAILGATE LOWER	1	58.70	5	55.76	3.90	59.66
84441-T5A-003ZB	POCKETTAILGATE LINING PULL	1	5.60	5	5.32	0.37	5.69
67550-T5A-N10ZZ	PANEL COMP,L,RR.DOOR	1	736.20	5	699.39	48.96	748.35
67865-T5A-003	TAPEL,RR.DOOR SASH	1	15.40	5	14.63	1.02	15.65
72864-T5A-J01	SUB SEALL,RR.DOOR	1	7.00	5	6.65	0.47	7.12
72650-T5H-H01	LATCH ASSYL,RR.DOOR	1	180.10	5	171.09	11.98	183.07
04711-T5A-J50ZZ	FACE,FR.BUMPER	1	517.70	5	491.81	34.43	526.24
91505-TM8-003	CLIP,BUMPER	19	2.30	5	41.51	2.91	44.42
71198-T5A-000	SPACERL,FR.BUMPER	1	10.40	5	9.88	0.69	10.57
71193-T5A-000	SPACERR,FR.BUMPER	1	10.40	5	9.88	0.69	10.57
71190-T5A-J50	BEAM UPPER,L,FR.BUMPER	1	28.40	5	26.96	1.89	28.87
71145-TAR-T50	BASE,FR.LICENCE PLATE	1	50.30	5	47.78	3.34	51.12
71130-T5A-J50ZZ	BEAM COMP,FR.BUMPER	1	218.50	5	207.57	14.53	222.10
71121-T5A-J50	BASE,FR.GRILLE HOOK	1	233.30	5	221.63	15.51	237.14
71122-T5A-J50	MOLDING LOWER,FR.GRILLE	1	152.70	5	145.06	10.15	155.21
75700-T5A-000	EMBLEM H	1	16.40	5	15.58	1.09	16.67
90301-ST0-003	NUTPUSH 3MM	2	2.10	5	3.99	0.28	4.27
71124-T5A-J50	STAY,FR.GRILLE	1	13.00	5	12.35	0.86	13.21
80100-T5B-003	CONDENSER ASSY	1	704.40	5	669.18	46.84	716.02
08CLA-P9911LK8	COOLANT ANTI-FREEZE TYPE 2	3	23.20	5	66.12	4.63	70.75
33150-T5A-J81	HEADLIGHT ASSY,L.	1	492.10	5	467.49	32.72	500.21
60400-T5B-J00ZZ	BULKHEAD COMP,FR.	1	391.70	5	372.11	26.05	398.16
04641-T5A-E50ZZ	PANEL L,SIDE SILL	1	220.20	5	209.19	14.64	223.83
74591-T5A-N00	COVER,L,RR.FENDER	1	43.70	5	41.51	2.91	44.42
90672-SNA-A01	HOLDERROD	1	0.80	5	0.57	0.04	0.61
SUM PARTS:					11,334.30	793.40	12,127.70
BOSUN	0760	1	30.00		30.00	2.10	32.10
	SUNDRIES						
BML01I	EXT-YJ	1	100.00		100.00	7.00	107.00
	INSPECT FR LIGHTING MECHANISMS & FOCUS						
	HEADLIGHTS.(N)						
BML02I	EXT-YJ	1	100.00		100.00	7.00	107.00
	INSPECT RR LIGHTING MECHANISMS.						
	PERFORM WATER TEST.(N)						
BOJSE	EXT-YBH	1	320.00		320.00	22.40	342.40
	BODY JOINT SEALANT.						
BOBC	EXT-YBH	1	100.00		100.00	7.00	107.00
	BODY UNDERSIDE COATING (N)						

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

Ⓢ SERVICE PRE-INVOICEGST Reg No.: M200050223
Company Ref. No.: S60FC1380G

PAGE 3/4

Customer:	CU0090447 / CHINA TAIPING	Document No:	SVO19079759
Chassis No:	JHMGK3850KS207772	Printed By:	JESHURUEBEN
License No:	SMJ4081H	Order Date:	11. December 2019
Mileage:	21837	Order Time:	8:25:19 AM
Engine No:	L13B14100238	Service Advisor:	RUEBEN THOMAS

BP00R	EXT-YBH	1	250.00	250.00	17.50	267.50
	APPLY BODY UNDERSIDE COATING (N).					
BA02R	EXT-YJ	1	130.00	130.00	9.10	139.10
	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)					
BMF00D	EXT-YJ	1	250.00	250.00	17.50	267.50
	REMOVE & INSTALL FUEL TANK FUEL PIPES.(N)					
BG51D	EXT-YJ	1	180.00	180.00	12.60	192.60
	REMOVE & INSTALL RR. L QTR GLASS. (N)					
BC012R	0760	1	300.00	300.00	21.00	321.00
	RESET VEHICLE SMART ENTRY SYSTEM					
BC011R	0760	1	300.00	300.00	21.00	321.00
	REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA					
BMI03D	EXT-YJ	1	350.00	350.00	24.50	374.50
	REMOVE & INSTALL REAR COMPARTMENT LININGS GARNISHES.(N)					
BMI01D	EXT-YJ	1	560.00	560.00	39.20	599.20
	REMOVE & INSTALL ROOF LINING GARNISHES SEATS SPEAKER BOARD CARPET & ETC.(N)					
BG02D	EXT-YJ	1	350.00	350.00	24.50	374.50
	REMOVE & INSTALL RR. WINDSCREEN. (N)					
BC01R	0760	1	350.00	350.00	24.50	374.50
	REMOVE & INSTALL IN-CAR DASH CAMERA (N)					
BKTG02R	EXT-YJ	1	560.00	560.00	39.20	599.20
	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST & ALIGN TAILGATE.(N)					
BMU02R	EXT-YJ	1	680.00	680.00	47.60	727.60
	REMOVE & REPLACE RR UNDERCARRIAGE PARTS. (N)					
BKRP22M	EXT-YJ	1	7,280.00	7,280.00	509.60	7,789.60
	CUT RR PANEL, FLOOR AND RR L FENDER, RR L CHASSIS ALIGN CHASSIS INCLUDING FITTING ON ATTACHMENT ITEM					
BP08R	EXT-YBH	1	3,600.00	3,600.00	252.00	3,852.00
	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS.(8P)					
BMC01D	EXT-YJ	1	230.00	230.00	16.10	246.10
	REMOVE & INSTALL RADIATOR WITH FITTINGS.					
	PRESSURE TEST COOLING SYSTEM.(N)					
BMA01D	EXT-YJ	1	280.00	280.00	19.60	299.60
	REMOVE & INSTALL A/C CONDENSER WITH FITTINGS.					
	VACUUM & RECHARGE A/C GAS.(N)					
BKBH01R	EXT-YJ	1	1,960.00	1,960.00	137.20	2,097.20
	REMOVE & RENEW BULKHEAD AND RENEW DAMAGED PARTS INCLUDING FITTING ON ATTACHMENT ITEMS					
BP05R		1	1,800.00	1,800.00	126.00	1,926.00

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

**SERVICE PRE-INVOICE**GST Reg No.: M200050223
Company Ref. No.: S80FC1380G

PAGE 4/4

Customer: CU0090447 / CHINA TAIPING
Chassis No: JHMGK3850KS207772
License No: SMJ4081H
Mileage: 21837
Engine No: L13B14100238

Document No: SVO19079759
Printed By: JESHURUEBEN
Order Date: 11. December 2019
Order Time: 8:25:19 AM
Service Advisor: RUEBEN THOMAS

BKSP11R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS.(5P)	1	1,120.00	1,120.00	78.40	1,198.40
	CUT OFF & RENEW L SILL PANEL. STRAIGHTEN ALIGN SIDE FLOOR PANEL & RENEW DAMAGE PARTS.					
			SUM LABOUR:	21,180.00	1,462.60	22,642.60
BO-R-COOL-RWS	SUPPLY & INSTALL SOLAR FILM ON REAR WINDSCREEN.	1	300.00	300.00	21.00	321.00
BO-WHEEL ALIGN X4	WHEEL ALIGNMENT X4	1	180.00	180.00	12.60	192.60
BO-TOW-SW	TOWING SERVICE	1	70.00	70.00	4.90	74.90
			SUM EXT SERVICE:	550.00	38.50	588.50
			TOTAL SGD	33,127.38	2,318.92	35,446.30
Total Payable (SGD)						35,446.30

GST Amount is calculated from individual line(s)



KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer	: CHINA TAIPING INSURANCE (S'PORE) PTE	Document No.	: SQT20000060	Page	1
	3 ANSON ROAD #16-00	Date	: 4. Jan 2020		
	SPRINGLEAF TOWER	Customer No.	: WZC008		
	SINGAPORE 079909	Svc Advisor	: RUEBEN THOMAS		
Registration No	: SMJ4081H	Engine No	: L13B14100238		
Chassis No	: JHMGK3850KS207772	Date Time	: 4. Jan 2020 9:49:04 AM		
Model	: JAZZ 1.3LXR CVT 19YM (EURO 6)	Surveyor Name	:		
Owner's Name	: NEO CHIN CHYE	Survey Date	:		
Ins Policy No.	:	Authorisation Date	:		
Date of Accident	: 4/12/2019				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
SUPPLEMENTARY PARTS & LABOUR							
35070	84181-TAR-T01ZB(GARNISH ASSY,L.QUARTER PILLAR)	1	66.40	5	63.08	4.42	67.50
			Sum G/L Account		63.08	4.42	67.50
04641-T5A-E50ZZ	PANEL L,SIDE SILL	1	220.20	5	209.19	14.64	223.83
74591-T5A-N00	COVER,L.RR.FENDER	1	43.70	5	41.51	2.91	44.42
90672-SNA-A01	HOLDER ROD	1	0.60	5	0.57	0.04	0.61
			Sum Item		251.27	17.59	268.86
BKSP11R	CUT OFF & RENEW L SILL PANEL STRAIGHTEN ALIGN	1	1120.00		1120.00	78.40	1198.40
			Sum Labor		1120.00	78.40	1,198.40

Survey By _____
Date & Time _____
Excess _____
Status _____
Signature _____

Total Amount 1,434.35 100.41 1,534.76
Total (Inclusive of GST) 1,534.76

Printed on 4/1/2020 9:52:12 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd., it will be refunded.

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	05 Dec 2019		06 Dec 2019 14:11 Edit Adj Rpt	S\$33,127.38 Edit Estimates	S\$33,127.38 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by Insurer]									
Insured:	Co. Reg. No.: -								
Main Claimant:	NEO CHIN CHYE , ID: S7308927A								
Vehicle Reg. No.:	SMJ4081H	Date of Loss:	04/12/2019 21:00 - :59 [9 Months From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM19D205791C02	Policy/Cover Note No.:	DMCVSN30106419000						
Vehicle Reg. No. (Insured):	GBF7306S	Policy No. (Claimant):	19-MS001788-R00						
		Excess:	S\$350.00						
Repairer:	Kah Motor Co Sdn Bhd (Ubi) 15 Ubi Road 4, 408610 Ubi - Tel: 68465671								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Tan Kah Leong - 63896193]								
Claimant's Insurer:	Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 17/12/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SMJ4081H (SNM19D205791C02)**
[GBF73065]
TP
NEO CHIN CHYE
Dec 4 2019 9:00PM
[-]
Kah Motor Co Sdn Bhd

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser	
Video							1 per page		☒	
No	Finalized On	Kah Motor Co Sdn Bhd (Ubl)		Thumbnail	Print					
1	05/12/19 14:10	Video - Accident [Linked Accident Report Documents]		Load MP4	☐					
2	05/12/19 14:10	Video - Accident [Linked Accident Report Documents]		Load MP4	☐					
Photos/Images							3 per page		☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print					
1	05/02/20 15:53	General View		Load JPG	☒					
2	05/02/20 15:53	General View		Load JPG	☒					
3	05/02/20 15:53	General View		Load JPG	☒					
4	05/02/20 15:53	General View		Load JPG	☒					
5	05/02/20 15:53	General View		Load JPG	☒					
6	05/02/20 15:53	General View		Load JPG	☒					
7	05/02/20 15:53	General View		Load JPG	☒					
8	05/02/20 15:53	General View		Load JPG	☒					
9	05/02/20 15:53	General View		Load JPG	☒					
10	05/02/20 15:53	General View		Load JPG	☒					
11	05/02/20 15:53	General View		Load JPG	☒					
12	05/02/20 15:53	General View		Load JPG	☒					
13	05/02/20 15:53	General View		Load JPG	☒					
14	05/02/20 15:53	General View		Load JPG	☒					
15	05/02/20 15:53	General View		Load JPG	☒					
16	05/02/20 15:53	General View		Load JPG	☒					
17	05/02/20 15:53	General View		Load JPG	☒					
18	05/02/20 15:53	General View		Load JPG	☒					
19	05/02/20 15:53	General View		Load JPG	☒					
20	05/02/20 15:53	General View		Load JPG	☒					
21	05/02/20 15:53	General View		Load JPG	☒					
22	05/02/20 15:53	General View		Load JPG	☒					
23	05/02/20 15:53	General View		Load JPG	☒					
24	05/02/20 15:53	General View		Load JPG	☒					
25	05/02/20 15:53	General View		Load JPG	☒					
26	05/02/20 15:53	General View		Load JPG	☒					
27	05/02/20 15:53	General View		Load JPG	☒					
28	05/02/20 15:53	General View		Load JPG	☒					
29	05/02/20 15:53	General View		Load JPG	☒					
30	05/02/20 15:53	General View		Load JPG	☒					
31	05/02/20 15:53	General View		Load JPG	☒					
32	05/02/20 15:53	General View		Load JPG	☒					

Video			1 per page	☒
No	Finalized On	Kah Motor Co Sdn Bhd (Ubi)	Thumbnail	Print
33	05/02/20 15:53	General View	 Load.JPG	☒
34	05/02/20 15:53	General View	 Load.JPG	☒
35	05/02/20 15:53	General View	 Load.JPG	☒
36	05/02/20 15:53	General View	 Load.JPG	☒
37	05/02/20 15:53	General View	 Load.JPG	☒
38	05/02/20 15:53	General View	 Load.JPG	☒
39	05/02/20 15:53	General View	 Load.JPG	☒
40	05/02/20 15:53	General View	 Load.JPG	☒
41	05/02/20 15:53	General View	 Load.JPG	☒
42	05/02/20 15:53	General View	 Load.JPG	☒
43	05/02/20 15:53	General View	 Load.JPG	☒
44	05/02/20 15:53	General View	 Load.JPG	☒
45	05/02/20 15:53	General View	 Load.JPG	☒
46	05/02/20 15:53	General View	 Load.JPG	☒
47	05/02/20 15:53	General View	 Load.JPG	☒
48	05/02/20 15:53	General View	 Load.JPG	☒
49	05/02/20 15:53	General View	 Load.JPG	☒
50	05/02/20 15:53	General View	 Load.JPG	☒
51	05/02/20 15:53	General View	 Load.JPG	☒
52	05/02/20 15:53	General View	 Load.JPG	☒
53	05/02/20 15:53	General View	 Load.JPG	☒
54	05/02/20 15:53	General View	 Load.JPG	☒
55	05/02/20 15:53	General View	 Load.JPG	☒
56	05/02/20 15:53	General View	 Load.JPG	☒
57	05/02/20 15:53	General View	 Load.JPG	☒
58	05/02/20 15:53	General View	 Load.JPG	☒
59	05/02/20 15:53	General View	 Load.JPG	☒
60	05/02/20 15:53	General View	 Load.JPG	☒
61	05/02/20 15:53	General View	 Load.JPG	☒
62	05/02/20 15:53	General View	 Load.JPG	☒
63	05/02/20 15:53	General View	 Load.JPG	☒
64	05/02/20 15:53	General View	 Load.JPG	☒
65	05/02/20 15:53	General View	 Load.JPG	☒
66	05/02/20 15:53	General View	 Load.JPG	☒
67	05/02/20 15:53	General View	 Load.JPG	☒
68	05/02/20 15:53	General View	 Load.JPG	☒
69	05/02/20 15:53	General View	 Load.JPG	☒
70	05/02/20 15:53	General View	 Load.JPG	☒
71	05/02/20 15:53	General View	 Load.JPG	☒
72	05/02/20 15:53	General View	 Load.JPG	☒
73	05/02/20 15:53	General View	 Load.JPG	☒
74	05/02/20 15:53	General View	 Load.JPG	☒
75	05/02/20 15:53	General View	 Load.JPG	☒
76	05/02/20 15:53	General View	 Load.JPG	☒
77	05/02/20 15:53	General View	 Load.JPG	☒
78	05/02/20 15:53	General View	 Load.JPG	☒
79	05/02/20 15:53	General View	 Load.JPG	☒
80	05/02/20 15:53	General View	 Load.JPG	☒
81	05/02/20 15:53	General View	 Load.JPG	☒
82	05/02/20 15:53	General View	 Load.JPG	☒

Video			1 per page	☒
No	Finalized On	Kah Motor Co Sdn Bhd (Ubi)	Thumbnail	Print
83	05/02/20 15:53	General View	 Load JPG	☒
84	05/02/20 15:53	General View	 Load JPG	☒
85	05/02/20 15:53	General View	 Load JPG	☒
86	05/02/20 15:53	General View	 Load JPG	☒
87	05/02/20 15:53	General View	 Load JPG	☒
88	05/02/20 15:53	General View	 Load JPG	☒
89	05/02/20 15:53	General View	 Load JPG	☒
90	05/02/20 15:53	General View	 Load JPG	☒
91	05/02/20 15:53	General View	 Load JPG	☒
92	05/02/20 15:53	General View	 Load JPG	☒
93	05/02/20 15:53	General View	 Load JPG	☒
94	05/02/20 15:53	General View	 Load JPG	☒
95	05/02/20 15:53	General View	 Load JPG	☒
96	05/02/20 15:53	General View	 Load JPG	☒
97	05/02/20 15:53	General View	 Load JPG	☒
98	05/02/20 15:53	General View	 Load JPG	☒
99	05/02/20 15:53	General View	 Load JPG	☒
100	05/02/20 15:53	General View	 Load JPG	☒
101	05/02/20 15:53	General View	 Load JPG	☒
102	05/02/20 15:53	General View	 Load JPG	☒
103	05/02/20 15:53	General View	 Load JPG	☒
104	05/02/20 15:53	General View	 Load JPG	☒
105	05/02/20 15:54	Reinspection Photo	 Load JPG	☒
106	05/02/20 15:54	Reinspection Photo	 Load JPG	☒
107	05/02/20 15:54	Reinspection Photo	 Load JPG	☒
108	05/02/20 15:54	Reinspection Photo	 Load JPG	☒
109	05/02/20 15:54	Reinspection Photo	 Load JPG	☒
110	05/02/20 15:54	Reinspection Photo	 Load JPG	☒
111	05/02/20 15:54	Reinspection Photo	 Load JPG	☒
112	05/02/20 15:54	Reinspection Photo	 Load JPG	☒
113	05/02/20 15:54	Reinspection Photo	 Load JPG	☒
114	05/02/20 15:54	Reinspection Photo	 Load JPG	☒
115	05/02/20 15:54	Reinspection Photo	 Load JPG	☒
116	05/02/20 15:54	Reinspection Photo	 Load JPG	☒
117	05/02/20 15:54	Reinspection Photo	 Load JPG	☒
118	05/02/20 15:54	Reinspection Photo	 Load JPG	☒
119	05/02/20 15:54	Reinspection Photo	 Load JPG	☒
120	05/02/20 15:54	Reinspection Photo	 Load JPG	☒
121	05/02/20 15:54	Reinspection Photo	 Load JPG	☒
122	05/02/20 15:54	Reinspection Photo	 Load JPG	☒
123	05/02/20 15:54	Reinspection Photo	 Load JPG	☒
124	05/02/20 15:54	Reinspection Photo	 Load JPG	☒
125	05/02/20 15:54	Reinspection Photo	 Load JPG	☒
126	05/02/20 15:54	Reinspection Photo	 Load JPG	☒
127	05/02/20 15:54	Reinspection Photo	 Load JPG	☒
128	05/02/20 15:54	Reinspection Photo	 Load JPG	☒
129	05/02/20 15:54	Reinspection Photo	 Load JPG	☒
130	05/02/20 15:54	Reinspection Photo	 Load JPG	☒
131	05/02/20 15:54	Reinspection Photo	 Load JPG	☒
132	05/02/20 15:54	Reinspection Photo	 Load JPG	☒

Video			1 per page	☒
No	Finalized On	Kah Motor Co Sdn Bhd (Ubi)	Thumbnail	Print
133	05/02/20 15:54	Reinspection Photo	 Load JPG	☒
134	05/02/20 15:54	Reinspection Photo	 Load JPG	☒
135	05/02/20 15:54	Reinspection Photo	 Load JPG	☒
136	05/02/20 15:54	Reinspection Photo	 Load JPG	☒
137	05/02/20 15:54	Reinspection Photo	 Load JPG	☒
138	05/02/20 15:54	Reinspection Photo	 Load JPG	☒
139	05/02/20 15:54	Reinspection Photo	 Load JPG	☒
140	05/02/20 15:54	Reinspection Photo	 Load JPG	☒
141	05/02/20 15:54	Reinspection Photo	 Load JPG	☒
142	05/02/20 15:54	Reinspection Photo	 Load JPG	☒
143	05/02/20 15:54	Reinspection Photo	 Load JPG	☒
144	05/02/20 15:54	Reinspection Photo	 Load JPG	☒
145	05/02/20 15:54	Reinspection Photo	 Load JPG	☒
146	05/02/20 15:54	Reinspection Photo	 Load JPG	☒
147	05/02/20 15:54	Reinspection Photo	 Load JPG	☒
148	05/02/20 15:54	Reinspection Photo	 Load JPG	☒
149	05/02/20 15:54	Reinspection Photo	 Load JPG	☒
150	05/02/20 15:54	Reinspection Photo	 Load JPG	☒
151	05/02/20 15:54	Reinspection Photo	 Load JPG	☒
152	05/02/20 15:54	Reinspection Photo	 Load JPG	☒
153	05/02/20 15:54	Reinspection Photo	 Load JPG	☒
154	05/02/20 15:54	Reinspection Photo	 Load JPG	☒
155	05/02/20 15:54	Reinspection Photo	 Load JPG	☒
156	05/02/20 15:54	Reinspection Photo	 Load JPG	☒
157	05/02/20 15:54	Reinspection Photo	 Load JPG	☒
158	05/02/20 15:54	Reinspection Photo	 Load JPG	☒
159	05/02/20 15:54	Reinspection Photo	 Load JPG	☒
160	05/02/20 15:54	Reinspection Photo	 Load JPG	☒
161	05/02/20 15:54	Reinspection Photo	 Load JPG	☒
162	05/02/20 15:54	Reinspection Photo	 Load JPG	☒
163	05/02/20 15:54	Before Repair Photo	 Load JPG	☒
164	05/02/20 15:54	Before Repair Photo	 Load JPG	☒
165	05/02/20 15:54	Before Repair Photo	 Load JPG	☒
166	05/02/20 15:54	Before Repair Photo	 Load JPG	☒
167	05/02/20 15:54	Before Repair Photo	 Load JPG	☒
168	05/02/20 15:54	Before Repair Photo	 Load JPG	☒
169	05/02/20 15:54	Before Repair Photo	 Load JPG	☒
170	05/02/20 15:54	Before Repair Photo	 Load JPG	☒
171	05/02/20 15:54	Before Repair Photo	 Load JPG	☒
172	05/02/20 15:54	Before Repair Photo	 Load JPG	☒
173	05/02/20 15:54	Before Repair Photo	 Load JPG	☒
174	05/02/20 15:54	Before Repair Photo	 Load JPG	☒
175	05/02/20 15:54	Before Repair Photo	 Load JPG	☒
176	05/02/20 15:54	Before Repair Photo	 Load JPG	☒
177	05/02/20 15:54	Before Repair Photo	 Load JPG	☒
178	05/02/20 15:54	Before Repair Photo	 Load JPG	☒
179	05/02/20 15:54	Before Repair Photo	 Load JPG	☒
180	05/02/20 15:54	Before Repair Photo	 Load JPG	☒

Linked Accident Report Documents

			View	View in Browser
Video			1 per page	☒
No	Finalized On	Kah Motor Co Sdn Bhd (Ubi)	Thumbnail	Print
1	05/12/19 14:10	Video - Accident FRONT	 Load MP4	
2	05/12/19 14:10	Video - Accident REAR	 Load MP4	
Assessment Reports			1 per page	☒
No	Finalized On	Kah Motor Co Sdn Bhd (Ubi)	Thumbnail	Print
1	06/12/19 19:31	Accident Statement	 Load HTM	
2	06/12/19 19:35	Accident Statement	 Load HTM	
3	06/12/19 19:41	Accident Statement	 Load HTM	
4	06/12/19 19:42	Accident Statement	 Load HTM	
Photos/Images			3 per page	☒
No	Finalized On	Kah Motor Co Sdn Bhd (Ubi)	Thumbnail	Print
1	05/12/19 14:10	Accident Photo	 Load JPG ☒	
2	05/12/19 14:10	Accident Photo	 Load JPG ☒	
3	05/12/19 14:10	Accident Photo	 Load JPG ☒	
4	05/12/19 14:10	Accident Photo	 Load JPG ☒	
5	05/12/19 14:10	Accident Photo	 Load JPG ☒	
6	05/12/19 14:10	Accident Photo	 Load JPG ☒	
7	05/12/19 14:10	Accident Photo	 Load JPG ☒	
8	05/12/19 14:10	Accident Scene Photo	 Load JPG ☒	
9	05/12/19 14:10	Accident Scene Photo	 Load JPG ☒	
10	05/12/19 14:10	Accident Scene Photo	 Load JPG ☒	
11	05/12/19 14:10	Accident Scene Photo	 Load JPG ☒	
12	05/12/19 14:10	Accident Scene Photo	 Load JPG ☒	
13	05/12/19 14:10	Accident Scene Photo	 Load JPG ☒	
Documentation			1 per page	☒
No	Finalized On	Kah Motor Co Sdn Bhd (Ubi)	Thumbnail	Print
1	05/12/19 14:10	Sketch Plan	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST Reset Save Print
There are no document checklists configured.
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) ^ v Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI19021571/GTF3E2

Date: 05/02/2020

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSN30106419000

Claimant Vehicle
No: SMJ4081HInsured Vehicle
No: GBF7306S

Date of Loss: 04/12/2019

Nature of Claim: TP

Claim
No: SNM19D205791C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMJ4081H

Make & Model: HONDA JAZZ, 1.3 LX (GE6) (A)

Reg. Date: 04/03/2019 (Man. Year: 2019)

Colour: Blue

Engine Capacity: 1318 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

Engine No: L13B14100238

Chassis No: JHMGK3850KS207772

Odometer: 21387 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/65 R15

Rear Tyre Size: 185/65 R15

Front Left Side: Habilead 7 mm

Rear Left Side: Habilead 7 mm

Front Right Side: Habilead 7 mm

Rear Right Side: Habilead 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,484.97	11,427.38	5,057.59	30.68
Miscellaneous Items	0.00	0.00	0.00	
Labour	24,350.00	21,700.00	2,650.00	10.88
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	40,834.97	33,127.38	7,707.59	18.87
+ GST 7.00/7.00% (S\$)	2,858.45	2,318.92	539.53	18.87
Nett Amount (S\$)	43,693.42	35,446.30	8,247.12	18.87

INSPECTION

Date of Assignment: 06/12/2019

Date Inspected: 09/12/2019

Inspected At:

Kah Motor Co Sdn Bhd (Ubi)

15 Ubi Road 4

Singapore 408610

Estimated Period of Repair: 22.0 days

Adjuster: XING GUO QIANG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 05 Feb 2020)
Parts: 144	HONDA JAZZ 1.3 LX (GE6) (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SMJ4081H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*NUMBER PLATE WITH CASING - L	Bent	90.00 FS	*90.00 FS
2	1		*GLASS SETRR.WINDSHIELD	Smashed	594.32 FS	*594.32 FS
3	1		*RUBBER CWINDSHIELD DAMPER	Necessary	11.11 FS	*11.11 FS
4	1		*RUBBERWINDSHIELD DAMPER (2PCS)	Necessary	13.49 FS	*13.49 FS
5	1		*DAMPERSTD 5X5	Necessary	8.26 FS	*8.26 FS
6	1		*WINDSCREEN SEALANT	Necessary	60.00 FS	*60.00 FS
7	1		*TAIL GATE COMP	Buckled	712.12 FS	*712.12 FS
8	1		*WEATHERSTRIPTAILGATE	Twisted	87.68 FS	*87.68 FS
9	1		*LOCK ASSY, TAILGATE	Bent	81.89 FS	*81.89 FS
10	1		*CABLETAILGATE OPENER	Not Necessary	26.79 FS	*- FS
11	1		*STAY ASSY,L.TAILGATE OPEN	Not Necessary	91.58 FS	*- FS
12	1		*STAY ASSYR.TAILGATE OPEN	Not Necessary	91.58 FS	*- FS
13	2		*HINGE COMP, TAILGATE	Not Necessary	59.66 FS	*- FS
14	1		*HANDLETAILGATE	Jammed	58.90 FS	*58.90 FS
15	1		*GARNISH ASSY,RR LICENCE	Cracked	102.79 FS	*102.79 FS
16	1		*EMBLEMH	Not Necessary	10.16 FS	*- FS
17	2		*NUTPUSH 3MM	Not Necessary	3.99 FS	*- FS
18	1		*EMBLEMRR.	Necessary	11.30 FS	*11.30 FS
19	2		*LIGHT ASSYLICENCE	Cut	66.50 FS	*66.50 FS
20	1		*LIGHT ASSYL.LID	Cracked	84.74 FS	*84.74 FS
21	1		*LIGHT ASSYR.LID	Not Necessary	84.74 FS	*- FS
22	1		*TAILLIGHT ASSYL	Cracked	232.37 FS	*232.37 FS
23	1		*TAILLIGHT ASSY,R	Cracked	232.37 FS	*232.37 FS
24	1		*LIGHT ASSYHIGH MOUNT STOP	Not Necessary	82.84 FS	*- FS
25	1		*MOTOR COMPRR.WINDSHIELD WIPER	Jammed	84.07 FS	*84.07 FS
26	1		*ARMRR.WIPER	Cut	41.51 FS	*41.51 FS
27	1		*CAPPIVOT	Scratched	5.22 FS	*5.22 FS
28	1		*BLADERR.WINDSHIELD WIPER 350M	Cut	39.99 FS	*39.99 FS
29	1		*CAMERA ASSY,RR.VIEW	Not Necessary	1,035.02 FS	*- FS
30	1		*DVR,IROAD 2 CHANNEL	Missing	429.90 FS	*429.90 FS
31	1		*FACE,RR.BUMPER	Deformed	468.06 FS	*468.06 FS
32	1		*CLIP, BUMPER (7PCS)	Necessary	15.29 FS	*15.29 FS
33	1		*SPACER,L.RR.BUMPER SIDE	Necessary	16.43 FS	*16.43 FS
34	1		*SPACER,R.RR.BUMPER SIDE	Necessary	16.43 FS	*16.43 FS
35	1		*COVER,RR.EXPI FIN	Not Necessary	9.02 FS	*- FS
36	1		*GARNISH,RR.BUMPER	Cut	37.24 FS	*37.24 FS
37	1		*COVER,L.RR.BUMPER	Cut	20.14 FS	*20.14 FS
38	1		*COVER,R.RR.BUMPER	Not Necessary	20.14 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
39	4		*ACT RR.SENSOR	Damaged	320.00 FS	*320.00 FS
40	1		*PANEL COMPRR.	Bent	312.17 FS	*312.17 FS
41	1		*GUTTER COMP,L.RR.PILLAR LOWER	Bent	86.45 FS	*86.45 FS
42	1		*GUTTER COMP,R.RR.PILLAR	Repair	86.45 FS	*- FS
43	1		*PANEL SET, RR.FLOOR	Buckled	665.95 FS	*665.95 FS
44	1		*OILSHEET	Necessary	39.61 FS	*39.61 FS
45	1		*STIFFENER COMP,L.RR.SIDE	Bent	84.74 FS	*84.74 FS
46	1		*STIFFENER COMP,R.RR	Not Necessary	84.74 FS	*- FS
47	1		*FLANGERR.FRAME END (2PCS)	Bent	21.47 FS	*10.73 FS
48	1		*FRAME BL.RR.	Bent	47.59 FS	*47.59 FS
49	1		*OUTLETRR AIR	Not Necessary	24.60 FS	*- FS
50	1		*PANEL SET,L.RR.OUTER	Buckled	556.03 FS	*556.03 FS
51	1		*FENDER,L.RR.INNER	Buckled	76.95 FS	*76.95 FS
52	1		*RUBBERRR QTR W/SHIELD (2PCS)	Necessary	18.81 FS	*18.81 FS
53	1		*CLIP A, QUARTER WINDSHIELD	Necessary	3.32 FS	*3.32 FS
54	1		*CLIP B, QUARTER WINDSHIELD	Necessary	3.51 FS	*3.51 FS
55	1		*CLIP C, QUARTER WINDSHIELD	Necessary	2.37 FS	*2.37 FS
56	1		*WINDSCREEN SEALANT	Necessary	60.00 FS	*60.00 FS
57	1		*PANEL COMP,L.RR.	Buckled	506.82 FS	*506.82 FS
58	1		*PANEL SETL.FR.OUTSIDE	Repair	705.66 FS	*- FS
59	1		*LINING ASSYRR.PANEL	Deformed	57.76 FS	*57.76 FS
60	1		*LINING ASSYL.TRUNK	Deformed	164.73 FS	*164.73 FS
61	1		*LINING ASSYR.TRUNK	Deformed	164.73 FS	*164.73 FS
62	1		*SHELF ASSY, RR.	Deformed	217.45 FS	*217.45 FS
63	1		*LID ASSYSPARE TIRE	Deformed	184.96 FS	*184.96 FS
64	1		*BOX ASSY, CARGO FLOOR GATE	Deformed	114.47 FS	*114.47 FS
65	1		*LINING ASSYTAILGATE LOWER	Deformed	55.76 FS	*55.76 FS
66	1		*POCKETTAILGATE LINING PULL	Deformed	5.32 FS	*5.32 FS
67	1		*PANEL COMP,L.RR.DOOR	Buckled	699.39 FS	*699.39 FS
68	1		*TAPEL.RR.DOOR SASH	Necessary	14.63 FS	*14.63 FS
69	1		*SUB SEALL.RR.DOOR	Necessary	6.65 FS	*6.65 FS
70	1		*LATCH ASSYL.RR.DOOR	Jammed	171.09 FS	*171.09 FS
71	1		*HOOD COMP	Repair	523.92 FS	*- FS
72	1		*LOCKASSY HOOD	Not Necessary	41.51 FS	*- FS
73	1		*FACE,FR.BUMPER	Deformed	491.81 FS	*491.81 FS
74	1		*CLIP, BUMPER (18PCS)	Necessary	41.51 FS	*41.51 FS
75	1		*SPACERL.FR.BUMPER	Necessary	9.88 FS	*9.88 FS
76	1		*SPACERR.FR.BUMPER	Necessary	9.88 FS	*9.88 FS
77	1		*BEAM UPPER,L.FR.BUMPER	Cracked	26.98 FS	*26.98 FS
78	1		*BEAM UPPER,R.FR.BUMPER	Not Necessary	26.98 FS	*- FS
79	1		*LOWER GRILLE ASSY,FR.	Not Necessary	143.16 FS	*- FS
80	1		*BASE,FR.LICENCE PLATE	Cut	47.78 FS	*47.78 FS
81	1		*GARNISH,L.FR.BUMPER	Not Necessary	28.21 FS	*- FS
82	1		*GARNISH,R.FR.BUMPER	Not Necessary	28.21 FS	*- FS
83	1		*GARNISH,L.FR.LOWER GRILLE	Not Necessary	8.45 FS	*- FS
84	1		*GARNISH,R.FR.LOWER GRI INT	Not Necessary	8.45 FS	*- FS
85	1		*BEAM COMP,FR.BUMPER	Bent	207.57 FS	*207.57 FS
86	1		*BASE,FR.GRILLE HOOK	Cracked	221.63 FS	*221.63 FS
87	1		*MOLDING LOWER,FR.GRILLE	Cracked	145.06 FS	*145.06 FS
88	1		*EMBLEM H	Necessary	15.58 FS	*15.58 FS
89	1		*NUTPUSH 3MM (2PCS)	Necessary	3.99 FS	*3.99 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
90	1		*MOLDING UPPER,FR.GRILLE	Not Necessary	120.93 FS	*. FS
91	1		*COVER,FR.GRILLE	Not Necessary	12.25 FS	*. FS
92	1		*STAY,FR.GRILLE	Broken	12.35 FS	*12.35 FS
93	1		*EMBLEM BASE,FR.GRILLE	Not Necessary	19.76 FS	*. FS
94	1		*CONDENSER ASSY	Cut	669.18 FS	*669.18 FS
95	1		*RADIATOR COMP	Not Necessary	1,180.56 FS	*. FS
96	1		*COOLANT ANTI-FREEZE TYPE 2 (3PCS)	Necessary	66.12 FS	*66.12 FS
97	1		*HEADLIGHT ASSY,L.	Cracked	467.49 FS	*467.49 FS
98	1		*HEADLIGHT ASSY,R.	Not Necessary	467.49 FS	*. FS
99	1		*BULKHEAD COMP,FR.	Bent	372.11 FS	*372.11 FS
100	1		*SUNDRIES	Necessary	50.00 FS	*30.00 FS
101	1		*GARNISH ASSY,L.QUARTER PILLAR	Missing	63.08 FS	*63.08 FS
102	1		*PANEL L,SIDE SILL	Buckled	209.19 FS	*209.19 FS
103	1		*COVER,L.RR. FENDER	Deformed	41.51 FS	*41.51 FS
104	1		*HOLDERROD	Necessary	0.57 FS	*0.57 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$)	16,484.97	11,427.38
---------------------------	------------------	------------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	SUPPLY & INSTALL SOLAR FILM ON REAR WINDSCREEN	New	300.00	300.00
2	WHEEL ALIGNMENT X4	New	180.00	180.00
3	TOWING SERVICE	New	70.00	70.00
4	INSPECT FR LIGHTING MECHANISMS & FOCUS	New	100.00	100.00
5	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	New	100.00	100.00
6	BODY JOINT SEALANT	New	400.00	320.00
7	BODY UNDERSIDE COATING	New	100.00	100.00
8	APPLY BODY UNDERSIDE COATING	New	250.00	250.00
9	REMOVE & RENEW REVERSE SENSORS - 4 PCS	New	150.00	130.00
10	REMOVE & INSTALL FUEL TANK FUEL PIPES	New	250.00	250.00
11	REMOVE & INSTALL RR.L QTR GLASS	New	250.00	180.00
12	RESET VEHICLE SMART ENTRY SYSTEM	New	350.00	300.00
13	REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA	New	350.00	300.00
14	REMOVE & INSTALL REAR COMPARTMENT LININGS	New	350.00	350.00
15	REMOVE & INSTALL ROOF LINING GARNISHES SEATS	New	560.00	560.00
16	REMOVE & INSTALL RR.WINDSCREEN	New	560.00	350.00
17	REMOVE & INSTALL IN-CAR DASH CAMERA	New	560.00	350.00
18	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &	New	560.00	560.00
19	REMOVE & REPLACE RR UNDERCARRIAGE PARTS	New	680.00	680.00
20	CUT RR PANEL, FLOOR AND RR L FENDER, RR L CHASSIS	New	8,000.00	7,280.00
21	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS (8P)	New	3,800.00	3,600.00
22	REMOVE & INSTALL RADIATOR WITH FITTINGS	New	230.00	230.00
23	REMOVE & INSTALL A/C CONDENSER WITH FITTINGS	New	280.00	280.00
24	REMOVE & RENEW BULKHEAD AND RENEW DAMAGED PARTS	New	2,400.00	1,960.00
25	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS (5P)	New	2,400.00	1,800.00
26	CUT OFF & RENEW L SILL PANEL. STRAIGHTEN ALIGN	New	1,120.00	1,120.00
Gross Labour Cost (\$\$)			24,350.00	21,700.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >