

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHD 4003A

MAKE :

MODEL : HYUNDAI IONIQ

Aig Asia-CPD

DATE 6/12/2019

(Fri)

IS

LKK - Ram

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Boot Lid BUC			\$ 2,480.40
	Boot Lid Lock Upper ? } sm			\$ 224.00
	Boot Lid Lock Lower ? } sm			\$ 51.30
	Boot Lid 'H' Emblem nec			\$ 28.00
	Emblem -Hybrid nec			\$ 24.30
	Emblem -Ioniq nec			\$ 31.30
	Boot Lid Glass, Lower nec			\$ 384.90
	Rear Bumper X (C)			\$ 459.40
	Rear Bumper Centre Moulding Assy cut			\$ 451.25
	Rear Bumper Lower Centre Moulding Assy xnn			\$ 155.00
	Rear Bumper Stay xnn			\$ 138.10
	Rear Bumper Side Bracket (LH/RH) xnn		\$ 33.10	\$ 66.20
	Rear Bumper Cover Clips xnn			\$ 22.00
	Rear Panel ?			\$ 532.00
	Rear Panel Garnish ?			\$ 155.00
	Rear Panel Lower Panel ?		\$ 39.40	\$ 78.80
	Rear Windscreen Glass xnn			\$ 607.20
	Rear Windscreen Moulding xnn			\$ 28.20
	SUB TOTAL			\$ 5,917.35
	LESS 20% to resurvey before/after spray painting			\$ 1,183.47
	DISCOUNTED TOTAL			\$ 4,733.88
	Boot Lid Comfort Logo & Tel No. Sticker nec			\$ 30.00
	Rear No. Plate Cva			\$ 25.00
	Rear Bumper Reverse Sensor xnn			\$ 135.70
	Rear Bumper Rubber Mat nec			\$ 50.00
	Rear Windscreen Sealant xnn			\$ 46.00
	Labour Charge			
	Panel Beating			\$ 750.00
	Spray Painting Charge			\$ 600.00
	Wiring Charge			\$ 50.00
	Tuff Kote			\$ 50.00
	Towing Charge			\$ 60.00
	Remove/Refix Cushion & Upholstery Rear			\$ 150.00
	Remove/Refix Rear Windscreen Glass			\$ 120.00
	Remove/Refix Reverse Sensor			\$ 80.00
	TOTAL LABOUR			\$ 1,860.00
	ESTIMATE TOTAL			\$ 6,880.58

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

TAKE mileage photo

Ram (LKK)
6/12/19 1130hrs
Rameswari LKK auto. cons
88622778
3 repair days
P/S Ref paint photo

\$ 750.00	\$480
\$ 600.00	\$400
\$ 50.00	\$30
\$ 50.00	\$30
\$ 60.00	\$30
\$ 150.00	\$150
\$ 120.00	\$50
\$ 80.00	xnn