

FASTECH AUTO PTE LTD  
BLK1 KAKI BUKIT AVE 6  
#01-46,48,50 AUTOBAY  
SINGAPORE 417883

VEHICLE NO:SLG 2328M

| QTY   | PARTICULAR                               |
|-------|------------------------------------------|
| 1 PCS | BONNET <b>685.30</b>                     |
| 1 PCS | BONNET LOCK                              |
| 1 PCS | BONNET INSULATOR                         |
| 1 SET | BONNET INSULATOR CLIPS                   |
| 1 PCS | BONNET HINGES @\$66.50                   |
| 1 PCS | FRONT BUMPER                             |
| 1 PCS | FRONT BUMPER REINFORCEMENT               |
| 1 SET | FRONT BUMPER CLIPS                       |
| 2 PCS | FRONT BUMPER SIDE RETAINERS @\$20.50     |
| 1 PCS | FRONT BUMPER CENTRE GRILLE <b>104.20</b> |
| 2 PCS | FRONT BUMPER FOG LAMPS @\$292.40         |
| 2 PCS | FRONT BUMPER FOG LAMP COVERS @\$10.50    |
| 1 PCS | FRONT BUMPER LICENCE GARNISH             |
| 2 PCS | HEADLAMPS @\$1820.00                     |
| 2 PCS | HEADLAMP LOWER BRACKETS @\$42.60         |
| 1 PCS | FRONT SUPPORT PANEL                      |
| 1 PCS | FRONT SUPPORT PANEL TOP GARNISH          |
| 1 PCS | FRONT FENDER N/S <b>450.50</b>           |
| 1 PCS | FRONT FENDER INNER SHIELD N/S            |
| 1 SET | FRONT FENDER INNER SHIELD CLIPS N/S      |
| 1 PCS | FRONT FENDER INNER PANEL N/S             |
| 1 PCS | FRONT GRILLE                             |
| 1 PCS | FRONT GRILLE CHROME MOULDING             |
| 1 PCS | FRONT GRILLE 'H' LOGO                    |
| 1 PCS | FRONT FENDER INNER TOP SIDE GARNISH N/S  |
| 1 PCS | FRONT WIPER PANEL GARNISH                |
| 1 PCS | AIR CON CONDENSER                        |
| 2 PCS | AIR CON CONDENSER BRACKETS @\$10.50      |
| 1 PCS | AIR CON DISCHARGE HOSE                   |
| 1 PCS | AIR CON SUCTION HOSE                     |
| 1 PCS | RADIATOR <b>1455.30</b>                  |
| 1 PCS | AIR CON FAN ASSY                         |
| 1 PCS | RADIATOR FAN COWLING                     |
| 1 PCS | RADIATOR FAN BLADE                       |
| 1 PCS | RADIATOR FAN MOTOR                       |
| 1 PCS | RADIATOR SPARE TANK                      |
| 1 PCS | AIR CLEANER BOX                          |
| 1 PCS | FRONT SHOCK ABSORBER N/S                 |
| 1 PCS | FRONT LOWER ARM N/S                      |
| 1 PCS | FRONT KNUCKLE ARM N/S                    |
| 1 PCS | FRONT KNUCKLE ARM BEARING N/S            |
| 1 PCS | FRONT DRIVESHAFT N/S                     |
| 2 PCS | ENGINE MOUNTINGS @\$285.00               |
| 1 PCS | FRONT DOOR N/S                           |
| 1 PCS | FRONT ENGINE LOWER COVER                 |

|          |             |     |
|----------|-------------|-----|
| Bum      | \$896.70    | ✓   |
| Twl      | \$85.10     | ✓   |
| De       | \$188.20    | ✓   |
| ner      | \$39.00     | ✓   |
| 11       | \$133.00    | α   |
| DeS      | \$638.00    | ✓   |
| ber      | \$295.40    | ✓   |
| ner      | \$39.00     | ✓   |
| M/bert   | \$41.00     | 1pc |
| Torn     | \$132.20    | ✓   |
| M/scne   | \$584.80    | 1pc |
| M/SBNO   | \$21.00     | 1pc |
| De       | \$48.50     | ✓   |
| M/scne   | \$3,640.00  | ✓   |
| M/Sbert  | \$85.20     | 1pc |
| ber/Twl  | \$440.50    | ✓   |
| De       | \$92.60     | ✓   |
| Buc      | \$619.00    | ✓   |
| Torn     | \$188.20    | ✓   |
| ner      | \$39.00     | ✓   |
| De/bert  | \$425.00    | ✓   |
| BNO/m.s  | \$224.60    | ✓   |
| BNO/m.s  | \$185.30    | ✓   |
| M/S      | \$32.50     | ✓   |
| 11       | \$46.70     | α   |
| 11       | \$182.60    | α   |
| Bert/Pu7 | \$1,100.00  | ✓   |
| 11       | \$21.00     | α   |
| 11       | \$281.60    | α   |
| 11       | \$266.30    | α   |
| Bert/ene | \$1,810.20  | ✓   |
| 11       | \$449.70    | X   |
| ene      | \$109.40    | ✓   |
| 11       | \$58.40     | α   |
| 11       | \$386.50    | α   |
| De       | \$105.00    | ✓   |
| 11       | \$366.20    | α   |
| 8u       | \$392.30    | α   |
| Buc      | \$366.50    | ✓   |
| Bert     | \$385.20    | ✓   |
| ner      | \$195.00    | ✓   |
| 11       | \$1,280.00  | X   |
| M/Torn   | \$570.00    | 1pc |
| ner      | \$981.00    | X   |
| Torn     | \$126.30    | ✓   |
|          | \$18,593.70 |     |

(507)  
WZ

10889.2

not Authorized  
date  
6/12/18  
L/S # 9250?  
7 day.



1 PCS S.NETT  
1 PCS FRONT LICENCE PLATE  
1 PCS FRONT TYRE N/S  
1 PCS BATTERY  
1 PCS FRONT SPORT RIM N/S

S.N  
\$20.00 ✓  
\$200.00 X  
\$180.00 X  
\$850.00 400

LABOUR CHARGES  
TO CHECK WIRING  
TO SPRAY RUST PROOFING  
TO CONDUCT WHEEL ALIGNMENT  
TO REFILL AIR CON GAS  
TO DISMANTLE & REPLACING FRONT UNDERCARRIAGE  
TO STRAIGHTEN FRONT CHASSIS MEMBER  
TO DISMANTLE & REPLACING FRONT ENGINE MOUNTING  
LABOUR FOR PANEL BEATING & REPLACING PARTS  
TO PUTTY & SPRAY PAINTING

\$80.00 30  
\$150.00 100  
\$120.00 60  
\$120.00 100  
\$280.00 120  
\$380.00 X  
\$120.00 30  
\$1,500.00 1000  
\$1,500.00 1000  
TOTAL \$24,093.70

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-8711-36  
S.N-420  
L-2440  
11571.36  
9257