

WinCar AUTOMOTIVE PTE LTD

2011 Mr. Andrew

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg

Company Reg. No. : 200714616M
GST Registration No. : 200714616M

DERRICK CHANG POO HWEE (ZENG
BUWEI)

BLK 184A RIVERVALE CRESCENT #04-163
SINGAPORE 541184

Contact : 91556259

ESTIMATE

Repair Code : CLM14784

Date in : 05/12/2019

Vehicle Num. : SFW2919U

Model : KIA FORTE K3 1.6A

Chassis/Eng# : KNAFZ411MF5337240/G4FGEH743568

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
FRONT RH DOOR <i>Dented</i>	1	1277.00	✓ 1,277.00
FRONT RH DOOR FRAME BLACK STICKER (UPPER) <i>2 New</i>	1	22.00	✓ 22.00
FRONT RH DOOR FRAME BLACK STICKER (VERTICAL) <i>1 New</i>	1	27.00	✓ 27.00
FRONT RH DOOR GLASS CHANNEL WEATHER STRIP <i>new</i>	1	119.00	X 119.00
FRONT RH DOOR GLASS REGULATOR <i>Dented</i>	1	319.00	✓ 319.00
FRONT RH DOOR GUIDE RUBBER STOPPER <i>2 New</i>	2	15.00	X 30.00
FRONT RH DOOR INNER PLASTIC SEAL COVER	1	18.00	X 18.00
FRONT RH DOOR INNER TRIM BOARD <i>caulked</i>	1	565.00	✓ 565.00
FRONT RH DOOR WEATHER STRIP SEAL <i>new</i>	1	123.00	X 123.00
REAR RH BEARING HUB <i>Dented</i>	1	352.00	✓ 352.00
REAR RH DOOR <i>Dented</i>	1	1309.00	✓ 1,309.00
REAR RH DOOR FRAME BLACK STICKER (UPPER) <i>2 New</i>	1	22.00	✓ 22.00
REAR RH DOOR FRAME BLACK STICKER (VERTICAL) <i>1 New</i>	1	25.00	✓ 25.00
REAR RH DOOR GLASS CHANNEL WEATHET STRIP <i>new</i>	1	161.00	X 161.00
REAR RH DOOR GLASS REGULATOR <i>new</i>	1	239.00	X 239.00
REAR RH DOOR GUIDE RUBBER STOPPER <i>2</i>	1	15.00	X 15.00
REAR RH DOOR INNER PLASTIC SEAL COVER <i>new</i>	1	18.00	X 18.00
REAR RH DOOR LOWER HINGE <i>new</i>	1	38.00	X 38.00

*** This is a computer-generated document which requires no signature.***

hCar AUTOMOTIVE PTE LTD

AutoHub
Unit Ave 2
#01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Phone 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
Email : sales@h51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

DERRICK CHANG POO HWEE (ZENG
BUWEI)
BLK 184A RIVERVALE CRESCENT #04-163
SINGAPORE 541184

Contact : 91556259

ESTIMATE

Repair Code : CLM14784

Date in : 05/12/2019

Vehicle Num. : SFW2919U

Model : KIA FORTE K3 1.6A

Chassis/Eng# : KNAFZ411MF5337240/G4FGEH743568

REAR RH DOOR WEATHER STRIP SEAL	<i>Not per</i>	1	122.00	X	122.00
REAR RH FENDER TRANSPARENT STICKER	<i>Not</i>	1	52.00	/	52.00
REAR RH SPORT RIM	<i>Not</i>	1	1014.00	<i>600 (sw)</i>	1,014.00
RH SIDE ROCKER PANEL	<i>Regis</i>	1	1304.00	X	1,304.00
Subtotal before discount					7,171.00
Percentage discount 10%					717.10
Sub-total 1					6,453.90
FRONT RH DOOR INNER TRIM BOARD CLIPS - SET	<i>Not</i>	1	50.00	<i>30</i>	50.00
REAR RH DOOR INNER TRIM BOARD CLIPS - SET	<i>Not per</i>	1	50.00	X	50.00
REAR RH TYRE	<i>Not per</i>	1	350.00	X	350.00
Subtotal before discount					450.00
Percentage discount 0%					0.00
Sub-total 2					450.00
Parts-total					6,903.90

LABOUR

To reset system after repair works	X	250.00
To remove, change rear suspension parts, axle carriage, absorber, lower arm, top arm, trailing arm, knuckle arm, wheel bearing, bearing hub and etc.	60	140.00
To road test driving, check and resetting wheel alignments system.	80	100.00
To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)	60	200.00

*** This is a computer-generated document which requires no signature.***

hCar AUTOMOTIVE PTE LTD

AutoHub
Unit Ave 2
#01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
Email : sales@h51.com.sg
Company Reg. No. : 200714616M
T Registration No. : 200714616M

DERRICK CHANG POO HWEE (ZENG
BUWEI)
BLK 184A RIVERVALE CRESCENT #04-163
SINGAPORE 541184

Contact : 91556259

ESTIMATE

Repair Code : CLM14784
Date in : 05/12/2019
Vehicle Num. : SFW2919U
Model : KIA FORTE K3 1.6A
Chassis/Eng# : KNAFZ411MF5337240/G4FGEH743568

To transfer door glass, regulator gear, motor, railing, channel, trim board, mechanism lock and handle.
To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.
To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.
To apply anti-rust chemical on repaired and replaced panel.

160	200.00
8W	1,500.00
2040	800 700 1,400.00
80	120.00
Labour Total	3,910.00
Parts & Labour Total	10,813.90

*** This is a computer-generated document which requires no signature.***

page 3

total: 6243

4/s: 51C

06 Days.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

51C