

ASS. REC. BY:

REF:

CS/SMO19021585/DS F3 02

Special Instruction:

Surveyor

Bryan

ASSIGNMENT (Office)

From (Person):

Henry Irene James

of

SMD

Date/Time:

6.12.19 4.01pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHA 7925K

Insured:

SMJ 746A

at Workshop m/s

Chunni

Tel:

65425119

of

Sam Hock motor # 0105706

Policy No:

Claim No:

CMD1905706

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

5.12.2019

CA / REV / REP. / REV 24 HRS

mp.1

9.12.2019

H.O.D. Endorsement:

Date/Time:

6.12.19 4.06pm

Person Contacted:

Irene

Vehicle IN / OUT

Date/Time

Action/Instruction (✓) Estimate

SMJ 746A X

SHA 7925K: HA/mis/MC/31/19 001245A/2019

23/12/19

@ 16:13 pm revised PA to Henry via email

ASS. FILED BY: Bryan

REF:

ASSIGNMENT

O/E June 2023

June 2015

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop n/s _____

of _____

Insured: _____

Policy No: _____

Claims No: _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 6 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SHA 7925K Yr Regn: June 2015

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai I40 c.c. 1685

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading: 690315 T/Radio: Insured / Std / NI / NA

Eng/No: D4FDEU494917

C/No: KMHLB41UMFu069620

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/60 R16

R: ———

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Hankook

Front

Rear

R/Bal: 5 mm

R/Bal: 5 mm

L/Bal: 5 mm

L/Bal: 5 mm

D.O.A. 05/12/2019

D.O.I. 09/12/2019

Survey held at Churni AMK

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

N/S Body y 4/5 Rm

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Sampo SMS 746 A

14/01/2020 Repair 2/5 6400/- with 6 days of rev
(\$ 8,267.48 Rev - 56%)

RECEIVED 14 JAN 2020

Date/Time, File Pass to?

14/01/20

By

Typ. 20

Date/Time, File Return to?

By

Rep. Form(s):

Lump Sum / L.B.: \$1,400/- 45

Days Of Repair: 6

Resurvey No. of Trip: 1

Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Invs (\$)☐ Weekend (\$)

Survey Fee:

Transportation:

S + RS: \$

Photos:

Film:

Total:

Total:

350



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: CMTD1905706

Date: 23 December 2019

Our Ref: CS/SMO19021585/Dsf3

The Motor Claims Department
SOMPO INSURANCE SINGAPORE PL

Dear Sir/Madam,


PRELIMINARY ADVISE REPORT OF VEHICLE NO. SHA 7925K .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 09/12/2019 at the premises of M/s Chunni Motor Works Pte Ltd and have the following to report:-

Workshop Estimate Amount	: <u>S\$ 14,667.48</u> .
Revised Estimate Amount	: <u>S\$ 7,960.36</u> .
"Check" Items Amount	: <u>S\$ -</u> .
Market Value	: <u>S\$ -</u> .
LTA Reimbursement Value	: <u>S\$ -</u> .
Nett Value	: <u>S\$ -</u> .

Description of Damage:

The vehicle sustained damages at the n/s body & n/s rear portion.



Comments/ Present Status:

Damages Consistent.

Repair days: 6 days

Yours faithfully

Bryan Ang
Automotive Assessor

Summer Lee (LKK Auto)

From: Henry, Irene James <irene.henry@sompo.com.sg>
Sent: Friday, 6 December, 2019 4:01 PM
To: assignments
Cc: sur@lkkauto.com; admin-d@lkkauto.com
Subject: FW: SOMPO REF:CMTD1905706/RE: Accident involving veh no: SHA 7925K & SMJ 746A on 5.12.2019
Attachments: 06122019131509.pdf

Dear LKK Auto,

Kindly arrange the motor survey.

Best Regards

Irene Henry

Claims Division

D: 6322 4618 | T: 6461 6555 | F: 6221 3147



Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sompo SG



¹ For Travel, Personal Accident & Home Insurance | ² For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: Chunni Motor <chunnimotor@gmail.com>

Sent: Friday, 6 December, 2019 3:46 PM

To: Henry, Irene James <irene.henry@sompo.com.sg>

Cc: Gnoh, Pau Loong <PauLoong.Gnoh@sompo.com.sg>; Teo, Grace <grace.teo@sompo.com.sg>; Ye, Yong Kang Melvin <melvin.ye@sompo.com.sg>

Subject: Re: SOMPO REF:CMTD1905706/RE: Accident involving veh no: SHA 7925K & SMJ 746A on 5.12.2019

Dear Sir,

We appoint LKK Auto Consultants P/L - Mohd Rasul.

Thank you

Regards,
Chunni Motor Work P/L

On Fri, Dec 6, 2019 at 3:26 PM Henry, Irene James <irene.henry@sompo.com.sg> wrote:

Our Reference : CMTD1905706/AGC

Your Reference: SHA 7925K

Without Prejudice

Date: 06.12.2019

Attention:

CHUNNI MOTOR

ACCIDENT INVOLVING SHA 7925K & SMJ 746A ON 05.12.2019

We refer to your Notice of Accident dated 06.12.2019.

Please be informed that **Pau Loong** the handler of this case who can be contacted at 6329 5217/
pauloong.gnoh@sompo.com.sg .

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Pre-Repair Survey

	Motor Surveyor	Surveyor	Selection (Indicate as tick)
1	Raleigh Services	Andrew Ow Yong	
		Vincent Ng	
2	LKK Auto Consultants	Kenneth Kong (North area)	
		Marcus Chua (East area)	
		Mohd Rasul (West area)	
		Mohd Taufikh (West area)	
3	Priority Services	Jimmy Lee	
		Lawrence Ng	
		Jeffery Ong	

Please let us know within **two (2) working days** whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select up to two of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Best Regards

Irene Henry

Claims Division

D: 6322 4618 | T: 6461 6555 | F: 6221 3147



SOMPO
INSURANCE

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | Facebook: www.facebook.com/SompoSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sompo SG

Download now @



or



¹ For Travel, Personal Accident & Home Insurance | ² For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: Chunni Motor <chunnimotor@gmail.com>

Sent: Friday, 6 December, 2019 1:25 PM

To: Claims - Motor Survey <MotorSurvey@sompo.com.sg>

Subject: Accident involving veh no: SHA 7925K & SMJ 746A on 5.12.2019

Dear Sir/Mdm,

We refer the above mentioned matter.

We enclosed herewith the relevant documents for your necessary action.

In line with the new protocol, kindly provide us with the list of surveyors on your panel for assessment of the damaged accident taxi involved.

Kindly survey at AMK Autopoint, Soon Hock Motor, #01-05/06.

Should you have any queries, please do not hesitate to contact Ms Lynn or Ms Irene at 65425119 or 6542 7162

Thank you for your kind assistance.

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto)
Sent: Monday, 23 December 2019 4:13 pm
To: 'Henry, Irene James'
Cc: SUR; assignments
Subject: RE: SOMPO REF:CMTD1905706/RE: Accident involving veh no: SHA 7925K & SMJ 746A on 5.12.2019
Attachments: PRELI ADVISE - SHA 7925K .pdf

Dear Henry,

Enclosed preliminary revised of vehicle SHA 7925K.

"Best Wishes for Merry Christmas & Happy New Year 2020"

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) <admin-d@lkkauto.com>
Sent: Friday, 6 December 2019 4:07 pm
To: 'Henry, Irene James' <irene.henry@sompo.com.sg>; assignments <assignments@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: RE: SOMPO REF:CMTD1905706/RE: Accident involving veh no: SHA 7925K & SMJ 746A on 5.12.2019

Dear Sir/Madam,

Thank you for your assignment.

Best Regards,

Summer Lee | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Henry, Irene James <irene.henry@sompo.com.sg>
Sent: Friday, 6 December, 2019 4:01 PM

CHUNNI MOTOR WORK PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHA 7925K

DATE : 5.12.2019

MAKE :

TEL : 6542 5119

MODEL : HYUNDAI i40

FAX : 6542 6039

longo

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper <i>bt mandy crack</i>			\$ 553.00
	Rear Bumper Clip 10 pcs <i>Hec</i>			\$ 22.00
	Rear Bumper Bracket, LH <i>MH</i>			\$ 35.60
	Rear Fender With Housing (LH) <i>Dented</i>		2020.00	\$ 4,736.80
	Rear Fender Inner Lining (LH) <i>SVC</i>			\$ 169.30
	Rear Windscreen Moulding <i>Hec</i>			\$ 28.30
	Rear Door (LH) <i>Dented</i>			\$ 2,201.10
	Rocker Panel Outer Garnish (LH) <i>MH</i>			\$ 341.40
	Rear Tyre Rim (LH) <i>& bt</i>			\$ 325.30
	Rear Wheel Hup-Cap (LH) <i>Cut</i>			\$ 107.10
	Rear Wheelbearing ING & Hub <i>& Down</i>			\$ 362.00
	Rear Trailing Arm (LH) <i>& distorted</i>			\$ 192.00
	Rear Assist (LH) <i>& distorted</i>			\$ 145.70
	Rear Shock Absorber (LH) <i>& distorted</i>			\$ 276.30
	Rear Shock Absorber Mounting (LH) <i>MH</i>			\$ 81.30
	Rear Crossmember <i>MH</i>			\$ 1,021.50
	Stabilizer Bar <i>MH</i>			\$ 199.60
	Stabilizer Link <i>MH</i>			\$ 85.90
	Rear Upper Arm (LH) <i>& distorted</i>		7467.95	\$ 335.75
	Rear Lower Arm (LH) <i>& distorted</i>			\$ 353.80
	Rear Knuckle Arm (LH) <i>& distorted</i>		5974.36	\$ 545.60
	SUB TOTAL			\$ 12,119.35
	LESS 20%			\$ 2,423.87
	DISCOUNTED TOTAL			\$ 9,695.48
	Rear Bumper Rubber Mat <i>Hec</i>			\$ 50.00
	Rear Windscreen Sealant <i>Hec</i>			\$ 46.00
	Rear Door Comfortdelgro & Apps Sticker (LH) <i>Hec</i>		176.00	\$ 80.00
	Rear Tyre (LH) <i>SVC</i>			\$ 216.00
				\$ 392.00

SHA 7925K

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Labour Charge			
	Panel Beating			\$ 1,200.00
	Spray Painting Charge			\$ 1,250.00
	Wiring Charge			\$ 50.00
	Tuff Kote			\$ 100.00
	Remove/Refix Cushion & Upholstery Rear			\$ 150.00
	Remove/Refix Rear Windscreen Glass			\$ 120.00
	Remove/Refix Reverse Sensor			\$ 120.00
	Remove/Refix Fuel Tank			\$ 150.00
	Transfer of Door		\$ 120.00	\$ 240.00
	Remove/Refix Undercarriage (RR)			\$ 200.00
	Rear Wheel Alignment		1850.00	\$ 120.00
	Re-set Rear ABS System			\$ 200.00
	Re-set Rear Power Window System			\$ 200.00
	Diagnostic & Resetting To Erase Fault Code			\$ 480.00
	TOTAL LABOUR			\$ 4,580.00
	ESTIMATE TOTAL			\$ 14,667.48
	09/12/2019 @ 0930h NA Author 2/Share 6 days Ryan LKK Auto 		8000.36 4/56400/-	
	LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:			
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

NAME
ADDRESS

Home Tel.:

VIN:

Registration: SHA 7925 K

Technician:

Mileage: 690315

Time Printed 9.12.19 12:08 PM

HYUNDAI I40

Front : Left

Actual	BEFORE	Specified Range
-1°10'		-3°00' 3°00'
3°32'		-0°19' 5°41'
-1°06'		-1°30' 1°30'
19°39'		
18°29'		

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.

Front : Right

Actual	BEFORE	Specified Range
-1°44'		-3°00' 3°00'
3°54'		-0°19' 5°41'
1°00'		-1°30' 1°30'
14°19'		
12°34'		

Front

	Actual	BEFORE	Specified Range
Cross Camber	0°34'		-3°00' 3°00'
Cross Caster	-0°22'		-3°00' 3°00'
Cross SAI	5°20'		-3°00' 3°00'
Total Toe	-0°06'		-3°00' 3°00'
Cross Turn Diff.			

Rear : Left

Actual	BEFORE	Specified Range
-0°22'		-3°30' 2°30'
2°20'		-1°30' 1°30'

Camber
Toe

Rear : Right

Actual	BEFORE	Specified Range
-0°47'		-3°30' 2°30'
-0°09'		-1°30' 1°30'

Rear

	Actual	BEFORE	Specified Range
Cross Camber	0°25'		-3°00' 3°00'
Total Toe	2°11'		-3°00' 3°00'
Thrust Angle	1°14'		-3°00' 3°00'



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL		Ref : CS/SMO19021585/Dsf3n2		
50 RAFFLES PLACE #05-01/06 SINGAPORE LAND TOWERSINGAPORE 048623		Date : 15-01-2020		
		Code : SMO		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SMJ 746A	Veh. Inspected	SHA 7925K	
Policy No.		Coverage (\$)	0.00	
Claim No.	CMTD1905706	Excess (\$)	0.00	
Assign From	HENRY IRENE JAMES	Assign Date	06/12/2019	
2. Vehicle Particulars & Condition				
Make & Model	HYUNDAI I40	c.c	1685	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	KMHLB41UMFU069620	Colour	BLUE	
Odometer	690315	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/60 R16	HANKOOK	5 mm	
L/H Front Tyre	205/60 R16	HANKOOK	5 mm	
R/H Rear Tyre	205/60 R16	HANKOOK	5 mm	
L/H Rear Tyre	205/60 R16	HANKOOK	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY AND N/S REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	05/12/2019	Inspection Date	09/12/2019	
Survey held at	CHUNNI MOTOR WORK PTE LTD BLK 10 ANG MO KIO IND. PARK 2A, #03-19 AMK AUTOPOINT SINGAPORE 568047.			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607196R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 7925K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	BENT / MOUNTING CRACKED	553.00	553.00
10	REAR BUMPER CLIP	NECESSARY	22.00	22.00
1	REAR BUMPER BRACKET, LH	NOT NECESSARY	35.60	-
1	REAR FENDER (LH)	DENTED	4,736.80	2,020.00
1	REAR FENDER INNER LINING (LH)	SERVICEABLE	169.30	-
1	REAR WINDSCREEN MOULDING	NECESSARY	28.30	28.30
1	REAR DOOR (LH)	DENTED	2,201.10	2,201.10
1	ROCKER PANEL OUTER GARNISH (LH)	NOT NECESSARY	341.40	-
1	REAR TYRE RIM (LH)	BENT	325.30	325.30
1	REAR WHEEL HUP-CAP (LH)	CUT	107.10	107.10
1	REAR WHEELBEARING ING & HUB	DAMAGED	362.00	362.00
1	REAR TRAILING ARM (LH)	DISTORTED	192.00	192.00
1	REAR ASSIST (LH)	DISTORTED	145.70	145.70
1	REAR SHOCK ABSORBER (LH)	DISTORTED	276.30	276.30
1	REAR SHOCK ABSORBER MOUNTING (LH)	NOT NECESSARY	81.30	-
1	REAR CROSSMEMBER	NOT NECESSARY	1,021.50	-
1	STABILIZER BAR	NOT NECESSARY	199.60	-
1	STABILIZER LINK	NOT NECESSARY	85.90	-
1	REAR UPPER ARM (LH)	DISTORTED	335.75	335.75
1	REAR LOWER ARM (LH)	DISTORTED	353.80	353.80
1	REAR KNUCKLE ARM (LH)	DISTORTED	545.60	545.60
	LESS 20% DISCOUNT		-2,423.87	-1,493.59
			9,695.48	5,974.36
SPECIAL NETT ITEMS				
1	REAR BUMPER RUBBER MAT (SN)	NECESSARY	50.00	50.00
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	46.00	46.00
1	REAR DOOR COMFORTDELGRO & APPS STICKER (LH) (SN)	NECESSARY	80.00	80.00
1	REAR TYRE (LH)(SN)	SERVICEABLE	216.00	-
			392.00	176.00

Report Ref No. CS/SMO19021585/Dsf3n2

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	PANEL BEATING.		1,200.00	600.00
	SPRAY PAINTING CHARGE.		1,250.00	600.00
	WIRING CHARGE.	NOT NECESSARY	50.00	-
	TUFF KOTE.		100.00	30.00
	REMOVE/REFIX CUSHION & UPHOLSTERY REAR.		150.00	80.00
	REMOVE/REFIX REAR WINDSCREEN GLASS.		120.00	80.00
	REMOVE/REFIX REVERSE SENSOR.		120.00	40.00
	REMOVE/REFIX FUEL TANK.	NOT NECESSARY	150.00	-
	TRANSFER OF DOOR.		240.00	60.00
	REMOVE/REFIX UNDERCARRIAGE (RR).		200.00	150.00
	REAR WHEEL ALIGNMENT.		120.00	60.00
	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE. }		480.00	150.00
	RE-SET REAR ABS SYSTEM. }		200.00	-
	RE-SET REAR POWER WINDOW SYSTEM. }		200.00	-
			4,580.00	1,850.00
	GRAND TOTAL		14,667.48	8,000.36
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			6,400.00

Report Ref No. CS/SMO19021585/Dsf3n2

ANG BRYAN TANI

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.