



19 Lorong 8 Toa Payoh
Singapore 319255



ESTIMATE / QUOTATION COST OF ACCIDENT REPAIR

REG NO: SLB8640Y	MODEL : FORESTER 2.0I-L AWD CVT
REF: INS/IC/CHI/0447/2019	YEAR: 26-APR-2016
ENGINE NO: FB20Y225570	CHASSIS NO: JF1SJ5KC5GG069160
DOA: 04 / 12 / 2019	TOA: 1815 HRS
TYPE OF CLAIM: OD	INS COMPANY: AIG

S/N	NATURE OF JOB	AMOUNT
1.	REPAIR/REPLACE FRH DOOR, FRH FENDER AND PANEL	\$ 1250.00
2.	RESpray FRH DOOR, FRH FENDER AND PANEL	\$ 1000.00
3.	TRANSFER / BALANCE TYRE / RIM	\$ 28.00
4.	DISMENTLE & REFIX UNDERCARRIAGE TO FACILITATE REPAIRS	\$ 684.00
5.	TRANSFER DOOR MECHANISM	\$ 142.00
6.	TO CONDUCT 4 WHEEL ALIGNMENT	\$ 171.00
7.	FAULT DIAGNOSTIC AND RESET SYSTEMS	\$ 235.00
8.	TO CONDUCT FRONT LIGHTING TEST	\$ 28.00
9.	SUNDRIES	\$ 100.00
Total Labour		\$ 3638.00

5001
400
2281
✓
✓
X
X

DATE APPROVAL:	
TIME APPROVAL:	
SURVEY BY:	Kenneth (LKK)
HP / EMAIL:	969106631
BEFORE PAINT:	Yes
DAYS GIVEN:	04 days

9/12/19

Not Authorized
Resurvey B4 paint
4 days

fax 62564315

disks body
4 days

LKK Auto-Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer
Signature:
Date:

Estimate

Date 12 / 06 / 2019

001 / 002

Name	QYOTATION FOR SLB8640Y	Tel (Home)	
Address		Tel (Office)	
E-Mail		Tel (Portable)	
		Fax	
		Model Name	S13
		Body Model	SJ5DK7C
		Vin-Code	JF1SJ5KC5GG069160

Part Number	Part Code Name	Part Code	Q'ty	Price	
57120SG0209P	FENDER COMPLETE-FRONT, RIGHT	FIG-540 57110	1	270.00	✓
59110SG021	MUD GUARD, FRONT RIGHT	FIG-541 59110B	1	108.00	X
60009SG0429P	PANEL ASSEMBLY-FRONT DOOR, RIGHT	FIG-605 60010	1	720.00	✓
61280SG020	WEATHER STRIP-DOOR, OUT RH	FIG-605 61280	1	100.80	?
61160FJ010V2	HANDLE-DOOR, OUTER	FIG-607 61160E	1	158.40	X
90422SG000	TAPE-FRONT DOOR, RIGHT	FIG-905 90422X	1	5.40	✓
90422SG020	TAPE-FRONT DOOR SASH RIGHT	FIG-905 90422A	1	18.00	✓
90422SG040	TAPE-FRONT DOOR SASH, REAR RIGHT	FIG-905 90422E	1	18.00	✓
63511SG001	WEATHER STRIP-FRONT DOOR, RIGHT	FIG-901 63511	1	122.40	X
63527SG100	RUN CHANNEL-FRONT DOOR, RIGHT	FIG-901 61234A	1	72.00	?
63571SG001	WEATHER STRIP-BODY SIDE, FLANGE FRONT	FIG-901 63571B	1	122.40	X
28111SG130	DISK WHEEL-ALUMINIUM	FIG-290 28111	1	1,500.00	✓
91112SG122	GARNISH-DOOR, RIGHT	FIG-914 91111B	1	198.00	X
60079AG003	HINGE-DOOR	FIG-605 60070	1	46.80	X
60079SG002	HINGE-FRONT DOOR, RIGHT	FIG-605 60070A	1	43.20	X
61124SG005	CHECKER ASSEMBLY-FRONT DOOR	FIG-605 61124	1	54.00	X
	TYRE (FRT RH) \$500				
		Page-Total		3,557.40	

Memo

--

70/50	Grand Total
	3,557.40

7,889.80#

Tel
