

rlimage

rong 8 Toa Payoh
Singapore 319255

ESTIMATE / QUOTATION COST OF AC

REG NO: SLB8640Y	MODEL : FORESTER 2.
REF: INS/IC/CHI/0447/2019	YEAR: 26-APR-2016
ENGINE NO: FB20Y225570	CHASSIS NO: JF1SJ5KC
DOA: 04 / 12 / 2019	TOA: 1815 HRS
TYPE OF CLAIM: OD	INS COMPANY: AIG

S/N	NATURE OF JOB
1.	REPAIR/REPLACE FRH DOOR, FRH FENDER AND
2.	RESPRAY FRH DOOR, FRH FENDER AND PANEL
3.	TRANSFER / BALANCE TYRE / RIM
4.	DISMENTLE & REFIX UNDERCARRIAGE TO FAC
5.	TRANSFER DOOR MECHANISM
6.	TO CONDUCT 4 WHEEL ALIGNMENT
7.	FAULT DIAGNOSTIC AND RESET SYSTEMS
8.	TO CONDUCT FRONT LIGHTING TEST
9.	SUNDRIES

DATE APPROVAL:	
TIME APPROVAL:	
SURVEY BY:	Kenneth (LKK)
HP / EMAIL:	96910663
BEFORE PAINT:	Yes
DAYS GIVEN:	04days

9/12/19

Not Authorized
Resurvey B4 paint

4days

 also body
4days

LKK Auto.
the Repair
• To resurvey
• To display de
• Parts prices &
• Third party su.
• No illegal mod.
• Supplementary
is subject to fine
Acknowledged by
Signature:
Date:

0.0
500.0+
400.0+
28.0+
228.0+
142.0+
171.0+
28.0+
=
1,497.0*
0.0
270.0+
720.0+
5.4+
18.0+
18.0+
1,500.0+
198,198.0+
18.0+
165.6+
10.8+
-
198,198.0+
198.0+
2,923.8+
0.0
270.0+
720.0+
5.4+
18.0+
18.0+
1,500.0+
198.0+
198.0+
18.0+
165.6+
10.8+
-
198.0+
2,923.8*
2,923.8x
70.0%
2,046.66*
0.0
0.0
1,497.0+
2,046.66+
350.0+
235.0+
=
4,128.66*

Tech Invs (\$
W