

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Chong Boon Sen

Date: 10 Dec 2019

## **Preliminary Advice**

Vehicle No	: SJZ4623X	Accident Date	: 03/12/2019
Make	: BMW 523I	Policy No.	: DMPCSN1834501901
Assignment Date	: 09/12/2019	Excess	: S\$0.00
Date of Inspection	: 09/12/2019	Est. Duration of Repair	: 4 days
Inspection At	: Jin Auto Services Pte Ltd (Defu) Blk 14 Defu Lane 10, #01-410/412 Singapore 539195		

### **Point of Impact / General Description of Damages**

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	4,274.69
Revised Amount	:S\$	4,214.69
Check Items (Estimated)	:S\$	0.00
Total	:S\$	4,214.69

Lump Sum Repair	:S\$	
-----------------	------	--

### **Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	31,000.00
COE / PARF Rebate	:S\$	24,269.00
Salvage Value	:S\$	
Margin for Repair	:S\$	6,731.00

### **Remarks**

- ( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : Repairer request to repair the vehicle on part by part basis due to no second hand parts.