

ASS. REC. BY:

REF:

CS/C12 M01617 / US f302

Special Instruction:

Surveyor:

Marcus

ASSIGNMENT (Office)

From (Person):

Chang Boun Sen

of

C12

Date/Time:

9.12.19 9.050.AM

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJZ 4623X

Insured:

at Workshop m/s:

Jm Auto Services

Tel:

62896126

of

BLK 14 Dafa Lane 10 #01-410/412

Policy No:

BMPESA B24501901

Claim No:

SNM M10205788

Sum Insured:

Excess:

Make of Veh:

D.O.A.

3.12.2019

(Client's Record)

CA REV

REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

9.12.19 10.26 a.m

Person Contacted:

Louis

Vehicle IN

OUT

Date/Time

Action/Instruction (✓) Estimate

SJZ 4623X - ✓

10/12/19

@ 11:27 am revised PA to Chang Boun Sen
via mmm.

10/12/19

@ 11:46 am mandate requested authorize repair to
Chang Boun Sen via mmm.

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: 5324623X
 at Workshop m/s Tin Auto.
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: 4 \$0/-
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 31k.
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 4 days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS 0220
 Date: _____ Person Contacted: 02716
 Vehicle: IN / OUT

Veh No: 5324623X Yr Regn: 29/1110
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or CA /
 Make: BMW 523i c.c. 2497
 Colour: Grey A/C: Insured / Std / NI / NA
 Sp. Reading: 257228 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: WBAFP32030C546971
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or
 Brake: Inorder / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 245-35-220
 R: 275-302R20
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or _____
 Front _____ Rear _____
 R/Bal. 6 mm R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. 3/12/19 D.O.I. 9/12/19
 Survey held at _____
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
RA.
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

1pm. net 6731wash want p/p for repair.

11/12/19 @ 11:20 am mandate approved by Alfred Toh via merimer
11/12/19 @ 14:44 pm informed c/n on part by part base to Louis
(repair) via email.

p/p 3870.19(15599.50 Red - 13%)

RECEIVED 09 JAN 2020

Date/Time, File Pass to?

09/01/20

Prel. Report



Final Report

1) Typist

Date/Time, File Return to?

2)

Days Of Repair: 4Resurvey No. of Trip: 1Survey Fee: 220

Transportation:

Add Fee:



Site Insp (\$

) S + RS, SI



Interview (\$

) Photos



Tech. Invs (\$

) Others



Weekend (\$

)

Report Format:

Lump sum I.B.I. (\$) 3870.19 p/p

TOTAL

220

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	06 Dec 2019 Sendback Est	06 Dec 2019 10:08 S\$4,274.69	09 Dec 2019 09:05 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured:	WILLIAM TAN KAY SOON, ID: S1547022D								
Vehicle Reg. No.:	SJZ4623X	Date of Loss:	03/12/2019 15:00 - :59 [108 Months and 4 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD / SNM19D205788/SJZ4623X/C BS	Policy/Cover Note No.:	DMPCSN1834501901 (Comprehensive)						
		Excess:	S\$0.00						
Repairer:	Jin Auto Services Pte Ltd (Defu) Blk 14 Defu Lane 10, #01-410/412, 539195 Defu Lane - Tel: 6289 8126								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 18/12/2019]								
Driver/Custodian:	TAN WEI LOONG, WILSON (/ Male), NRIC: S9211067B Email:								
ASSOCIATED MAIL RECEIVED									
View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS									
View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	022D
Vehicle Details	
Vehicle No.:	SJZ4623X
Vehicle to be Exported:	No
Intended Deregistration Date:	10 Dec 2019
Vehicle Make:	B.M.W.
Vehicle Model:	523I 2.5 AT ABS D/AB 2WD 4DR GAS/D
Primary Colour:	Grey
Manufacturing Year:	2010
Engine No.:	05397598N52B25AF
Chassis No.:	WBAFP32030C546971
Maximum Power Output:	150.0 kW (201 bhp)
Open Market Value:	\$39,742.00
Original Registration Date:	29 Nov 2010
First Registration Date:	29 Nov 2010
Transfer Count:	0
Actual ARF Paid:	\$39,742.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	28 Nov 2020
PARF Rebate Amount:	\$19,871.00
Intended COE Rebate Details	
COE Expiry Date:	28 Nov 2020
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$45,501.00
COE Rebate Amount:	\$4,398.00
Total Rebate Amount:	\$24,269.00

The information contained herein is correct as at 10 Dec 2019

OK



CONNECTING CAR BUYERS & SELLERS.
We'll handle your loans, insurance & other paperwork for FREE.

[Find out more](#)

bmw 523

Price Range ▼

Depreciation ▼

2010 ▼

Vehicle Type ▼


[Home](#) » [Used Cars](#) » [Direct Owners](#) » [BMW 5 Series 523i](#)

BMW 5 Series 523i

[Overview](#)
[Financial](#)
[Insurance](#)
[Accessories](#)
[Similar](#)
[Research](#)
[Photos](#)
[Map](#)

Price \$29,700

Depreciation ① \$20,160 /yr
View models with similar depre

Reg Date 28-Jun-2010
(6mths 17days COE left)

Mileage 107,000 km (11.3k /yr)

Manufactured ② 2010

Road Tax ③ \$1,796 /yr

Transmission Auto

Dereg Value ④ \$20,737 as of today (change)

OMV ⑤ \$37,309

COE ⑥ \$38,000

ARF ⑦ \$37,309

Engine Cap 2,497 cc

Power 150.0 kW (201 bhp)

Curb Weight ⑧ 1,650 kg

No. of Owners ⑨ 5

Type of Vehicle Luxury Sedan

Features

Award Winning Reliable BMW 6 Cylinder Engine. Enjoy The Sound And Power Without The Worries. View specs of the BMW 5 Series Sedan

Accessories

Standard Accessories Plus In Car Camera, M5 Rims And Sprint Booster. No Oil Leaks! All Wear And Tear Done Up! See Pics! Workshop Inspection Welcomed.

Description

Perfect Daily Driver. Sleek Piano Black Interior, No Uncle Feels. Serviced By R2D And 2G. Wear And Tear Are All Done Up. P Lanned For COE Extension But Job Dictates Otherwise. No Finance On The Car, Handover Anytime For Full Cash Deals. You Can Buy My Car And Drive Without Worries Or Buy A Cheaper One And Spend More Money Doing It Up At The Workshop!

Category


PARF Car, Direct Owner Sale

Status

Available

[Compare](#)


100% FREE
PAPERWORK
SUPPORT FOR
BOTH BUYER
& SELLER

[Price Chart](#)


Click on the point to view the vehic

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto)
Sent: Thursday, 9 January 2020 10:29 am
To: jouis@jinauto.com.sg
Cc: SUR
Subject: RE: SJZ 4623X OD (CTI) DOA - 03/12/2019
Attachments: SJZ 4623X - AUDATEX 1.pdf

Hi Jouis,

As spoken, Confirmed final fig \$ 3,870.19 @ 4 days of repairs before excess \$ 0/- & GST.

Wishing you a Happy and Prosperous Lunar New Year



Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Wednesday, 11 December 2019 2:44 pm
To: jouis@jinauto.com.sg
Cc: SUR <sur@lkkauto.com>
Subject: SJZ 4623X OD (CTI) DOA - 03/12/2019

Hi Jouis,

As instructed by our client, please proceed to repair the insured vehicle **SJZ 4623X (Excess \$ 0/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto)
Sent: Wednesday, 11 December 2019 2:44 pm
To: jouis@jinauto.com.sg
Cc: SUR
Subject: SJZ 4623X OD (CTI) DOA - 03/12/2019

Hi Jouis,

As instructed by our client, please proceed to repair the insured vehicle **SJZ 4623X (Excess S 0/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right not to pay if there is no valid approval obtained before repair.

"Best Wishes for Merry Christmas & Happy New Year 2020"

Thank you,

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

View Received Message

This mail is associated with :

SJZ4623X (SNM19D205788/SJZ4623X/CBS)

OD

Dec 3 2019 3:00PM

[WILLIAM TAN KAY SOON]

Jin Auto Services Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From China Taiping Insurance (Singapore) Pte. Ltd. (HQ) (CHINA_TAIPING), sent on 09/01/2020 10:05 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$3870.19) - SJZ4623X - Claim Handler: Chong Boon Sen

Approved:3870.19:Please proceed to authorize repairs at \$3870.19 (part by part basis) Excess waived, RE-INSPECTION OF VEHICLE REQUIRED.

DOCUMENTS SUMMARY

There are no documents.

View Received Message

This mail is associated with :

SJZ4623X (SNM19D205788/SJZ4623X/CBS)
OD
Dec 3 2019 3:00PM
[WILLIAM TAN KAY SOON]
Jin Auto Services Pte Ltd

Reply Reply All Mark as Unread Print Message Delete Message Forward

From China Taiping Insurance (Singapore) Pte. Ltd, (HQ) (CHINA_TAIPING), sent on 11/12/2019 11:20 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (\$4214.69) - SJZ4623X - Claim Handler: Chong Boon Sen

Approved:4214.69:Please proceed to authorize repairs at \$4,214.69 (part by part basis) Excess waived. RE-INSPECTION OF VEHICLE REQUIRED.

DOCUMENTS SUMMARY
There are no documents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Chong Boon Sen

Date: 08 Jan 2020

Preliminary Advice

Vehicle No	: SJZ4623X	Accident Date	: 03/12/2019
Make	: BMW 523i	Policy No.	: DMPCSN1834501901
Assignment Date	: 09/12/2019	Excess	: S\$0.00
Date of Inspection	: 09/12/2019	Est. Duration of Repair	: 4 days
Inspection At	: Jin Auto Services Pte Ltd (Defu) Blk 14 Defu Lane 10, #01-410/412 Singapore 539195		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	4,469.69 (inclusive supp)
Revised Amount	:S\$	3,870.19 (inclusive supp)
Check Items (Estimated)	:S\$	0.00
Total	:S\$	3,870.19
Lump Sum Repair	:S\$	3,850.00

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	31,000.00
COE / PARF Rebate	:S\$	24,269.00
Salvage Value	:S\$	
Margin for Repair	:S\$	6,731.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : We have received supplementary from repairer. Our surveyor had since checked and verified the supplementary parts and is of the view that the supplementary parts are consistent to the nature of the accident and is economical to repair. Supplementary amount is \$ 195.00

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Chong Boon Sen

Date: 08 Jan 2020

Preliminary Advice

Vehicle No	: SJZ4623X	Accident Date	: 03/12/2019
Make	: BMW 523i	Policy No.	: DMPCSN1834501901
Assignment Date	: 09/12/2019	Excess	: S\$0.00
Date of Inspection	: 09/12/2019	Est. Duration of Repair	: 4 days
Inspection At	: Jin Auto Services Pte Ltd (Defu) Blk 14 Defu Lane 10, #01-410/412 Singapore 539195		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	4,469.69 (inclusive supp)
Revised Amount	:S\$	3,870.19 (inclusive supp)
Check Items (Estimated)	:S\$	0.00
Total	:S\$	3,870.19

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	31,000.00
COE / PARF Rebate	:S\$	24,269.00
Salvage Value	:S\$	
Margin for Repair	:S\$	6,731.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : We have received supplementary from repairer. Our surveyor had since checked and verified the supplementary parts and is of the view that the supplementary parts are consistent to the nature of the accident and is economical to repair. Supplementary amount is \$ 195.00

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Chong Boon Sen

Date: 08 Jan 2020

Preliminary Advice

Vehicle No	: SJZ4623X	Accident Date	: 03/12/2019
Make	: BMW 523i	Policy No.	: DMPCSN1834501901
Assignment Date	: 09/12/2019	Excess	: S\$0.00
Date of Inspection	: 09/12/2019	Est. Duration of Repair	: 4 days
Inspection At	: Jin Auto Services Pte Ltd (Defu) Blk 14 Defu Lane 10, #01-410/412 Singapore 539195		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	4,469.69
Revised Amount	:S\$	3,870.19
Check Items (Estimated)	:S\$	0.00
Total	:S\$	3,870.19
Lump Sum Repair	:S\$	3,850.00

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	31,000.00
COE / PARF Rebate	:S\$	24,269.00
Salvage Value	:S\$	
Margin for Repair	:S\$	6,731.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Chong Boon Sen

Date: 10 Dec 2019

Preliminary Advice

Vehicle No	: SJZ4623X	Accident Date	: 03/12/2019
Make	: BMW 523i	Policy No.	: DMPCSN1834501901
Assignment Date	: 09/12/2019	Excess	: S\$0.00
Date of Inspection	: 09/12/2019	Est. Duration of Repair	: 4 days
Inspection At	: Jin Auto Services Pte Ltd (Defu) Blk 14 Defu Lane 10, #01-410/412 Singapore 539195		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	4,274.69
Revised Amount	:S\$	4,214.69
Check Items (Estimated)	:S\$	0.00
Total	:S\$	4,214.69
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	31,000.00
COE / PARF Rebate	:S\$	24,269.00
Salvage Value	:S\$	
Margin for Repair	:S\$	6,731.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Repairer request to repair the vehicle on part by part basis due to no second hand parts.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	04/12/2019 15:02
Date Of Accident	03/12/2019 15:05
Exact Location Of Accident	CTE TOWARDS PIE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJZ4623X
Insured/Policyholder	
Name Of Registered Owner	WILLIAM TAN KAY SOON
NRIC No	S1547022D
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96791538
Alternative Phone No	OFFICE-93889551

Vehicle Particulars

Manufacturer	BMW
Model	523I
Exact Purpose for which vehicle was being used at time of accident	WORK
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMPCSN1834501901
Cover Note Number	

Driver

Name of Driver	TAN WEI LOONG, WILSON
NRIC No	S9211067B
Date Of Birth	12/03/1992
Occupation	INDOOR
Date Of Driving Pass	09/01/2012
Driving Experience	7 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-93889551
Fax Number	
Contact Number	

Address	15 KAMPONG SIREH
Postcode	537127
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	CHILDREN
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

WHEN I WAS TRAVELLING ALONG CTE TOWARDS PIE, THE FRONT VEHICLE B SUDDENLY JAM BRAKE. I COULDN'T BRAKE IN TIME AND ACCIDENTALLY HIT ONTO THE REAR PORTION OF VEHICLE B. NO ONE WAS INJURED.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBE2538C
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

14:15 pm
~ ~ ~

Sketch Plan #2

SKETCH PLAN

PTE



DOA: 03/12/19

A: SJZ 4623X

B: GBE 2538C

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

When I was travelling along CTE towards PTE, the front vehicle B suddenly jam brake. I couldn't brake in time and accidentally hit onto the rear portion of vehicle B. No one was injured.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



中国太平
CHINA TAIPIING

中国太平保险(新加坡)有限公司
CHINA TAIPIING INSURANCE (SINGAPORE) PTE. LTD.
Co. Reg. No. 20000344E

MOTOR PRIVATE CAR

HKIE
R. SN
ANDSONA
Civ. Type: C

CERTIFICATE OF INSURANCE

Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189)
Motor Vehicles (Third-Party Risks and Compensation) Rules, 1960
Road Transport Act, 1967 (Malaysia)
Motor Vehicles (Third-Party Risks) Rules, 1959 (Malaysia)

ORIGINAL

CERTIFICATE No: **CHPCS1834502901** Engine No: **05357598N526254P**
Chassis: **WBAFP32030C546971**

1. Make Mark and Registration Number of Vehicle: **S124023X** AUTOSAFE

2. Name of Policy Holder: **WILLIAM TAN KAY SOON**

3. Effective date of the Commencement of Insurance for the purpose of the Regulations, Ordinance or Enactment: **29 November 2019** Named Drivers Ex Sect. 1 \$11,000.00
Additional Ex Other than Named Drivers:
Ex Sect. 1 - Age <= 25 \$11,000.00
Ex Sect. 1 - Age >= 26 \$1500.00
* Age as at date of accident
EX ON WINDSCREEN \$1100.00

4. Date of Expiry of Insurance: **28 November 2020**

5. Persons or Classes of Persons entitled to drive*

(a) the Policyholder,

(b) any other person who is driving on the Policyholder's order or with his permission.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

E. Limitations as to use*

use for social, domestic and pleasure purposes and for the Policyholder's business.
The policy does not cover use for hire or reward tuition driving test racing pace-making, reliability trial, speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with the Motor Trade.

Excess whichever is applicable for losses occurring outside Singapore (Constructive Total Loss/Theft) will be doubled.

One time waiver of Excess for the first \$11,000 will apply to the Insured and Named Drivers in the event of Own Damage Claim at our Authorised workshops for each Policy year.

HIRE PURCHASE CO.: **IKING LEONG FINANCE LTD AS HP OWNER**

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act 1967 (Malaysia), are not to be included under these headings.

I/We hereby Certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1967 (Malaysia).

Please see reverse

For CHINA TAIPIING INSURANCE (SINGAPORE) PTE. LTD.

By **HO LI HUA IRENE**
Authorised Officer

Authorised Signatory

3 Anson Road #15-00 Springwell Tower Singapore 079909 Tel: 6389 6111 Fax: 6225 3582 Website: www.ag.chinaping.com

Jin Auto Services Pte Ltd
#01-410/412, 14 Defu Lane 10
539195

Insurer Reference: DMPCSN1834501901
Repairer Reference: 023575
Date calculated: 06/12/2019 10:05 AM

Full Report
Registration: SJZ4623X
Printed: 06/12/2019 10:05 AM

Summary Information

Claim

Location:	Singapore (SG)	Work Provider:	China Taiping Insurance (Singapore) Pte Ltd
Printed by:	JOUIS SEOW	Currency:	SGD
Claim Reference:	DMPCSN1834501901	Date of Incident:	05/12/19
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle

Manufacturer:	BMW
Model:	5 SERIES F10
Sub Model:	523 I
Model Sheet Number:	01 42 01
Registration:	SJZ4623X
VIN number:	WBAFP32030C546971
Odometer:	

Model Specs

FROM 09/2010	AIR CON AUTO 2-ZONES	COMFORT ACCESS SYST	DIP REAR VIEW MIRROR
XENON HEADLAMPS	INTER LIGHT AMBIENCE	HEADLAMP WASHERS	DAKOTA LEATHER TRIM
ELEC/SEAT ADJ MEMORY	AUTO TAILGATE CONTR	DIP REAR VIEW MIRROR	FRT/RR PARK DIST CON
2.5 LTR 150KW	8-GEAR AUTOMATIC	TYRES 225/55 YR 17	WHEELS 8J X 17 ALLOY
INT MOULDING BLACK	VERSION HOT COUNTRY	TYRE W/FLAT RUNNING	PREPARE OFF VEHICLE
TWO COAT PEARL/MICA			

Vehicle Condition


Vehicle Status

Pre-Accident Damage:

Date of Inspection:

Damage Areas

All ☐
Underbody ☐



Labour

Code	Description	Time Base 12 WU/h	Price = 42.00 SGD/h	
			WU	Price SGD
NO NUMBER	ADD/TIME FOR MAIN WORK		2.0	7.00
51 11 656	R + R FRONT BUMPER		9.0	31.50
51 11 551	R + R FRONT UPPER BUMPER CARRIER		4.0	14.00
51 11 592	REMOVE/REFIT FRONT BUMPER BAR TRIM (WITH FRONT BUMPER BAR REMOVED)		6.0	21.00
66 20 610	ADD/WORK PARK DISTANCE CONTROL		4.0	14.00
41 61 510	R + R BONNET		4.0	14.00
41 61 503	REPLACE BONNET (WITH BONNET REMOVED)		10.0	35.00
Labour Cost		Hrs	WU	
Panel / Mechanical Labour		3.30	39.0	136.50
Total of Labour				136.50

Paint

Paint Work		SYSTEM AZT	Time Basis 10 WU/h	
Code	Description - TWO COAT PEARL/MICA		WU	Price SGD
	BONNET NEW PART PAINTING		30.0	
	FRONT BUMPER NEW PART PAINT K1G/P		35.0	
	L/F WING REPAIR PAINTING >50%		18.0	
	R/F WING REPAIR PAINTING >50%		18.0	

Paint Material Per Part

Code	Description	Price SGD
0471	BONNET NEW PART PAINTING	104.75

Paint Material Per Part

Code	Description	Price SGD
0283	FRONT BUMPER NEW PART PAINT K1G/P	142.20
0741	L/F WING REPAIR PAINTING >50%	18.57
0742	R/F WING REPAIR PAINTING >50%	18.57

Labour Cost - Paint

	Hrs	WU	Price SGD
Factor	42.00 SGD/h		
Time Paint		101.0	
Preparation Main Work Metal	2.50	25.0	105.00
Preparation Comp. Work Plastic	0.80	8.0	33.60
Total	10 WU/h	13.40	562.80
Total	12 WU/h	13.40	562.80

Material Cost - Paint

	Price SGD
New Part Painting	104.75
New Part Painting - Plastic K1G/PUR	142.20
Repair Painting	37.14
Material-constant Metal Preparation	28.60
Material-constant Plastic	12.70
Total	325.39

Spare Parts

Code	Description	Part Number	Supplier	prices as at 2019-11-11	Price SGD
0283	FRONT BUMPER COVER	51 11 7 285 961	DO ✓	less 20%	980.00 ✓
0303	FRT BUMPER GRILLE	51 11 7 285 950	11X ✓		60.00 X
0308	R/BUMPER AIR GRILLE	51 11 7 200 700	707 ✓	less 20%	60.00 ✓
0340	FRT UPP IMPACT DAMP	51 11 7 200 707	7.5 ✓	less 20%	50.00 ✓
0415	L/F GRILLE	51 13 7 203 649	CNE ✓	S.N	100.00 ✓
0416	R/F GRILLE	51 13 7 203 650	CNE ✓	S.N	100.00 ✓
0431	GRILLE BADGE	51 14 7 057 794	SEN ✓		75.00 ✓
0471	BONNET	41 61 7 207 194	Buc ✓	less 20%	1,680.00 ✓
0623	TUBE	61 67 7 178 742	NEC ✓	less 20%	45.00 ✓
f: OEM Parts	Savings				0.00
n: Non-OEM Parts	Subtotal				3,150.00
u: Used parts	Fixed Sundry Parts Price				100.00
	Total				3,250.00

Final Calculation

	SGD	SGD
Parts	3,150.00	
Fixed Sundry Parts Price	100.00	
Total Parts		3,250.00
Labour Time Base 12 WU/h		
Total 39.0 WU X 42.00 SGD/h	136.50 75	
Total of Labour		136.50
Paint Work Time Base 10 WU/h		
Labour Cost 134.0 WU X 42.00 SGD/h	562.80	
Material Cost	325.39	
Total Paint Including Material		888.19
Repair Cost Excludes GST		4,274.69
GST (+7.00%)		299.23
Repair Cost Included GST		4,573.92

4469.69

Comments

* - USER SUPPLIED DATA
NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS

Assessment Note

No assessment notes entered.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 06 Jan 2020)

Parts: 143 BMW 523I 2.5 AT ABS D/AB 2WD 4DR GAS/D NAV (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Jin Auto Services Pte Ltd/SJZ4623X/06/01/2020 15:46

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1	51 74 7 200 787	*radiator air guide	0.00	0.00	*185.00 F
2	1		*L/WASHER JET CARRIER	0.00	0.00	*10.00 F
Total Parts (S\$)						195.00

F=Franchise part.

Jin Auto Services Pte Ltd/SJZ4623X/06/01/2020 15:46. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

TAX INVOICE

INVOICE NO. **81718**

DATE	12/12/2019	PAGE	1
TERM	30 Days Net	SALESMAN	Ong Hai C
CUSTOMER REF.	SJZ4623	OUR REF.	58832

GST REG. NO.: M2-0090482-6 CO REG. NO.: 198905613E


ACCOUNT NUMBER : JIN AUTO2 TIME:12:15

JIN AUTO SERVICES PTE LTD
 BLK 14, #01-412,
 DEFU LANE 10,
 SINGAPORE 539191
 Telephone No : 62898126

ROUTE
 UB12

DELIVER TO :

JIN AUTO SERVICES PTE LTD
 BLK 14, #01-412,
 DEFU LANE 10,
 SINGAPORE 539191



PART NO.	PARTICULARS	LOC	QUANTITY	UNIT PRICE	AMOUNT
1 BW/51 13 7 203 649	RAD GRILLE LH	1D-8F	1 PC	100.00	
2 BW/51 13 7 203 650	RAD GRILLE RH	1E-13G	1 PC	100.00	
3 BW/51 74 7 200 781	FR CENTRE AIR DUCT M AERO	6D-6B	1 PC	185.00	

GOODS RECEIVED IN GOOD ORDER
 AND CONDITION.

*GOODS SOLD ARE NOT RETURNABLE.
 *OVERDUE ACCOUNTS SHALL BEAR INTEREST AT UOB'S
 PREVAILING LENDING RATE
 *CASH INVOICE MUST BE PAID WITHIN 7 DAYS
 FROM DATE OF INVOICE.

Exclusive Distributor



Stockists



Payment via telegraphic transfer to
 Name of Bank: United Overseas Bank
 Account Name: Min Ghee Auto Pte Ltd
 Branch Code: 046
 Account No.: 503-309-511-3
 *Please send a screenshot of your payment/
 transfer confirmation to
 account@minghee.com

TOTAL

SIN

ADD GST

7%

AMOUNT DUE

SIN

SIGN & COMPANY'S STAMP

DATE

ALL CHEQUES MUST BE MADE PAYABLE TO
 MIN GHEE AUTO PTE. LTD.

For MIN GHEE AUTO PT

1, Jalan Lembah Kallang, #01-01 Min Ghee Building Singapore 339564
Main Tel: 6298 3888 Fax: 6291 2172, 6294 1450 Accounts Tel: 6297 0863
Email: info@minghee.com (Main), account@minghee.com (Accounts)
Website: http://www.minghee.com

TAX INVOICE

INVOICE NO. 817191

DATE	12/12/2019	PAGE	1
TERM	30 Days Net	SALESMAN	Ong Hai C
CUSTOMER REF.		OUR REF.	58939

GST REG. NO.: M2-0090482-6 CO REG. NO.: 198905613E

ACCOUNT NUMBER : JIN AUTO2 TIME:13:52

JIN AUTO SERVICES PTE LTD
BLK 14, #01-412,
DEFU LANE 10,
SINGAPORE 539191
Telephone No : 62898126

ROUTE
UB12

DELIVER TO :

JIN AUTO SERVICES PTE LTD
BLK 14, #01-412,
DEFU LANE 10,
SINGAPORE 539191



PART NO.	PARTICULARS	LOC	QUANTITY	UNIT PRICE	AMOUNT
1 BW51 11 7 200 791	LEVER H/L WASHER LH	1E-7D	1 PC	10.00	

GOODS RECEIVED IN GOOD ORDER AND CONDITION.

*GOODS SOLD ARE NOT RETURNABLE.
*OVERDUE ACCOUNTS SHALL BEAR INTEREST AT UOB'S PREVALING LENDING RATE
*CASH INVOICE MUST BE PAID WITHIN 7 DAYS FROM DATE OF INVOICE.

Exclusive Distributor
HDK
Stockists

Payment via telegraphic transfer to
Name of Bank: United Overseas Bank
Account Name: Min Ghee Auto Pte Ltd
Branch Code: 046
Account No.: 503-309-511-3
*Please send a screen shot of your payment/transfer confirmation to account@minghee.com.

TOTAL	SIN
ADD GST	7%
AMOUNT DUE	SIN

SIGN & COMPANY'S STAMP

DATE

ALL CHEQUES MUST BE MADE PAYABLE TO MIN GHEE AUTO PTE. LTD.



For MIN GHEE AUTO PT

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park, 51
Ubi Avenue 1
408933

Insurer Reference: DMPCSN1834501901
Repairer Reference: 023575
Date calculated: 08/01/2020 2:44 PM

Full Report
Registration: SJZ4623X
Printed: 08/01/2020 2:45 PM

Summary Information

Claim

Location:	Singapore (SG)	Work Provider:	China Taiping Insurance (Singapore) Pte Ltd
Printed by:	KK LAU	Currency:	SGD
Claim Reference:	DMPCSN1834501901	Date of Incident:	05/12/19
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle

Manufacturer:	BMW
Model:	5 SERIES F10
Sub Model:	523 I
Model Sheet Number:	01 42 01
Registration:	SJZ4623X
VIN number:	WBAFP32030C546971
Odometer:	

Model Specs

FROM 09/2010	AIR CON AUTO 2-ZONES	COMFORT ACCESS SYST	DIP REAR VIEW MIRROR
XENON HEADLAMPS	INTER LIGHT AMBIENCE	HEADLAMP WASHERS	DAKOTA LEATHER TRIM
ELEC/SEAT ADJ MEMORY	AUTO TAILGATE CONTR	DIP REAR VIEW MIRROR	FRT/RR PARK DIST CON
2.5 LTR 150KW	8-GEAR AUTOMATIC	TYRES 225/55 YR 17	WHEELS 8J X 17 ALLOY
INT MOULDING BLACK	VERSION HOT COUNTRY	TYRE W/FLAT RUNNING	PREPARE OFF VEHICLE
TWO COAT PEARL/MICA			

Vehicle Condition


Vehicle Status

Pre-Accident Damage:

Date of Inspection:

Damage Areas

All ☐
Underbody ☐



Labour

Code	Description	Time Base 12 WU/h	Price = 42.00 SGD/h	
			WU	Price SGD
NO NUMBER	ADD/TIME FOR MAIN WORK		2.0	7.00
51 11 656	R + R FRONT BUMPER		9.0	31.50
51 11 566	R + R BOTH FRONT BUMPER CARRIERS		7.0	24.50
51 11 551	R + R FRONT UPPER BUMPER CARRIER		4.0	14.00
51 11 592	REMOVE/REFIT FRONT BUMPER BAR TRIM (WITH FRONT BUMPER BAR REMOVED)		6.0	21.00
66 20 610	ADD/WORK PARK DISTANCE CONTROL		4.0	14.00
51 71 600)	R + R RADIATOR AIR GUIDE		2.0	7.00
61 67 621	R + R L/HEADLAMP WASHER NOZZLE		2.0	7.00
41 61 510	R + R BONNET		4.0	14.00
41 61 503	REPLACE BONNET (WITH BONNET REMOVED)		10.0	35.00
Labour Cost		Hrs	WU	
Panel / Mechanical Labour		4.20	50.0	175.00
Total of Labour				175.00

Paint

Paint Work		SYSTEM AZT	Time Basis 10 WU/h	
Code	Description - TWO COAT PEARL/MICA		WU	Price SGD
	BONNET NEW PART PAINTING		30.0	
	FRONT BUMPER NEW PART PAINT K1G/P		35.0	
	L/F WING REPAIR PAINTING >50%		18.0	
	R/F WING REPAIR PAINTING >50%		18.0	

Paint Material Per Part

Code	Description	Price SGD
0471	BONNET NEW PART PAINTING	104.75
0283	FRONT BUMPER NEW PART PAINT K1G/P	142.20
0741	L/F WING REPAIR PAINTING >50%	18.57
0742	R/F WING REPAIR PAINTING >50%	18.57

Labour Cost - Paint

Factor	42.00 SGD/h	Hrs	WU	Price SGD
Time Paint			101.0	
Preparation Main Work Metal		2.50	25.0	105.00
Preparation Comp. Work Plastic		0.80	8.0	33.60
Total	10 WU/h	13.40	134.0	562.80
Total	12 WU/h	13.40	160.8	562.80

Material Cost - Paint

	Price SGD
New Part Painting	104.75
New Part Painting - Plastic K1G/PUR	142.20
Repair Painting	37.14
Material-constant Metal Preparation	28.60
Material-constant Plastic	12.70
Total	325.39

Spare Parts

				prices as at 2019-12-16
Code	Description	Part Number	Supplier	Price SGD
0283	FRONT BUMPER COVER	51 11 7 285 961		784.00
0308	R/BUMPER AIR GRILLE	51 11 7 200 700		48.00
0340	FRT UPP IMPACT DAMP	51 11 7 200 707		40.00
0415	L/F GRILLE	51 13 7 203 649		100.00
0416	R/F GRILLE	51 13 7 203 650		100.00
0431	GRILLE BADGE	51 14 7 057 794		60.00
0471	BONNET	41 61 7 207 194		1,344.00
0623	TUBE	61 67 7 178 742		36.00
0631	L/WASHER JET CARRIER	51 11 7 200 791		10.00
1009	RADIATOR AIR GUIDE	51 74 7 200 787		185.00
f: OEM Parts	Savings			0.00
n: Non-OEM Parts	Subtotal			2,707.00
u: Used parts	Fixed Sundry Parts Price			100.00
	Total			2,807.00

Final Calculation

	SGD	SGD
Parts	2,707.00	
Fixed Sundry Parts Price	100.00	
Total Parts		2,807.00
Labour Time Base 12 WU/h		
Total 50.0 WU X 42.00 SGD/h	175.00	
Total of Labour		175.00
Paint Work Time Base 10 WU/h		
Labour Cost 134.0 WU X 42.00 SGD/h	562.80	
Material Cost	325.39	
Total Paint Including Material		888.19
Repair Cost Excludes GST		3,870.19
GST (+7.00%)		270.91
Repair Cost Included GST		4,141.10

Comments

* - USER SUPPLIED DATA

NN - NO MANUFACTURERS CODE EXISTS

) - WU PARTIAL INCL IN OTHER POSITIONS

Assessment Note

No assessment notes entered.

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	06 Dec 2019 Sendback Est	06 Dec 2019 10:08 S\$4,274.69	09 Dec 2019 09:05 Edit Adj Rpt	S\$3,870.19 Edit Estimates	S\$3,870.19 View Rpt		Pending for Survey Report Cancel Case
Supp #1	06 Jan 2020 15:44	06 Jan 2020 15:46 S\$195.00	06 Jan 2020 15:46			(Combined)	Combined with Main Uncombine Suppl.

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured:	WILLIAM TAN KAY SOON, ID: S1547022D								
Vehicle Reg. No.:	SJZ4623X	Date of Loss:	03/12/2019 15:00 - :59 [108 Months and 4 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD / SNM19D205788/SJZ4623X/CBS	Policy/Cover Note No.:	DMPCSN1834501901 (Comprehensive)						
		Excess:	S\$0.00						
Repairer:	Jin Auto Services Pte Ltd (Defu) Blk 14 Defu Lane 10, #01-410/412, 539195 Defu Lane - Tel: 6289 8126								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 18/12/2019]								
Driver/Custodian:	TAN WEI LOONG, WILSON (/ Male) , NRIC: S9211067B Email:								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> CHINA_TAIPING (09/01/2020): Alert - Adj Mandate Approved (S\$3870.19) - SJZ4623X - Claim Handler: Chong Boon ... CHINA_TAIPING (11/12/2019): Alert - Adj Mandate Approved (S\$4214.69) - SJZ4623X - Claim Handler: Chong Boon ... 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SJZ4623X (SNM19D205788/SJZ4623X/CBS)

OD

Dec 3 2019 3:00PM

[WILLIAM TAN KAY SOON]

Jin Auto Services Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)
View [View in Browser](#)

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Jin Auto Services Pte Ltd (Defu)	Thumbnail	Print
1	06/12/19 10:08	Repairer Estimates	Load HTM	<input checked="" type="checkbox"/>
2	06/01/20 15:46	Repairer Estimates Suppl. #1	Load HTM	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	10/12/19 11:27	Adjuster Immediate Advice	Load HTM	<input checked="" type="checkbox"/>
2	08/01/20 15:10	Adjuster Immediate Advice	Load HTM	<input checked="" type="checkbox"/>
3	08/01/20 15:28	Adjuster Immediate Advice	Load HTM	<input checked="" type="checkbox"/>
4	08/01/20 15:35	Adjuster Immediate Advice	Load HTM	<input checked="" type="checkbox"/>
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Jin Auto Services Pte Ltd (Defu)	Thumbnail	Print
1	06/12/19 09:45	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
2	06/12/19 09:45	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
3	06/12/19 09:45	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
4	06/12/19 09:45	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
5	06/12/19 09:45	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
6	06/12/19 09:45	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
7	06/12/19 09:45	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
8	06/12/19 09:45	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
9	06/12/19 09:46	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
10	06/12/19 09:46	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
11	06/12/19 09:46	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
12	06/12/19 09:46	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
13	06/12/19 09:46	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
14	06/12/19 09:46	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
15	06/12/19 09:46	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
16	06/12/19 09:46	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
17	06/12/19 09:46	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	09/12/19 17:43	Chassis Number	Load JPG	<input checked="" type="checkbox"/>
2	09/12/19 17:43	Odometer Reading	Load JPG	<input checked="" type="checkbox"/>
3	09/12/19 17:45	General View	Load JPG	<input checked="" type="checkbox"/>
4	09/12/19 17:45	General View	Load JPG	<input checked="" type="checkbox"/>
5	09/12/19 17:45	General View	Load JPG	<input checked="" type="checkbox"/>
6	09/12/19 17:45	General View	Load JPG	<input checked="" type="checkbox"/>
7	09/12/19 17:45	General View	Load JPG	<input checked="" type="checkbox"/>
8	09/12/19 17:45	General View	Load JPG	<input checked="" type="checkbox"/>
9	09/12/19 17:45	General View	Load JPG	<input checked="" type="checkbox"/>
10	09/12/19 17:45	General View	Load JPG	<input checked="" type="checkbox"/>
11	09/12/19 17:45	General View	Load JPG	<input checked="" type="checkbox"/>
12	09/12/19 17:45	General View	Load JPG	<input checked="" type="checkbox"/>
13	09/12/19 17:45	General View	Load JPG	<input checked="" type="checkbox"/>
14	09/12/19 17:45	General View	Load JPG	<input checked="" type="checkbox"/>
15	09/12/19 17:45	General View	Load JPG	<input checked="" type="checkbox"/>
16	09/12/19 17:45	General View	Load JPG	<input checked="" type="checkbox"/>
17	09/12/19 17:45	General View	Load JPG	<input checked="" type="checkbox"/>
18	09/12/19 17:45	General View	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Jin Auto Services Pte Ltd (Defu)		Thumbnail	Print
19	09/12/19 17:45	General View		Load JPG	<input checked="" type="checkbox"/>
20	09/12/19 17:45	General View		Load JPG	<input checked="" type="checkbox"/>
21	09/12/19 17:45	General View		Load JPG	<input checked="" type="checkbox"/>
22	09/12/19 17:45	General View		Load JPG	<input checked="" type="checkbox"/>
23	09/12/19 17:45	General View		Load JPG	<input checked="" type="checkbox"/>
24	09/12/19 17:45	General View		Load JPG	<input checked="" type="checkbox"/>
25	09/12/19 17:45	General View		Load JPG	<input checked="" type="checkbox"/>
26	09/12/19 17:45	General View		Load JPG	<input checked="" type="checkbox"/>
27	09/12/19 17:45	General View		Load JPG	<input checked="" type="checkbox"/>
28	09/12/19 17:45	General View		Load JPG	<input checked="" type="checkbox"/>
29	09/12/19 17:45	General View		Load JPG	<input checked="" type="checkbox"/>
30	09/12/19 17:45	General View		Load JPG	<input checked="" type="checkbox"/>
31	09/12/19 17:45	General View		Load JPG	<input checked="" type="checkbox"/>
32	09/12/19 17:45	General View		Load JPG	<input checked="" type="checkbox"/>
33	09/12/19 17:45	General View		Load JPG	<input checked="" type="checkbox"/>
34	09/12/19 17:45	General View		Load JPG	<input checked="" type="checkbox"/>
35	09/12/19 17:45	General View		Load JPG	<input checked="" type="checkbox"/>
36	09/12/19 17:45	General View		Load JPG	<input checked="" type="checkbox"/>
37	09/12/19 17:45	General View		Load JPG	<input checked="" type="checkbox"/>
38	09/12/19 17:45	General View		Load JPG	<input checked="" type="checkbox"/>
39	09/12/19 17:45	General View		Load JPG	<input checked="" type="checkbox"/>
40	09/12/19 17:45	General View		Load JPG	<input checked="" type="checkbox"/>
41	31/12/19 07:49	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
42	31/12/19 07:49	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
43	31/12/19 07:49	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
44	31/12/19 07:49	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
45	31/12/19 07:49	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
46	31/12/19 07:49	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
47	31/12/19 07:49	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
48	31/12/19 07:49	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
49	31/12/19 07:49	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
50	31/12/19 07:49	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
51	31/12/19 07:49	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
52	31/12/19 07:49	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
53	31/12/19 07:49	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
54	31/12/19 07:49	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
55	31/12/19 07:49	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
56	31/12/19 07:49	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
57	31/12/19 07:49	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Jin Auto Services Pte Ltd (Defu)		Thumbnail	Print
1	06/12/19 09:44	E-filed GIA report		Load PDF	
2	06/12/19 10:08	AUDATEX		Load PDF	
3	06/12/19 10:09	PARF VALUE		Load PDF	
4	06/01/20 15:46	Purchase Invoice		Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	10/12/19 11:23	ESTIMATE.pdf		Load PDF	
2	10/12/19 11:23	SJZ 4623X GIA.pdf		Load PDF	
3	10/12/19 11:44	AUDATEX.pdf		Load PDF	
4	08/01/20 15:07	ESTIMATE & SUPP MARKED.pdf		Load PDF	
5	08/01/20 15:07	SJZ 4623X - AUDATEX.pdf		Load PDF	
6	09/01/20 10:24	SJZ 4623X - AUDATEX 1.pdf		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Repairer ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CT119021617/USF3E2

Date: 14/01/2020

REFERENCE

Insured/Claimant:	WILLIAM TAN KAY SOON	Policy No:	DMPCSN1834501901	Claim No:	SNM19D205788/SJZ4623X/CBS
Date of Loss:	03/12/2019	Nature of Claim:	OD		

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJZ4623X	
Make & Model:	BMW 523i, 2.5 AT ABS D/AB 2WD 4DR GAS/D NAV (A)	Engine No: 05397598N52B25AF
Reg. Date:	29/11/2010 (Man. Year: 2010)	Chassis No: WBAFP32030C546971
Colour:	Grey	Odometer: 257228 km
Engine Capacity:	2497 cc	
Market Value/New Car Price:	S\$31,000.00	
Sum Insured (S\$):	Market Value/New Car Price	

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/35Z R20	Rear Tyre Size:	275/30Z R20
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,445.00	2,807.00	638.00	18.52
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,024.69	1,063.19	-38.50	-3.76
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	4,469.69	3,870.19	599.50	13.41
+ GST 7.00/7.00% (S\$)	312.88	270.91	41.97	13.41
Nett Amount (S\$)	4,782.57	4,141.10	641.47	13.41

INSPECTION

Date of Assignment:	09/12/2019	Present Location:	Jin Auto Services Pte Ltd (Defu)
Date Inspected:	09/12/2019	Inspected At:	Jin Auto Services Pte Ltd (Defu) Blk 14 Defu Lane 10, #01-410/412 Singapore 539195

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 14 Jan 2020)
Parts:	143	BMW 523I 2.5 AT ABS D/AB 2WD 4DR GAS/D NAV (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJZ4623X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TOTAL PARTS		3,250.00 F	*2,890.00 FL
2	1		*L/F GRILLE	Cracked	-	*100.00 FS
3	1		*R/F GRILLE	Cracked	-	*100.00 FS
4	1		*SUNDRY	Necessary	-	*100.00 FS
Supplementary #1						
5	1	51 74 7 200 787	*radiator air guide	Torn	185.00 F	*185.00 FS
6	1		*LWASHER JET CARRIER	Cracked	10.00 F	*10.00 FS
					Sub Total (\$\$)	3,445.00
					- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00
					Total Parts (\$\$)	3,445.00
						2,807.00

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TOTAL PAINT	New	888.19	888.19
2	TOTAL LABOUR	New	136.50	175.00
Gross Labour Cost (S\$)			1,024.69	1,063.19

Report was unsubmitted during this print-out.

< END OF ESTIMATES >