From (Perzon)	Kothuriro Won	ASSIGN of	MENT (Office)	Dute/Ti	me 09/11/19.
Estimated Cos		,	Bill to:		
100	Ch	ES/EVA/INV/MY	/ FCS	Insured: 2	LR 2813×
at Workshop i	H Don L + 0	e Batteries R	Mohor Shig	r Tel: 96	
Policy No:			Claim No:	608804	
Sum branted:			Excess:		
Make of Veh: (Client's Record				D.O.A.	15-10-2019
CA / REV /	REP. / REV 24 3-10-19 938	HRS 0. Person Confuct	ed Paul Ho	e vehice	Edorsement
	-				
Date/Time	Action/instruction	n (X) Estina	Ate		
_	SMY HAFEE		Ate		
Date/Time	SIN HEE	-×	ate		
Date/Time	SILVER SUBMIT I	~ ~		70.	
Date/Time	SILV REPORT A Submit A Submit	185. LS \$1400, 4		70-1	₹.
Date/Time	SILV REPORT A Submit A Submit	185. LS \$1400, 4		mont	4
Date/Time	SILV REPORT A Submit A Submit	~ ~		month	4

RECEIVED 1 9 DEC 2019

Do Not Finalise

17

WHAL

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	399Z
Vehicle Details	
Vehicle No.:	SMC1076E
Vehicle to be Exported:	No
Intended Deregistration Date:	25 Oct 2019
Vehicle Make:	HONDA
Vehicle Model:	VEZEL 1.5X CVT
Primary Colour:	Brown
Manufacturing Year:	2018
Engine No.:	L15B5553709
Chassis No.:	RU11303702
Maximum Power Output:	96.0 kW (128 bhp)
Open Market Value:	\$21,536.00
Original Registration Date:	26 Jun 2018
First Registration Date:	26 Jun 2018
Transfer Count:	0
Actual ARF Paid: Intended PARF Rebate Details	\$12,151.00 - 6075
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	25 Jun 2028
PARF Rebate Amount:	\$9,113.00
Intended COE Rebate Details	
COE Expiry Date:	25 Jun 2028
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$34,110.00
COE Rebate Amount:	\$29,562.00
Total Rebate Amount:	\$38,675.00

The information contained herein is correct as at 25 Oct 2019

Enquire Vehicle Transfer Fee

Vehicle Details

SMC1074E

HONDA / VEZEL LIX CVT

P10 - Passenger Motor Car

Ventore Scheme

Normal

Propries

Petrol

94stor 74s.:

Fower Rating:

Maximum Later Weight

1465 kg

Hear Of Many/acture

2018

Lifespor Enerry Date:

Quota Premium \$34,110.00

Road Tax Exproy State 25 Jun 2020

Inquestion Due Date:

25 Jun 2021

CO2 Erresson 123.00 (g/km)

CDEmum

0.037000 (g/km)

NOs Ensurer

0.002000 (a/km)

No Attachment

Characters:

#U11303702

Engine No.: L1585553709

Engine Cassotty

1496 CE

Maritmen France Photos.

96.0 kW (128 bhai

Unlater Weight

1190 kg

Drights Registration Date:

26 Jun 2018

A - Car up to 1600cc & 97kW (130khp)

COE Every Date

25 Jun 2026

RARF Eligibility Enpiry Date 25 Jun 2028

Interested Transfer Date:

25 Oct 2019

CEVIVES Retails Utilised Amount

\$10,000.00

HC Employ 0.009000 (g/km)

PM Emission

2.200000 (mg/km)

Fees To Be Paid For Transfer

Transfer Fees

DOA = 15/10/19

Print

mv - 75000

PV - 38675

NV - 36000

Bulow 8 yer Punth

oge: 8000 gr 0x.

8000+12=666

64000 +5328+605

\$25.00

- 75403

Copy as Text

SGCARMART.COM

Login Sign up

New Cars

Used Care

Sell My Car

Directory

Products

Insurance

* Vehicle Type

Articles

R

Forum

Rε



* Depreciation * 2018

Honda Vezel 1.5A X

Financial

Honda Vezel

Insurance

Accessories

Price Range

Similar

Research

Photos

Map



Pionie * Used Cars * Benefit Auto Enterprise Pte Ltd * Honda Vezei 1.5A X





















Price Chart Summar MISSON May-18

Reg Date Click on the point to view the vehicle

Shortlist Report Error Compare

More Actions

Saller Information

Company

Benefit Auto Enterprise

E)

· dealer's problet

\$75,800 \$8,320 /yr

Reg Date

08-Mar-2018 (flyrs 4mths 11days COE left)

Road Tax \$682 /yr Manufactured 7

Transmission

Auto

2017

Dereg Value

Depreciation

Price

Mileage

\$42,589 as of today (change)

View models with similar dopre

39,900 km (24,4k /yr)

OMV ARF

\$12,240

\$21,600

Engine Cap

COE

1,496 cc

\$39,903

96.0 kW (128 bhp)

Curb Weight

1,190 kg

No. of Owners

Type of Vehicle SIV

Powered By 4 Cylinders Inline DOHC I-VTEC Engine, CVT Transmission, 1288hp, FWD, Fuel Tank 40L, Traction Control, Cruise Control, Airbags. View specs of the Honda Vizzel (2014)

Keyless Entry/Start, Fog Lamps, Leather Seats, DVD Player With Bluetooth, Solar Films, Car Mat, Reverse Sensors. Reverse Camera.

Description

Excellent Condition In And Out White Unit Previously Owned By One Meticulous Owner, Well Spaced Interior And One Of The Top Selling Models By Honda. Flexible Loan Available, Price Negotiable, All Offer Considered. High Trade In. It Is Available For Viewing At Our Showroom, Make It Yours Today.

Category

PARF Car, Premium Ad Car

Status

Available

Resources

ket value of your existing car for free, Get started

https://www.sgcarmart.com/used_cars/info.php?ID=849054&DL=2077

- Free

Add no

PRO-OPTION SERVICES

Malling address: Blk 189B Rivervale Drive, #04-1004, Singapore 542189 Fax: 6315 3298, Mobile: 9061 0543

ACCIDENT VEHICLE INSPECTION REPORT

Report no

: 424M1019.PH

Vehicle no

: SMC1076E

1 REFERENCE

Date of Inspection

: 22 October 2019

Requested by

: Leong Kok May

23 Canberra Drive

#04-48

Singapore 768077

Type of survey

: Independent

Repairer

: Paul Hoe Batteries & Motor Services

Blk 1 Kaki Bu

Blk 1 Kaki Bukit Ave 6, #01-109 AutoBay @ Kaki Bukit, Singapore 417883

Date of accident

: 15 October 2019

2 VEHICLE DATA

Make/model

: HONDA VEZEL 1.5X CVT

Chassis no

: RU11303702

Engine no

: L15B5553709

Date of registration

: 26 Jun 2018

COE Expiry Date:

25 Jun 2028

Engine capacity

: 1496 cc

Odometer reading

: 027608 km

Colour

: Grey

3 STATIC CONDITION CHECK

Steering

: Serviceable

Foot brakes

: Serviceable

Hand brakes

: Serviceable

Paintwork

: Good

General Condition

: Good

4 TIRE CONDITION CHECK

RH/MAKE

LH/MAKE

SIZE

Front tread

: 6 mm/Dunlop

6 mm/Dunlop

215/60R16

Rear tread

: 6 mm/Dunlop

6 mm/Dunlop

215/60R16

5 BRIEF DESCRIPTION OF DAMAGE

Front bumper scraped/bent/deformed, front LH fender scaped/bent, LH wheel arc garnish bent/bracket distorted, LH headlamp casing bent/broken, etc. Please see para. 8 of this report for more details.

6 REMARKS

This inspection is carried out on a "WITHOUT PREJUDICE" basis and I have not authorized any repairs.

7 RECOMMENDATION

Cost of repairs

\$3,120.00 (lump sum)

Estimated no of days

Four (4)

ASSESSMENT OF DAMAGE AND COSTS

Report no: Vehicle no:

424M1019.PH SMC1076E

A	SPARE PARTS		Assessed	R	epairer's	Revised
	Description	Qty	Condition	E	Amount	Amount 765
	Front bumper	1	scraped/bent/deformed		927.50	927.50
	Front bumper side retainer LH	1	bent/tab fractured (c fl~)		23.40	23.40 ~
	Front bumper clip	10	necessary (nec)		39.00	39.0023
	Fog lamp assy LH	1	serviceable × (svc)		327.70	-0.00
	Fog lamp garnish LH	1	twisted/distorted (care)		165.80	165.80 78
	Headlamp assy LH	1	casing bent/broken × (SUE)		1,859.40	1,859.40
	Headlamp lower bracket LH	1	bent/distorted \smile come)		83.90	83:9076
	Front fender LH	1	to repair × (/L)		580.00	-0.00
	Front wheel arc garnish LH	1	bent/bracket distorted (10%)		185.60	185.60/5#
	Front wheel arc garnish clip	7	necessary (nac)		21.00	21.00 15
			Subtotal of the above		4,213.30	3,305.60
			Discount 20%/	20%	842.66	661.12
			Total cost of parts:		3,370.64	2,644.48
В	LABOUR					
	To check wiring.			430	45.00	30:00
	To align headlamps and refocus headlar	np bea	ams to specifications.	15	90.00	69:00
	To apply anti-rust undercoat.			1	120.00	€0.00
	Labour charges to remove and replace affected and damaged parts.	to cu	t and weld, to panel beating		900.00	800.00 400
	Spray painting charges to paint the necessary areas.	front	bumper, front fender and	ē	750.00	500:00 4
			Total cost of labour:		1,905.00	1,250.00
			Total cost of repair:		5,275.64	3,894.48

Report no:

424M1019.PH

Vehicle no:

SMC1076E

9 CONCLUSION

The revised or adjusted cost of repairs to restore the vehicle is

\$3,894.48

(a) However, the recommended cost of repair based on lump sum basis would be

\$3,120.00

(b) The estimated number of days taken to complete the repairs are

Four (4)

(1st re-inspection conducted on 1st November 2019) (Post Repair Inspection conducted on 4th November 2019)

The above recommendations in my view are fair and reasonable for the restoration of the vehicle to its preaccident condition.

Note: Lump Sum Repair Basis

This means the repairer is allowed to replace the damaged parts with used, reconditioned or new parts, or repair it to a roadworthy condition.

Yours faithfully

Llaw Leong San

Licensed Automotive Appraiser

Dated:

18 November 2019

LKK Auto Consultants hence notify

the Repairer of the following:

- . To resurvey before/after spray painting
- * To display damaged part(s) during resurvey
- * Parts prices are subject to certifimation.
- * Third party survey is on a "Without Prejudice" basis
- * No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

1154 200/6 123.20 830 1753.20 415 less 200/6 1402.56

As Log on 13/12/12 Poper and on 13/12/12 10-45 AT 10-45 AT Porty and part

PRO-OPTION SERVICES

Mailing address: Blk 189B Rivervale Drive, #04-1004, Singapore 542189 Fax: 6315 3298, Mobile: 9061 0543

ACCIDENT VEHICLE INSPECTION REPORT

Report no

: 424M1019.PH

Vehicle no

: SMC1076E

1 REFERENCE

Date of inspection

: 22 October 2019

Requested by

: Leong Kok May

23 Canberra Drive

#04-48

Singapore 768077

Type of survey

: Independent

Repairer

: Paul Hoe Batteries & Motor Services

Blk 1 Kaki Bukit Ave 6, #01-109 AutoBay @ Kaki Bukit, Singapore 417883

COE Expiry Date:

Date of accident

: 15 October 2019

2 VEHICLE DATA

Make/model

: HONDA VEZEL 1.5X CVT

Chassis no

: RU11303702

Engine no

: L15B5553709

Date of registration

: 26 Jun 2018

Engine capacity

: 1496 cc

Odometer reading

: 027608 km

Colour

: Grey

3 STATIC CONDITION CHECK

Steering

: Serviceable

Foot brakes

: Serviceable

Hand brakes

: Serviceable

Paintwork

: Good

General Condition

: Good

TIRE CONDITION CHECK RH/MAKE

LH/MAKE

SIZE

25 Jun 2028

Front tread

: 6 mm/Dunlop

6 mm/Dunlop

215/60R16

Rear tread

: 6 mm/Dunlop

6 mm/Dunlop

215/60R16

5 BRIEF DESCRIPTION OF DAMAGE

Front bumper scraped/bent/deformed, front LH fender scaped/bent, LH wheel arc garnish bent/bracket distorted, LH headlamp casing bent/broken, etc. Please see para. 8 of this report for more details.

6 REMARKS

This inspection is carried out on a "WITHOUT PREJUDICE" basis and I have not authorized any repairs.

7 RECOMMENDATION

Cost of repairs

\$3,120.00 (lump sum)

Estimated no of days

Four (4)

8 'ASSESSMENT OF DAMAGE AND COSTS

Report no:

424M1019.PH

Vehicle no:

SMC1076E

Α	SPARE PARTS		Assessed			Repairer's	Revised
	Description	Qty	Condition			Amount	Amount
	Front bumper	1	scraped/bent/deformed			927.50	927.50
	Front bumper side retainer LH	1	bent/tab fractured			23.40	23.40
	Front bumper clip	10	necessary			39.00	39.00
	Fog lamp assy LH	1	serviceable			327.70	0.00
	Fog lamp garnish LH	1	twisted/distorted			165.80	165.80
	Headlamp assy LH	1	casing bent/broken			1,859.40	1,859.40
	Headlamp lower bracket LH	1	bent/distorted			83.90	83.90
	Front fender LH	1	to repair			580.00	0.00
	Front wheel arc garnish LH	1	bent/bracket distorted			185.60	185.60
	Front wheel arc garnish clip	7	necessary			21.00	21.00
			Subtotal of the above			4,213.30	3,305.60
			Discount	20%/	20%	842.66	661.12
			Total cost of parts:		10	3,370.64	2,644.48
В	LABOUR						
	To check wiring.					45.00	30.00
	To align headlamps and refocus headla	mp be	ams to specifications.			90.00	60.00
	To apply anti-rust undercoat.					120.00	60.00
	Labour charges to remove and replace affected and damaged parts.	e, to cu	t and weld, to panel beating			900.00	600.00
	Spray painting charges to paint the necessary areas.	front	bumper, front fender and			750.00	500.00
			Total cost of labour:			1,905.00	1,250.00
			Total cost of repair:		[5,275.64	3,894.48

Report no:

424M1019.PH

Vehicle no:

SMC1076E

9 CONCLUSION

The revised or adjusted cost of repairs to restore the vehicle is

\$3,894.48

(a) However, the recommended cost of repair based on lump sum basis would be

\$3,120.00

(b) The estimated number of days taken to complete the repairs are

Four (4)

(1" re-inspection conducted on 1" November 2019) (Post Repair Inspection conducted on 4th November 2019)

The above recommendations in my view are fair and reasonable for the restoration of the vehicle to its preaccident condition.

Note: Lump Sum Repair Basis

This means the repairer is allowed to replace the damaged parts with used, reconditioned or new parts, or repair it to a roadworthy condition.

Yours faithfully

Liaw Leong San

Licensed Automotive Appraiser

Dated:

18 November 2019

MSME19137415 / SME Motor Pie Ltd - Kaki Bukit. ENTRY DATE & TIME: 16/10/2019 16:20 SUBMITTED BY: Chia Pai Ying

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for Investigation.
- This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

By the lodgement of this report to the insurers, you aforesaid.	ou hereby consent to the archiving of this report at the centre and to copies of the report being made available
	ACCIDENT STATEMENT
Date Of Report	16/10/2019 16:20
Date Of Accident	15/10/2019 17:10
Exact Location Of Accident	JOHOR CUSTOM BEFORE IMMIGRATION CHECKPOINT
Country/State of Loss	SINGAPORE
	DETAILS OF OWN VEHICLE
Vehicle Registration Number	SMC1076E
Insured/Policyholder	
Name Of Registered Owner	LEONG KOK MAY
NRIC No	S7041399Z
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-98622983

OFFICE-98622983

Alternative Phone No Vehicle Particulars

Manufacturer HONDA Model VEZEL

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy

for repair to your vehicle?

If No, Please state action to be taken THIRD PARTY Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company NTUC INCOME INSURANCE CO-OPERATIVE LTD

Type Of Coverage COMPREHENSIVE

Fleet Policy NO

Policy Number 5101648190-01

Cover Note Number

Driver

Name of Driver OOI ENG THYE NRIC No S7109043D Date Of Birth 09/03/1971 Occupation INDOOR Date Of Driving Pass 17/06/1988

Driving Experience 31 YEARS AND 3 MONTHS

Gender MALE

Mobile Number (LOCAL) +65-98622983

Fax Number Contact Number

Address

23 CANBERRA DRIVE #04-48

Postcode

768077

Was driver an employee of the Insured's Company

If No. Relationship of the Driver with the Insured

SPOUSE

NO

Vehicle Registration Number of Driver's Own

Vehicle

-

Insurance Company of Driver's Own Vehicle

.

General Information of the Accident

Type Of Accident

COLLISION - CHANGE/CROSS LANE

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

Number of vehicles (including own vehicle) involved in the accident

2

NO

Note and a supplied of the supplied with

NO

Was any body injured in the Accident?
Was any injured conveyed to hospital by

NO

ambulance?

Was any other material or property damaged?

YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

1

Details of Police Action

Was the accident reported to the police?

NO

If Yes.Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

ON 15/10/2019 AT 1710HRS, I WAS DRIVING TOWARDS JOHOR IMMIGRATION CHECKPOINT ALONG MIDDLE LANE. IT WAS HEAVY JAM DURING THE INCIDENT HAPPENED. SUDDENLY, I FELT A JERK AT THE FRONT OF MY CAR AND I NOTICED MY CAR COLLIDED WITH THE OTHER CAR ON MY LEFT.

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SLR2813X

Vehicle Make/Model/Colour

Details Of Properties

VEHICLE B

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

- Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of reputational facts may allow insurance companies to repudiate policy liability.
- The Issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5 Any false reporting may be referred to the Police for Investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance
 Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by
 interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurers) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents[including their lawyers/law firms], which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholdece Signature

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature Name:

NRIC/FIN Na.:

E TON PLAN	
	A SMC/076
	13 SLA 1973 X
	10 50 75
1090	++++
A A	11111111111111111
	1
A SECURE OF THE ACCIDENT	
SCFE IR CIRCUMSTANCES OF THE ACCIDENT	
On 150ct 19, 17104, 1 2004 drang	Joseph toward John
immy immyration check point along i	and de lone. It was
months immigration creek point wong	1 C. 11. 1 1 C.14 a
neavy jam during the mordent happener	d. Judderm I selt a
jerk at the front of my car-and I not	riced my car was
collided with the other car on my le	H.
COLLINER MAIN THE OTHE CON ST. T.	4

olicyholder's Signature ute & Time:

Oriver's Signature (If driver is not the policyholder)
Date & Time: 161014

Reporting Centre Personnel's Signature Name: NRIC/FIN No.1

2
























SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wiful misrepresentation or witholding of material facts may allow insurance companies to
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the ladgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available

	ACCIDENT STATEMENT	
Date Of Report	16/10/2019 16:32	
Date Of Accident	15/10/2019 17:15	
Exact Location Of Accident	JB CUSTOM TOWARDS SINGAPORE	
Country/State of Loss	MALAYSIA/JOHOR DARUL TAKZIM	

是可能的政策。	DETAILS OF OWN VEHICLE
THE REPORT OF THE PERSON NAMED IN COLUMN TWO IS NOT THE PERSON NAMED IN COLUMN TWO IS NAMED IN COLUMN TWO	The second secon

Vehicle Registration Number SLR2813X

Insured/Policyholder

Name Of Registered Owner HAN YONG TENG

NRIC No S8175727E

Email Address YTHAN,81@YAHOO.COM Mobile Phone No. (LOCAL) +55-96494262 Alternative Phone No. OFFICE-96494262

Vehicle Particulars

Manufacturer HONDA

Model SHUTTLE-1.5 (A)

Exact Purpose for which vehicle was being used at

time of accident

Are you claiming under your own insurance policy

for repair to your vehicle?

If No. Please state action to be taken

THIRD PARTY

Vehicle Category

PRIVATE CAR

Insurance Company

Name of Insurance Company

MSIG INSURANCE (SINGAPORE) PTE. LTD.

Type Of Coverage

COMPREHENSIVE

Fleet Policy

NO

Policy Number

P29003533DUP

Cover Note Number

Driver

Name of Driver HAN YONG TENG

NRIC No S8175727E Date Of Birth 11/08/1981 Occupation INDOOR Date Of Driving Pass 14/07/2007

Driving Experience 12 YEARS AND 3 MONTHS

Gender MALE

Mobile Number (LOCAL) +65-95494262

Fax Number

Contact Number OFFICE-96494262

EMail Address YTHAN,81@YAHOO.COM

BLK 484 ADMIRALTY LINK Address

#04-63

750484 Postcode

Was driver an employee of the Insured's Company NO

OWNER If No. Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

COLLISION - CHANGE/CROSS LANE Type Of Accident

CLEAR Weather Conditions DRY

Road Surface Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles (including own vehicle)

involved in the accident.

NO Was any body injured in the Accident?

Was any injured conveyed to hospital by

ambulance?

YES Was any other material or property damaged? I have been approached by unknown person(s) NO

soliciting/offering accident claims assistance.

Number of Passengers (Including Driver) 2

Passenger 1 NAME:

GENDER: : MALE

Details of Police Action

Was the accident reported to the police?

If Yes, Please state which Police Station

NANYANG N.P.C Police Station Name

ROAD: 2 JURONG WEST AVE 5 , POSTCODE: 649482 , COUNTRY: Police Station Address SINGAPORE

SON

TEL NO: 1800-7929999 - FAX NO: Police Station Contact

Was notice of intended Prosecution given?

If Yes, against whom?

Circumstances of Accident

REFER TO ATTACHED.

Attachment(s)

Are accident photos available for attachment?

YES

NO

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

DETAILS OF OTHER VEHICLE PROPERTY 1

SMC1076E Vehicle Registration Number

HONDA VEZEL Vehicle Make/Model/Colour

Details Of Properties

PRIVATE CAR Vehicle Category

Name of Driver

NRIC/Passport Number

96822983 Contact Number

SKETCH PLAN

IMPORTANT NOTICE

- 1 Please report correctly the details of the accident to speed up the claims process
- This Form must be completed by the Policyholder and/or the Authorised Driver
- 3 Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4 The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance
 Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by
 interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid
- 8. Consent under the Personal Data Protection Act (PDPA)

Lunderstand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of ...
 - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Palicyholder's Signature

Date & Time:


Driver's Signature (if driver is not the policyholder)

Date & Time:

114 20 P

Reporting Centre Personnel's Signature Name

NRIC/FIN No.



A = My vehicle (SLR 7813x) B = 3d party (SMC 1076E)

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

B wa	changing Lone from Right to middle lane and	d		
and 1	knocked my vehicle (A) Kehicle A is on the middle lan			

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature Date & Time:

Driver's Signature (if driver vilnot the policyholder) Date & Time Reporting Centre Personnel's Signature

NRIC/FIN No.:



NOTICE OF COMPLIANCE

This is to confirm that

HAN YONG TENG HP: 9649 4262 NRIC: S8175727E,

Driving vehicle: SLR2813X.

has reported to the police a non-injury traffic accident which occurred along JOHOR BAHRU CHECKPOINT on 15/10/2019 at about 1715hrs involving a Black Colour Honda: SMC1076E. I manage to get the driver's handphone number HP: 9862 2983. No pedestrians and government property was damaged

He/She has therefore complied with Sec 84(2) of the Road Traffic Act, Cap 276.

SINGAPORE 649482
TEL: 1800-7929099

Date: ____16/10/2019_____ Name of Issuing Officer: _SGT T180213 Jialei_

S/D Ref: 492 Police Post/Unit: Jurong Police Div/Nanyang NPC

...CLAIM SUBFOLDER...(Pending for Survey Report)

	OLDER TRA	Est Submitted	Ads Assigned	Aiti Rpt	Add 5	Submitted	Ins Auth'ed	Statu	s
	Notified 18 Oct 2019	Est Submitted	21 Oct 2019 17:12 Edit Adj Rbt	S\$1,400.00 Edit Estimates	5\$1	400.00 tw Apt	55 -001-00	Pend	ing for Survey
21	dain	R	eference	Claim D	etails		Documents		Show All
CLAIM SUI	BFOLDER DI	TAILS					by insurer]		
Insured:	HAN YON	G TENG, ID: 58	175727E, Tel: +6	596494262, Emai	YTHA	N.81@YAHO	O.COM		
Main Claimant:	LEONG K	OK MAY, ID: S	7041399Z						
Vehicle Reg No.:	SMC107	76E		Date o	Loss:		9 17:00 - :59 s and 19 Days Fro	m LTA R	eg Date (Man Yr))
Claim Type:	TP / 608	TP / 608804			Cover lo.:		(Comprehensive) 08/08/2019 - 07/	08/2020	
Vehicle Reg No. (Insured):	SLR2813	×		Policy (Claure					
				Exces			10.110.000.000.000.000		
Repairer:	Paul Hoe	Batteries & Mot	or Services (HQ)	1 KAKI BUKIT AVE	#01-1	09, 417883	Kaki Bukit - Tel:		
Handling Insurer:	E-11-9-2-4-2-1-2-3-1-2-3	TO PART OF THE PAR) - Tel: +65 6827 7	- 2111 1-11 2-1	The Desire of the second			
Adjuster:	LKK Auto	Consultants Pte	Ltd (HQ) - Tel: 6	256-3561 [Handi	ed by L	EE HOCK A	NN] [Final R	pt due (09/12/2019]
Driver/Cust dian (Insured):		TENG (38 / Male), NRIC: S81757	27E, Tel: +65964	94262	Email: YTHA	N.81@YAHOO.CO	4	
Adj Asg. Remarks:	on WP. Lie	ab: unclear. Disag	ree on SJE. Contact	: Paul Hoe @ 9623	5068.				
ASSOCIAT	ED MAIL RE	CEIVED					Vie	w.All	Compose Case M
 MSIG_St 	3 (05/12/201	9): Report Send	Back Alerts - SMC	1076E (TP)					
ALL ASSO	CIATED TAS	sks=				View All	Search Tasks 0	reate Ne	v Task Comple
Due Date	e Priority	Type Tasi	Group Subje	ct Handler	Assign	ned By	Completed On	Cre	ated On Doo

Claim Documents

*SMC1076E (608804) [SLR2813X] TP LEONG KOK MAY Oct 15 2019 5:00PM [HAN YONG TENG] Paul Hoe Batteries & Motor Services

Pho	tos/Images		3 per page V	1 2
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbna	-
1	25/10/19 09:29	Chassis Number	■ Load 3PG	6770
2	25/10/19 09:30	Odometer Reading	■ Load JPG	970
)	25/10/19 09:30	General View	Ecad JPG	-
4	25/10/19 09:30	General View	■ Load 3PG	-
5	25/10/19 09:30	General View	■ Load JPG	-
6	25/10/19 09:30	General View	■ Load 3PG	200
7	25/10/19 09:30	General View	■ Load 3PG	perio
8	25/10/19 09:30	General View	■ Load 3PG	275
9	25/10/19 09:30	General View	■ Load 3PG	_
10	25/10/19 09:30	General View	Load JPG	-
11	25/10/19 09:30	General View	Load 3PG	670
12	25/10/19 09:30	General View	O Load JPG	erro.
13	25/10/19 09:30	General View	■ Load JPG	-
	25/10/19 09:30	General View	Load JPG	-
14	Constitution of the Consti	Contracting satisfies		100
15	25/10/19 09:30	General View	Load JPG	-
16	25/10/19 09:30	General View	Load 3PG	-
17	25/10/19 09:30	General View	Load 3PG	1000
18	25/10/19 09:30	General View	1 Load JPG	+=
19	25/10/19 09:30	General View	1 Load JPG	
20	25/10/19 09:30	General View	① Load 3PG	-
21	25/10/19 09:31	General View	■ Load 3PG	-
22	25/10/19 09:31	General View	€ Load JPG	_
23	25/10/19 09:31	General View	■ Load JPG	_
24	25/10/19 09:31	General View	■ Load JPG	_
25	25/10/19 09:31	General View	Load 3PG	-
26	25/10/19 09:31	General View	Ebed JPG	8
27	25/10/19 09:31	General View	Ecad JPG	80
28	25/10/19 09:31	General View	1 Load JPG	_
29	25/10/19 09:31	General View	1 Load JPG	82
30	25/10/19 09:31	General View	■ Load 3PG	2
31	25/10/19 09:31	General View	■ Load JPG	2
32	25/10/19 09:31	General View	■ Load JPG	2
33	25/10/19 09:31	General View	■ Load JPG	52
34	25/10/19 09:31	General View	■ Load JPG	W
35	25/10/19 09:31	General View	Load 3PG	₩.
36	25/10/19 09:31	General View	€ Load JPG	82
37	25/10/19 09:31	General View	€ Load JPG	52
38	25/10/19 09:31	General View	1 Load JPG	82
39	25/10/19 09:31	General View	1 Load JPG	₩.
40	25/10/19 09:31	General View	 Load 3PG 	52
41	25/10/19 09:31	General View	■ Load JPG	Artesia
42	07/11/19 09:20	Reinspection Photo	■ Load JPG	-
43	07/11/19 09:20	Reinspection Photo	■ Load 3PG	

Pho	tos/Images		3 per page	
Νo	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbna	
6-4	07/11/19 09:20	Reinspection Photo	€ Load 3PC	
15	07/11/19 09:20	Reinspection Photo	1 Load 3PC	
6	07/11/19 09:20	Reinspection Photo	(3) Load 3PC	_
7	07/11/19 09:20	Reinspection Photo	1 Load JPC	_
iB	07/11/19 09:20	Reinspection Photo	€ Load JPC	5 2
19	07/11/19 09:20	Reinspection Photo	€ Load 3PC	3 2
50	07/11/19 09:20	Reinspection Photo	■ Load 3PC	G 2
51	07/11/19 09:20	Reinspection Photo	■ Load 3PC	3 2
52	07/11/19 09:20	Reinspection Photo	€ Load 3PC	G 2
93	07/11/19 09:20	Reinspection Photo	■ Load 3PC	G 2
54	07/11/19 09:20	Reinspection Photo	■ Load 3PC	G 😿
55	07/11/19 09:20	Reinspection Photo	■ Load 3PG	3 2
56	07/11/19 09:20	Reinspection Photo	O Load JPC	
57	07/11/19 09:20	Reinspection Photo	€ Load JPC	-
88	07/11/19 09:20	Reinspection Photo	■ Load 3PG	
59	AND CONTRACTOR OF STREET	Reinspection Photo	O Load JPG	
-	07/11/19 09:20		G Load JPC	-
50	07/11/19 09:20	Reinspection Photo	6 Load JP	
1	07/11/19 09:20	Reinspection Photo		
52	07/11/19 09:20	Reinspection Photo	C Load 3P	_
3	07/11/19 09:20	Reinspection Photo	€ Load JPG	_
14	07/11/19 09:20	Reinspection Photo	Load 3PG	-
55	07/11/19 09:20	Reinspection Photo	1 Load 3PG	
6	07/11/19 09:20	Reinspection Photo	€ Load 3P0	
7	07/11/19 09:20	Reinspection Photo	€ Load 3PC	_
88	07/11/19 09:20	Reinspection Photo	63 Load 3P0	_
9	07/11/19 09:20	Reinspection Photo	■ Load 3PG	G 💆
70	07/11/19 09:20	Reinspection Photo	■ Load 3PG	G 🙀
71	07/11/19 09:20	Reinspection Photo	■ Load JPC	G 2
72	07/11/19 09:21	Reinspection Photo	€ Load 3PC	G &
73	07/11/19 09:21	Reinspection Photo	€ Load 3PG	G 💀
74	07/11/19 09:21	Reinspection Photo	■ Load 3PG	G 💀
75	07/11/19 09:21	Reinspection Photo	■ Load 3P(6 2
76	07/11/19 09:21	Reinspection Photo	■ Load JPC	5 2
77	07/11/19 09:21	Reinspection Photo	■ Load JPC	g 🔛
78	07/11/19 09:21	Reinspection Photo	■ Load 1P0	
79	07/11/19 09:21	Reinspection Photo	■ Load 3PG	
90	07/11/19 09:21	Reinspection Photo	O Load 3PG	-
11	07/11/19 09:21	Reinspection Photo	3 Load JP	-
	The state of the s	[]		- 1
12	07/11/19 09:21	Reinspection Photo	E Load JP(
13	07/11/19 09:21	Reinspection Photo		
14	07/11/19 09:21	Reinspection Photo	C Load JP(-
15	07/11/19 09:21	After Repair Photo	€ Load JP(
16	07/11/19 09:21	After Repair Photo	€ Load 3PC	-
17.	07/11/19 09:21	After Repair Photo	1 Load JPC	
8	07/11/19 09:21	After Repair Photo	1 Load JPC	
9	07/11/19 09:21	After Repair Photo	1 Load JPC	
Ю	07/11/19 09:21	After Repair Photo	€3 Load 3PC	
1	07/11/19 09:21	After Repair Photo	€ Load 3PC	-
2	07/11/19 09:21	After Repair Photo	■ Load 3PC	
3	07/11/19 09:21	After Repair Photo	■ Load 3PC	G 🔽
14	07/11/19 09:21	After Repair Photo	1 Load 3PC	G 5
5	07/11/19 09:21	After Repair Photo	E Load JPC	G 😿
-	umentation			2 P
é0	Finalized On	M5IG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbna	all Prin
	21/10/19 14:25	TP SMC1076E GIA REPORT Frum:SC - lieg. Nu: SLR2813X, Claimant: HAN YORG TEMG	6 Load PD	E.

Page 3 of 3 Merimen e-Claims

Pho	Photos/Images		3 per page		2
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
2	05/12/19 14:48	Survey Report	0	Load PDF	
3	05/12/19 14:48	Survey Photos	0	Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnall	Print
1	20/12/19 17:53	PRS Invoice	0	Load PDF	
2	20/12/19 17:53	Colour Photo	0	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset Save Print
There are no document checklists configured.	
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)	
	^
	~
Show Remarks To: Handling Insurer Note: Remarks are private unless you abow it to other parties.	

LKK Auto Consultants Pte Ltd (Co.Reg. No:199607198R)

51 Ubi Ave 1 #01-25, Pava Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CS3/MSG19018611/HQF3E2-1

Date:

23/12/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No:

29003533

Claimant

SMC1076E

Insured Vehicle No:

SLR2813X

Vehicle No : Date of Loss:

15/10/2019

Nature of Claim:

TP

Claim No: 608804

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SMC1076E

Make & Model:

HONDA VEZEL, 1.5 X CVT (A) 26/06/2018 (Man. Year: 2018)

Engine No: Chassis No: L15B5553709 RU11303702

Reg. Date: Colour:

Brown

Odometer:

27608 km

Engine Capacity: Market Value/New Car Price: N/A

1496 cc

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:

215/60 R16

Rear Tyre Size:

215/60 R16

Front Left Side: Front Right Side: Dunlop 6 mm

Rear Left Side: Rear Right Side: Dunlop 6 mm Dunlop 6 mm

Dunlop 6 mm The above values represent the remaining tyre treads depth

Repairer's	Adjuster's	Difference	Diff %
3,370.64	923.20	2,447.44	72.61
0.00	0.00	0.00	
1,905.00	830.00	1,075.00	56.43
0.00	0.00	0.00	
0.00	0.00	0.00	
5,275.64	1,753.20	3,522.44	66.77
	1,400.00		
5,275.64	1,400.00	3,875.64	73.46
	3,370.64 0.00 1,905.00 0.00 0.00 5,275.64	3,370.64 923.20 0.00 0.00 1,905.00 830.00 0.00 0.00 0.00 0.00 5,275.64 1,753.20 1,400.00	3,370.64 923.20 2,447.44 0.00 0.00 0.00 1,905.00 830.00 1,075.00 0.00 0.00 0.00 0.00 0.00 0.00 5,275.64 1,753.20 3,522.44 1,400.00

INSPECTION

Date of Assignment:

21/10/2019

Date Inspected:

22/10/2019 Inspected At:

Paul Hoe Batteries & Motor Services

(HQ)

1 KAKI BUKIT AVE 6 #01-109

Singapore 417883

Estimated Period of Repair:

4.0 days

Adjuster: LEE HOCK ANN

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Referen	ce	
Part Source:	: MRM-SG	Version: 1.0 (Last Synchronised: 23 Dec 2019)
Parts:	M1-SUV	HONDA VEZEL 1.5 X CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted,	no print-code for SMC1076E)
Validity:	These estimated numbers with	tes are valid only if they contain the print code (above) on all estimate pages, running page the END OF ESTIMATES marker on the last estimate page
Further Info	: Items/values i	not in reference catalogue are prefixed with an asterisk *.

P	ecom	mer	hahr	Part	c
Γ	econ	me	lueu		Э.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Scraped/Bent/Deformed	927.50 FL	*765.50 FL
2	1		*FRONT BUMPER SIDE RETAINER LH	Crushed	23.40 FL	*23.40 FL
3	10		*FRONT BUMPER CLIP	Necessary	39.00 FL	*25.00 FL
4	1		*FOG LAMP ASSY LH	Serviceable	327.70 FL	*-FL
5	1		*FOG LAMP GARNISH LH	Crushed	165.80 FL	*98.00 FL
6	1		*HEADLAMP ASSY LH	Serviceable	1,859.40 FL	*-FL
7	1		*HEADLAMP LOWER BRACKET LH	Crushed	83.90 FL	*76.30 FL
8	1		*FRONT FENDER LH	Repair	580.00 FL	*-FL
9	1		*FRONT WHEEL ARC GARNISH LH	Scratched	185.60 FL	*150.80 FL
10	1		*FRONT WHEEL ARC GARNISH CLIP (7PCS)	Necessary	21.00 FL	*15.00 FL
F=Fri	anchise	part. L=List!	temDisc.	Sub Total (S\$)	4,213.30	1,154.00
			- List Item Discount o	n L Items 20.00/20.00% (S\$)	842.66	230.80
				Total Parts (S\$)	3,370.64	923.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO CHECK WIRING }	New	45.00	30.00
2	TO ALIGN HEADLAMPS AND REFOCUS HEADLAMP BEAMS TO SPECIFICATIONS }	New	90.00	0.00
3	TO APPLY ANTI-RUST UNDERCOAT	New	120.00	0.00
4	LABOUR CHARGES TO REMOVE AND REPLACE, TO CUT AND WELD, TO PANEL BEATING AFFECTED AND DAMAGED PARTS	New	900.00	400.00
5	SPRAY PAINTING CHARGES TO PAINT THE FRONT BUMPER, FRONT FENDER AND NECESSARY AREAS	New	750.00	400.00
	Gross Labour	Cost (S\$)	1,905.00	830.00

< END OF ESTIMATES >