

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: ERGO Insurance Pte. Ltd.  
5 Temasek Boulevard  
#04-01 Suntec Tower Five  
Singapore 038985

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn:

Date: 10 Dec 2019

### **Preliminary Advice**

Insured Vehicle No : GBB4490H

TP Vehicle No : SMB64B

Make : MERCEDES-BENZ OC500LE1830H

Date of Inspection : 09/12/2019

Inspection At : SMRT AUTOMOTIVE SERVICES PTE LTD (WOODLANDS)  
60 WOODLANDS INDUSTRIAL PARK E4  
SINGAPORE 757705

Accident Date : 02/12/2019

Assignment Date : 10/12/2019

Est. Duration of Repair : 7 days

### **Point of Impact / General Description of Damages**

The vehicle sustained impact / damages front n/s & n/s front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	19,888.02
Revised Amount	:S\$	19,188.02
Check Items (Estimated)	:S\$	0.00
Total	:S\$	19,188.02

Lump Sum Repair :S\$

### **Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

### **Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : TP : WP