

Tel: 6258 1955 Email: tap.finalization@gmail.com / teamautooffice@gmail.com

Vehicle Nos : SKD 7590 R

Model : Mercedes C180

Year :

Chassis No :

Amount:

Working Day:

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$
1	Bootlid	1	\$ 1,424.00	\$ 1,424.00
2	Bootlid chrome moulding	1	\$ 286.40	\$ 286.40
3	Bootlid logo	1	\$ 85.90	\$ 85.90
4	Bootlid emblem " C180 "	1	\$ 67.00	\$ 67.00
5	Bootlid emblem " CC "	1	\$ 105.60	\$ 105.60
6	Bootlid emblem " Kompressor "	1	\$ 90.00	\$ 90.00
7	Bootlid inner lock	1	\$ 235.00	\$ 235.00
8	Bootlid lock switch	1	\$ 112.00	\$ 112.00
9	Bootlid lock stricker	1	\$ 85.40	\$ 85.40
10	Bootlid smart open lock sensor	1	\$ 375.00	\$ 375.00
11	Bootlid inner trim	1	\$ 180.00	\$ 180.00
12	Bootlid inner trim garnish	1	\$ 110.00	\$ 110.00
13	Bootlid hinge garnish	2	\$ 84.00	\$ 168.00
14	Bootlid weatherstrip	1	\$ 219.50	\$ 219.50
15	Rear bumper	1	\$ 1,186.00	\$ 1,186.00
16	Rear bumper side retainer	2	\$ 115.00	\$ 230.00
17	Rear bumper bracket	2	\$ 51.20	\$ 102.40
18	Rear bumper chrome moulding centre	1	\$ 241.50	\$ 241.50
19	Rear bumper chrome moulding side	1	\$ 216.50	\$ 216.50
20	Rear bumper chrome moulding side	1	\$ 216.50	\$ 216.50
21	Rear bumper tow cover	1	\$ 145.00	\$ 145.00
22	Rear bumper carrier	1	\$ 168.40	\$ 168.40
23	Rear bumper reinforcement	1	\$ 982.40	\$ 982.40
24	Rear bumper reinforcement spacer	1	\$ 85.20	\$ 85.20
25	Rear bumper reinforcement spacer	1	\$ 85.20	\$ 85.20
26	Rear end panel	1	\$ 1,198.50	\$ 1,198.50
27	Rear end panel top garnish	1	\$ 425.90	\$ 425.90
28	Spare tyre panel	1	\$ 581.60	\$ 581.60
29	Rear fender inner trim	2	\$ 482.50	\$ 965.00
30	Taillamp	2	\$ 852.00	\$ 1,704.00
31	Taillamp lower bracket	2	\$ 94.60	\$ 189.20
32	Exhaust pipe assy	1	\$ 1,852.10	\$ 1,852.10
33	Exhaust mounting	2	\$ 89.40	\$ 178.80
34	Exhaust pipe chrome sleeve	1	\$ 119.30	\$ 119.30
35	Driver seat headrest	1	\$ 1,375.00	\$ 1,375.00
36	Front passenger seat headrest	1	\$ 1,375.00	\$ 1,375.00
37	Air bag sensor	1	\$ 425.00	\$ 425.00
38	Air bags ECU module	1	\$ 4,280.00	\$ 4,280.00
Parts Sub Total :				\$10108.50 22,209.90
10% Discount				\$1010.85 2,220.99
PARTS TOTAL :				\$9097.65 19,988.91

Nos.	SPECIAL NETT	Qty	Unit S\$	TOTAL S\$
1	Sundries	1	\$ 100.00	\$ 100.00
2	Rear number plate	1	\$ 80.00	\$ 80.00
3	Rear end panel sealant	1	\$ 80.00	\$ 80.00
4	Taillamp seal	2	\$ 80.00	\$ 160.00
5	Reverse sensor with module (4pcs type)	4	\$ 200.00	\$ 800.00
6	Bootlid inner trim clip	1	\$ 80.00	\$ 80.00
7	Bootlid inner trim garnish clip	1	\$ 80.00	\$ 80.00
8	Rear bumper clip	1	\$ 100.00	\$ 100.00
9	Rear fender inner trim clip	2	\$ 80.00	\$ 160.00
10	Taillamp clip	2	\$ 80.00	\$ 160.00
11	Rear end panel top garnish clip	1	\$ 80.00	\$ 80.00
SPECIAL NETT TOTAL :				\$ 1,880.00

Nos.	LABOUR		S\$
1	Panel beating	Resetting Module 200.00 +	\$ 800.00 1,600.00
2	R&R bootlid component		\$ 60.00 100.00
3	R&R reverse sensor		\$ 60.00 100.00
4	To disconnect wire harness to facilitate repair work, reconnect and check functions		\$ 30.00 80.00
5	R&R interior upholstery		\$ 100.00
6	Upholstery Head Rest		\$ 400.00
7	R&R Air Bag Sensor		\$ 60.00 150.00
8	R&R Air Bag ECU		\$ 100.00 350.00
9	R&R Driver Seat		\$ 250.00
10	Programming		\$ 500.00
11	R&R exhaust pipe		\$ 100.00 280.00
12	R&R safety belt		\$ 200.00
13	Diagnostic & reset fault code		\$ 100.00 350.00
14	To drill holes on replaced rear bumper & position and install reverse sensor		\$ 60.00 80.00
15	R&R Console box		\$ 150.00
16	Spray paint		\$ 800.00 1,400.00
LABOUR TOTAL :			\$ 2370.00 6,090.00

Survey 9/12/19

Tata in line,

1500 hrs

Lump sum

Resurvey 10/12/19

1630 hrs

TGtin mu

Repair days 7 @ 20%

PARTS TOTAL: \$9097.65 19,988.91

SPECIAL NETT TOTAL: \$ 490.00 1,880.00

LABOUR TOTAL: \$2370.50 6,090.00

GRAND TOTAL : \$ 27,958.91

11957.65

2391.53

9566.12

4/5 9550/2

Tim
13/12/19

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: