

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 137Z**

**AAD1912-021**

*Not Authorized  
L/Smp @ 1250/-*

Vehicle No.:  
Chassis No.:  
Vehicle Make:  
Vehicle Model:  
Date of Accident :  
Third Party Insurer :  
Date of Registration :

04 DEC 2019

**SHD 137Z**

VF1ABL15AUC282241

RENAULT

LATITUDE

2.12.19

**III**

1/9/2015

		<b>PART</b>		<b>LIST</b>	
1	1	BUMPER COVER REAR	\$	<i>Bu</i> 561.70	✓
2	1	BUMPER LOWER REAR	\$	<i>Ad/W</i> 411.90	✓
3	1	BUMPER BRACKET CTR REAR	\$	<i>SL</i> 98.10	X
4	1	BUMPER BRACKET SIDE RH REAR	\$	<i>SL</i> 82.10	X
5	1	BUMPER RETAINER RH REAR	\$	<i>SL</i> 59.80	X
6	1	BUMPER REFLECTOR RH	\$	<i>Bu</i> 16.60	✓
7	1	BUMPER BRACKET SIDE LH REAR	\$	<i>SL</i> 80.80	} X
8	1	BUMPER RETAINER LH REAR	\$	<i>SL</i> 54.20	
9	1	BUMPER REFLECTOR LH	\$	<i>SL</i> 16.60	
10	1	BUMPER BEAM REAR	\$	<i>R</i> 547.80	
11	1	BUMPER BEAM BRACKET LH REAR	\$	<i>R</i> 114.50	
12	1	BUMPER BEAM BRACKET RH REAR	\$	<i>R</i> 100.90	
13	1	OUTER PANEL REAR (End Panel)	\$	<i>R</i> 745.80	
14	1	OUTER PANEL REAR (End Panel) TRIM	\$	<i>SL</i> 404.56	
15	1	TAILLAMP RH	\$	<i>SL</i> 313.10	
16	1	TAILLAMP PANEL RH	\$	<i>R</i> 401.40	
17	1	TAILLAMP LH	\$	<i>SL</i> 401.40	
18	1	TAILLAMP PANEL LH	\$	<i>R</i> 401.40	
19	1	BOOT REAR	\$	<i>R</i> 1,677.20	
20	1	BOOT FINISHER	\$	<i>SL</i> 344.70	
21	1	BOOT WHEATERSTRIP	\$	<i>SL</i> 178.20	
22	1	BOOT REFLECTOR LAMP LH	\$	<i>SL</i> 277.70	
23	1	BOOT REFLECTOR LAMP RH	\$	<i>SL</i> 277.70	
24	1	BOOT BADGE 'RENAULT'	\$	<i>nn</i> 82.40	
25	1	BOOT BADGE	\$	<i>nn</i> 95.80	
26	1	BOOT STRUT LH	\$	<i>SL</i> 145.10	

**Trans-cab Auto Services Pte Ltd**

**AAD1912-021**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 137Z**

27	1	BOOT STRUT RH	\$	Sm	145.10	}
28	1	BOOT HINGE LH	\$	R	254.20	
29	1	BOOT HINGE RH	\$	R	253.80	
30	2	BOOT RUBBER PLUG	\$	Sm	139.90	
31	2	BOOT BUFFER	\$	Sm	26.80	
32	1	BOOT LOCK LINKAGE	\$	Sm	20.60	
33	1	BOOT LOCK LINKAGE HOLDER	\$	Sm	99.50	
34	1	BOOT INNER TRIM BOARD	\$	Sm	611.00	
35	1	BOOT SWITCH	\$	Sm	113.00	
36	1	BOOT LOCK	\$	R	246.60	
37	1	BOOT LOCK CATCH	\$	R	41.70	
38	1	EXHAUST CAP REAR	\$	Sm	125.40	
<b>TOTAL</b>			<b>\$</b>		<b>9,969.06</b>	
<b>10%</b>			<b>\$</b>		<b>996.91</b>	
			<b>\$</b>		<b>8,972.15</b>	

**Special Nett**

1	1SET	PARKING AID	\$	Sm	700.00	X
2	1SET	REAR BUMPER CLIP	\$	na	66.00	—
3	1SET	BUMPER BRACKET CTR CLIP	\$	na	33.00	—
4	1SET	BUMPER BRACKET SIDE CLIP RH RR	\$	na	10.00	X
5	1SET	BUMPER RETAINER RH CLIP RR	\$	na	20.00	X
6	1SET	BUMPER BRACKET SIDE CLIP LH RR	\$	na	10.00	X
7	1SET	BUMPER RETAINER CLIP LH RR	\$	na	20.00	X
8	1SET	BUMPER LOWER REAR RIVET	\$	na	22.00	X
9	1SET	BUMPER LOWER REAR CLIP	\$	na	66.00	—
10	1	BOOT STICKER "Trans-cab"	\$	na	30.00	}
11	1	BOOT STICKER "6555-3333"	\$	na	30.00	
12	2	REAR WINDSCREEN SEALANT	\$	na	80.00	
13	1	WINDSCREEN MOULDING	\$	na	100.00	
14	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	na	100.00	
15	1	BOOT INNER TRIM CLIP	\$	na	45.00	
16	1SET	BOOT FINISHER CLIP	\$	na	24.20	
17	1	TAILLAMP CLIP LH	\$	na	5.00	
18	1	TAILLAMP CLIP RH	\$	na	5.00	
19	1	Rear Bumper Protector	\$	na	100.00	

**Trans-cab Auto Services Pte Ltd**

AAD1912-021

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 137Z**

20	1	EXHAUST MOUNTING REAR	\$	<i>16.00</i>	<i>X</i>
<b>TOTAL</b>			<b>\$</b>	<b>1,482.20</b>	
<b>TOTAL PARTS</b>			<b>\$</b>	<b>10,454.35</b>	

**LABOUR**

To transfer of bootlid fittings, attachments and perform water seepage test.	\$	<i>170.00</i>	<i>X</i>
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>380.00</i>	<i>X</i>
To Rust-Proofing Of The Affected Areas.	\$	<i>170.00</i>	<i>X</i>
To Check Electrical Lighting Concerned.	\$	170.00	<i>101</i>
To transfer of tire, rim and on wheel balancing.	\$	<i>170.00</i>	<i>X</i>
To reinstall rear bumper parking sensor.	\$	170.00	<i>601</i>
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	6,000.00	<i>2001</i>
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	<i>170.00</i>	<i>X</i>
To transfer of rear windscreen glass to facilitate bodywork repair.	\$	<i>170.00</i>	<i>X</i>
To check steering geometry and computer wheel alignment	\$	<i>220.00</i>	<i>X</i>
To repair and realign rear exhaust pipe.	\$	<i>170.00</i>	<i>X</i>
To transfer of rear bumper fittings, attachment and perform water seepage test.	\$	<i>170.00</i>	<i>X</i>

**Trans-cab Auto Services Pte Ltd**

**AAD1912-021**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 137Z**

Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	<i>nn</i> 380.00 <i>X</i>
Putty and spray painting of the affected portion.	\$	6,000.00 <i>2201</i>
<b>TOTAL</b>	<b>\$</b>	<b>14,510.00</b>
<b>Over All Total</b>	<b>\$</b>	<b>24,964.35</b>

**LUMP SUM ( REPAIR DAY)**

~~20 DAYS~~

*2 days*

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
  - To display damaged part(s) during resurvey
  - Parts prices are subject to confirmation
  - Third party survey is on a "Without Prejudice" basis
  - No illegal modification(s) is allowed
  - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: