

INS. CASE OWNER:

CC 4/FWD190

N 635, H

LKK:
IDAC:

Surveyor:

HA

DOI:

ASSIGNMENT

10/11/19

Date / Time:

9/11/19

Registered in Merimen:

9/11/19

Pre-assign / CCU / FTE



Insured Vehicle No.:

SMC 4444G

Claim No.:

Name of Insured:

WU GUOQIAN BEN

Policy No.:

PHIPV219-000 15637

Insured Tel No.:

HP:

Make / Model:

BMW 1

Excess Sec II :S\$

D.O.A.:

3/11/19

Place of Accident:

ROBINSON RD

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability:

Final ? Yes / No

SMN 2087A



INSRS:

WSP:

Tel:

Liability:

RMKS:

Auto

Bullox



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

30/12 - TO check COR and to HOLD GAVI. NOT
TALK TO HIS FINANCE and ✓.
31/12 - REC COR to TP (Pending LOD).
30/120 - LOD in, file pass & type report.
4/2 - Pending mandate approval ✓
14/2 - OFF to settle @ \$4047.45, DV send (Pending
DV).
17/2 - DV in, file pass me to close.

STAGE	DATE / PIC	
Non-Reporting hr (1st):		
Non-Reporting hr (2nd):		
Non-Reporting hr (Final):		
Notification hr (If non-pickup):		
Call OI:		
After call hr to OI:		
Documentation Check List:	Handler	Typist
Notification hr (if non-pickup)	☒	☐
After call hr to OI:	☒	☐
Authorisation To Act:	☒	☐
Release Voucher:	☒	☐
Final Repair Bill:	☒	☐
Car Rental Invoice:	☒	☐
Towing Invoice	☒	☐
LTA / GIA :	☒	☐
Medical Bill:	☒	☐
PIR:	☒	☐
Mandate/Reject Instruction:	☒	☐
LOD	☒	☐
Payment Breakdown Form:		☐
Post-Repair Photos:	☒	☐
Others: <i>Washing</i>	☒	☐

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

45

S\$ 4300.00

1

6

days

Reduction:

4300.13

%

41

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

100

(Agreed / Assessed)

BOLA S/N No.:

29

If NO or B 28, Ass. Lia:

Repair Cost:

S\$

4300.00

Loss of Rental (LOR):

S\$

-

(

1

days)

Loss of Use (LOU):

S\$

540.00

(\$ 90

x

6

days)

Loss of Income (LOI):

S\$

-

(\$

x

days)

LOR only

☒

LOU only

☐

LOR + LOU

☐

LOR + LO

☐

(Tick only one)

GIA/LTA Search

S\$

7.45

Medical:

S\$

-

Disbursement:

S\$

-

(e.g. Tow/Independent)

Legal Cost

S\$

-

Total:

S\$

4847.45

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

4847.45

Name 1:

Auto Bullox Pte Ltd

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

1) Claim status: Normal/Reject/Private Settle
2) Report Format: TP
3) Survey fee: \$500.

COPY SENT
18/2/2020

CLASS. REC. BY: H-ANNREF: FWD

ASSIGNMENT

From _____ Date: 10-12-2019

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SMM 2083Aat Workshop m/s Auto Bulloxof 53 Ubi Ave / #01-19 Pava Ubi

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: Aster 104000

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S
X	X

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 6 days Res.: Yes or NoLum Sum: 20. % 3 Val: Yes or NoCA / REV / REP. / 24 HRS mp"

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SMM 2083A Yr Regn: 21/06/2017Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Toyota NOAH c.c. 1797Colour: Blue A/C: Insured / Std / NI / NASp. Reading: 32447km T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: 2WR800383887Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt or _____Brake: Inorder / Jammed / Leaked / Burnt or _____Modi: Nil / S/Rim / STD A/Rim or _____Tyre Size: F: 195/55/R15R: 195/55/R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front

Rear

R/Bal. 5 mm 4 mmL/Bal. 5 mm 4 mmD.O.A. 3/12/19 D.O.I. 10/12/19Survey held at Auto BulloxDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop of _____

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>L/C \$4300 - (Red = \$3007.15/411) * SMM 2083A</u>
	<u>- DO done by Father.</u>
	<u>MV - 109000</u>
	<u>PV - 62571</u>
	<u>NV - 46000</u>
	<u>11/01/2020 - 97693293</u>

Date/Time, File Pass to?

☐ : Prel. Report

Days Of Repair: _____

1)

☐ : Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

S + RS \$ _____

Phone _____

Other _____

TOTAL

Report Format: _____

Lump Sum / L.R. (\$ _____)

AUTO BULLOX PTE LTD

LIK Auto Consultants hence and the Repairer of the following:

- To survey before/after scope of work
- To display damaged parts during survey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Vehicle: SMM2083A

Make & Model: TOYOTA NOAH HYBRID

Register No.: 201919765N

Estimate

L/S report without previous painting refer part 10/12/19 12.10pm 6 day

Handwritten: 8531188

No	Particular	Qty	Amount
List Price			
1	Rear boot lid ✓ BT	1pc	1,920.50
2	Rear boot logo (Hybrid Synergy Drive) ✓ REC	1pc	68.50
3	Rear boot Chrome moulding X (SVC)	1pc	158.48
4	Rear boot inner lock ✓ Jm	1pc	524.60
5	Rear boot weatherstrip ✓ CRU	1pc	323.60
6	Rear boot inner trim board ✓ CRU	1pc	421.90
7	Rear bumper ✓ BT	1pc	1,230.80
8	Rear bumper side holder @\$48.60 X (SVC)	2pcs	97.20
9	Rear bumper side retainer @\$64.43 X (SVC)	2pcs	128.86
10	Rear end panel ✓ BT	1pc	824.60
11	Rear end panel garnish ✓ CRU	1pc	178.80
12	Rear lock sensor (boot) ✓ CRU	1pc	5,877.84
Less 25%			(1,469.46)
Sub-Total cost for parts			4,408.38
Part Replacement - Special			
Nett Item			
1	Rear reverse sensor ✓ short	1 set	280.00
2	Rear bumper clip ✓ REC	1 set	50.00
3	Rear boot inner trim clip ✓ REC	1 set	35.00
Sub-Total cost for parts			365.00
Labour & MISC Charges			
1	To remove, refix reverse sensor ✓		60.00
2	To remove, refix rear interior upholstery to assist repair X		150.00
3	To respray painting & etc ✓		800.00
4	Panel beating, remove & replacing above parts ✓		1,000.00
5	To respray undercoating ✓		200.00
Sub-Total Labour			2,210.00
Grand Total			6,983.38

1692.50 ✓
68.50 ✓
390.80 ✓
235.80 ✓
371.80 ✓
1025.30 ✓
687.80 ✓
137.80 ✓

200 ✓
20 ✓
15 ✓

20 ✓
650 ✓
700 ✓
30 ✓

To remove, refix rear windscreen

To remove, refix rear boot assy

parts 4720.10

spec mat 235

parts 250/0

labour 1580

3540.07

5355.07

150 120

80 60

5355.07

20/0

4284.05

Total 11220.07

AUTO BULLOX PTE LTD

LKK Auto Consultants hence and

the Repairer of the following:

- To resurvey before/after repair
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

53 Ubi Avenue 1#01-19 Paya Ubi Industrial Park Singapore 408934

Tel: 6844 4290 Fax: 6841 6043 Email: motoricarzgarage@gmail.com

Register No.: 201919765N

Estimate

L/S report
without pre-fee
resurvey after paint
10/12/19
12-10pm
6 day

Huck Auto 5/11/19
853/1873

Acknowledged by Repairer

Vehicle: SMM2083A

Make & Model: TOYOTA NOAH HYBRID

No	Particular	Qty	Amount
List Price			
1	Rear boot lid ✓ BT	1pc	1,920.50
2	Rear boot logo (Hybrid Synergy Drive) ✓ nec	1pc	68.50
3	Rear boot Chrome moulding X (svc)	1pc	158.48
4	Rear boot inner lock ✓ Jm	1pc	524.60
5	Rear boot weatherstrip ✓ can	1pc	323.60
6	Rear boot inner trim board ✓ can	1pc	421.90
7	Rear bumper ✓ BT	1pc	1,230.80
8	Rear bumper side holder @\$48.60 X (svc)	2pcs	97.20
9	Rear bumper side retainer @\$64.43 X (svc)	2pcs	128.86
10	Rear end panel ✓ BT	1pc	824.60
11	Rear end panel garnish ✓ can	1pc	178.80
12	Rear lock sensor (boot) ✓ can \$125		5,877.84
	Less 25%		(1,469.46)
	Sub-Total cost for parts		4,408.38
Part Replacement - Special			
Nett Item			
1	Rear reverse sensor ✓ short	1 set	280.00
2	Rear bumper clip ✓ nec	1 set	50.00
3	Rear boot inner trim clip ✓ nec	1 set	35.00
	Sub-Total cost for parts		365.00
Labour & MISC Charges			
1	To remove, refix reverse sensor ✓		60.00
2	To remove, refix rear interior upholstery to assist repair X		150.00
3	To respray painting & etc ✓		800.00
4	Panel beating, remove & replacing above parts ✓		1,000.00
5	To respray undercoating ✓		200.00
	Sub-Total Labour		2,210.00
	Grand Total		6,983.38

200
20
15

70
650
700
30

To remove, refix rear windscreen
To remove, refix rear boot assy

\$150 120 ✓
\$80 60 ✓
\$7307.13

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Business
Owner ID:	119L

Vehicle Details

Vehicle No.:	SMM2083A
Vehicle to be Exported:	No
Intended Deregistration Date:	11 Dec 2019
Vehicle Make:	TOYOTA
Vehicle Model:	NOAH HYBRID 1.8X CVT
Primary Colour:	Black
Manufacturing Year:	2019
Engine No.:	2ZR0D60856
Chassis No.:	ZWR800385887
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$33,350.00
Original Registration Date:	21 Jun 2019
First Registration Date:	21 Jun 2019
Transfer Count:	0
Actual ARF Paid:	\$28,690.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	20 Jun 2029
PARF Rebate Amount:	\$21,517.00

Intended COE Rebate Details

COE Expiry Date:	20 Jun 2029
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$43,102.00
COE Rebate Amount:	\$41,054.00
Total Rebate Amount:	\$62,571.00

The information contained herein is correct as at 11 Dec 2019

OK

Hock Ann (LKK Auto)

From: Hock Ann (LKK Auto)
Sent: Monday, 30 December, 2019 6:03 PM
To: motoricarz garage
Cc: Cecilia Chong (LKK Auto)
Subject: RE: SMM 2083A FINALIZED CALCULATE ADJUSTMENT AMOUNT UPDATED 28.12.2019

'WITHOUT PREJUDICE'
SAVE AS TO COSTS

Dear kaman ,

Good day, o.k will be process base on finalized total amount COR \$ 4300 Lump/sump REPAIR and DOR 6 days close.

Noted : All finalized document > LOA ,LOD,DV,LTA need send to lkk claim dept person incharge (Cecilia chong >ceciliachong@lkkauto.com)

Thanks.

Best Regards,
Hock Ann | Assistant Automotive Assessor
LKK Auto Consultants
Phone: 6741 3061 | Email: HockAnn@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: motoricarz garage [mailto:motoricarzgarage@gmail.com]
Sent: Monday, 30 December, 2019 10:39 AM
To: Hock Ann (LKK Auto)
Cc: Cecilia Chong (LKK Auto)
Subject: Re: SMM 2083A FINALIZED CALCULATE ADJUSTMENT AMOUNT UPDATED 28.12.2019

Dear Hock Ann,

We accept your offer.Kindly proceed.
Thank you.

Best regards,
Elma

On Mon, Dec 30, 2019 at 10:06 AM Hock Ann (LKK Auto) <HockAnn@lkkauto.com> wrote:

'WITHOUT PREJUDICE'

SAVE AS TO COSTS

Dear Kaman ,

Good day , Kindly attached refer SMM 2083A TOYOTA NOAH HYBRID finalized updated calculate adjustment on 28.12.2019 .

COR - \$ 4300

DOR – 6 DAYS

Please refer adjustment updated total LUMP/SUMP amount \$ 4300 if agree total LUMP/SUMP amount and repair days, will be to close case.

Please to updated email back asap.

Thanks.

Best Regards,

Hock Ann| Assistant Automotive Assessor

LKK Auto Consultants

Phone: 6741 3061 | Email: HockAnn@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Best Car Repair Workshops in Singapore

Browse more than 3,000 car workshops in Singapore.

You can read customers' reviews & ratings on their services too.

Toyota Min Price No Max Depreciation Vehicle Type Category

Home » New Cars » New Car Brands » Toyota » Toyota Noah Hybrid

Resources

Car Buying

Car Selling

Car Ownership

Car Aftermarket

On The Move

Lifestyle

Toyota Noah Hybrid (Parallel Imported)

Select Another Make

Select The Make

Overview

Pricing

Photos

Research

Reviews

Specs

Features

Similar

Accessories

Prom

Add to Shortlist

Submit a Review

Report Error

Share



Details

Sold by Parallel Importers | 45 dealers

Built in Japan (launched 2017)

Variants 2 submodel(s) » Show pricelist

Promotion **\$121,888!** Guaranteed COE! VAC Ready Stocks/Imme Delivery/1.99% Flexible Loan/Trade In/Consignment/Lease-To-Own Available.

USER RATINGS:

(1 review)

» View 1 promotions for Noah Hybrid

Add to Shortlist

We have some dealers currently running very good deals on the Toyota Noah Hybrid. Get them to contact you directly with more info.

Name*

I'm not a robot

Contact No*

hCAPTCHA
Privacy - Terms

Submit

Submodel

1.8 X 7-Seater (A) ☒

1.8 Si 7-Seater (A)

new car
less 15%
↓
109000

\$129,000

\$139,000

Depreciation

ECO

Power

Detailed

23.8km/L

134bhp

Specs | Fe

23.8km/L

134bhp

Specs | Fe

☒ Verified Ready Stocks are vehicles that have cleared all LTA paperwork and ready to be registered immediately. This is verified by sgCarMart with the VITAS Approval Code (VAC) issued by LTA.

» View all the Toyota Noah Hybrid that are Ready Stock.

Showing 9 out of 45 dealers selling this vehicle

MS Carz

Tel: 64681101 / 91390860

Tan Wei Auto

Tel: 64595535 / 92770277

Car Empire Automobiles

Tel: 88668682

Venture Cars

This Dealer has Ready Stocks

Tel: 65528800 / 88268800

Tai Huat Automobile

Tel: 63443786 / 96237977

Prime Car Traders

Tel: 63666000 / 86666565

HTS Motor

Tel: 64752126 / 90298853

Cars & Coffee Singapore

Tel: 63974080 / 81278060

Car Search

Tel: 66944667 / 93388994

Featured Merchants



Related Articles



5 value-for-money luxury PI cars of 2019 (so far)



Dip in COE supply for November to January

» Go to article

Hello, NAC_PAYA_UBI_800601

[Change Language](#)[Change Password](#)[Log Out](#)[My Desktop](#)[Notice of Loss](#)

Policy Query

Policy No.

5108614334

Date of Accident

03/12/2019 17:28

Vehicle No. (For Motor)

SMM2083A

Certificate Number

Select	Policy No.	Certificate Number	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
	5108614334	5108614334-000023	SUPER STAR LIMO & CAR RENTAL	53359119L	GFM	drive CLASSIC	SMM2083A	SMM2083A	21/06/2019	11/04/2020

Summer Lee (LKK Auto)

From: venessa.chan@fwd.com
Sent: Monday, 9 December, 2019 9:48 AM
To: 'admin-d@lkkauto.com'; 'admin-a@lkkauto.com'
Cc: motorclaims.sg@fwd.com; eileen.bay@fwd.com
Subject: ACCIDENT INVOLVING VEHICLES SMM2083A AND SMC4444G ON 03/12/2019
Attachments: PRI - AUTO BULLOX PTE LTD.PNG

Dear Nivitha/Celine,

Please refer to the email below and liaise with TP repairer for PRS.

TP request to arrange for photo taking today.

Please create the case in Merimen.

Kindly upload all correspondence emails/documents sent to you into Merimen.

Thank you.

Best Regards,

Venessa Chan




FWD Singapore Pte. Ltd.

6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986

E venessa.chan@fwd.com

W www.fwd.com.sg



From: motoricarz garage [mailto:motoricarzgarage@gmail.com]

Sent: Monday, December 9, 2019 9:22 AM

To: Motor Claims SG - SG Common

Subject: ACCIDENT INVOLVING VEHICLES SMM2083A AND SMC4444G ON 03/12/2019

Our Vehicle: SMM2083A

Your Vehicle : SMC4444G

Dear Motor Survey Department,

Kindly arrange a pre-repair inspection for the **ABOVEMENTIONED** Vehicle at our workshop:

Blk 53, Paya Ubi Industrial Park, Ubi Avenue 1, #01-19 | S(408934) .

97699299 Carman.

✓Est
Veh out

'DS'
09/12/19 @ 11.20am Carman.

Attached herewith a pre-repair inspection request letter and GIA Report for your perusal and attention.

Best Regards,

Elma

Auto Bullox Pte Ltd

Phone: 6844-4290 | fax: 6841-6043 | email: motoricarzgarage@gmail.com

Blk 53, Paya Ubi Industrial Park, Ubi Avenue 1, #01-19| S(408934).

ATTENTION:

The email and any attachments transmitted with it are private and confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender immediately and delete this email and any attachments from your system. You should not use, disclose, copy or store this email and any attachments.

Messages and attachments are scanned for all viruses known. However, you are advised that you open any attachments at your own risk. If this message contains password-protected attachments, the files have NOT been scanned for viruses by our mail domain. Please always scan for viruses before opening any attachments.

Print Received Message

This mail is associated with :

***SMM2083A (1201900038747)**

[SMC4444G]

TP

SUPER STAR LIMO & CAR RENTAL

Dec 3 2019 4:00PM

[Wu Guoquan Benjamin]

Auto Bullox Pte Ltd

From FWD Singapore Pte. Ltd. (HQ) (FWD_SG), sent on 11/02/2020 13:19 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$4847.45) - SMM2083A - Claim Handler: Eileen Bay

Approved:4847.45.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	09 Dec 2019 Edit Reg		09 Dec 2019 00:00 Edit Adj Rpt	S\$4,300.00 Edit Estimates	S\$4,300.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	Wu Guoquan Benjamin, ID: S8124088D								
Main Claimant:	SUPER STAR LIMO & CAR RENTAL, Co. Reg. No.: 53359119L								
Vehicle Reg. No.:	SMM2083A	Date of Loss:	03/12/2019 16:00 - :59 [5 Months and 12 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 1201900038747	Policy/Cover Note No.:	PNPV2019-00015677 (Comprehensive) Coverage: 29/09/2019 - 28/09/2020						
Vehicle Reg. No. (Insured):	SMC4444G	Policy No. (Claimant):	5108614334						
		Excess:							
Repairer:	Auto Bullox Pte Ltd (HQ) 53 UBI AVE 1, #01-19 PAYA UBI INDUSTRIAL PARK, 408934 Ubi - Tel:								
Handling Insurer:	FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700 ... [Handled by Eileen Bay]								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by LEE HOCK ANN] ... [Final Rpt due 18/12/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
• FWD_SG (11/02/2020): Alert - Adj Mandate Approved (S\$4847.45) - SMM2083A - Claim Handler: Eileen Bay									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SMM2083A (1201900038747)
[SMC4444G]
TP
SUPER STAR LIMO & CAR RENTAL
Dec 3 2019 4:00PM
[Wu Guoquan Benjamin]
Auto Bullox Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View View in Browser

Letters/Correspondences				1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
1	(Draft)	Third Party Express Settlement – Payment Breakdown		Edit	

Assessment Reports				1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
1	11/12/19 14:35	Adjuster Immediate Advice		Load HTM	

Photos/Images				3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
1	11/12/19 11:02	Chassis Number		Load JPG	☒
2	11/12/19 11:02	Odometer Reading		Load JPG	☒
3	11/12/19 11:02	General View		Load JPG	☒
4	11/12/19 11:02	General View		Load JPG	☒
5	11/12/19 11:02	General View		Load JPG	☒
6	11/12/19 11:02	General View		Load JPG	☒
7	11/12/19 11:02	General View		Load JPG	☒
8	11/12/19 11:02	General View		Load JPG	☒
9	11/12/19 11:02	General View		Load JPG	☒
10	11/12/19 11:02	General View		Load JPG	☒
11	11/12/19 11:02	General View		Load JPG	☒
12	11/12/19 11:03	General View		Load JPG	☒
13	11/12/19 11:03	General View		Load JPG	☒
14	11/12/19 11:03	General View		Load JPG	☒
15	11/12/19 11:03	General View		Load JPG	☒
16	11/12/19 11:03	General View		Load JPG	☒
17	11/12/19 11:03	General View		Load JPG	☒
18	11/12/19 11:03	General View		Load JPG	☒
19	11/12/19 11:03	General View		Load JPG	☒
20	11/12/19 11:03	General View		Load JPG	☒
21	11/12/19 11:03	General View		Load JPG	☒
22	11/12/19 11:03	General View		Load JPG	☒
23	11/12/19 11:03	General View		Load JPG	☒
24	11/12/19 11:03	General View		Load JPG	☒
25	11/12/19 11:03	General View		Load JPG	☒
26	11/12/19 11:03	General View		Load JPG	☒
27	11/12/19 11:03	General View		Load JPG	☒
28	11/12/19 11:03	General View		Load JPG	☒
29	11/12/19 11:03	General View		Load JPG	☒
30	11/12/19 11:04	General View		Load JPG	☒
31	11/12/19 11:04	General View		Load JPG	☒
32	11/12/19 11:04	General View		Load JPG	☒
33	11/12/19 11:04	General View		Load JPG	☒
34	11/12/19 11:04	General View		Load JPG	☒
35	11/12/19 11:04	General View		Load JPG	☒
36	11/12/19 11:04	General View		Load JPG	☒

Letters/Correspondences			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
37	11/12/19 11:04	General View		☒
38	11/12/19 11:04	General View		☒
39	11/12/19 11:04	General View		☒
40	11/12/19 11:04	General View		☒
41	11/12/19 11:04	General View		☒
42	11/12/19 11:04	General View		☒
43	11/12/19 11:04	General View		☒
44	11/12/19 11:04	General View		☒
45	11/12/19 11:04	General View		☒
46	11/12/19 11:04	General View		☒
47	11/12/19 11:04	General View		☒
48	11/12/19 11:04	General View		☒
49	11/12/19 11:04	General View		☒
50	11/12/19 11:04	General View		☒
51	11/12/19 11:04	General View		☒
52	11/12/19 11:04	General View		☒
53	11/12/19 11:04	General View		☒
54	11/12/19 11:04	General View		☒
55	11/12/19 11:04	General View		☒
56	11/12/19 11:04	General View		☒
57	11/12/19 11:04	General View		☒
58	11/12/19 11:04	General View		☒
59	11/12/19 11:05	Reinspection Photo		☒
60	11/12/19 11:05	Reinspection Photo		☒
61	11/12/19 11:05	Reinspection Photo		☒
62	11/12/19 11:05	Reinspection Photo		☒
63	11/12/19 11:05	Reinspection Photo		☒
64	11/12/19 11:05	Reinspection Photo		☒
65	11/12/19 11:05	Reinspection Photo		☒
66	11/12/19 11:05	Reinspection Photo		☒
67	11/12/19 11:05	Reinspection Photo		☒
68	11/12/19 11:05	Reinspection Photo		☒
69	11/12/19 11:05	Reinspection Photo		☒
70	11/12/19 11:05	Reinspection Photo		☒
71	11/12/19 11:05	Reinspection Photo		☒
72	11/12/19 11:05	Reinspection Photo		☒
73	11/12/19 11:05	Reinspection Photo		☒
74	11/12/19 11:05	Reinspection Photo		☒
75	11/12/19 11:05	Reinspection Photo		☒
76	11/12/19 11:05	Reinspection Photo		☒
77	11/12/19 11:05	Reinspection Photo		☒
78	11/12/19 11:05	Reinspection Photo		☒
79	11/12/19 11:05	Reinspection Photo		☒
80	11/12/19 11:05	Reinspection Photo		☒
81	11/12/19 11:05	Reinspection Photo		☒
82	11/12/19 11:05	Reinspection Photo		☒
83	11/12/19 11:05	Reinspection Photo		☒
84	11/12/19 11:05	Reinspection Photo		☒
85	11/12/19 11:05	Reinspection Photo		☒
86	11/12/19 11:05	Reinspection Photo		☒
87	11/12/19 11:05	Reinspection Photo		☒
88	11/12/19 11:05	Reinspection Photo		☒
89	11/12/19 11:05	Reinspection Photo		☒
90	11/12/19 11:05	Reinspection Photo		☒
91	11/12/19 11:05	Reinspection Photo		☒
92	11/12/19 11:05	Reinspection Photo		☒

Letters/Correspondences				1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
93	11/12/19 11:05	Reinspection Photo		Load JPG	☒
94	11/12/19 11:05	Reinspection Photo		Load JPG	☒
95	11/12/19 11:05	Reinspection Photo		Load JPG	☒
96	11/12/19 11:05	Reinspection Photo		Load JPG	☒
97	11/12/19 11:05	Reinspection Photo		Load JPG	☒
98	11/12/19 11:05	Reinspection Photo		Load JPG	☒
99	18/12/19 08:58	After Repair Photo		Load JPG	☒
100	18/12/19 08:58	After Repair Photo		Load JPG	☒
101	18/12/19 08:58	After Repair Photo		Load JPG	☒
102	18/12/19 08:58	After Repair Photo		Load JPG	☒
103	18/12/19 08:58	After Repair Photo		Load JPG	☒
104	18/12/19 08:58	After Repair Photo		Load JPG	☒
105	18/12/19 08:58	After Repair Photo		Load JPG	☒
106	18/12/19 08:58	After Repair Photo		Load JPG	☒
107	18/12/19 08:58	After Repair Photo		Load JPG	☒
Documentation				1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	09/12/19 15:01	EMAIL FROM FWD 09122019		Load PDF	
2	09/12/19 15:01	TP GIA REPORT		Load PDF	
3	09/12/19 15:01	WKSP NOTICE		Load JPG	☒
4	09/12/19 15:01	FWD TO OI DD 09122019		Load PDF	
5	11/12/19 15:40	TP ESTIMATE- MARKED		Load PDF	
6	21/01/20 11:51	WORKSHOP INVOICE		Load PDF	
7	21/01/20 11:51	LTA SEARCH		Load PDF	
8	21/01/20 11:51	LOD		Load PDF	
9	18/02/20 12:12	AUTHORISATION TO ACT FORM		Load PDF	
10	18/02/20 12:12	Release Voucher		Load PDF	
11	18/02/20 12:12	LEASING		Load PDF	
No	Finalized On	FWD Singapore Pte. Ltd. (HQ)		Thumbnail	Print
1	09/12/19 15:26	SMC4444G OI GIA		Load PDF	
2	09/12/19 15:26	SMM2083A TP GIA		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) ^ v			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SMC4444G (Insd veh)	Model:	TOYOTA NOAH 1.8 (A)
	SMM2083A (TP veh)		
Date of Accident:	03/12/2019		

Global Sum Settlement	:	☐ Yes	☒ No
Repair Estimate	:	\$	7,307.13
Final Repair Cost	:	\$	4,300.00
Loss of Use	:	\$	540.00
Rental (if any)	:	\$	0.00
LTA / GIA Search Fee	:	\$	7.45
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	4,847.45

6.00 days at \$90.00 per day
days

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability _____ 100 _____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: _____

BOLA Liability: _____ (%) Assessed Liability (*): _____ (%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Auto Bullox Pte Ltd	:	\$ 4,847.45
2)		:	\$
3)		:	\$
4)		:	\$

JOANNE LEE KHANG MIN

18 Feb
2020

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report;
Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/FWD19021635/HGS3Q2

Date: 18/02/2020

REFERENCE

Handling Insurer: FWD Singapore Pte. Ltd. Policy No: PNPV2019-00015677

Claimant Vehicle No : SMM2083A Insured Vehicle No : SMC4444G

Date of Loss: 03/12/2019 Nature of Claim: TP Claim No: 1201900038747

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMM2083A	Engine No:	22R0D60856
Make & Model:	TOYOTA NOAH, 1.8 (A)	Chassis No:	ZWR800385887
Reg. Date:	21/06/2019 (Man. Year: 2019)	Odometer:	32442 km
Colour:	Black		
Engine Capacity:	1797 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/55 R15	Rear Tyre Size:	195/55 R15
Front Left Side:	Goodyear 5 mm	Rear Left Side:	Goodyear 4 mm
Front Right Side:	Goodyear 5 mm	Rear Right Side:	Goodyear 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,867.13	3,775.07	1,092.06	22.44
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,440.00	1,580.00	860.00	35.25
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,307.13	5,355.07	1,952.06	26.71
Approved Total (Overridden) (S\$)		4,300.00		
Nett Amount (S\$)	7,307.13	4,300.00	3,007.13	41.15
+ Loss of Use (6.0 x S\$90.00/day) (S\$)		540.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		4,847.45		

INSPECTION

Date of Assignment: 09/12/2019

Date Inspected: 10/12/2019 Inspected At:

 Auto Bullox Pte Ltd (HQ)
 53 UBI AVE 1, #01-19 PAYA UBI
 INDUSTRIAL PARK
 Singapore 408934

Estimated Period of Repair: 6.0 days

Adjuster: LEE HOCK ANN

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 21 Jan 2020)
Parts:	M1-MPV	TOYOTA NOAH 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMM2083A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT LID	Bent	1,920.50 FL	*1,692.50 FL
2	1		*REAR BOOT LOGO (HYBRID SYNERGY DRIVE)	Necessary	68.50 FL	*68.50 FL
3	1		*REAR BOOT CHROME MOULDING	Serviceable	158.48 FL	*- FL
4	1		*REAR BOOT INNER LOCK	Jammed	524.60 FL	*390.80 FL
5	1		*REAR BOOT WEATHERSTRIP	Crumpled	323.60 FL	*235.80 FL
6	1		*REAR BOOT INNER TRIM BOARD	Crumpled	421.90 FL	*371.80 FL
7	1		*REAR BUMPER	Bent	1,230.80 FL	*1,025.30 FL
8	2		*REAR BUMPER SIDE HOLDER	Serviceable	97.20 FL	*- FL
9	2		*REAR BUMPER SIDE RETAINER	Serviceable	128.86 FL	*- FL
10	1		*REAR END PANEL	Bent	824.60 FL	*687.80 FL
11	1		*REAR END PANEL GARNISH	Crumpled	178.80 FL	*137.80 FL
12	1		*REAR LOCK SENSOR (BOOT)	Cracked	125.00 FL	*109.80 FL
13	1		*SET REAR REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS
14	1		*SET REAR BUMPER CLIP	Necessary	50.00 FS	*20.00 FS
15	1		*SET REAR BOOT INNER TRIM CLIP	Necessary	35.00 FS	*15.00 FS
					Sub Total (S\$)	6,367.84 4,955.10
					- List Item Discount on L Items 25.00/25.00% (S\$)	1,500.71 1,180.03
					Total Parts (S\$)	4,867.13 3,775.07

F=Franchise part. S=SpcNelt. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE ,REFIX REVERSE SENSOR	New	60.00	20.00
2	TO REMOVE,REFIX REAR INTERIOR UPHOLSTERY TO ASSIST REPAIR	New	150.00	0.00
3	TO RESPRAY PAINTING & ETC	New	800.00	650.00
4	PANEL BEATING ,REMOVE & REPLACING ABOVE PARTS	New	1,000.00	700.00
5	TO RESPRAY UNDERCOATING	New	200.00	30.00
6	TO REMOVE ,REFIX REAR WINDSCREEN	New	150.00	120.00
7	TO REMOVE,REFIX REAR BOOT ASSY	New	80.00	60.00
Gross Labour Cost (\$\$)			2,440.00	1,580.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >