

INS. CASE OWNER:

Arda

CC 4 / III 190 21636

G

g23

LKK:

IDAC:

Surveyor:

XGD

DOI:

ASSIGNMENT

9/12/19

Date / Time:

6/12/19

Registered in Merimen:

9/12/19

Pre-assign / CCU / FTE



Insured Vehicle No. : GBH 1001 A

Claim No. : _____

Name of Insured : _____

Policy No. : _____

Insured Tel No. : _____ HP: _____

Make / Model : _____

Excess Sec II : S\$

D.O.A : 05/12/2019

Place of Accident : _____

Is driver the owner? (YES / NO)

Nature of Accident : _____

If NO, Driver Name / Age :

Driver Tel No. :

(V/L: YES / NO)

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability : % Final ? Yes / No

SGD 912 P

INSRS:
WSP: SUCCESS UNITED
Tel :
Liability :
RMKS:INSRS:
WSP:
Tel :
Liability :
RMKS:INSRS:
WSP:
Tel :
Liability :
RMKS:INSRS:
WSP:
Tel :
Liability :
RMKS:

Date/ Time	STAGE	DATE / PIC
	Non-Reporting ltr (1st):	
	Non-Reporting ltr (2nd):	
	Non-Reporting ltr (Final):	
	Notification ltr (if non-pickup):	
	Call OI:	
	After call ltr to OI:	
	Documentation Check List: Handler Typist	
	Notification ltr (if non-pickup)	☒
	After call ltr to OI:	☒
	Authorisation To Act:	☒
	Release Voucher:	☒
	Final Repair Bill:	☒
	Car Rental Invoice:	☒
	Towing Invoice:	☒
	UTA / GIA :	☒
	Medical Bill:	☒
	PIR:	☒
	Mandate/Reject Instruction:	☒
	LOD	☒
	Payment Breakdown Form:	☒
	Post-Repair Photos:	☒
	Others:	☒
PRELIMINARY ADVICE Date/Time: _____ Sent By: _____		
FINALIZATION Date/Time: _____ Confirm with: _____ Confirm by: GHO & ANG		
Repair Cost: 45	S\$ 8450.00	(7 days) Reduction: \$13,453.20 % 62
FINAL SETTLEMENT Date/Time: 14/12/2020 Confirm with: SWINA Email: ☒ Call: ☒		
Final Liability:	% 100 (Agreed / Assessed) BOLA S/N No. : 28	If NO, or B 28, Ass. Lia : C.C. (at 124)
Repair Cost: (WERS)	S\$ 9041.50	
Loss of Rental (LOR):	S\$ - (days)	
Loss of Use (LOU):	S\$ 1088.00 (\$ 90 x 12 days)	
Loss of Income (LOI):	S\$ - (\$ x days)	
LOR only ☐ LOU only ☐	☒ LOR + LOU ☐ LOR + LO ☐ [Tick only one]	
GLA/LTA Search	S\$ 2.45	
Medical:	S\$ -	
Disbursement:	S\$ - (e.g. Tow/ Independent)	
Legal Cost	S\$ -	
Total:	S\$ 10,128.95	Global Sum S\$: 10,100.00
FINAL PAYMENT Date/Time: _____ Confirm with: _____ Email: ☒ Call: ☒		
Payee 1:	S\$ 10,100.00	Name 1: Success United Pte Ltd
Payee 2: (Strike if N.A.)	S\$ -	Name 2: _____
Payee 3: (Strike if N.A.)	S\$ -	Name 3: _____

SUCCESS UNITED PTE LTD

2 Kaki Bukit Ave 2, #01-33 / #02-29

Kaki Bukit Autohub, Singapore 417921

Tel No. : 67461515 / 67471787 Fax No. : 67485015

Website : www.successunited.com.sg

Buss. Reg. No. : GST No. 200402570G

India International Insurance Pte Ltd

64 Cecil Street

#04/06 IOB Building

Singapore 049711

Attention : Motor Claim Department

Contact : 63476100 Fax No. : 62257743/62244174

Estimate : TP19-163

Date : 05/12/2019

Vehicle Num. : SGD912P

Make/Model : Mazda 5-2015

Chassis/Eng# : JM6CW1071F0121493/PE10221686

Accident Date : 05/12/2019

Claim No. :

Reference :

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LIST ITEMS:				
1.	1 pc	Bonnet <i>X Repair</i>	1,086.00	X
2.	1 pc	Bonnet Weatherstrip <i>X</i>	92.00	X
3.	1 pc	Bonnet Mechanism Lock <i>X</i>	207.00	X
4.	2 pcs	Frt Headlamp L/R <i>X</i>	1,482.00	2,964.00 X
5.	1 pc	Frt Bumper Assy <i>le</i>	1,045	1,109.00
6.	12 pcs	Frt Bumper Clips <i>le</i>	5.00	60.00
7.	2 pcs	Frt Bumper Side Holder L/R <i>le</i>	22.00	44.00
8.	2 pcs	Frt Bumper Bracket L/R <i>X NN</i>	42.00	84.00 X
9.	1 pc	Frt Bumper Inner Sponge <i>R / CAA</i>		80.00
10.	1 pc	Frt Bumper Reinforcement <i>R / BT</i>		532.00
11.	1 pc	Frt Air Grille <i>le</i>		182.00
12.	1 pc	Frt Tow Hook Cover <i>le</i>		55.00
13.	1 pc	Frt Grille Assy <i>le</i>		703.00
14.	1 pc	Frt Grille Mazda Logo <i>le</i>		46.00
15.	1 pc	Frt Foglamp Cover LH <i>le</i>		7.00
16.	1 pc	Radiator Support Panel Assy <i>R / CAA</i>		79.00
17.	1 pc	Aircon Condenser <i>X</i>		813.00 X
18.	1 pc	Horn <i>X</i>		169.00 X
19.	1 pc	Aircon Liquid Pipe <i>X</i>		362.00 X
20.	1 pc	Aircon Aluminium Pipe <i>X</i>		258.00 X
21.	1 pc	Rear Boot Lid <i>Buc</i>		1,637.00
22.	1 pc	Rear Windscreen <i>SM</i>	1,071.8	1,126.00
23.	1 pc	Rear Heater Sensor <i>X</i>		150.00 X
24.	2 pcs	Rear Boot Hinge L/R <i>X NN</i>	39.00	78.00 X
25.	1 pc	Rear Boot Lid Weatherstrip <i>T</i>		178.00
26.	1 pc	Rear Boot Lid Mechanism Lock <i>Tw</i>		257.00
27.	1 pc	Rear Boot Lid 'Mazda 5' Emblem <i>Jm</i>		83.00
28.	1 pc	Rear Boot Lid 'Mazda' Logo <i>le</i>		45.00
29.	1 pc	Rear Boot Lid 'SkyActiv' Emblem <i>le</i>		80.00
30.	1 pc	Rear No. Plate Lamp <i>X NN</i>		52.00 X
31.	1 pc	Rear No Plate Garnish <i>le</i>	142.8	459.00
32.	1 pc	Rear Wiper Motor <i>X NN</i>		317.00 X

CONTINUE / ...

SUCCESS UNITED PTE LTD

2 Kaki Bukit Ave 2, #01-33 / #02-29

Kaki Bukit Autohub, Singapore 417921

Tel No. : 67461515 / 67471787 Fax No. : 67485015

Website : www.successunited.com.sg

Buss. Reg. No. : GST No. 200402570G

India International Insurance Pte Ltd

64 Cecil Street

#04/06 IOB Building

Singapore 049711

Attention : Motor Claim Department

Contact : 63476100 Fax No. : 62257743/62244174

Estimate : TP19-163

Date : 05/12/2019

Vehicle Num. : SGD912P

Make/Model : Mazda 5-2015

Chassis/Eng# : JM6CW1071F0121493/PE10221686

Accident Date : 05/12/2019

Claim No. :

Reference :

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
33.	1 pc	Rear Wiper Blade <i>- Cat</i>		25.00
34.	1 pc	Rear Wiper Arm <i>X NN NN</i>		99.00
35.	2 pcs	Rear Lamp L/R <i>CH X NN RH - CRA</i>	602.00	1,204.00
36.	2 pcs	Rear Boot Lid Damper L/R <i>X NN</i>	178.00	356.00
37.	2 pcs	Rear Boot Lid Lamp L/R <i>CH X NN RH - CRA</i>	389.00	778.00
38.	1 pc	Rear Boot Lid Inner Trim Board <i>- DE</i>		432.00
39.	2 pcs	Rear Boot Lid Inner Trim Garnish L/R <i>CH X NN, RH - Cat</i>	29.00	58.00
40.	1 pc	Rear Fender Inner Trim Garnish RH <i>P - DE</i>		492.00
41.	1 pc	Rear Bumper Assy <i>- DE</i>		962.00
42.	10 pcs	Rear Bumper Clips <i>- DE</i>	5.00	50.00
43.	2 pcs	Rear Bumper Side Holder L/R <i>CH X NN, HH - DE</i>	48.00	96.00
44.	2 pcs	Rear Bumper Bracket L/R <i>X NN</i>	5.00	10.00
45.	1 pc	Rear Bumper Reinforcement <i>P - DE</i>		156.00
46.	1 pc	Rear Bumper Reflector Lamp RH <i>- SCR</i>		53.00
47.	1 pc	Rear Bumper Inner Liner RH <i>P - DE</i>		40.00
48.	5 pcs	Rear Bumper Inner Liner Clips <i>P - DE</i>	5.00	25.00
49.	1 pc	Rear End Panel <i>P - DE</i>	485.00	818.00
50.	1 pc	Rear Lamp Panel RH <i>P - DE</i>	120.00	120.00
51.	1 pc	Rear End Panel Inner Top Garnish <i>P - DE</i>		81.00
52.	1 pc	Rear Tyre Panel <i>X Repair</i>		1,182.00
List Total S\$:			9830.4	20,454.00
20.00% Discount S\$:			7864.32	4,090.80
				16,363.20
SPECIAL NETT ITEMS				
1.	1 set	Reverse Sensor <i>DM</i>	200	450.00
2.	2 set	Frt & Rear No. Plate w/Frame <i>BT</i>	45.00	90.00
3.	1 set	Windscreen Sealant <i>- DE</i>		40.00
Special Nett Total S\$:			330	580.00
LABOUR :				
To remove, rearrange electrical wirings, check lighting			30	80.00

CONTINUE / ...

SUCCESS UNITED PTE LTD

2 Kaki Bukit Ave 2, #01-33 / #02-29
 Kaki Bukit Autohub, Singapore 417921
 Tel No. : 67461515 / 67471787 Fax No. : 67485015
 Website : www.successunited.com.sg
 Buss. Reg. No. : GST No. 200402570G

India International Insurance Pte Ltd
 64 Cecil Street
 #04/06 IOB Building
 Singapore 049711

Attention : Motor Claim Department

Contact : 63476100 Fax No. : 62257743/62244174

Estimate : TP19-163

Date : 05/12/2019
 Vehicle Num. : SGD912P
 Make/Model : Mazda 5-2015
 Chassis/Eng# : JM6CW1071F0121493/PE10221686
 Accident Date : 05/12/2019
 Claim No. :
 Reference :
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
		To remove, instal aircon parts, vacuum, refill gas.	120	200.00
		To remove, replace rear windscreen.	100	200.00
		To remove, replace & transfer rear boot lid components.	60	250.00
		To remove, instal upholstery, inner trim garnishes.	60	250.00
		To remove, repair and replaced damaged bodyparts, realign bodyworks & where consistent to the accident	800	2,400.00
		To putty and respray painting on affected area.	1200	2,000.00
		Towing Fees.	2370	80.00
		Labour Total S\$:		5,460.00

7 Days.
 Unpin repair.
 After repair photos.
 Eno Qian - 82880282
 09/12/19.

10564.32
 20%: 8450

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplementary items must be surveyed and is subject to final approval of Insurance Company

Total S\$ 22,403.20

Acknowledged by Repairer

Signature:

Date:

SUCCESS UNITED PTE LTD

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	251B
Vehicle Details	
Vehicle No.:	SGD912P
Vehicle to be Exported:	No
Intended Deregistration Date:	09 Dec 2019
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA5 5-DOOR WAGON 2.0L SP,6EAT SUNROOF
Primary Colour:	Red
Manufacturing Year:	2015
Engine No.:	PE10221686
Chassis No.:	JM6CW1071F0121493
Maximum Power Output:	111.0 kW (148 bhp)
Open Market Value:	\$17,183.00
Original Registration Date:	12 Jun 2015
First Registration Date:	12 Jun 2015
Transfer Count:	1
Actual ARF Paid:	\$12,183.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	11 Jun 2025
PARF Rebate Amount:	\$9,137.00
Intended COE Rebate Details	
COE Expiry Date:	11 Jun 2025
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$75,000.00
COE Rebate Amount:	\$41,291.00
Total Rebate Amount:	\$50,428.00

The information contained herein is correct as at 09 Dec 2019

OK

▶ Mazda 5 Used Vehicle List (14 vehicles)

Car Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Company	Availabi
Mazda 5 2.0A Sunroof	\$57,800	\$10,000 /yr	30-Jan-2015	1,998 cc	60,890 km	AA Trust Automotive	Availal

1 Doctor Owner! AA Trust Certified Pre-Owned Vehicle! Full Agent Serviced Since Day 1! Genuine Low Mileage Done At 60890! Current Pape Value At \$49125! COE Paid At \$76790! Twin Auto Sliding Door! Rel...

Office No. - 63450381

Clement - 93365036 | Dave - 98500051 | Willey - 91692071

Mazda 5 2.0A Sunroof	\$55,822	\$9,450 /yr	27-Feb-2015	1,998 cc	35,368 km	D2 Motors	Availal
----------------------	----------	-------------	-------------	----------	-----------	-----------	---------

Lowest Mileage 2015 Mazda 5 In Pre-Owned Market. Only 7.4k KM Done Per Annum. Fully Serviced & Maintained By Agent (TransEurokar). Owner With Accident Free Status. Original Jet Black Pearl Paintwork...

Office No. - 63655933

Wei Xiong - 92278426 | Cheong - 83802222 | Shaun - 96803767

Mazda 5 2.0A Sunroof	\$59,800	\$9,830 /yr	13-May-2015	1,998 cc	34,000 km	Hua Yang Credit Pte Ltd	Availal
----------------------	----------	-------------	-------------	----------	-----------	-------------------------	---------

No Gimmick! Get Promotion Price! Super Low Mileage! One Year Comprehensive Warranty! Serviced By Agent! Only One Owner! Reliable MP With Low Maintenance Cost. Good Fuel Efficiency! Accident Free! 100...

Office No. - 64635111

Eric - 91982642 | Kamen - 88621923

Mazda 5 2.0A Sunroof	\$57,900	\$9,320 /yr	30-Jun-2015	1,998 cc	61,200 km	Fu Yiap Motor Trading	Availal
----------------------	----------	-------------	-------------	----------	-----------	-----------------------	---------

Accredited Company! 1 Owner! Accident Free, Low Mileage! High Paper Value, Attractive Interest Rates, 100% Loan Approval With Flexible 1 House Financing/Bank Loan Available. Well Maintained! That Is ...

Office No. - 67760119

Doreen - 98171817 | Mr Ho - 98161816

Mazda 5 2.0A Sunroof	\$60,800	\$9,080 /yr	28-Aug-2015	1,998 cc	-	Prime Motor & Leasing	Availal
----------------------	----------	-------------	-------------	----------	---	-----------------------	---------

Elegant Red MPV, With Sunroof And Auto Sliding Doors, One Owner Only, Serviced By Agent In May 2019, Low Maintenance Cost, Very Well Maintained, Easy Financing, Flexible In House Loan Available.

Office No. - 67782233

Bobby - 86863300 | Danny - 83661373

Mazda 5 2.0A Sunroof	\$61,800	\$9,090 /yr	22-Sep-2015	1,998 cc	52,300 km	Hanns Auto	Availal
----------------------	----------	-------------	-------------	----------	-----------	------------	---------

1 Owner, Agent Serviced Till 2018. New Service Done. Low Mileage, Full Size MPV, Original Paintwork. Well Maintained By Owner, Reliable M With Low Maintainance Cost. Good Fuel Efficiency, Sliding Do...

Office No. - 62712252

Desmond Chan - 91717808 | Tan - 96232252

Mazda 5 2.0A Sunroof	\$59,800	\$8,740 /yr	23-Sep-2015	1,998 cc	-	Star A Motor	Availal
----------------------	----------	-------------	-------------	----------	---	--------------	---------

Elegant Blue MPV, With Sunroof And Auto Sliding Doors, One Owner Only, Low Maintenance Cost, Serviced By Agent In May 2019, Very Wel Maintained, Easy Financing, Flexible In House Loan Available.

Office No. - 62840089

May - 90671717 | Richard - 98429922

Mazda 5 2.0A Sunroof	\$60,800	\$8,790 /yr	20-Oct-2015	1,998 cc	102,260 km	Mayfair Motoring	Availal
----------------------	----------	-------------	-------------	----------	------------	------------------	---------

1 Owner Only! Super Well Maintained/Tip Top Condition With Sunroof. Buy It From Us With A Peace Of Mind, A Company Accredited With Outstanding Awards, Professional After Sales Service Assured. High Lo...

Office No. - 64792220

Richard Ho - 98625691 | Alvin Joo - 92722283 | Nelson Ng - 92369669

Mazda 5 2.0A Sunroof	\$62,000	\$8,970 /yr	30-Oct-2015	1,998 cc	56,000 km	Quality Motor Trading Enterprise	Availal
----------------------	----------	-------------	-------------	----------	-----------	----------------------------------	---------

Beautiful Bronze Grey Finishing, Impeccable Interior Condition! New Road Tax Paid For 6 Months. Achievable Fuel Consumption 14-15 Km/Li

https://www.sgcarmart.com/used_cars/search_result_pricelist_print.php?SA=&MOD=Mazda 5&RPG=20&VEH=0&RGD=2015&AVL=2&ORD=RG... 1/2

Affordable MPV With Twin Power Sliding Doors! Responsive And...

Office No. - 64738668

Sharon - 97882224 | Dominic - 86685757

Mazda 5 2.0A Sunroof	\$64,800	\$9,340 /yr	25-Nov-2015	1,998 cc	46,000 km	Ritz Auto	Availal
-----------------------------	-----------------	--------------------	--------------------	-----------------	------------------	------------------	----------------

One Owner. Original Paintwork. Super Low Mileage Done. Very Good Condition. Well Maintained By Previous Owner. Accident-Free. Impecca Interior Condition! New Road-tax Still Nov 2020. Achievable Fue...

Office No. - 62556118

Simon Tan - 91261801 | Ouyang - 97227737

Mazda 5 2.0A Sunroof	\$61,800	\$8,830 /yr	26-Nov-2015	1,998 cc	62,500 km	Prime Car Traders Pte Ltd	Availal
-----------------------------	-----------------	--------------------	--------------------	-----------------	------------------	----------------------------------	----------------

One Owner. Low Mileage. Good Condition. Well Maintained By Previous Owner. Accident-Free. Low Interest Rate. Call/SMS For More Details.

Office No. - 63166000

Jessy - 91690999 | Nicolas Lim - 96849675 | Tony Chua - 90885037

Mazda 5 2.0A Sunroof	\$60,000	\$8,510 /yr	30-Nov-2015	1,998 cc	105,000 km		Availal
-----------------------------	-----------------	--------------------	--------------------	-----------------	-------------------	--	----------------

1 Owner Only! No Accident, Super Well Maintained/Tip Top Condition With Sunroof. Buy It From Me With A Peace Of Mind.

Office No. - -

Mark Ma - 82233225

Mazda 5 2.0A Sunroof	\$60,800	\$8,650 /yr	30-Nov-2015	1,998 cc	57,000 km		Availal
-----------------------------	-----------------	--------------------	--------------------	-----------------	------------------	--	----------------

Low Mileage. Low Profile Sports Rims, Tyre Size 225/40/R18, Last Servicing Done 29/9/19, Rare Mazda Original Beige Colour Leather Seats. Depreciation \$8k+. 1 Owner Since Registration. Accident Free. O...

Office No. - -

Muhammad Haizal - 98534604

Mazda 5 2.0A Sunroof	\$62,800	\$8,850 /yr	31-Dec-2015	1,998 cc	80,000 km	Hua Yang Credit Pte Ltd	Availal
-----------------------------	-----------------	--------------------	--------------------	-----------------	------------------	--------------------------------	----------------

1 Careful Owner, Well Taken Care. 100% Accident Free. Engine/Gearbox In Good Condition, No Further Repairs Needed. One Year Comprehensive Warranty! Low Interest Bank Rate From 2.28%! Buy With A Peace ...

Office No. - 64658348

Elwin Wong - 82182346 | Emily Teo - 86689797

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale even for COE cars, OPC cars, vans, trucks, hybrid cars, sports cars or stationwagons. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. We have new car dealers comprising parallel importers, authorized car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions, and also motoring advice, car reviews & car news on the latest models. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

© 2004-2019 sgCarMart. All rights reserved.

Summer Lee (LKK Auto)

From: Motor Claim - III <motorclaim@iii.com.sg>
Sent: Friday, 6 December, 2019 4:36 PM
To: Keong; 'sur@lkkauto.com'; Nivitha (LKK Auto)
Cc: Sirina Soon; ELAINE SOON; Zuhaidah Samsuri
Subject: RE: TP PRI - SGD 912P / GBH 1001A / DoA 05.12.2019
Attachments: PRI.PDF

Dear Sir / Mdm,

Please conduct a survey on TP vehicle SGD912P and let us have your report urgently.

This claim will be handled by Ms Aida.

*Kindly upload this survey request email to merimen.

Thank You.

Best Regards,
Gabriel Wee



64 Cecil Street; #05 - IOB Building
Singapore 049711
Tel: 6347 6100, Ext - 248

p. Wu Keong
T. 4.57p.m
V: 14
E. ✓

From: Keong [mailto:keong@successunited.com.sg]
Sent: 06 December, 2019 1:28 PM
To: Motor Claim - III <motorclaim@iii.com.sg>
Cc: Sirina Soon <sirina@successunited.com.sg>; ELAINE SOON <elaine@successunited.com.sg>
Subject: Re: TP PRI - SGD 912P / GBH 1001A / DoA 05.12.2019

Hi Gabriel,

Kindly assign **LKK Auto Consultants Pte Ltd** to conduct the PRI.

Thank you.

Best Regards,

Teo Wee Keong

Claim Executive
Mobile: +65 86512856

SUCCESS UNITED PTE LTD
2 Kaki Bukit Ave 2
#01-33 / #02-29
Kaki Bukit AutoHub

On Fri, 6 Dec 2019 at 13:19, Motor Claim - III <motorclaim@iii.com.sg> wrote:

Dear Sir / Mdm,

We acknowledge receipt of your email.

We propose using one of the following motor surveyors:

- LKK Auto Consultants Pte Ltd
- Vicom Assessment Centre Pte Ltd

Please notify us within 02 days of receipt of this letter for surveyor agreed on or if you have any objections to the above list.

Best Regards,

Gabriel Wee



64 Cecil Street; #05 - IOB Building

Singapore 049711

Tel: 6347 6100, Ext – 248

From: Keong [mailto:keong@successunited.com.sg]

Sent: 06 December, 2019 11:14 AM

To: Motor Claim - III <motorclaim@iii.com.sg>

Cc: Sirina Soon <sirina@successunited.com.sg>; ELAINE SOON <elaine@successunited.com.sg>

Subject: TP PRI - SGD 912P / GBH 1001A / DoA 05.12.2019

Hi

Kindly arranged for TP PRI for our client's vehicle no. SGD 912P which was damaged due to accident.

For your information, the vehicle already lying on our workshop since 05/12/2019.

Attached herein the necessary documents for your reference.

Thank you.

Best Regards,

Teo Wee Keong

Claim Executive

Mobile: +65 86512856

SUCCESS UNITED PTE LTD

2 Kaki Bukit Ave 2

#01-33 / #02-29

Kaki Bukit AutoHub

Singapore 417921

Tel: 6746 1515 Fax: 6748 5015

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

Print Received Message

This mail is associated with :

***SGD912P (MFL2019D0001633)**
[GBH1001A]
TP
AZAHARI BIN ALI
Dec 5 2019 10:00AM
[-]
Success United Pte Ltd

From India International Insurance Pte Ltd (HQ) (III_SG), sent on 09/03/2020 09:43 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$10248.95) - SGD912P - Claim Handler: Zuhaidah Bte Samsuri

Approved:10248.95.

Claim Documents

*SGD912P (MFL2019D0001633)
[GBH1001A]
TP
AZAHARI BIN ALI
Dec 5 2019 10:00AM
[PAN PACIFIC VAN & TRUCK LEASING PTE LTD]
Success United Pte Ltd

Upload DocumentsUpload PhotosCompose New LetterViewView in Browser

Photos/Images			3 per page	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	06/02/20 09:49	General View		Load JPG ☒
2	06/02/20 09:49	General View		Load JPG ☒
3	06/02/20 09:49	General View		Load JPG ☒
4	06/02/20 09:49	General View		Load JPG ☒
5	06/02/20 09:49	General View		Load JPG ☒
6	06/02/20 09:49	General View		Load JPG ☒
7	06/02/20 09:49	General View		Load JPG ☒
8	06/02/20 09:49	General View		Load JPG ☒
9	06/02/20 09:49	General View		Load JPG ☒
10	06/02/20 09:49	General View		Load JPG ☒
11	06/02/20 09:49	General View		Load JPG ☒
12	06/02/20 09:49	General View		Load JPG ☒
13	06/02/20 09:49	General View		Load JPG ☒
14	06/02/20 09:49	General View		Load JPG ☒
15	06/02/20 09:49	General View		Load JPG ☒
16	06/02/20 09:49	General View		Load JPG ☒
17	06/02/20 09:50	General View		Load JPG ☒
18	06/02/20 09:50	General View		Load JPG ☒
19	06/02/20 09:50	General View		Load JPG ☒
20	06/02/20 09:50	General View		Load JPG ☒
21	06/02/20 09:50	General View		Load JPG ☒
22	06/02/20 09:50	General View		Load JPG ☒
23	06/02/20 09:50	General View		Load JPG ☒
24	06/02/20 09:50	General View		Load JPG ☒
25	06/02/20 09:50	General View		Load JPG ☒
26	06/02/20 09:50	General View		Load JPG ☒
27	06/02/20 09:50	General View		Load JPG ☒
28	06/02/20 09:50	General View		Load JPG ☒
29	06/02/20 09:50	General View		Load JPG ☒
30	06/02/20 09:50	General View		Load JPG ☒
31	06/02/20 09:50	General View		Load JPG ☒
32	06/02/20 09:50	General View		Load JPG ☒
33	06/02/20 09:50	General View		Load JPG ☒
34	06/02/20 09:50	General View		Load JPG ☒
35	06/02/20 09:50	General View		Load JPG ☒
36	06/02/20 09:50	General View		Load JPG ☒
37	06/02/20 09:50	General View		Load JPG ☒
38	06/02/20 09:50	General View		Load JPG ☒
39	06/02/20 09:50	General View		Load JPG ☒
40	06/02/20 09:50	General View		Load JPG ☒
41	06/02/20 09:50	General View		Load JPG ☒
42	06/02/20 09:50	General View		Load JPG ☒
43	06/02/20 09:50	General View		Load JPG ☒

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
44	06/02/20 09:50	General View	 Load JPG	☒
45	06/02/20 09:50	General View	 Load JPG	☒
46	06/02/20 09:50	General View	 Load JPG	☒
47	06/02/20 09:50	General View	 Load JPG	☒
48	06/02/20 09:50	General View	 Load JPG	☒
49	06/02/20 09:50	General View	 Load JPG	☒
50	06/02/20 09:50	General View	 Load JPG	☒
51	06/02/20 09:50	General View	 Load JPG	☒
52	06/02/20 09:50	General View	 Load JPG	☒
53	06/02/20 09:50	General View	 Load JPG	☒
54	06/02/20 09:50	General View	 Load JPG	☒
55	06/02/20 09:50	General View	 Load JPG	☒
56	06/02/20 09:50	General View	 Load JPG	☒
57	06/02/20 09:50	General View	 Load JPG	☒
58	06/02/20 09:50	General View	 Load JPG	☒
59	06/02/20 09:50	General View	 Load JPG	☒
60	06/02/20 09:51	Chassis Number	 Load JPG	☒
61	06/02/20 09:51	Odometer Reading	 Load JPG	☒
62	19/02/20 12:32	Dismantled Parts	 Load JPG	☒
63	19/02/20 12:32	Dismantled Parts	 Load JPG	☒
64	19/02/20 12:32	Dismantled Parts	 Load JPG	☒
65	19/02/20 12:32	Dismantled Parts	 Load JPG	☒
66	19/02/20 12:32	Dismantled Parts	 Load JPG	☒
67	19/02/20 12:32	Dismantled Parts	 Load JPG	☒
68	19/02/20 12:32	Dismantled Parts	 Load JPG	☒
69	19/02/20 12:32	Dismantled Parts	 Load JPG	☒
70	19/02/20 12:32	Dismantled Parts	 Load JPG	☒
71	19/02/20 12:32	Dismantled Parts	 Load JPG	☒
72	19/02/20 12:32	Dismantled Parts	 Load JPG	☒
73	19/02/20 12:32	Dismantled Parts	 Load JPG	☒
74	19/02/20 12:32	Dismantled Parts	 Load JPG	☒
75	19/02/20 12:32	Dismantled Parts	 Load JPG	☒
76	19/02/20 12:32	Dismantled Parts	 Load JPG	☒
77	19/02/20 12:32	Dismantled Parts	 Load JPG	☒
78	19/02/20 12:32	Dismantled Parts	 Load JPG	☒
79	19/02/20 12:32	Dismantled Parts	 Load JPG	☒
80	19/02/20 12:32	Dismantled Parts	 Load JPG	☒
81	19/02/20 12:32	Dismantled Parts	 Load JPG	☒
82	19/02/20 12:32	Dismantled Parts	 Load JPG	☒
83	19/02/20 12:32	Dismantled Parts	 Load JPG	☒
84	19/02/20 12:32	Dismantled Parts	 Load JPG	☒
85	19/02/20 12:32	Dismantled Parts	 Load JPG	☒
86	19/02/20 12:32	Dismantled Parts	 Load JPG	☒
87	19/02/20 12:32	Dismantled Parts	 Load JPG	☒
88	19/02/20 12:32	Dismantled Parts	 Load JPG	☒
89	19/02/20 12:32	Dismantled Parts	 Load JPG	☒
90	19/02/20 12:32	Dismantled Parts	 Load JPG	☒
91	19/02/20 12:32	Dismantled Parts	Load JPG	☒
92	19/02/20 12:32	Dismantled Parts	Load JPG	☒
93	19/02/20 12:32	Dismantled Parts	Load JPG	☒
94	19/02/20 12:32	Dismantled Parts	Load JPG	☒
95	19/02/20 12:32	Dismantled Parts	Load JPG	☒
96	19/02/20 12:32	Dismantled Parts	Load JPG	☒
97	19/02/20 12:32	Dismantled Parts	Load JPG	☒
98	19/02/20 12:32	Dismantled Parts	Load JPG	☒
99	19/02/20 12:32	Dismantled Parts	Load JPG	☒

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
100	19/02/20 12:32	After Repair Photo	 Load JPG	☒
101	19/02/20 12:32	After Repair Photo	 Load JPG	☒
102	19/02/20 12:32	After Repair Photo	 Load JPG	☒
103	19/02/20 12:32	After Repair Photo	 Load JPG	☒
104	19/02/20 12:32	After Repair Photo	 Load JPG	☒
105	19/02/20 12:32	After Repair Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	14/12/19 19:15	TP ESTIMATE - MARKED	 Load PDF	
2	14/12/19 19:15	TP GIA REPORT	 Load PDF	
3	16/12/19 09:26	EMAIL FROM III DD 06.12.19	 Load PDF	
4	24/02/20 09:50	LOD AND OTHER DOCUMENTS	 Load PDF	
5	28/02/20 15:31	WORKSHOP INVOICE	 Load PDF	
6	28/02/20 15:31	LTA SEARCH	 Load PDF	
7	28/02/20 15:31	LOD	 Load PDF	
8	30/03/20 10:17	AUTHORISATION TO ACT FORM	 Load PDF	
9	30/03/20 10:17	DISCHARGE VOUCHER	 Load PDF	
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	10/12/19 08:22	Singapore Accident Statement	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

ResetSavePrint

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

⬆⬇

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III19021636/GGA3Q2

Date: 30/03/2020

REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D19MFL0005549
Claimant Vehicle No :	SGD912P	Insured Vehicle No :	GBH1001A
Date of Loss:	05/12/2019	Nature of Claim:	TP
		Claim No:	MFL2019D0001633

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGD912P	Engine No:	PE10221686
Make & Model:	MAZDA 5, 2.0 SP.6EAT SUNROOF (A)	Chassis No:	JM6CW1071F0121493
Reg. Date:	12/06/2015 (Man. Year: 2015)	Odometer:	65266 km
Colour:	Red		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,943.20	8,194.32	8,748.88	51.64
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,460.00	2,370.00	3,090.00	56.59
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	22,403.20	10,564.32	11,838.88	52.84
Approved Total (Overridden) (S\$)		8,450.00		
(S\$)	22,403.20	8,450.00	13,953.20	62.28
+ GST 7.00/7.00% (S\$)	1,568.22	591.50	976.72	62.28
Nett Amount (S\$)	23,971.42	9,041.50	14,929.92	62.28
+ Loss of Use (12.0 x S\$90.00/day) (S\$)		1,080.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		10,128.95		
Global Sum Settlement (S\$)		10,000.00		

INSPECTION

Date of Assignment:	06/12/2019	
Date Inspected:	09/12/2019 Inspected At:	Success United Pte Ltd (HQ) 2 Kaki Bukit Ave 2 #01-33, Kaki Bukit

AutoHub
Singapore 417921

Estimated Period of Repair: 7.0 days

Adjuster: XING GUO QIANG

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 28 Feb 2020)	
Parts:	N/A	MAZDA 5 2.0 SP.6EAT SUNROOF (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGD912P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Repair	1,086.00 FL	*- FL
2	1		*BONNET WEATHERSTRIP	Not Necessary	92.00 FL	*- FL
3	1		*BONNET MECHANISM LOCK	Not Necessary	207.00 FL	*- FL
4	2		*FRT HEADLAMP L/R	Not Necessary	2,964.00 FL	*- FL
5	1		*FRT BUMPER ASSY	Deformed	1,109.00 FL	*1,045.00 FL
6	12		*FRT BUMPER CLIPS	Necessary	60.00 FL	*30.00 FL
7	2		*FRT BUMPER SIDE HOLDER L/R	Deformed	44.00 FL	*44.00 FL
8	2		*FRT BUMPER BRACKET L/R	Not Necessary	84.00 FL	*- FL
9	1		*FRT BUMPER INNER SPONGE	Cracked	80.00 FL	*80.00 FL
10	1		*FRT BUMPER REINFORCEMENT	Bent	532.00 FL	*506.00 FL
11	1		*FRT AIR GRILLE	Deformed	162.00 FL	*162.00 FL
12	1		*FRT TOW HOOK COVER	Missing	55.00 FL	*42.60 FL
13	1		*FRT GRILLE ASSY	Deformed	703.00 FL	*558.40 FL
14	1		*FRT GRILLE MAZDA LOGO	Necessary	46.00 FL	*46.00 FL
15	1		*FRT FOGLAMP COVER LH	Deformed	7.00 FL	*7.00 FL
16	1		*RADIATOR SUPPORT PANEL ASSY	Cracked	79.00 FL	*79.00 FL
17	1		*AIRCON CONDENSER	Not Necessary	813.00 FL	*- FL
18	1		*HORN	Not Necessary	169.00 FL	*- FL
19	1		*AIRCON LIQUID PIPE	Not Necessary	362.00 FL	*- FL
20	1		*AIRCON ALUMINIUM PIPE	Not Necessary	256.00 FL	*- FL
21	1		*REAR BOOT LID	Buckled	1,637.00 FL	*1,637.00 FL
22	1		*REAR WINDSCREEN	Smashed	1,126.00 FL	*1,071.80 FL
23	1		*REAR HEATER SENSOR	Not Necessary	150.00 FL	*- FL
24	2		*REAR BOOT HINGE L/R	Not Necessary	78.00 FL	*- FL
25	1		*REAR BOOT LID WEATHERSTRIP	Twisted	178.00 FL	*178.00 FL
26	1		*REAR BOOT LID MECHANISM LOCK	Jammed	257.00 FL	*257.00 FL
27	1		*REAR BOOT LID MAZDA 5 EMBLEM	Necessary	83.00 FL	*41.80 FL
28	1		*REAR BOOT LID MAZDA LOGO	Necessary	45.00 FL	*45.00 FL
29	1		*REAR BOOT LID SKYACTIV EMBLEM	Necessary	80.00 FL	*80.00 FL
30	1		*REAR NO.PLATE LAMP	Not Necessary	52.00 FL	*- FL
31	1		*REAR NO PLATE GARNISH	Deformed	459.00 FL	*142.80 FL
32	1		*REAR WIPER MOTOR	Not Necessary	317.00 FL	*- FL
33	1		*REAR WIPER BLADE	Cut	25.00 FL	*25.00 FL
34	1		*REAR WIPER ARM	Not Necessary	99.00 FL	*- FL
35	1		*REAR LAMP L/R	N/S Not Necessary /O/S Cracked	1,204.00 FL	*389.90 FL
36	2		*REAR BOOT LID DAMPER L/R	Not Necessary	356.00 FL	*- FL
37	1		*REAR BOOT LID INNER L/R	N/S Not Necessary / O/S Cracked	778.00 FL	*389.00 FL
38	1		*REAR BOOT LID INNER TRM BOARD	Deformed	432.00 FL	*432.00 FL
39	1		*REAR BOOT LID INNER TRIM GARNISH L/R	N/S Not Necessary / O/S Cut	58.00 FL	*29.00 FL
40	1			Deformed	492.00 FL	*492.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
			*REAR FENDER INNER TRIM GARNISH RH			
41	1		*REAR BUMPER ASSY	Deformed	962.00 FL	*962.00 FL
42	10		*REAR BUMPER CLIPS	Necessary	50.00 FL	*50.00 FL
43	1		*REAR BUMPER SIDE HOLDER L/R	N/SNot Necessary/ N/S Deformed	96.00 FL	*48.00 FL
44	2		*REAR BUMPER BRACKET L/R	Not Necessary	10.00 FL	*- FL
45	1		*REAR BUMPER REINFORCEMENT	Bent	156.00 FL	*156.00 FL
46	1		*REAR BUMPER REFLECTOR LAMP RH	Scratched	53.00 FL	*53.00 FL
47	1		*REAR BUMPER INNER LINER RH	Deformed	40.00 FL	*40.00 FL
48	5		*REAR BUMPER INNER LINER CLIPS	Necessary	25.00 FL	*25.00 FL
49	1		*REAR END PANEL	Buckled	816.00 FL	*485.10 FL
50	1		*REAR LAMP PANEL RH	Buckled	167.00 FL	*120.00 FL
51	1		*REAR END PANEL INNER TOP GARNISH	Deformed	81.00 FL	*81.00 FL
52	1		*REAR TYRE PANEL	Repair	1,182.00 FL	*- FL
53	1		*SET REVERSE SENSOR	Damaged	450.00 FS	*200.00 FS
54	2		*SET FRT & REAR NO.PLATE W/FRAME	Bent	90.00 FS	*90.00 FS
55	1		*SET WINDSCREEN SEALANT	Necessary	40.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

	Sub Total (S\$)	21,034.00	10,160.40
- List Item Discount on L Items 20.00/20.00% (S\$)	4,090.80	1,966.08	
	Total Parts (S\$)	16,943.20	8,194.32

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE,REARRANGE ELECTRICAL WIRINGS ,CHECK LIGHTING	New	80.00	30.00
2	TO REMOVE,REINSTALL AIRCON PARTS ,VACUUM ,REFILL GAS	New	200.00	120.00
3	TO REMOVE,REPLACE REAR WINDSCREEN	New	200.00	100.00
4	TO REMOVE,REPLACE & TRANSFER REAR BOOT LID COMPONENTS	New	250.00	60.00
5	TO REMOVE,REINSTAL UPHOLSTERY INNER TRIM GARNISHES	New	250.00	60.00
6	TO REMOVE,REPAIR AND REPLACED DAMAGED BODYPARTS,REALIGN BODYWORK & WHERE CONSISTENT TO THE ACCIDENT	New	2,400.00	800.00
7	TO PUTTY AND RESPRAY PAINTING ON AFFECTED AREA	New	2,000.00	1,200.00
8	TOWING FEES	New	80.00	0.00
Gross Labour Cost (S\$)			5,460.00	2,370.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >