



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

LONPAC INSURANCE BHD  
300 BEACH ROAD  
#17-04/07 THE CONCOURSE  
SINGAPORE 199555

INV No. AC2004500  
INV Date 24/06/2020  
Reference CC4/LPC19021637/Eea3n2  
Code LPC2



### PROFESSIONAL SERVICE FEE

Vehicle No. SLT 4664K  
Insured Veh. SLE 9351J  
Claim No. 19/19/19/VP05/022760  
Policy No. Z19VP05024165  
Accident Date 09/12/2019  
Inspection Date 09/12/2019

Description	Total
Third Party Express Settlement	400.00
<b>Subtotal</b>	<b>400.00</b>
<b>GST (7%)</b>	<b>28.00</b>
<b>Grand Total</b>	<b>428.00</b>

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

*HYN*



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref : CC4/LPC19021637/Eea3n2

300 BEACH ROAD  
#17-04/07 THE CONCOURSESINGAPORE 199555

Date : 24-06-2020



Code : LPC2

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLE 9351J	Veh. Inspected	SLT 4664K
Policy No.	Z19VP05024165	Coverage (\$)	0.00
Claim No.	19/19/19/VP05/022760	Excess (\$)	0.00
Assign From	ONG LI LI	Assign Date	09/12/2019

### 2. Vehicle Particulars & Condition

Make & Model	MAZDA 3	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	JM6BN22A8H0158361	Colour	BLUE
Odometer	137857	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/60 R16	TRIANGLE	5 mm
L/H Front Tyre	205/60 R16	TRIANGLE	5 mm
R/H Rear Tyre	205/60 R16	TRIANGLE	5 mm
L/H Rear Tyre	205/60 R16	TRIANGLE	5 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

### 5. General Information

Accident Date	09/12/2019	Inspection Date	09/12/2019
Survey held at	74 KIAN TECK ROAD		
Repairer	PEGASUS ENGINEERING & TRADING PTE LTD		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	2 Working Days
-------------------------------------	----------------



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLT 4664K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	REAR BUMPER	BROKEN	1,175.00	1,075.00
10	REAR BUMPER CLIPS @\$4.00	NECESSARY	40.00	30.00
4	REAR BUMPER RIVET @\$5.00	NECESSARY	20.00	10.00
2	REAR BUMPER TOW COVER @\$40.00	MISSING	80.00	80.00
1	REAR BUMPER INNER CENTER BRACKET	NOT NECESSARY	45.00	-
1	REAR REINFORCEMENT	NOT NECESSARY	545.00	-
1	REAR END PANEL	TO REPAIR SEE LABOUR	712.00	-
2	REAR BUMPER REFLECTOR @\$115.00	NOT NECESSARY	230.00	-
	LESS 20% DISCOUNT		-569.40	-239.00
			2,277.60	956.00
<b><u>SPECIAL NETT ITEMS</u></b>				
1	REAR REVERSE SENSOR (SN)	SHORTED	280.00	200.00
			280.00	200.00
<b><u>LABOUR</u></b>				
	TO REMOVE & REPLACED REAR REVERSE SENSOR .		100.00	20.00
	TO APPLY RUST PROOFING & TUFFCOATING TREATMENT.		100.00	30.00
	TO KNOCKING & PANEL BEATING.INCLUSIVE OF THE REPAIR OF REAR END PANEL .		1,000.00	300.00
	TO PUTTY & SPRAY PAINT ON THE AFFECTED AREAS.		1,000.00	300.00
			2,200.00	650.00
<b>GRAND TOTAL</b>			<b>4,757.60</b>	<b>1,806.00</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>1,806.00</b>

Report Ref No. CC4/LPC19021637/Eea3n2

CHEN TSUE YEE

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLT 4664K

INSPECTION







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLT 4664K

RE-INSPECTION

