

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/FWD19021638/QGS3Q2

Date: 30/06/2020

REFERENCE

Handling Insurer: FWD Singapore Pte. Ltd. Policy No: PNPV2019-00002781

Claimant
Vehicle No : SLF7873C **Insured Vehicle No :** SGR1836X

Date of Loss: 06/12/2019 Nature of Claim: TP Claim No: 1201900038698

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLF7873C**

Make & Model: MAZDA 3, 1.4 SEDAN 1.5L SP.6EAT (A)

Engine No: P520374230

Reg. Date: 09/09/2016 (Man. Year: 2016)

Chassis No: JM6BM42A8G0345958

Colour: White

Odometer: 243273 km

Engine Capacity: 1496 cc

Market Value/New Car

Price: N/A

Sum Insured (\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60 R16

Rear Tyre Size: 205/60 R16

Front Left Side: Firenza 5 mm

Rear Left Side: Firenza 5 mm

Front Right Side: Firenza 5 mm

Rear Right Side: Firenza 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,192.00	1,916.00	276.00	12.59
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,750.00	1,530.00	220.00	12.57
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$)	3,942.00	3,446.00	496.00	12.58
Approved Total (Overridden) (\$)		2,750.00		
(S\$)	3,942.00	2,750.00	1,192.00	30.24
+ GST 7.00/7.00% (\$)	275.94	192.50	83.44	30.24
Nett Amount (\$)	4,217.94	2,942.50	1,275.44	30.24
+ Loss of Use (7.0 x S\$60.00/day) (\$)		420.00		
+ Doc/Search Fee (\$)		2.00		
Nett Liability (\$)		3,364.50		
Global Sum Settlement (\$)		3,350.00		

INSPECTION

Date of Assignment: 09/12/2019

Date Inspected: 09/12/2019 Inspected At:

Lion City Rentals Pte Ltd
1090 LOWER DELTA ROAD #05-12
Singapore 169201

Estimated Period of Repair: 5.0 days

Adjuster: OI SUN PIN**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 22 May 2020)
Parts:	143	MAZDA 3 1.4 SEDAN 1.5L SP.6EAT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLF7873C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*F/L DOOR MIRROR	Crumpled	480.00 FL	*480.00 FL
2	1		*F/L DOOR	Dented	1,480.00 FL	*1,380.00 FL
3	1		*F/L DOOR MIRROR COVER	Missing	135.00 FN	*135.00 FN
4	1		*F/L DOOR MIRROR LEN	Missing	90.00 FN	*90.00 FN
5	1		*F/L DOOR MIRROR GARNISH	Scratched	30.00 FN	*30.00 FN
6	1		*F/L DOOR GARNISH	Scratched	100.00 FN	*100.00 FN
7	1		*F/L DOOR TOP MOULDING	Cut	180.00 FN	*180.00 FN
					Sub Total (\$\$)	2,495.00
					- List Item Discount on L Items 10.00/20.00% (\$\$)	196.00
					- Nett Item Discount on N Items 20.00/20.00% (\$\$)	107.00
					Total Parts (\$\$)	2,192.00

F=Franchise part. L=ListItemDisc. N=NettItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO RESPRAY F/L DOOR AND F/L DOOR MIRROR ,RL DOOR ,EAR FENDER FL AFILKER	New	900.00	800.00
2	TO LABOUR CHARGE FOR REMOVING F/L DOOR OUT TO FACILITATE REPAIRS AND REPLACEMENT OF PARTS	New	750.00	650.00
3	TRANSFER F/L DOORMECHANISM	New	100.00	80.00
Gross Labour Cost (\$\$)			1,750.00	1,530.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >