

LCRF PTE LTD
CARROS CENTER
60 JALAN LAM HUAT #04-01 S(737869)
Main +65 62524991

Ms FWD Singapore Pte Ltd
Date: 9/12/2019
Attn : MOTOR CLAIMS DEPT

ESTIMATE

VEHICLE NO: SLF7873C
Chassis No: JM6BN22A8G0345968
MAKE / MODEL : Mazda 3 Sedan 1.5 AT
DATE OF ACCIDENT : 06/12/2019
YOUR INSURED VEHICLE NUMBER :SGR1836X
MILEAGE : 243273 km

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

	<u>PARTS DESCRIPTION</u>	<u>QTY</u>	<u>UNIT PRICE</u>	<u>LIST PRICE</u>
1	F/R door mirror / CRY	1PC	\$480.00	\$480.00
2	F/R door / DO	1PC	\$1,480.00	\$1,480.00
LIST TOTAL S\$:				\$1,960.00
10% DISCOUNT S\$:				\$196.00
				<u>\$1,764.00</u>

	<u>LABOUR CHARGES</u>	
1	To labour charge for removing F/R door out to facilitate repairs and replacement of parts	\$750.00 650.
2	To respray F/R door and F/R door mirror, RL door, Rear fender, FL A-Pillar	\$900.00 800
3	Transfer F/R doormechanism	\$100.00 80
LABOUR TOTAL S\$:		\$1,750.00
TOTAL S\$:		\$3,514.00
7% GST		\$245.98
GRAND TOTAL S\$:		<u>\$3,759.98</u>

Sun Pin (UIC)
09/12/2019.
TP without prejudice.

Repair day - 5 days.

Lump Sum
~~Ref~~ After spray photo