

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/III19021641/EPA3Q2

**Date:** 27/04/2020

### REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D19MFL0005549
<b>Claimant Vehicle No :</b>	GBD9366R	<b>Insured Vehicle No :</b>	GBH4942P
Date of Loss:	28/11/2019	Nature of Claim:	TP
		Claim No:	MFL2019D0001597

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>GBD9366R</b>		
Make & Model:	MITSUBISHI L200, 2.5 D TRITON DOUBLE CAB (M)	Engine No:	4D56UCFS7763
Reg. Date:	22/07/2015 (Man. Year: 2015)	Chassis No:	MMBJYKB40FD062406
Colour:	Silver	Odometer:	65674 km
Engine Capacity:	2477 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	245/70 R16	Rear Tyre Size:	245/70 R16
Front Left Side:	Yokohama 5 mm	Rear Left Side:	Yokohama 5 mm
Front Right Side:	Yokohama 5 mm	Rear Right Side:	Yokohama 5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	4,250.00	2,860.20	1,389.80	32.70
Miscellaneous Items	0.00	0.00	0.00	
Labour	980.00	800.00	180.00	18.37
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>5,230.00</b>	<b>3,660.20</b>	<b>1,569.80</b>	<b>30.02</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,950.00</b>		
<b>(S\$)</b>	5,230.00	2,950.00	2,280.00	43.59
<b>+ GST 7.00/7.00% (S\$)</b>	366.10	206.50	159.60	43.59
<b>Nett Amount (S\$)</b>	<b>5,596.10</b>	<b>3,156.50</b>	<b>2,439.60</b>	<b>43.59</b>
<b>+ Car Rental (3.0 x S\$80.00/day + 7.00% GST) (S\$)</b>		256.80		
<b>+ Doc/Search Fee (S\$)</b>		7.45		
<b>Nett Liability (S\$)</b>		<b>3,420.75</b>		

### INSPECTION

Date of Assignment: 06/12/2019

Date Inspected: 11/12/2019 Inspected At:

Huatiang Contractor Pte Ltd (HQ)  
9 Benoi Crescent  
Singapore 629972

Estimated Period of Repair: 3.0 days

---

**Adjuster:** CHEN TSUE YEE

**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 27 Feb 2020)	
<b>Parts:</b>	N/A	mitsubishi L200 2.5 D TRITON DOUBLE CAB (M) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for GBD9366R)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE ASSY	Dented	2,500.00 F	*2,500.00 FL
2	1		*REAR LEFT TAILLAMP ASSY	Broken	650.00 F	*650.00 FL
3	1		*REAR LEFT REFLECTOR	Broken	200.00 F	*28.00 FL
4	1		*REAR NUMBER PLATE ASSY	Not Necessary	50.00 F	*- FL
5	1		*REAR REVERSE SENSOR COMPLETE ASSY	Not Necessary	850.00 F	*- FL

F=Franchise part. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>4,250.00</b>	<b>3,178.00</b>
<b>- List Item Discount on L Items 0.00/10.00% (S\$)</b>	<b>0.00</b>	<b>317.80</b>
<b>Total Parts (S\$)</b>	<b>4,250.00</b>	<b>2,860.20</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	BODY	New	480.00	400.00
2	PAINT	New	500.00	400.00
<b>Gross Labour Cost (\$)</b>			<b>980.00</b>	<b>800.00</b>

Report was unsubmitted during this print-out.

**< END OF ESTIMATES >**